

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Penrith South Public School (4138)  
**Region :** Western Sydney  
**State Electorate :** Penrith  
**Local Government Area :** Penrith

**Initial Survey :** Noel Arnold & Associates : 12 - Jun - 2008  
**Reviewed By :** Parsons Brinckerhoff : 14 - May - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Library - 1958 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - R0001 - Principal (24.52 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0002 - Clerical Office (13.08 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0003 - Movement (23.66 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0004 - Staff Toilet (4.81 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0005 - Staff Toilet (4.77 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0006 - Cleaning Supplies (7.74 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0007 - Distribution Board (0.49 m2)**

No Asbestos	Note: No inspection of live electrical installation.					
-------------	--	--	--	--	--	--

**B00A - R0008 - Staff Room (94.95 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0009 - Security Store (20.88 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0010 - Sick Bay (15.08 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00A/R0010/Floor Coverings Res/Textile/S9					<b>Chrysotile (White asbestos)</b>

**B00A - R0011 - Movement (7.19 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4138/B00A/R1001/Ceiling Structures/Linings/S8					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0012 - Staff Toilet (4.03 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0013 - Deputy Principal (16.45 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0014 - Clerical Office/Workroom (17.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0015 - General Storeroom (3.67 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0016 - Entry Vestibule (22.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0017 - Duplicating Workroom (19.59 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0018 - General Storeroom (1.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0019 - Cleaning Distributed Store (0.8 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0020 - Clerical Office (17.57 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0021 - External Movement (90.13 m2)</b>						
No Asbestos						
<b>B00A - R0022 - Lift (4.42 m2)</b>						
No Asbestos						
<b>B00A - R0023 - Lift (2.25 m2)</b>						
No Asbestos						
<b>B00A - R0024 - Movement (9.57 m2)</b>						
No Asbestos						
<b>B00A - R1001 - Reading Area (51.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite		4138/B00A/R1001/Ceiling Structures/Linings/S8			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1002 - Movement (20.99 m2)</b>						
No Asbestos						
<b>B00A - R1003 - Library Office/Workroom (18.74 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1004 - Library Office/Workroom (6.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1006 - Distribution Board (0.93 m2)</b>					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1007 - Staff Toilet (4.04 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1008 - Cleaning Distributed Store (0.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1009 - Toilets - Girls (3.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1010 - Library Office/Workroom (12.64 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1011 - Seminar/Study (12.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1001/Ceiling Structures/Linings/S8				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1014 - Lift (2.25 m2)</b>						
No Asbestos						
<b>B00A - R1015 - Movement (5.24 m2)</b>						
No Asbestos						
<b>B00A - R1016 - Reading Area (215.36 m2)</b>						
Ceiling Structures/Linings	Vermiculite	4138/B00A/R1016/Ceiling Structures/Linings/S24				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1973 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	16m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Toilets - Girls (1.59 m2)**

No Asbestos

**B00B - R0002 - Home Base Store (10.95 m2)**

No Asbestos

**B00B - R0003 - Home Base Store (8.06 m2)**

No Asbestos

**B00B - R0004 - Home Base (91.63 m2)**

No Asbestos

**B00B - R0005 - External Movement (75.8 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00B/R0005/Ceiling Structures/Linings/S5				<b>Chrysotile (White asbestos) , Amosite (Brown asbestos)</b>	

**B00B - R0006 - External Movement (131.02 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	132m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00B/R0005/Ceiling Structures/Linings/S5				<b>Chrysotile (White asbestos) , Amosite (Brown asbestos)</b>	

**B00B - R0009 - External Movement (4.94 m2)**

No Asbestos

**B00B - R0010 - Movement (19.69 m2)**

No Asbestos

**B00B - R0012 - Home Base (66.34 m2)**

No Asbestos

**B00B - R0013 - Home Base (65.79 m2)**

No Asbestos

**B00B - R0016 - Seminar/Study (36.77 m2)**

No Asbestos

**B00B - R0017 - External Movement (78.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00B/R0005/Ceiling Structures/Linings/S5				<b>Chrysotile (White asbestos) , Amosite (Brown asbestos)</b>	

**B00B - R0018 - Home Base Store (11.73 m2)**

No Asbestos

**B00B - R0019 - Home Base Store (4.38 m2)**

No Asbestos

**B00B - R0020 - Practical Activities - 1hb (7.04 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0024 - Home Base (83.51 m2)</b>						
No Asbestos						
<b>B00B - R0025 - Practical Activities - 1hb (9.77 m2)</b>						
No Asbestos						
<b>B00B - R0026 - Home Base Store (4.27 m2)</b>						
No Asbestos						
<b>B00B - R0027 - External Movement (4.28 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	4138/B00B/R0027/Ceiling Structures/Linings/S20					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Administration - 1958 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00C - R0001 - Home Base (68.3 m2)**

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
					<b>Assumed Asbestos - HECLA Heater unit</b>	

**B00C - R0002 - Personal Effects Storage (6.37 m2)**

No Asbestos

**B00C - R0003 - External Movement (4.74 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00C - R0004 - Home Base (68.19 m2)**

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
					<b>Assumed Asbestos - HECLA Heater unit</b>	

**B00C - R0005 - Home Base (68.46 m2)**

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
					<b>Assumed Asbestos - HECLA Heater unit</b>	

**B00C - R0006 - Movement (6.98 m2)**

No Asbestos

**B00C - R0007 - External Movement (9.85 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00C - R0008 - Home Base (68.66 m2)**

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
					<b>Assumed Asbestos - HECLA Heater unit</b>	

**B00C - R0009 - Home Base (45.9 m2)**

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
					<b>Assumed Asbestos - HECLA Heater unit</b>	

**B00C - R0010 - Practical Activities - 1hb (21.91 m2)**

No Asbestos

**B00C - R0011 - Personal Effects Storage (6.39 m2)**

No Asbestos

**B00C - R0012 - External Movement (4.9 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00C - R0013 - Interview (19.48 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00C - R0014 - Disabled Shower/Toilet (5.14 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1958 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - External Movement (20.29 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00D - R0002 - Home Base (69.21 m2)**

No Asbestos

**B00D - R0003 - Home Base (103.22 m2)**

No Asbestos

**B00D - R0004 - External Movement (18.77 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1958 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00E - R0001 - Home Base (57.86 m2)**

No Asbestos

**B00E - R0002 - Home Base Store (5.23 m2)**

No Asbestos

**B00E - R0003 - Distribution Board (3.07 m2)**

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0003/Wall Linings Internal/S21				<b>Chrysotile (white asbestos)</b>	
Electrical Backing Board	Resinous Board	2Unit	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4138/B00E/R0003/Electrical Backing Board/S22				<b>Chrysotile (white asbestos)</b>	
Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard - Metal Cased unit -**

**B00E - R0004 - Personal Effects Storage (4.3 m2)**

No Asbestos

**B00E - R0005 - Movement (5.77 m2)**

No Asbestos

**B00E - R0006 - External Movement (1.64 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00E - R0007 - Home Base (57.83 m2)**

No Asbestos

**B00E - R0008 - Home Base Store (5.26 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1958 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - Home Base (56.77 m2)**

No Asbestos

**B00F - R0002 - Home Base Store (4.7 m2)**

No Asbestos

**B00F - R0005 - Cleaning Distributed Store (0.52 m2)**

No Asbestos

**B00F - R0006 - External Movement (1.65 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00F - R0007 - Cleaning Distributed Store (0.52 m2)**

No Asbestos

**B00F - R0008 - Home Base (56.47 m2)**

No Asbestos

**B00F - R0009 - Home Base Store (4.72 m2)**

No Asbestos

**B00F - R0010 - Personal Effects Storage (14.49 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1958 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4138/B00G/Underfloor Voids/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**Interior**

**B00G - R0001 - Home Base Store (5.36 m2)**

No Asbestos

**B00G - R0004 - External Movement (1.29 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00G - R0007 - Home Base Store (5.31 m2)**

No Asbestos

**B00G - R0008 - General Storeroom (5.27 m2)**

No Asbestos

**B00G - R0012 - Cleaning Distributed Store (0.63 m2)**

No Asbestos

**B00G - R0013 - External Movement (1.68 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00G - R0014 - Cleaning Distributed Store (0.45 m2)**

No Asbestos

**B00G - R0015 - Home Base (57.37 m2)**

No Asbestos

**B00G - R0016 - Home Base (57.05 m2)**

No Asbestos

**B00G - R0017 - Home Base Store (4.76 m2)**

No Asbestos

**B00G - R0018 - Personal Effects Storage (7.43 m2)**

No Asbestos

**B00G - R0019 - External Movement (1.37 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00G - R0020 - Personal Effects Storage (13.68 m2)**

No Asbestos

**B00G - R0021 - Home Base (107.64 m2)**

No Asbestos

**B00G - R0022 - Practical Activities - 1hb (6.87 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - R0023 - Plant (0.65 m2)**

No Asbestos

**B00G - R0024 - Movement (6.19 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 1958 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00H - R0001 - Home Base Store (5.39 m2)**

No Asbestos

**B00H - R0002 - Personal Effects Storage (6.67 m2)**

No Asbestos

**B00H - R0003 - External Movement (1.39 m2)**

No Asbestos

**B00H - R0004 - Home Base (56.39 m2)**

No Asbestos

**B00H - R0005 - Home Base (57.17 m2)**

No Asbestos

**B00H - R0006 - Home Base Store (4.07 m2)**

No Asbestos

**B00H - R0009 - Personal Effects Storage (6.69 m2)**

No Asbestos

**B00H - R0010 - External Movement (4.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>

**B00H - R0011 - Home Base (57.51 m2)**

No Asbestos

**B00H - R0012 - Home Base Store (4.13 m2)**

No Asbestos

**B00H - R0013 - General Storeroom (12.03 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 2001 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B001/Eaves Linings/S14					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B001 - R0001 - No Access (7.77 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1940 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00J/Eaves Linings/S15					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00J - R0001 - External Movement (11.35 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>

**B00J - R0002 - Staff Toilet (2.39 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>

**B00J - R0003 - Canteen Office/Store (4.04 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>

**B00J - R0004 - Movement (13.69 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>
Infill panel above door	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00J/R0007/Infill panel above door/S23					<b>Chrysotile (white asbestos)</b>

**B00J - R0007 - Canteen (31.67 m2)**

Infill panel above door	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00J/R0007/Infill panel above door/S23					<b>Chrysotile (white asbestos)</b>

**B00J - R0008 - Canteen Office/Store (2.9 m2)**

No Asbestos

**B00J - R0009 - Canteen Office/Store (3.06 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 1958 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
In-fill-panel	Compressed AC Sheet	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00K/In-fill-panel/S2				<b>Chrysotile (White asbestos)</b>	

**Interior****B00K - R0001 - External Movement (50.86 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00K - R0002 - Personal Effects Storage (8.15 m2)**

No Asbestos

**B00K - R0003 - Home Base Store (5.53 m2)**

No Asbestos

**B00K - R0004 - Home Base (57.27 m2)**

No Asbestos

**B00K - R0005 - Home Base (56.81 m2)**

No Asbestos

**B00K - R0006 - Home Base Store (5.44 m2)**

No Asbestos

**B00K - R0010 - Home Base Store (5.47 m2)**

No Asbestos

**B00K - R0011 - Home Base (57.36 m2)**

No Asbestos

**B00K - R0013 - Practical Activities - 1hb (12.6 m2)**

No Asbestos

**B00K - R0014 - General Storeroom (3.43 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 1958 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
In-fill-panel	Compressed AC Sheet	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00K/In-fill-panel/S2				<b>Chrysotile (White asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Flat AC Sheeting	3m2	West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4138/B00L/Underfloor Voids/S13				<b>Chrysotile (white asbestos)</b>	

**Interior**

**B00L - R0001 - External Movement (57.47 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/R0006/Ceiling Structures/Linings/S1				<b>Chrysotile (White asbestos)</b>	

**B00L - R0010 - Movement (7.07 m2)**

No Asbestos

**B00L - R0012 - Staff Toilet - Pre (2.53 m2)**

No Asbestos

**B00L - R0013 - Toilets - Boys/Girls - Pre (4.13 m2)**

No Asbestos

**B00L - R0014 - Toilets - Boys/Girls - Pre (7.93 m2)**

No Asbestos

**B00L - R0015 - Home Base - Pre (52.52 m2)**

No Asbestos

**B00L - R0018 - Home Base Store (12.8 m2)**

No Asbestos

**B00L - R0019 - Home Base Store (12.8 m2)**

No Asbestos

**B00L - R0020 - Home Base Store (1.58 m2)**

No Asbestos

**B00L - R0021 - Home Base Store (1.58 m2)**

No Asbestos

**B00L - R0023 - Home Base Store (8.92 m2)**

No Asbestos

**B00L - R0024 - No Access (0.27 m2)**

Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard - Unable to access**

**B00L - R0025 - Home Base (59.59 m2)**

No Asbestos

**B00L - R0026 - Practical Activities - 1hb (7.79 m2)**

No Asbestos

**B00L - R0027 - Home Base (43.7 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00L - R0028 - Practical Activities - 1hb (16.34 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	6m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Eaves Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00E/Gable Verge Lining/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**Interior**

**B00M - R0001 - External Movement (18.02 m2)**

No Asbestos

**B00M - R0002 - Toilets - Girls (49.06 m2)**

No Asbestos

**B00M - R0003 - General Storeroom (5.61 m2)**

No Asbestos

**B00M - R0004 - No Access (16.96 m2)**

No Asbestos

**B00M - R0005 - Toilets - Boys (58.44 m2)**

No Asbestos

**B00M - R0006 - Cleaning Supplies (5.61 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00Q - Other-Community Use - 1958 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Wall Cladding	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/Wall Cladding/S4				<b>Chrysotile (White asbestos) , Amosite (Brown asbestos)</b>	
Eaves Linings	Flat AC Sheeting	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/Eaves Linings/S16				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00Q - R0001 - Community Clinic (11.18 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0001/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Wall Linings Internal/S18				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Floor Coverings Res/Textile/S19				<b>Chrysotile (white asbestos)</b>	

**B00Q - R0002 - Staff Toilet (4.18 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Wall Linings Internal/S18				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Floor Coverings Res/Textile/S19				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0001/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos)</b>	

**B00Q - R0003 - Community Clinic (11.13 m2)**

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Wall Linings Internal/S18				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Floor Coverings Res/Textile/S19				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0001/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos)</b>	

**B00Q - R0004 - Community Clinic (6.97 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Wall Linings Internal/S18				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0002/Floor Coverings Res/Textile/S19				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4138/B00Q/R0001/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00S - Communal Facilities/Building Services - 1996 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

#### Interior

**B00S - R0001 - Distribution Board (0.69 m2)** Note: No inspection of live electrical installation.

No Asbestos

**B00S - R0002 - Staff Kitchen (25.88 m2)**

No Asbestos

**B00S - R0003 - General Assistant/Bulk Store (14.05 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00S - R0004 - Garden Store (13.24 m2)**

No Asbestos

**B00S - R0005 - Toilets - Girls (7.91 m2)**

No Asbestos

**B00S - R0007 - Staff Shower/Change (2.41 m2)**

No Asbestos

**B00S - R0008 - Toilets - Boys (5.93 m2)**

No Asbestos

**B00S - R0009 - P.E. Store (16.12 m2)**

No Asbestos

**B00S - R0010 - Hall Chair Store (9.93 m2)**

No Asbestos

**B00S - R0011 - Sports Store (16.16 m2)**

No Asbestos

**B00S - R0012 - Disabled Toilet (6.62 m2)**

No Asbestos

**B00S - R0013 - Cleaning Distributed Store (3.1 m2)**

No Asbestos

**B00S - R0014 - External Movement (40.28 m2)**

No Asbestos

**B00S - R0015 - Communal Space (231.18 m2)**

No Asbestos

**B00S - R0016 - Plant (0.47 m2)**

No Asbestos

**B00S - R0017 - External Movement (2.65 m2)**

No Asbestos

**B00S - R0018 - External Movement (2.01 m2)**

No Asbestos

**B00S - R0019 - Raised Platform (46.1 m2)**

No Asbestos

**B00S - R0020 - Lift (1.34 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00T - Building Services - 2010 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00T - R0001 - Sports Store (91.37 m2)**

No Asbestos

**B00T - R0002 - Sports Store (31.8 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

4138\_ASB\_010313\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017