

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Parkes East Public School (4204)
Region : Western NSW
State Electorate : Orange
Local Government Area : Parkes

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Reviewed By : : 30 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 4204/B00A/Gable Verge Lining/S8	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 4204/B00A/Eaves Linings/S2					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 4204/B00A/In-fill-panel/S1	32m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Sla on ground construction.					

Interior

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Deputy Principal

No Asbestos

B00A - R0004 - Deputy Principal

No Asbestos

B00A - R0005 - Clerical Office

No Asbestos

B00A - R0006 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4204/B00A/R0015/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0007 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 4204/B00A/R0015/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Staff Room Annexe

No Asbestos

B00A - R0010 - Staff Room

No Asbestos

B00A - R0011 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 4204/B00A/R0015/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 4204/B00A/Eaves Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0014 - Duplicating Workroom

No Asbestos

B00A - R0015 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 4204/B00A/R0015/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0016 - Sick Bay

No Asbestos

B00A - R0017 - Interview

No Asbestos

B00A - R0018 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - Special Programs Room

No Asbestos

B00A - R0022 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
4204/B00A/Eaves Linings/S2

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00B/Gable Verge Lining/S32				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00B/R0007/Ceiling Structures/Linings/S31				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00A/In-fill-panel/S1				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Home Base Store

No Asbestos

B00B - R0003 - Personal Effects Storage

No Asbestos

B00B - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	0.1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00B/R0004/Electrical Backing Board/S29				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00B/R0004/Wall Linings Internal/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00B - R0005 - Home Base Store

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00B/R0007/Ceiling Structures/Linings/S31				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Infill panels	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00A/In-fill-panel/S1				Chrysotile (white asbestos)	



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1962 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	24m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
4204/B00C/Gable Verge Lining/S28					Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4204/B00C/Eaves Linings/S27					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4204/B00C/Underfloor Voids - Packing to Floor Joists/S25					Chrysotile (white asbestos)	

Interior

B00C - R0001 - Cleaning Distributed Store

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	22m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4204/B00C/R0004/Wall Linings Internal/S24					Chrysotile (white asbestos)	

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0011 - Staff Room Annexe

No Asbestos

B00C - R0012 - General Storeroom

No Asbestos

B00C - R0013 - Personal Effects Storage

No Asbestos

B00C - R0014 - Home Base Store

No Asbestos

B00C - R0015 - Home Base

No Asbestos

B00C - R0016 - Home Base

No Asbestos

B00C - R0017 - Home Base Store

No Asbestos

B00C - R0018 - Personal Effects Storage

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0019 - Movement						
No Asbestos						
B00C - R0020 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0021 - General Storeroom						
No Asbestos						
B00C - R0022 - General Storeroom						
No Asbestos						
B00C - R0023 - Craft Store						
No Asbestos						
B00C - R0024 - External Movement						
No Asbestos						
B00C - R0025 - External Movement						
No Asbestos						
B00C - R0026 - External Movement						
No Asbestos						
B00C - R0027 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

4204/B00C/R0027/Ceiling Structures/Linings/S26

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 4204/B00D/Gable Verge Lining/S23	5m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting 4204/B00D/Eaves Linings/S21	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Ends	Flat AC Sheeting 4204/B00D/Gable Ends/S20					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Home Base Store

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 4204/B00D/R0007/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0008 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 4204/B00D/R0007/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1962 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00E/Gable Verge Lining/S19				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00E/Eaves Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

Interior

B00E - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00E/R0001/Partition Walls (Cubicles)/S7				Chrysotile (white asbestos)	

B00E - R0002 - Cleaning Distributed Store

No Asbestos

B00E - R0003 - Withdrawal Space - 1hb

No Asbestos

B00E - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00E/R0001/Partition Walls (Cubicles)/S7				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/Gable Verge Lining/S22				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Underfloor Voids	Non Accessible Area - Area inaccessible no hatch.					
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0002 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0005 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0006 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00F - R0007 - Home Base

No asbestos found No Asbestos Found

B00F - R0008 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0008/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00F - R0009 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00F/R0008/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00G/Gable Verge Lining/S12					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	16m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00A/In-fill-panel/S1					Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area - Shallow void without manhole.					
Ceiling Voids	No Asbestos Found					

Interior

B00G - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4204/B00A/Eaves Linings/S2					

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Comms box cover. 'Lebah' resinous board	Resinous Board	0.1m2	Cover	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00G/R0003/Comms box cover. 'Lebah' resinous board/S10					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00G/R0003/Wall Linings Internal/S11					Chrysotile (white asbestos)

B00G - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00G/R0004/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

B00G - R0005 - Home Base

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00G/R0004/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

B00G - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 1994 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00L - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0002 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0003 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0004 - Plant

No Asbestos

B00L - R0005 - Distribution Board

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0006 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 1953 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00N/Eaves Linings/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Variable positions	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	4204/B00N/Underfloor Voids - Packing to Floor Joists/S16			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00N - R0001 - Withdrawal Space - 1hb

No Asbestos

B00N - R0002 - Interview

No Asbestos

B00N - R0003 - Withdrawal Space - 1hb

No Asbestos

B00N - R0004 - Staff Kitchen

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Withdrawal Space - 1hb

No Asbestos

B00N - R0007 - General Storeroom

No Asbestos

B00N - R0008 - Staff Shower/Change

Wall Linings Internal	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00N/R0010/Wall Linings Internal/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	3m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00N/R0010/Wall Linings Internal/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0010 - Movement

Wall Linings Internal	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00N/R0010/Wall Linings Internal/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Ceiling Structures/Linings	Flat AC Sheeting	6.63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4204/B00N/R0010/Ceiling Structures/Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0011 - Withdrawal Space - 1hb

No Asbestos

B00N - R0012 - General Storeroom

No Asbestos

B00N - R0013 - Staff Shower/Change

No Asbestos

B00N - R0014 - General Storeroom

No Asbestos

B00N - R0015 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00N - R0016 - Movement						
Wall Linings Internal	Flat AC Sheeting		4204/B00N/R0016/Wall Linings Internal/S17			No Asbestos Detected
B00N - R0017 - General Storeroom						
No Asbestos						
B00N - R0018 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B000 - R0001 - Access Shower/Toilet/Change

No Asbestos

B000 - R0002 - Main Switch Board

No Asbestos

B000 - R0003 - Cleaning Distributed Store

No Asbestos

B000 - R0004 - Plant

No Asbestos

B000 - R0005 - Movement

No Asbestos

B000 - R0006 - Toilets - Boys

No Asbestos

B000 - R0007 - Sound Cupboard

No Asbestos

B000 - R0008 - Toilets - Girls

No Asbestos

B000 - R0009 - Movement

No Asbestos

B000 - R0010 - P.E. Store

No Asbestos

B000 - R0011 - Communal/Performance Store

No Asbestos

B000 - R0012 - Communal Space

No Asbestos

B000 - R0013 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11660 - Learning Unit - Standard With P.A.A. : Placement Date - 6/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017