

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Parkview Public School (4413)
Region : Riverina
State Electorate : Murray
Local Government Area : Leeton

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Greencap-NAA : 18 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1972 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Asbestos Dust	0.5m2	Throughout	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)
Assumed Asbestos - Area inaccessible. Associated with						

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - General Storeroom

Ceiling Structures/Linings	Strawboard 4413/B00A/R0002/Ceiling Structures/Linings/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4413/B00A/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4413/B00A/R0004/Floor Coverings Res/Textile/S1	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00A - R0003 - Staff Toilet

Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4413/B00A/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0006 - Staff Toilet

Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4413/B00A/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0007 - General Storeroom

Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4413/B00A/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0015 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 4413/B00A/R0015/Wall Linings Internal/S3	3m2	Door Lining	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00A/R0015/Wall Linings Internal/S3	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical Mounting Board	Resinous Board	1Unit	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00A - R0017 - Staff Room

Floor Coverings Res/Textile	Vinyl Tiles 4413/B00A/R0004/Floor Coverings Res/Textile/S1	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00A/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

- B00A - R0019 - Toilet - Lobby**
Recently Modified Space Requires Inspection
- B00A - R0020 - Staff Toilet**
Recently Modified Space Requires Inspection
- B00A - R0021 - Movement**
Recently Modified Space Requires Inspection
- B00A - R0022 - Staff Room**
Recently Modified Space Requires Inspection
- B00A - R0023 - Principal**
Recently Modified Space Requires Inspection
- B00A - R0024 - Clerical Office**
Recently Modified Space Requires Inspection
- B00A - R0025 - Interview**
Recently Modified Space Requires Inspection
- B00A - R0026 - Computer Room**
Recently Modified Space Requires Inspection
- B00A - R0027 - Clerical Office**
Recently Modified Space Requires Inspection
- B00A - R0028 - Sick Bay**
Recently Modified Space Requires Inspection
- B00A - R0029 - General Storeroom**
Recently Modified Space Requires Inspection
- B00A - R0030 - Clerical Office**
Recently Modified Space Requires Inspection
- B00A - R0031 - Computer Room**
Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Asbestos Dust	0.5m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Area inaccessible. Associated with**Interior****B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

B00B - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

B00B - R0004 - Craft Store

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00A/R0004/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00B - R0005 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00A/R0004/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00B - R0006 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00A/R0004/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00B - R0007 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

B00B - R0008 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00A/R0004/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Straw board				No Asbestos Detected	
4413/B00A/R0002/Ceiling Structures/Linings/S4						

Ceiling Structures/Linings	Flat AC Sheeting	89m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00D/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	

B00B - R0009 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00A/R0004/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	89m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00B - R0010 - Deputy Principal						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4413/B00A/R0004/Floor Coverings Res/Textile/S1	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	14m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00B - R0011 - Distribution Board						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00A/R0015/Wall Linings Internal/S3	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting 4413/B00A/R0015/Wall Linings Internal/S3	5m2	Door linings	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00B - R0012 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	4m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles 4413/B00A/R0004/Floor Coverings Res/Textile/S1	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00B - R0013 - Toilets - Boys/Girls						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00B - R0014 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	4m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles 4413/B00A/R0004/Floor Coverings Res/Textile/S1	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00B - R0015 - Toilets - Boys/Girls						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	4m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos)	
B00B - R0016 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4413/B00A/R0004/Floor Coverings Res/Textile/S1	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	90m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Asbestos Dust	0.5m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction. Associated with						
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior

B00C - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
4413/B00C/R0002/Ceiling Structures/Linings/S6						

B00C - R0002 - Raised Platform

Ceiling Structures/Linings	Flat AC Sheeting	91m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00C/R0002/Ceiling Structures/Linings/S6						
Chrysotile (white asbestos)						

Partition Walls (Cubicles)	Flat AC Sheeting					No Asbestos Detected
4413/B00C/R0002/Partition Walls (Cubicles)/S2						

Wall Linings Internal	Flat AC Sheeting	4m2	North & west	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00C/R0002/Ceiling Structures/Linings/S6						
Chrysotile (white asbestos)						

B00C - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00C/R0002/Ceiling Structures/Linings/S6						
Chrysotile (white asbestos)						

B00C - R0004 - Cleaning Supplies Store

No Asbestos

B00C - R0005 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4413/B00C/R0002/Ceiling Structures/Linings/S6						
Chrysotile (white asbestos)						

B00C - R0006 - Staff Toilet

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Canteen Office/Store

No Asbestos

B00C - R0009 - Canteen

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
4413/B00A/R0015/Wall Linings Internal/S3						

Electrical Mounting Board	Resinous Board	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00C - R0012 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4413/B00C/R0002/Ceiling Structures/Linings/S6						
Chrysotile (white asbestos)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Asbestos Dust	0.5m2	Throughout	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)
Assumed Asbestos - Area inaccessible. Associated with						

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4413/B00A/R0004/Floor Coverings Res/Textile/S1 Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				4413/B00D/R0004/Ceiling Structures/Linings/S7 Chrysotile (white asbestos)		
Ceiling Structures/Linings	Straw board					No Asbestos Detected
				4413/B00A/R0002/Ceiling Structures/Linings/S4		

B00D - R0003 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				4413/B00D/R0004/Ceiling Structures/Linings/S7 Chrysotile (white asbestos)		

B00D - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				4413/B00D/R0004/Ceiling Structures/Linings/S7 Chrysotile (white asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Stored panels	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				4413/B00D/R0004/Partition Walls (Cubicles)/S8 Chrysotile (white asbestos)		

B00D - R0005 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	3m2	Door lining	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				4413/B00A/R0015/Wall Linings Internal/S3 Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
				4413/B00A/R0015/Wall Linings Internal/S3 Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)
				4413/B00D/R0004/Ceiling Structures/Linings/S7 Chrysotile (white asbestos)		

B00D - R0007 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4413/B00A/R0004/Floor Coverings Res/Textile/S1 Chrysotile (white asbestos)		
Ceiling Structures/Linings	Straw board					No Asbestos Detected
				4413/B00A/R0002/Ceiling Structures/Linings/S4		
Ceiling Structures/Linings	Flat AC Sheeting	60m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				4413/B00D/R0004/Ceiling Structures/Linings/S7 Chrysotile (white asbestos)		

B00D - R0008 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4413/B00A/R0004/Floor Coverings Res/Textile/S1 Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	70m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00D - R0009 - Staff Room Annexe						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4413/B00A/R0004/Floor Coverings Res/Textile/S1	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	13m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00D - R0010 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00D - R0011 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4413/B00A/R0004/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Straw board 4413/B00A/R0002/Ceiling Structures/Linings/S4				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting 4413/B00D/R0004/Ceiling Structures/Linings/S7	70m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 1971 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	North & west	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4413/B00E/R0002/Wall Linings Internal/S11					Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	2Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B00E - R0003 - Library Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4413/B00E/R0003/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4413/B00E/R0003/Floor Coverings Res/Textile/S10					

B00E - R0004 - Reading Area

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					No Asbestos Detected
	4413/B00E/R0003/Floor Coverings Res/Textile/S10					
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4413/B00E/R0003/Floor Coverings Res/Textile/S10					

B00E - R0005 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4413/B00E/R0003/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-After School Care - 1998 - Steel (Steel)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00G - R0001 - Other-After School Care

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Communal Space

No Asbestos

B00H - R0002 - Raised Platform

No Asbestos

B00H - R0003 - Hall Chair Store

No Asbestos

B00H - R0004 - Communal/Performance Store

No Asbestos

B00H - R0005 - P.E. Store

No Asbestos

B00H - R0006 - Toilet - Lobby

No Asbestos

B00H - R0007 - Toilets - Girls

No Asbestos

B00H - R0008 - Sound Cupboard

No Asbestos

B00H - R0009 - Toilet - Lobby

No Asbestos

B00H - R0010 - Toilets - Boys

No Asbestos

B00H - R0011 - Cleaning Distributed Store

No Asbestos

B00H - R0012 - Plant

No Asbestos

B00H - R0013 - Main Switch Board

No Asbestos

B00H - R0014 - Access Shower/Toilet

No Asbestos

B00H - R0015 - Movement

No Asbestos

B00H - R0016 - Movement

No Asbestos

B00H - R0017 - Movement

No Asbestos

B00H - R0018 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Storage - 1971 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00I - R0001 - General Assistant/Bulk Store

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11392 - Learning Unit - Standard With P.A.A. : Placement Date - 1/07/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D12440 - Learning Unit - Standard/Withdrawal : Placement Date - 29/01/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 603 - D12785 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 1/05/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12908 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13314 - Learning Unit - Standard With P.A.A. : Placement Date - 16/02/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14430 - Learning Unit - Standard With P.A.A. : Placement Date - 28/02/2013

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D14524 - Learning Unit - Standard With P.A.A. : Placement Date - 24/06/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

- D18260 - : Placement Date - 13/02/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017