

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Petersham Public School (4502)  
**Region :** Sydney  
**State Electorate :** Summer Hill  
**Local Government Area :** Marrickville

**Initial Survey :** Noel Arnold & Associates : 11 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00B/Eaves Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**Interior**

**B00B - R0001 - Drinking Facilities**

No Asbestos

**B00B - R0002 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00B/R0004/Partition Walls (Cubicles)/S1			<b>Chrysotile (white asbestos)</b>		

**B00B - R0004 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00B/R0004/Partition Walls (Cubicles)/S1			<b>Chrysotile (white asbestos)</b>		

**B00B - R0005 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Other-Community Use/General Learning - 1940 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00C/R0003/Ceiling Structures/Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable verge lining	Flat AC Sheeting	40m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00C/Gable verge lining/S10			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00C/Eaves Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**Interior**

**B00C - R0001 - General Storeroom**

No Asbestos

**B00C - R0002 - Movement**

No Asbestos

**B00C - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00C/R0003/Ceiling Structures/Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0007 - Toilets - Boys/Girls**

No Asbestos

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0009 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4502/B00C/R0003/Ceiling Structures/Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0010 - General Storeroom**

No Asbestos

**B00C - R0011 - Movement**

No Asbestos

**B00C - R0012 - Communal/Performance Store**

No Asbestos

**B00C - R0013 - Communal Space**

No Asbestos

**B00C - R0014 - Raised Platform**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1960 - Timber (Timber)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00E - R0001 - Home Base**

No Asbestos

**B00E - R0002 - Practical Activities - 1hb**

No Asbestos

**B00E - R0003 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00F - General Learning/Administration - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Gable verge lining	Flat AC Sheeting 4502/B00F/Gable verge lining/S9	40m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		
Eaves Linings	Flat AC Sheeting 4502/B00F/Eaves Linings/S8	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Ceiling Void	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4502/B00F/Underfloor Voids - Packing to Floor Joists/S11	1m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Underfloor Voids	AC Fragments/Debris 4502/B00F/Underfloor Voids/S12	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**Interior**

**B00F - R0001 - General Storeroom**

No Asbestos

**B00F - R0002 - Movement**

No Asbestos

**B00F - R0003 - Movement**

No Asbestos

**B00F - R0004 - Home Base**

No Asbestos

**B00F - R0005 - Home Base**

No Asbestos

**B00F - R0006 - Movement**

No Asbestos

**B00F - R0007 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4502/B00F/R0012/Ceiling Structures/Linings/S3	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0008 - Home Base**

No Asbestos

**B00F - R0009 - Personal Effects Storage**

No Asbestos

**B00F - R0010 - Personal Effects Storage**

No Asbestos

**B00F - R0011 - Personal Effects Storage**

No Asbestos

**B00F - R0012 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4502/B00F/R0012/Ceiling Structures/Linings/S3	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0013 - General Storeroom**

No Asbestos

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00F - R0016 - General Storeroom**

No Asbestos

**B00F - R0017 - Special Programs Room**

No Asbestos

**B00F - R0018 - General Storeroom**

No Asbestos

**B00F - R0019 - Staff Toilet**

No Asbestos

**B00F - R0020 - Deputy Principal**

No Asbestos

**B00F - R0021 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

4502/B00F/R0012/Ceiling Structures/Linings/S3

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00F - R9001 - Sports Store**

Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4502/B00F/R9001/Ceiling Structures/Linings/S2

**Chrysotile (white asbestos)**

**B00F - R9002 - Cleaning Supplies**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4502/B00F/R9001/Ceiling Structures/Linings/S2

**Chrysotile (white asbestos)**

**B00F - R9003 - General Assistant/Bulk Store**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4502/B00F/R9001/Ceiling Structures/Linings/S2

**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Electrical Services - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00H - R0001 - Plant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Other-After School Care - 2006 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

<b>B00I - R0001 - Other-After School Care</b>	No Asbestos
<b>B00I - R0002 - Other-After School Care</b>	No Asbestos
<b>B00I - R0003 - Toilets-Unisex</b>	No Asbestos
<b>B00I - R0004 - Other-After School Care</b>	No Asbestos
<b>B00I - R0005 - Other-After School Care</b>	No Asbestos
<b>B00I - R0006 - Other-After School Care</b>	No Asbestos
<b>B00I - R0007 - Other-After School Care</b>	No Asbestos
<b>B00I - R0008 - Other-After School Care</b>	No Asbestos
<b>B00I - R0009 - Other-After School Care</b>	No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning/Library - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Home Base**

No Asbestos

**B00J - R0002 - Home Base Store**

No Asbestos

**B00J - R0003 - Practical Activities - 1hb**

No Asbestos

**B00J - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00J - R0005 - Home Base**

No Asbestos

**B00J - R0006 - Home Base Store**

No Asbestos

**B00J - R0007 - Practical Activities - 1hb**

No Asbestos

**B00J - R0008 - External Movement**

No Asbestos

**B00J - R0009 - Reading Area**

No Asbestos

**B00J - R0010 - Library Office/Workroom**

No Asbestos

**B00J - R0011 - K.L.A. Store**

No Asbestos

**B00J - R0012 - Communications Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 502 - D11009 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 30/09/2005**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	23.04 m2

**Interior**

**R1 - Clerical Office**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2

**R10 - Store**

Ceiling	Flat AC Sheet	Assumed Asbestos	12 m2
---------	---------------	------------------	-------

**R2 - Security Store**

Ceiling	Flat AC Sheet	Assumed Asbestos	1 m2
---------	---------------	------------------	------

**R3 - Duplicating Wookroom**

Ceiling	Flat AC Sheet	Assumed Asbestos	12 m2
---------	---------------	------------------	-------

**R4 - Clinic-Waiting**

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

**R5 - Staff Room**

Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2
---------	---------------	------------------	-------

**R6 - Principal**

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

**R7 - Staff Toilet**

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

**R8 - Staff Toilet**

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

**R9 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	27 m2

**OS 602 - D11858 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2010**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12679 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 31/03/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 601 - D13623 - Learning Unit - Standard/Withdrawal : Placement Date - 6/04/2006**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

**R2 - General Learning Space**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

**R3 - Store**

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 602 - D14953 - Learning Unit - Standard With P.A.A. : Placement Date - 5/05/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017