


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Parry School (5580)
Region : New England
State Electorate : Tamworth
Local Government Area : Tamworth

Initial Survey : Noel Arnold & Associates : 25 - Mar - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 2015 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior**B00A - R0001 - Entry Vestibule**

No Asbestos

B00A - R0002 - Clerical/Printing

No Asbestos

B00A - R0003 - Sick Bay

No Asbestos

B00A - R0004 - Staff Room

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Toilets-Unisex

No Asbestos

B00A - R0007 - Toilets-Unisex

No Asbestos

B00A - R0008 - Toilets-Unisex

No Asbestos

B00A - R0009 - Main Switch Board Cupboard

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0012 - Cleaning Distributed Store

No Asbestos

B00A - R0013 - Other

No Asbestos

B00A - R0014 - Security Store

No Asbestos

B00A - R0015 - Deputy Principal

No Asbestos

B00A - R0016 - Principal

No Asbestos

B00A - R0017 - Staff Room

No Asbestos

B00A - R0018 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Administration/Pupil Facilities - 2015 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 5580/B00B/Wall Cladding/S1					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0001 - Special Learning Space**

No Asbestos

B00B - R0002 - Special Programs Room

No Asbestos

B00B - R0003 - Laundry - P

No Asbestos

B00B - R0004 - Withdrawal - M

No Asbestos

B00B - R0005 - General Storeroom

No Asbestos

B00B - R0006 - Practical Activities

No Asbestos

B00B - R0007 - General Storeroom

No Asbestos

B00B - R0008 - Communications Room

No Asbestos

B00B - R0009 - Entry Vestibule

No Asbestos

B00B - R0010 - Toilets - Boys

No Asbestos

B00B - R0011 - Toilets - Boys

No Asbestos

B00B - R0012 - Toilets - Girls

No Asbestos

B00B - R0013 - Toilets-Unisex

No Asbestos

B00B - R0014 - Disabled Shower/Toilet

No Asbestos

B00B - R0015 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00B - R0016 - Cleaning Supplies

No Asbestos

B00B - R0017 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other - 2015 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Practical Activities

No Asbestos

B00C - R0002 - Special Learning Space

No Asbestos

B00C - R0003 - Breakout Area

No Asbestos

B00C - R0004 - General Storeroom

No Asbestos

B00C - R0005 - Main Switch Board

No Asbestos

B00C - R0006 - Withdrawal - M

No Asbestos

B00C - R0007 - Withdrawal - M

No Asbestos

B00C - R0008 - General Storeroom

No Asbestos

B00C - R0009 - Breakout Area

No Asbestos

B00C - R0010 - Special Learning Space

No Asbestos

B00C - R0011 - Practical Activities

No Asbestos

B00C - R0012 - External Movement

No Asbestos

B00C - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other - 2015 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00D - R0001 - Practical Activities

No Asbestos

B00D - R0002 - Home Base - Bd/Cd/Ed

No Asbestos

B00D - R0003 - Breakout Area

No Asbestos

B00D - R0004 - Home Base Store

No Asbestos

B00D - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0006 - Withdrawal - M

No Asbestos

B00D - R0007 - Withdrawal - M

No Asbestos

B00D - R0008 - Home Base Store

No Asbestos

B00D - R0009 - Breakout Area

No Asbestos

B00D - R0010 - Home Base - Bd/Cd/Ed

No Asbestos

B00D - R0011 - Practical Activities

No Asbestos

B00D - R0012 - External Movement

No Asbestos

B00D - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0AA - General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B0AA - R0002 - Principal

No Asbestos

B0AA - R0003 - Movement

No Asbestos

B0AA - R0004 - Clerical Office

No Asbestos

B0AA - R0005 - General Storeroom

No Asbestos

B0AA - R0006 - General Storeroom

No Asbestos

B0AA - R0007 - Staff Toilet

No Asbestos

B0AA - R0008 - Staff Kitchen

No Asbestos

B0AA - R0009 - Laundry

No Asbestos

B0AA - R0010 - Toilets-Unisex

No Asbestos

B0AA - R0011 - Staff Room

No Asbestos

B0AA - R0013 - Staff Study

No Asbestos

B0AA - R0015 - Movement

No Asbestos

B0AA - R0016 - General Learning Space

No Asbestos

B0AA - R0017 - General Learning Space

No Asbestos

B0AA - R0019 - Toilets - Boys/Girls

No Asbestos

B0AA - R0020 - External Movement

No Asbestos

B0AA - R0021 - Access Shower/Toilet/Change

No Asbestos

B0AA - R0022 - Clerical Office

No Asbestos

B0AA - R0023 - Entry Vestibule

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0BB - Art - 2002 - Concrete (Concrete)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B0BB - R0005 - Home Base

No Asbestos

B0BB - R0006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017