


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Palm Avenue School (5650)
Region : Western Sydney
State Electorate : Seven Hills
Local Government Area : Parramatta

Initial Survey : Parsons Brinckerhoff : 25 - Nov - 2016
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 2010 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Non Accessible Area - No Access - No manhole in building

Interior

B00A - R0001 - Principal

No Asbestos

B00A - R0002 - Deputy Principal

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Clerical Office

No Asbestos

B00A - R0005 - Duplicating Workroom

No Asbestos

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Toilet - Lobby

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Toilet - Lobby

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - General Storeroom

No Asbestos

B00A - R0013 - Interview

No Asbestos

B00A - R0014 - Interview

No Asbestos

B00A - R0015 - Staff Room

No Asbestos

B00A - R0016 - Staff Kitchen

No Asbestos

B00A - R0017 - External Movement

No Asbestos

B00A - R0018 - Movement

No Asbestos

B00A - R0019 - Clerical Office

No Asbestos

B00A - R0020 - Clerical Office

No Asbestos

B00A - R0021 - Clerical Office

No Asbestos

B00A - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 501 - D15190 - Admin Staff/Principal/Deputy/Dup/Clinic : Placement Date - 14/01/2010

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R10 - Staff Toilet

No Asbestos Found.

R11 - Cleaning Supplies

No Asbestos Found.

R12 - Handicap toilet

No Asbestos Found.

R13 - Clerk

No Asbestos Found.

R2 - Clinic-Waiting

No Asbestos Found.

R3 - Security Store

No Asbestos Found.

R4 - Duplicating Wookroom

No Asbestos Found.

R5 - Clerical Office

No Asbestos Found.

R6 - Staff Room

No Asbestos Found.

R7 - Deputy Principal

No Asbestos Found.

R8 - Principal

No Asbestos Found.

R9 - Staff Toilet

No Asbestos Found.

OS 750 - D17708 - Learning Unit - ESL : Placement Date - 12/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017