


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Peterborough School (5666)  
**Region :** Illawarra and South East  
**State Electorate :** Shellharbour  
**Local Government Area :** Shellharbour

**Initial Survey :** Noel Arnold & Associates : 22 - Apr - 2008  
**Reviewed By :** Parsons Brinckerhoff : 15 - Feb - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Support Unit - 1988 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00A - R0001 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0002 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0006 - General Storeroom**

No Asbestos

**B00A - R0007 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0009 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0010 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0011 - Toilet - P**

No Asbestos

**B00A - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0013 - Garden Store**

No Asbestos

**B00A - R0014 - Movement**

Ceiling Structures/Linings Flat AC Sheeting  
5666/B00A/R0021/Ceiling Structures/Linings/S1

**No Asbestos Detected**

**B00A - R0015 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0016 - Home Base - P**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0017 - Personal Effects Storage**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0018 - Practical Activities - Pre**

No Asbestos

**B00A - R0019 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0020 - Wheelchair Store-Special Ed**

Ceiling Structures/Linings No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0021 - Covered Outdoor Learning Area - Pre</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	5666/B00A/R0021/Ceiling Structures/Linings/S1					No Asbestos Detected
<b>B00A - R0022 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	5666/B00A/R0021/Ceiling Structures/Linings/S1					No Asbestos Detected
<b>B00A - R0023 - Covered Vehicle Area/Porte Cochere</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	5666/B00A/R0021/Ceiling Structures/Linings/S1					No Asbestos Detected
<b>B00A - R0024 - Movement</b>						
In-fill-panel	Flat AC Sheeting					
	5666/B00A/R0024/In-fill-panel/S2					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	5666/B00A/R0021/Ceiling Structures/Linings/S1					No Asbestos Detected
<b>B00A - R0028 - Toilet - P</b>						
No Asbestos						
<b>B00A - R0029 - Toilets-Unisex</b>						
No Asbestos						
<b>B00A - R0030 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0031 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0033 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	5666/B00A/R0021/Ceiling Structures/Linings/S1					No Asbestos Detected
<b>B00A - R0034 - Movement</b>						
No Asbestos						
<b>B00A - R0035 - Access Shower/Toilet/Change</b>						
No Asbestos						
<b>B00A - R0036 - Home Base/Practical Activities</b>						
No Asbestos						
<b>B00A - R0037 - Laundry - P</b>						
No Asbestos						
<b>B00A - R0038 - Resource/Toy Space</b>						
No Asbestos						
<b>B00A - R0039 - Access Shower/Toilet/Change</b>						
No Asbestos						
<b>B00A - R0040 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Support Unit/Staff Facilities - 1988 - Timber (Timber)****Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	5666/B00B/Eaves Linings/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior****B00B - R0001 - Staff Study**

Ceiling space access panel No Asbestos Found

**B00B - R0002 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0003 - Cleaning Distributed Store**

No Asbestos

**B00B - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0006 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0007 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0008 - Practical Activities**

No Asbestos

**B00B - R0009 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0010 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0011 - Resource/Toy Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0014 - Kitchen - Pre**

No Asbestos

**B00B - R0015 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0016 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0017 - Staff Toilet**

No Asbestos

**B00B - R0018 - Staff Toilet**

No Asbestos

**B00B - R0019 - Staff Shower/Change**

No Asbestos

**B00B - R0020 - Duplicating Workroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00B - R0021 - Security Store**

No Asbestos

**B00B - R0022 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0023 - Interview**

Ceiling space access panel      No Asbestos Found

**B00B - R0024 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0025 - Movement**

No Asbestos

**B00B - R0026 - Movement**

No Asbestos

**B00B - R0027 - Staff Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1988 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5666/B00C/Eaves Linings/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	40m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	5666/B00C/Underfloor Voids/S6				<b>Chrysotile (white asbestos)</b>	

**Interior****B00C - R0001 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0002 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0004 - Cleaning Distributed Store**

Ceiling space access panel No Asbestos Found

**B00C - R0006 - Laundry - P**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0007 - Home Base Store - M**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0008 - Security Store**

Ceiling space access panel No Asbestos Found

**B00C - R0009 - Practical Activities - M - 1hb**

No Asbestos

**B00C - R0010 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0011 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00C - R0012 - Toilet - P**

No Asbestos

**B00C - R0013 - Withdrawal - M**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0014 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0016 - Personal Effects Storage**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0017 - Home Base - M**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0018 - Security Store**

No Asbestos

**B00C - R0019 - Special Programs Room**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
<b>B00C - R0020 - Adjoining School</b>						
	No Asbestos					
<b>B00C - R0021 - Adjoining School</b>						
	No Asbestos					
<b>B00C - R0022 - Adjoining School</b>						
	No Asbestos					
<b>B00C - R0023 - Adjoining School</b>						
	Non Accessible					
<b>B00C - R0024 - Home Base</b>						
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
<b>B00C - R0025 - Home Base</b>						
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
<b>B00C - R0026 - Movement</b>						
	No Asbestos					
<b>B00C - R0027 - Library Office/Workroom</b>						
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities/Support Unit - 1988 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Toilets - Girls**

No Asbestos

**B00D - R0003 - Toilet - P**

No Asbestos

**B00D - R0004 - Toilets - Boys**

No Asbestos

**B00D - R0005 - Toilet - P**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Support Unit (M P S) - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Hydrotherapy - Pool**

No Asbestos

**B00E - R0002 - Access Shower/Toilet/Change**

No Asbestos

**B00E - R0003 - Access Shower/Toilet/Change**

No Asbestos

**B00E - R0004 - Cleaning Supplies**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00F - R0001 - Communal Space**

No Asbestos

**B00F - R0002 - P.E. Store**

No Asbestos

**B00F - R0003 - Covered Outdoor Learning Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0CS - General Learning - 1962 - Timber (Timber)****Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	40m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	5666/B0CS/Underfloor Voids/S7					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B0CS - R0001 - General Storeroom**

No Asbestos

**B0CS - R0002 - Toilets-Unisex**

No Asbestos

**B0CS - R0003 - Withdrawal Space - 1hb**

No Asbestos

**B0CS - R0006 - Interview**

No Asbestos

**B0CS - R0007 - Interview**

No Asbestos

Wall Linings Internal	Flat AC Sheeting	1.5m2	Heater liner on wall	Good Condition (1)	Low (1)	Low Priority (2-3)
	5666/B0CS/R0007/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>

**B0CS - R0008 - Home Base Store**

No Asbestos

**B0CS - R0009 - Staff Room**

No Asbestos

**B0CS - R0010 - Home Base**

No Asbestos

Wall Linings Internal	Flat AC Sheeting	1.5m2	Wall Heater - Liner of wall behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	5666/B0CS/R0010/Wall Linings Internal/S10					<b>Chrysotile (white asbestos)</b>

**B0CS - R0011 - Home Base**

No Asbestos

**B0CS - R0012 - General Storeroom**

No Asbestos

**B0CS - R0014 - Home Base Store**

No Asbestos

**B0CS - R0017 - Home Base Store**

No Asbestos

**B0CS - R0019 - Cleaning Distributed Store**

No Asbestos

**B0CS - R0022 - Staff Toilet**

No Asbestos

**B0CS - R0023 - General Storeroom**

No Asbestos

**B0CS - R0024 - Home Base**

No Asbestos

**B0CS - R0025 - Home Base**

No Asbestos

**B0CS - R0026 - Movement**

No Asbestos

**B0CS - R0027 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0FS - Pupil Facilities - 1962 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Extreme Access Issue - Other					
Ceiling Voids	AC Fragments/Debris 5666/B0FS/Ceiling Voids/S8	50m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**Interior****B0FS - R0003 - Adjoining School**

No Asbestos

**B0FS - R0004 - Adjoining School**

No Asbestos

**B0FS - R0007 - Adjoining School**

No Asbestos

**B0FS - R0008 - Disabled Toilet**

No Asbestos

**B0FS - R0009 - Toilets-Unisex**

No Asbestos

**B0FS - R0010 - Adjoining School**

No Asbestos

**B0FS - R0011 - Toilets - Girls**

No Asbestos

**B0FS - R0012 - No Access**

No Asbestos

**B0FS - R0013 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0GS - Library - 1968 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

**Interior****B0GS - R0003 - Practical Activities**

No Asbestos

**B0GS - R0004 - External Movement**

No Asbestos

**B0GS - R0005 - Home Base**

No Asbestos

**B0GS - R0006 - General Storeroom**

No Asbestos

**B0GS - R0007 - No Access**

No Asbestos

**B0GS - R0008 - Home Base**

No Asbestos

**B0GS - R0009 - Practical Activities**

No Asbestos

**B0GS - R0010 - Clerical Office**

No Asbestos

**B0GS - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B0GS - R0012 - Movement**

No Asbestos

**B0GS - R0013 - Personal Effects Storage**

No Asbestos

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017