

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Library/Science - 1972 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - M1007 - Movement (0.87 m2)**

No Asbestos

B00B - M1008 - Movement (6.78 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - M1009 - Other-Vacant (20.84 m2)

No Asbestos

B00B - M1010 - Senior Study (88.79 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - M1011 - Movement (7.33 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - M1012 - Plant (30.83 m2)

No Asbestos

B00B - M1013 - Plant (29.87 m2)

No Asbestos

B00B - R0001 - Laboratory L.S. (91.24 m2)Ceiling Structures/Linings Vermiculite
8163/B00B/R0001/Ceiling Structures/Linings/S2

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B00B - R0002 - Apparatus Store (13.78 m2)**

No Asbestos

B00B - R0005 - Laboratory L.S. (91.24 m2)Ceiling Structures/Linings Vermiculite
8163/B00B/R0001/Ceiling Structures/Linings/S2

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B00B - R0008 - Laboratory L.S. (91.23 m2)**Ceiling Structures/Linings Vermiculite
8163/B00B/R0001/Ceiling Structures/Linings/S2

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B00B - R0012 - Laboratory L.S. (91.24 m2)**Ceiling Structures/Linings Vermiculite
8163/B00B/R0001/Ceiling Structures/Linings/S2

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B00B - R0014 - Movement (3.26 m2)**

No Asbestos

B00B - R0015 - Preparation - Science (34.08 m2)

No Asbestos

B00B - R0016 - Preparation - Science (48.37 m2)

No Asbestos

B00B - R0017 - Movement (75.74 m2)

No Asbestos

B00B - R0018 - Plant (1.4 m2)

No Asbestos

B00B - R0019 - Secure Storeroom (18.45 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0020 - Lift (2.37 m2)						
No Asbestos						
B00B - R0021 - External Movement (28.98 m2)						
No Asbestos						
B00B - R0022 - Cleaning Supplies Store (7.97 m2)						
No Asbestos						
B00B - R0023 - Stairs (8.09 m2)						
No Asbestos						
B00B - R0024 - External Movement (14.91 m2)						
No Asbestos						
B00B - R1001 - Staff - Toilet (3.24 m2)						
No Asbestos						
B00B - R1008 - Cleaning Store - Distributed (0.36 m2)						
No Asbestos						
B00B - R1009 - Movement (4.91 m2)						
No Asbestos						
B00B - R1010 - Distribution Board Cupboard (0.33 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1017 - Staff - Toilet (3.24 m2)						
No Asbestos						
B00B - R1018 - Movement (1.84 m2)						
No Asbestos						
B00B - R1019 - Computer Learning Space (56.38 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1020 - Library Administration (55.9 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1021 - Seminar (16.65 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1022 - Seminar (13.76 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1023 - Main Area (388.04 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1024 - Computer Resource (19.54 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1025 - Control Room (10.51 m2)						
No Asbestos						
B00B - R1026 - External Movement (21.69 m2)						
No Asbestos						
B00B - R1027 - Store (2.2 m2)						
No Asbestos						
B00B - R1028 - Stairs (7.97 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00C/Eaves Linings/S12					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00C/Gable Verge Lining/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Toilets-Boys (27.34 m2)**

No Asbestos

B00C - R0002 - Staff - Toilet (3.29 m2)

No Asbestos

B00C - R0003 - Staff - Toilet (3.29 m2)

No Asbestos

B00C - R0004 - Toilets-Girls (27.34 m2)

No Asbestos

B00C - R0005 - Staff Study (51.39 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8163/B00G/R0011/Floor Coverings Res/Textile/S6					

B00C - R0006 - Apparatus Store (12.26 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00C - R0007 - Distribution Board Cupboard (0.6 m2)	Note: No inspection of live electrical installation.				
--	--	--	--	--	--

No Asbestos

B00C - R0011 - External Movement (33.31 m2)

No Asbestos

B00C - R0012 - External Stairs (6.38 m2)

No Asbestos

B00C - R0013 - Secure Storeroom (15.37 m2)

No Asbestos

B00C - R0014 - Stairs (16.14 m2)

No Asbestos

B00C - R0015 - Cleaning Store - Distributed (5.53 m2)

No Asbestos

B00C - R0016 - Laboratory L.S. (127.17 m2)

No Asbestos

B00C - R0017 - Stairs (0.54 m2)

No Asbestos

B00C - R0018 - External Movement (56.9 m2)

No Asbestos

B00C - R1001 - Food Technology L.S. (101.29 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00C - R1002 - Food/Research Space (18.23 m2)

No Asbestos

B00C - R1003 - Pantry (10.73 m2)

No Asbestos

B00C - R1004 - Food/Research Space (5.01 m2)

No Asbestos

B00C - R1005 - Laundry (14.88 m2)

No Asbestos

B00C - R1006 - Distribution Board Cupboard (0.48 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board Resinous Board
8163/B00C/R1006/Electrical Backing Board/S26

No Asbestos Detected

B00C - R1007 - Food Technology L.S. (101.28 m2)

No Asbestos

B00C - R1008 - Movement (74.5 m2)

Ceiling Structures/Linings Flat AC Sheeting 75m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

8163/B00F/R1006/Ceiling Structures/Linings/S7

Chrysotile (white asbestos)

B00C - R1009 - External Movement (54.19 m2)

No Asbestos

B00C - R1010 - External Stairs (6.3 m2)

No Asbestos

B00C - R1011 - Stairs (13.6 m2)

No Asbestos

B00C - R1012 - Movement (9.2 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies - 1980 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00D/Eaves Linings/S14					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00D/Gable Verge Lining/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00D - R0001 - Design L.S. (51.5 m2)**

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0002 - Distribution Board Cupboard (0.44 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00D/R0002/Electrical Backing Board/S27					Chrysotile (white asbestos)

B00D - R0003 - Materials Store (23.05 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles					
	8163/B00G/R0011/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00D - R0004 - Design L.S. (51.5 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0005 - Toilets-Girls (23.65 m2)

No Asbestos

B00D - R0006 - Movement (57.97 m2)

No Asbestos

B00D - R1001 - Design L.S. (62.87 m2)

No Asbestos

B00D - R1002 - Distribution Board Cupboard (0.56 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00D/R1002/Ceiling Structures/Linings/S28					Chrysotile (white asbestos)

B00D - R1003 - Movement (4.32 m2)

No Asbestos

B00D - R1004 - Workshop (11.52 m2)

No Asbestos

B00D - R1005 - Materials Store (9.36 m2)

No Asbestos

B00D - R1006 - Design L.S. (63.1 m2)

No Asbestos

B00D - R1007 - Movement (54.33 m2)

Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Technological & Applied Studies - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00E/Eaves Linings/S16					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00E/Gable Verge Lining/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Toilets-Boys (31.32 m2)**

No Asbestos

B00E - R0002 - Materials Store (29.17 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0003 - Distribution Board Cupboard (0.7 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0004 - Materials Technology L.S. (70.51 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0005 - Metal Technology Bay (40.47 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0006 - Welding Area (4.14 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0007 - Welding Area (9.12 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0008 - Materials Technology L.S. (67.17 m2)

Ceiling Structures/Linings	Vermiculite					
	8163/B00B/R0001/Ceiling Structures/Linings/S2					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0009 - Workshop Area (62.38 m2)

Ceiling Structures/Linings	Flat AC Sheeting	63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)
Heat-proof Mat	Compressed AC Sheet					
	8163/B00E/R0009/Heat-proof Mat/S8					No Asbestos Detected

B00E - R0010 - General Storeroom (3.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0011 - L.P.G. Store (1.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0012 - Welding Area (13.55 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
B00E - R0013 - T.A.S. Outdoor Area (13.88 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
B00E - R0014 - Movement (72.04 m2)						
No Asbestos						
B00E - R0015 - Ancillary Staff (6.3 m2)						
No Asbestos						
B00E - R0016 - Stairs (15 m2)						
No Asbestos						
B00E - R0017 - Stairs (0.55 m2)						
No Asbestos						
B00E - R1001 - Staff Study (28.82 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
8163/B00G/R0011/Floor Coverings Res/Textile/S6					No Asbestos Detected	
B00E - R1002 - Materials Store (31.06 m2)						
No Asbestos						
B00E - R1003 - Distribution Board Cupboard (0.56 m2)						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8163/B00E/R1003/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
B00E - R1004 - Materials Technology L.S. (80.92 m2)						
No Asbestos						
B00E - R1005 - Wood Technology Bay (12.87 m2)						
No Asbestos						
B00E - R1006 - Resource/Project Store (14.02 m2)						
No Asbestos						
B00E - R1007 - Dust Extraction Space (4.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8163/B00E/R1007/Ceiling Structures/Linings/S30					Chrysotile (white asbestos)	
B00E - R1008 - Materials Technology L.S. (78.78 m2)						
No Asbestos						
B00E - R1009 - Movement (73.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8163/B00F/R1006/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
B00E - R1010 - Stairs (24.61 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/Eaves Linings/S18					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00F/Gable Verge Lining/S19					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0001 - General Learning Space (51.14 m2)**

No Asbestos

B00F - R0002 - Distribution Board Cupboard (0.48 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - General Learning Space (50.53 m2)

No Asbestos

B00F - R0004 - General Learning Space (50.86 m2)

No Asbestos

B00F - R0005 - Staff Study (16.31 m2)Floor Coverings
Res/Textile

Vinyl Tiles

8163/B00G/R0011/Floor Coverings Res/Textile/S6

No Asbestos Detected**B00F - R0006 - Maintenance Bulk Store (6.85 m2)**

No Asbestos

B00F - R0007 - Movement (68.25 m2)

No Asbestos

B00F - R0008 - External Stairs (17.27 m2)

No Asbestos

B00F - R0009 - External Stairs (38.15 m2)

No Asbestos

B00F - R0010 - External Stairs (2.83 m2)

No Asbestos

B00F - R1001 - General Learning Space (51.14 m2)

No Asbestos

B00F - R1002 - Distribution Board Cupboard (0.48 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings

Flat AC Sheeting

1m2

Throughout

Good Condition (1)

Low (1)

Low Priority (2-3)

8163/B00F/R1006/Ceiling Structures/Linings/S7

Chrysotile (white asbestos)**B00F - R1003 - General Learning Space (102.25 m2)**Floor Coverings
Res/Textile

Vinyl Tiles

8163/B00G/R0011/Floor Coverings Res/Textile/S6

No Asbestos Detected**B00F - R1004 - Staff Study (11.42 m2)**

No Asbestos

B00F - R1005 - Staff Study (11.42 m2)

No Asbestos

B00F - R1006 - Movement (64.23 m2)

Ceiling Structures/Linings

Flat AC Sheeting

65m2

Throughout

Good Condition (1)

Low (1)

Low Priority (2-3)

8163/B00F/R1006/Ceiling Structures/Linings/S7

Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - R1007 - External Stairs (18.31 m2)

No Asbestos

B00F - R1008 - External Stairs (41.85 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Physical Education - 1972 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Staff - Toilet (2.04 m2)

No Asbestos

B00G - R0002 - General Storeroom (2.86 m2)

No Asbestos

B00G - R0003 - Student Canteen (62.8 m2)

No Asbestos

B00G - R0004 - Movement (199.59 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0005 - Distribution Board Cupboard (0.75 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0006 - Sport Equipment Store (51.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

In-fill-panel	Flat AC Sheeting	20m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0006/In-fill-panel/S31					Chrysotile (white asbestos)

B00G - R0007 - Toilets-Girls (8.07 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0008 - Shower/Change (26.42 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0009 - Shower/Change (27.35 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0010 - Cleaning Store - Distributed (1.74 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0011 - Staff Change (8.67 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	8163/B00G/R0011/Floor Coverings Res/Textile/S6					No Asbestos Detected

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

B00G - R0012 - Movement (5.78 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0013 - Movement (31.41 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0014 - Shower/Change (33.46 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0015 - Shower/Change (28.31 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0016 - Movement (2.43 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0017 - Staff Change (8.75 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	8163/B00G/R0011/Floor Coverings Res/Textile/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0018 - Toilets-Boys (17.11 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting					
	8163/B00G/R0004/Ceiling Structures/Linings/S5					No Asbestos Detected
B00G - R0019 - Sport Equipment Store (15.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0019/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	1m2	Infill panel above roller door	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00G/R0019/Wall Linings Internal/S33					Chrysotile (white asbestos)
B00G - R0020 - Gymnasium (446.46 m2)						
No Asbestos						
B00G - R0021 - External Movement (46.73 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 1927 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 8163/B001/Wall Cladding/S9					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8163/B001/Eaves Linings/S20					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B001 - R0001 - General Learning Space (46.87 m2)

No Asbestos

B001 - R0002 - General Learning Space (46.86 m2)

No Asbestos

B001 - R0003 - Movement (24.99 m2)

Wall Linings Internal	Flat AC Sheeting 8163/B001/Wall Cladding/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1927 - Timber (Timber)**Exterior**

Wall Cladding	Flat AC Sheeting 8163/B001/Wall Cladding/S9					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8163/B00J/Eaves Linings/S21					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - General Learning Space (46.74 m2)**

No Asbestos

B00J - R0002 - General Learning Space (46.73 m2)

No Asbestos

B00J - R0003 - Movement (24.99 m2)

Wall Linings Internal	Flat AC Sheeting 8163/B001/Wall Cladding/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1950 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	150m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/Eaves Linings/S22					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - General Learning Space (53.16 m2)**

No Asbestos

B00K - R0002 - Cleaning Store - Distributed (4.01 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/R0010/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0003 - Movement (15.41 m2)

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/R0010/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0004 - General Learning Space (53.16 m2)

No Asbestos

B00K - R0005 - Staff Study (30.81 m2)

No Asbestos

B00K - R0006 - Staff Study (22.22 m2)

No Asbestos

B00K - R0007 - General Learning Space (53.16 m2)

No Asbestos

B00K - R0008 - General Learning Space (53.01 m2)

No Asbestos

B00K - R0009 - General Storeroom (10.62 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/R0010/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0010 - Movement (22.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/R0010/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0011 - Movement (29.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8163/B00K/R0010/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Physical Education - 1972 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Sport Equipment Store (35.55 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Art - 1988 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00M - R0001 - General Learning Space (60.71 m2)**

No Asbestos

B00M - R0002 - Art Learning Space (60.69 m2)

No Asbestos

B00M - R0003 - Resources Store (26.67 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00M - R0004 - No Access (18.93 m2)**

No Asbestos

B00M - R0005 - General Storeroom (7.16 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00M - R0006 - Staff Study (24.17 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00M - R0007 - Cleaning Store - Distributed (2.12 m2)**

No Asbestos

B00M - R0008 - Art Learning Space (60.71 m2)

No Asbestos

B00M - R0009 - Art Learning Space (65.34 m2)

No Asbestos

B00M - R0010 - Art Learning Space (60.69 m2)

No Asbestos

B00M - R0011 - Staff - Toilet (2.87 m2)

No Asbestos

B00M - R0012 - Distribution Board Cupboard (0.7 m2)

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Music - 2008 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00N - R0001 - External Movement (97.28 m2)**

No Asbestos

B00N - R0002 - Performance Workshop (101.43 m2)

No Asbestos

B00N - R0003 - Music Store (13.62 m2)

No Asbestos

B00N - R0004 - Communication Space (0.84 m2)

No Asbestos

B00N - R0005 - Plant (0.85 m2)

No Asbestos

B00N - R0006 - Staff Study (21.21 m2)

No Asbestos

B00N - R0007 - Music Learning Space (59.27 m2)

No Asbestos

B00N - R0008 - Music Learning Space (59.34 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Building Services - 2008 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B000 - R0001 - General Assistants (19.94 m2)

No Asbestos

B000 - R0002 - General Assistants (24.69 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0A1 - Administration/General Learning - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8163/B0A1/Eaves Linings/S23					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B0A1 - R0001 - Chair Store (9.72 m2)**

No Asbestos

B0A1 - R0002 - Stage (69.64 m2)

No Asbestos

B0A1 - R0003 - Multi-Purpose Space (317.89 m2)

No Asbestos

B0A1 - R0004 - Movement (3.02 m2)

No Asbestos

B0A1 - R0005 - Administration - Clerical (14.66 m2)

No Asbestos

B0A1 - R0006 - Distribution Board Cupboard (0.27 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0A1 - R0007 - Public Entry (42.01 m2)

No Asbestos

B0A1 - R0008 - General Storeroom (2.42 m2)

No Asbestos

B0A1 - R0009 - Main Switchroom (1.86 m2)

No Asbestos

B0A1 - R0010 - Interview/Office - Type 1 (7.41 m2)

No Asbestos

B0A1 - R0011 - Interview/Office - Type 1 (9.64 m2)

No Asbestos

B0A1 - R0012 - Administration - Clerical (19.54 m2)

No Asbestos

B0A1 - R0013 - Ancillary Staff (10.91 m2)

No Asbestos

B0A1 - R0014 - Staff - Toilet (9.65 m2)

No Asbestos

B0A1 - R0015 - Toilets-Girls (9.44 m2)

No Asbestos

B0A1 - R0016 - Principal Office (19.77 m2)

No Asbestos

B0A1 - R0017 - Deputy Principal Office (19.77 m2)

No Asbestos

B0A1 - R0018 - Staff - Toilet (9.29 m2)

No Asbestos

B0A1 - R0019 - Security Store (6.47 m2)

No Asbestos

B0A1 - R0020 - Movement (27.76 m2)

No Asbestos

B0A1 - R0021 - Stairs (2.23 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B0A1 - R1001 - Commonroom (106.41 m2)

No Asbestos

B0A1 - R1002 - Staff Study (39.19 m2)

No Asbestos

B0A1 - R1003 - Secure Storeroom (3.85 m2)

No Asbestos

B0A1 - R1004 - Staff - Toilet (12.24 m2)

No Asbestos

B0A1 - R1005 - Staff Kitchen (12.96 m2)

No Asbestos

B0A1 - R1006 - Administration - Clerical (14.07 m2)

No Asbestos

B0A1 - R1007 - Staff - Toilet (9.45 m2)

No Asbestos

B0A1 - R1008 - Movement (23.23 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0A2 - General Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 8163/B0A2/Eaves Linings/S24					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B0A2 - R0001 - Cleaning Store - Distributed (3.25 m2)

No Asbestos

B0A2 - R0002 - General Storeroom (14.03 m2)

No Asbestos

B0A2 - R0003 - General Learning Space (52.33 m2)

No Asbestos

B0A2 - R0004 - General Learning Space (52.32 m2)

No Asbestos

B0A2 - R0005 - Staff Study (52.33 m2)

No Asbestos

B0A2 - R0006 - Administration - Clerical (6.01 m2)

No Asbestos

B0A2 - R0007 - Clinic - Boys (6.57 m2)

No Asbestos

B0A2 - R0008 - Movement (204.44 m2)

No Asbestos

B0A2 - R0009 - Movement (5.31 m2)

No Asbestos

B0A2 - R0010 - Cleaning Store - Distributed (3.25 m2)

No Asbestos

B0A2 - R0011 - Administration - Clerical (27.01 m2)

No Asbestos

B0A2 - R0012 - Movement (3.78 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8163/B0A2/R0012/Floor Coverings Res/Textile/S1					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B0A2 - R0013 - Clinic - Girls (6.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8163/B0A2/R0012/Floor Coverings Res/Textile/S1					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B0A2 - R0014 - Interview/Office - Type 1 (13.44 m2)

No Asbestos

B0A2 - R0015 - General Learning Space (52.81 m2)

No Asbestos

B0A2 - R0016 - General Learning Space (52.81 m2)

No Asbestos

B0A2 - R0017 - General Learning Space (52.82 m2)

No Asbestos

B0A2 - R0018 - Movement (8.45 m2)

No Asbestos

B0A2 - R0019 - Cleaning Store - Distributed (2.86 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0A2 - R0020 - Movement (7.2 m2)						
No Asbestos						
B0A2 - R0021 - Stairs (8.93 m2)						
No Asbestos						
B0A2 - R0022 - Stairs (9.35 m2)						
No Asbestos						
B0A2 - R0023 - Stairs (3.06 m2)						
No Asbestos						
B0A2 - R1001 - General Storeroom (14.04 m2)						
No Asbestos						
B0A2 - R1002 - General Learning Space (52.59 m2)						
No Asbestos						
B0A2 - R1003 - General Learning Space (52.41 m2)						
No Asbestos						
B0A2 - R1004 - General Learning Space (52.42 m2)						
No Asbestos						
B0A2 - R1005 - General Storeroom (7.56 m2)						
No Asbestos						
B0A2 - R1006 - General Storeroom (4.73 m2)						
No Asbestos						
B0A2 - R1007 - General Storeroom (11.97 m2)						
No Asbestos						
B0A2 - R1008 - Movement (187.12 m2)						
No Asbestos						
B0A2 - R1009 - General Learning Space (52.42 m2)						
No Asbestos						
B0A2 - R1010 - General Learning Space (52.41 m2)						
No Asbestos						
B0A2 - R1011 - General Learning Space (52.41 m2)						
No Asbestos						
B0A2 - R1012 - General Learning Space (52.41 m2)						
No Asbestos						
B0A2 - R1013 - Stairs (12.77 m2)						
No Asbestos						
B0A2 - R1014 - Stairs (13.61 m2)						
No Asbestos						
B0A2 - R1015 - Stairs (12.82 m2)						
No Asbestos						
B0A2 - R9001 - Plant (8.27 m2)						
No Asbestos						
B0A2 - R9002 - No Access (19.21 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0A3 - General Learning - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8163/B0A3/Eaves Linings/S25					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B0A3 - R0001 - Staff - Toilet (14.57 m2)**

No Asbestos

B0A3 - R0002 - G.L.S. Store (8.33 m2)

No Asbestos

B0A3 - R0003 - G.L.S. Store (8.33 m2)

No Asbestos

B0A3 - R0004 - General Learning Space (39.67 m2)

No Asbestos

B0A3 - R0005 - Staff Study (40.32 m2)

No Asbestos

B0A3 - R0006 - General Learning Space (37.39 m2)

No Asbestos

B0A3 - R0007 - Duplicating Workroom (21.66 m2)

No Asbestos

B0A3 - R0008 - General Learning Space (41.95 m2)

No Asbestos

B0A3 - R0009 - General Learning Space (43.57 m2)

No Asbestos

B0A3 - R0010 - Movement (77.94 m2)

No Asbestos

B0A3 - R0011 - Plant (3.86 m2)

No Asbestos

B0A3 - R0012 - Stairs (24.84 m2)

No Asbestos

B0A3 - R0013 - Stairs (0.33 m2)

No Asbestos

B0A3 - R1001 - General Storeroom (14.74 m2)

No Asbestos

B0A3 - R1002 - Staff Study (17.11 m2)

No Asbestos

B0A3 - R1003 - Music Learning Space (60.23 m2)

No Asbestos

B0A3 - R1004 - Music Store (21.85 m2)

No Asbestos

B0A3 - R1005 - Music Learning Space (73.98 m2)

No Asbestos

B0A3 - R1006 - Music Store (29.29 m2)

No Asbestos

B0A3 - R1007 - General Learning Space (44.1 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Hatch	Flat AC Sheeting	1Unit(s)	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos

B0A3 - R1008 - Movement (78.72 m2)

No Asbestos

B0A3 - R1009 - Distribution Board Cupboard (0.12 m2) Note: No inspection of live electrical installation.

No Asbestos

B0A3 - R1010 - Stairs (11.8 m2)

No Asbestos

B0A3 - R1011 - Movement (8.69 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0A4 - Art/Building Services - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8163/B0A4/Eaves Linings/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B0A4 - R0001 - General Assistants (70.16 m2)**

No Asbestos

B0A4 - R0002 - Toilets-Girls (43.01 m2)

No Asbestos

B0A4 - R0003 - Movement (28.21 m2)

No Asbestos

B0A4 - R0004 - Darkroom Space (39.49 m2)

No Asbestos

B0A4 - R0006 - Toilets-Boys (16.72 m2)

No Asbestos

B0A4 - R0007 - Other-Vacant (3.44 m2)

No Asbestos

B0A4 - R0008 - Toilets-Disabled (5.37 m2)

No Asbestos

B0A4 - R0009 - External Movement (32.66 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 720 - D14786 - Science Laboratory/Prep Room : Placement Date - 6/02/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		17.28 m2

Interior

R1 - Laboratory L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		90 m2

R2 - Preparation

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		19 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8163_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017