


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Picton High School (8215)
Region : South Western Sydney
State Electorate : Wollondilly
Local Government Area : Wollondilly

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : Parsons Brinckerhoff : 11 - Sep - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 8215/B00A/Gable Verge Lining/S28					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00A/R0015/Ceiling Structures/Linings/S1	24m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Void Access					

Interior

B00A - R0002 - Secure Storeroom (16.95 m2)

No Asbestos

B00A - R0003 - Principal Office (21.98 m2)

No Asbestos

B00A - R0004 - Public Reception (28.76 m2)

No Asbestos

B00A - R0005 - Deputy Principal Office (21.75 m2)

No Asbestos

B00A - R0006 - Interview/Office - Type 1 (10.76 m2)

No Asbestos

B00A - R0007 - Administration - Clerical (17.79 m2)

No Asbestos

B00A - R0008 - Cleaning Store - Distributed (0.47 m2)

No Asbestos

B00A - R0010 - Staff - Toilet (4.4 m2)

No Asbestos

B00A - R0011 - Staff - Toilet (4.43 m2)

No Asbestos

B00A - R0013 - General Storeroom (5.3 m2)

No Asbestos

B00A - R0015 - External Movement (8.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00A/R0015/Ceiling Structures/Linings/S1	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	------------	--------------------	---------	---

B00A - R0016 - External Movement (12.79 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00A/R0015/Ceiling Structures/Linings/S1	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	------------	--------------------	---------	---

B00A - R0017 - Deputy Principal Office (13.74 m2)

No Asbestos

B00A - R0018 - Clinic (5.47 m2)

No Asbestos

B00A - R0019 - Administration - Clerical (40.3 m2)

No Asbestos

B00A - R0020 - Administration - Clerical (9.13 m2)

No Asbestos

B00A - R0023 - Staff Kitchen (8.89 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0024 - Commonroom (85.05 m2)

No Asbestos

B00A - R0025 - Administration - Clerical (11.07 m2)

No Asbestos

B00A - R0026 - Movement (26.11 m2)

No Asbestos

B00A - R0027 - Student Waiting (6.87 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Music - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 8215/B00B/Gable Verge Lining/S29					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00B/R0009/Ceiling Structures/Linings/S3	22m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris 8215/B00B/Underfloor Voids/S30					No Asbestos Detected

Interior

B00B - R0001 - Music Learning Space (66.46 m2)

No Asbestos

B00B - R0002 - Music Store (25.21 m2)

No Asbestos

B00B - R0004 - Distribution Board Cupboard (0.28 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 8215/B00B/R0004/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00B - R0007 - Music Learning Space (80.76 m2)

No Asbestos

B00B - R0008 - Movement (19.26 m2)

No Asbestos

B00B - R0009 - External Movement (4.32 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00B/R0009/Ceiling Structures/Linings/S3	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0010 - Staff Study (21.42 m2)

No Asbestos

B00B - R0011 - Tea Room (3.97 m2)

Floor Coverings Res/Textile	Vinyl Sheet 8215/B00B/R0011/Floor Coverings Res/Textile/S31					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00B - R0012 - Practice/Seminar (44.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Computer Learning - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 8215/B00C/Gable Verge Lining/S33					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00C/R0005/Ceiling Structures/Linings/S4	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Encapsulated Insulation material within unit 8215/B00C/Ceiling Voids/S32					No Asbestos Detected
Underfloor Voids	Non Accessible Area - No Asbestos Found - Limited Access Due to Restrictions					

Interior

B00C - R0001 - General Learning Space (66.61 m2)

No Asbestos

B00C - R0002 - General Learning Space (47.57 m2)

No Asbestos

B00C - R0003 - General Learning Space (66.33 m2)

No Asbestos

B00C - R0004 - Movement (51.31 m2)

No Asbestos

B00C - R0005 - External Movement (3.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
	8215/B00C/R0005/Ceiling Structures/Linings/S4					

B00C - R0006 - Staff Study (50.04 m2)

No Asbestos

B00C - R0007 - Study Space (23.36 m2)

No Asbestos

B00C - R0009 - General Learning Space (47.5 m2)

No Asbestos

B00C - R0010 - Computer Learning Space (66.54 m2)

No Asbestos

B00C - R0011 - Movement (27.69 m2)

No Asbestos

B00C - R0012 - External Movement (3.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
	8215/B00C/R0005/Ceiling Structures/Linings/S4					

B00C - R0013 - Resources Store (13.14 m2)

No Asbestos

B00C - R0014 - Staff - Toilet (2.43 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Computer Learning - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 8215/B00D/Gable Verge Lining/S35					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00D/Eaves Linings/S34	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access Due To Hatch Being Bolted Closed					

Interior

B00D - R0001 - Computer Learning Space (66.63 m2)

No Asbestos

B00D - R0002 - General Learning Space (52.86 m2)

No Asbestos

B00D - R0003 - Resources Store (26.17 m2)

No Asbestos

B00D - R0004 - Staff Study (16.11 m2)

No Asbestos

B00D - R0005 - Movement (16.3 m2)

No Asbestos

B00D - R0006 - Uniform Shop (19.84 m2)

No Asbestos

B00D - R0007 - External Movement (35.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00D/R0007/Ceiling Structures/Linings/S5					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Art/Physical Education - 1958 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00E/R0010/Ceiling Structures/Linings/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Distribution Board Cupboard (0.74 m2)**

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting					
	8215/B00E/R0001/Wall Linings Internal/S7					No Asbestos Detected

B00E - R0002 - Interview/Office - Type 1 (13.82 m2)

No Asbestos

B00E - R0003 - Resources Store (14.54 m2)

No Asbestos

B00E - R0005 - Staff - Toilet (3.29 m2)

No Asbestos

B00E - R0006 - General Learning Space (66.34 m2)

No Asbestos

B00E - R0008 - Art Learning Space (63.77 m2)

No Asbestos

B00E - R0010 - External Movement (2.98 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00E/R0010/Ceiling Structures/Linings/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0011 - External Movement (15.53 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00E/R0010/Ceiling Structures/Linings/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0012 - Kiln Space (9.74 m2)

No Asbestos

B00E - R0013 - Staff Study (39.84 m2)

No Asbestos

B00E - R0014 - Movement (32.4 m2)

No Asbestos

B00E - R0015 - Staff Study (24.69 m2)

Floor Coverings Res/Textile	Flat AC Sheeting					
	8215/B00E/R0015/Floor Coverings Res/Textile/S57					No Asbestos Detected

B00E - R0016 - Tea Room (2.02 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Art - 1958 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting 8215/B00F/Gable Verge Lining/S36					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00F/R0006/Ceiling Structures/Linings/S10	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0001 - Art Learning Space (83.1 m2)**

No Asbestos

B00F - R0002 - Distribution Board Cupboard (0.36 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 8215/B00F/R0002/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00F - R0003 - Multi Media Workshop (52.45 m2)

No Asbestos

B00F - R0004 - Art Learning Space (86.63 m2)

No Asbestos

B00F - R0005 - Movement (12.6 m2)

No Asbestos

B00F - R0006 - External Movement (3.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00F/R0006/Ceiling Structures/Linings/S10	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0007 - Interview/Office - Type 1 (12.89 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Technological & Applied Studies/Building Services - 1958 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting 8215/B00G/Gable Verge Lining/S37					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris 8215/B00G/Underfloor Voids/S38	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00G - M1001 - Materials Store (15.21 m2)

No Asbestos

B00G - R0001 - Sport Equipment Store (15.94 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 8215/B00G/R0005/Partition Walls (Cubicles)/S15					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00G - R0002 - General Storeroom (4.85 m2)

No Asbestos

B00G - R0003 - Movement (2.99 m2)

No Asbestos

B00G - R0004 - Main Switchroom (9.94 m2)

Electrical Backing Board	Resinous Board 8215/B00G/R0004/Electrical Backing Board/S39					No Asbestos Detected
--------------------------	--	--	--	--	--	----------------------

B00G - R0005 - Toilets-Boys (15.91 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 8215/B00G/R0005/Partition Walls (Cubicles)/S15					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00G - R0006 - General Storeroom (4.85 m2)

No Asbestos

B00G - R0007 - Movement (2.9 m2)

No Asbestos

B00G - R0008 - Maintenance Bulk Store (80.81 m2)

No Asbestos

B00G - R0009 - External Movement (14.65 m2)

Ceiling Structures/Linings	Fibre Cement Sheet 8215/B00G/R0009/Ceiling Structures/Linings/S40					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00G - R0010 - External Stairs (0.73 m2)

Ceiling Structures/Linings	Fibre Cement Sheet 8215/B00G/R0009/Ceiling Structures/Linings/S40					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00G - R1001 - Class Tools Storage (2.87 m2)

No Asbestos

B00G - R1002 - Workshop Area (77.2 m2)

No Asbestos

B00G - R1004 - Movement (6.57 m2)

No Asbestos

B00G - R1006 - Materials Store (9.39 m2)

No Asbestos

B00G - R1009 - Staff - Toilet (3.34 m2)

No Asbestos

B00G - R1010 - Distribution Board Cupboard (1.09 m2)

No Asbestos Note: No inspection of live electrical installation.

B00G - R1011 - Movement (9.87 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00G - R1013 - Materials Store (16.17 m2)						
No Asbestos						
B00G - R1014 - Movement (3.26 m2)						
No Asbestos						
B00G - R1016 - External Movement (3.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8215/B00G/R1016/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00G - R1018 - External Movement (19.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
8215/B00G/R1018/Ceiling Structures/Linings/S41						
B00G - R1019 - Materials Store (5.94 m2)						
No Asbestos						
B00G - R1020 - External Stairs (7.82 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8215/B00G/R1016/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00G - R1021 - Metal Technology L.S. (90.3 m2)						
No Asbestos						
B00G - R1022 - Welding Area (8.43 m2)						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
8215/B00G/R1022/Wall Linings Internal/S42						
B00G - R1023 - Materials Technology L.S. (66.07 m2)						
No Asbestos						
B00G - R1024 - Handwashing Facilities (0.96 m2)						
No Asbestos						
B00G - R1025 - Materials Technology L.S. (114.42 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8215/B00G/R1025/Ceiling Structures/Linings/S43				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00G - R1026 - Handwashing Facilities (1.46 m2)						
No Asbestos						
B00G - R1027 - Project Store - Type 1 (6.13 m2)						
No Asbestos						
B00G - R1028 - Materials Store (6.11 m2)						
No Asbestos						
B00G - R1029 - Staff Study (33.56 m2)						
No Asbestos						
B00G - R1030 - Tea Room (1.08 m2)						
No Asbestos						
B00G - R1031 - Materials Technology L.S. (81.76 m2)						
No Asbestos						
B00G - R1032 - Handwashing Facilities (1.06 m2)						
No Asbestos						
B00G - R1033 - Handwashing Facilities (1.27 m2)						
No Asbestos						
B00G - R1034 - L.P.G. Store (0.8 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities/Computer Learning - 1958 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 8215/B00H/Gable Verge Lining/S44					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00H - R0002 - Office/Store (3.15 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0003 - General Storeroom (4.61 m2)

No Asbestos

B00H - R0004 - Staff - Toilet (1.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Wall Linings Internal	Flat AC Sheeting 8215/B00H/R0004/Wall Linings Internal/S27					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00H - R0005 - Pantry (13.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0007 - Toilets-Boys (39.97 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0008 - Toilets-Girls (37 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0009 - Cleaning Store - Distributed (3.26 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0011 - External Movement (34.96 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0013 - Movement (25.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0015 - Student Canteen (52.04 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0012/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0016 - General Storeroom (29.42 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00H/R0016/Ceiling Structures/Linings/S45					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00H - R0019 - Computer Learning Space (81.27 m2)

No Asbestos

B00H - R0020 - Tea Room (4.15 m2)

No Asbestos

B00H - R0021 - External Movement (52.05 m2)

No Asbestos

B00H - R0022 - Covered Area (150.35 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00H - R0023 - Movement (6.56 m2)

No Asbestos

B00H - R0024 - Cleaning Supplies Store (2.22 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - General Learning/Support Unit/Science Learning - 1968 - Brick/Block (Brick/Block)						
Exterior						
Eaves Linings	Flat AC Sheeting	100m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No Access Due To Height Restrictions						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Interior						
B001 - R0007 - Food Technology L.S. (110.67 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0008 - Special Learning Space (51.76 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0009 - Distribution Board Cupboard (1.47 m2)						
Note: No inspection of live electrical installation.						
No Asbestos						
B001 - R0010 - Staff - Toilet (6.21 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	South, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B001/R0010/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting					
	8215/B001/R0012/In-fill-panel/S17					No Asbestos Detected
B001 - R0011 - Staff Kitchen (17.33 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0012 - Laboratory L.S. (94.4 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
In-fill-panel	Flat AC Sheeting					
	8215/B001/R0012/In-fill-panel/S17					No Asbestos Detected
B001 - R0013 - Staff Study (29.93 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0015 - Laboratory L.S. (95.77 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0017 - General Storeroom (2.88 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0018 - Distribution Board Cupboard (1.27 m2)						
Note: No inspection of live electrical installation.						
No Asbestos						
B001 - R0021 - External Movement (1.55 m2)						
No Asbestos						
B001 - R0022 - External Stairs (0.78 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R0023 - Dark Room (10.04 m2)						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
		8215/B00I/R0023/Wall Linings Internal/S18				
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
		8215/B00I/R0023/Wall Linings Internal/S18				
B00I - R0024 - External Stairs (1.11 m2)						
No Asbestos						
B00I - R0025 - External Movement (0.84 m2)						
No Asbestos						
B00I - R0027 - General Storeroom (3.33 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8215/B00I/R0020/Ceiling Structures/Linings/S16				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R0028 - Change (12.66 m2)						
No Asbestos						
B00I - R0029 - Staff - Toilet (4.7 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8215/B00I/R0034/Ceiling Structures/Linings/S46				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R0030 - Cleaning Store - Distributed (1.09 m2)						
No Asbestos						
B00I - R0031 - External Movement (87.12 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8215/B00I/R0034/Ceiling Structures/Linings/S46				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R0032 - External Movement (142.01 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8215/B00I/R0034/Ceiling Structures/Linings/S46				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R0033 - Darkroom Space (2.61 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
		8215/B00I/R0033/Ceiling Structures/Linings/S48				
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
		8215/B00I/R0033/Wall Linings Internal/S49				
B00I - R0034 - Dark Room (21.07 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8215/B00I/R0034/Ceiling Structures/Linings/S46				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
		8215/B00I/R0034/Wall Linings Internal/S47				
B00I - R0035 - General Storeroom (8.17 m2)						
No Asbestos						
B00I - R0036 - Lift (1.44 m2)						
No Asbestos						
B00I - R0037 - Handwashing Facilities (0.4 m2)						
No Asbestos						
B00I - R0038 - Plant (0.57 m2)						
No Asbestos						
B00I - R0039 - Seminar (50.4 m2)						
No Asbestos						
B00I - R0040 - Kitchen - Type 1 (108.89 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00I - R0041 - Class Tools Storage (19.88 m2)						
No Asbestos						
B00I - R0042 - Preparation - Materials (19.44 m2)						
No Asbestos						
B00I - R0043 - Pantry (12.94 m2)						
No Asbestos						
B00I - R1001 - General Learning Space (51.55 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1002 - Design/Technology L.S. (69.28 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1003 - Resources Store (7.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0034/Ceiling Structures/Linings/S46					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1005 - Senior Study (25.81 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1006 - General Learning Space (42.06 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1007 - General Learning Space (54.72 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1010 - Resources Store (7.81 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0034/Ceiling Structures/Linings/S46					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1011 - Distribution Board Cupboard (1.61 m2)						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00I/R1012/Ceiling Structures/Linings/S50					Chrysotile (white asbestos)
B00I - R1012 - Staff - Toilet (6.45 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00I/R1012/Ceiling Structures/Linings/S50					Chrysotile (white asbestos)
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	South, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No Access						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	South, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8215/B00I/R0010/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)
B00I - R1013 - Resources Store (15.72 m2)						
Ceiling Structures/Linings	Vermiculite					
	8215/B00I/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00I - R1014 - General Learning Space (55.39 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1015 - General Learning Space (54.18 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1016 - General Learning Space (52.64 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1017 - General Learning Space (53.45 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1018 - General Learning Space (56.68 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1019 - Staff Study (19.58 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0020/Ceiling Structures/Linings/S16					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1020 - Cleaning Store - Distributed (2.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8215/B001/R1023/Ceiling Structures/Linings/S51	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B001 - R1021 - Distribution Board Cupboard (1.29 m2) Note: No inspection of live electrical installation.						
No Asbestos						
B001 - R1022 - External Movement (219.87 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8215/B001/R0020/Ceiling Structures/Linings/S16					No Asbestos Detected
B001 - R1023 - External Stairs (4.28 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8215/B001/R1023/Ceiling Structures/Linings/S51	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B001 - R1024 - External Stairs (4.63 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8215/B001/R1023/Ceiling Structures/Linings/S51	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B001 - R1025 - Added Room						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0034/Ceiling Structures/Linings/S46					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1026 - Computer Learning Space (66.04 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0034/Ceiling Structures/Linings/S46					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1027 - Handwashing Facilities (4.53 m2)						
Ceiling Structures/Linings	Vermiculite 8215/B001/R0034/Ceiling Structures/Linings/S46					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R1028 - Staff Study (28.56 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 8215/B001/R0034/Ceiling Structures/Linings/S46 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R1029 - Tea Room (1.38 m2)

Ceiling Structures/Linings Vermiculite
 8215/B001/R0034/Ceiling Structures/Linings/S46 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R1030 - Handwashing Facilities (0.39 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning/Building Services - 1987 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8215/B00J/R0022/Ceiling Structures/Linings/S23					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - General Learning Space (39.87 m2)**

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0002 - General Storeroom (10.57 m2)

No Asbestos

B00J - R0003 - Leading Teacher (16.32 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0004 - General Learning Space (48.36 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0005 - Distribution Board Cupboard (1.88 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0006 - Cleaning Store - Distributed (3.41 m2)

No Asbestos

B00J - R0007 - Performance Store (24.29 m2)

No Asbestos

B00J - R0008 - General Storeroom (2.53 m2)

No Asbestos

B00J - R0009 - Resources Store (17.74 m2)

No Asbestos

B00J - R0011 - Careers Advisers Office (15.4 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0012 - Computer Learning Space (62.37 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0013 - Computer Resource (10.5 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0014 - Computer Store (9.77 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0015 - Toilets-Disabled (6.72 m2)

No Asbestos

B00J - R0016 - General Storeroom (19.16 m2)

No Asbestos

B00J - R0017 - General Learning Space (39.17 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0018 - General Learning Space (53.35 m2)

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00J - R0019 - General Learning Space (53.58 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R0020 - Movement (135.02 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R0021 - External Movement (3.25 m2)						
No Asbestos						
B00J - R0022 - External Movement (24.15 m2)						
Ceiling Structures/Linings	Flat AC Sheeting		8215/B00J/R0022/Ceiling Structures/Linings/S23			No Asbestos Detected
B00J - R0023 - Stairs (4.47 m2)						
No Asbestos						
B00J - R0024 - Stairs (2.39 m2)						
No Asbestos						
B00J - R0025 - Staff Study (46.25 m2)						
No Asbestos						
B00J - R0026 - Tea Room (2.55 m2)						
Floor Coverings Res/Textile	Vinyl Tiles		8215/B00J/R0026/Floor Coverings Res/Textile/S52			No Asbestos Detected
B00J - R1001 - General Learning Space (39.81 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1002 - Leading Teacher (16.2 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1003 - General Learning Space (48.23 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1004 - Cleaning Store - Distributed (4.87 m2)						
No Asbestos						
B00J - R1005 - Staff Study (12.88 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1006 - Staff - Toilet (4.9 m2)						
No Asbestos						
B00J - R1007 - Resources Store (36.93 m2)						
No Asbestos						
B00J - R1008 - Distribution Board Cupboard (0.41 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00J - R1009 - General Learning Space (48.66 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1010 - Interview/Office - Type 1 (15.61 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1011 - General Learning Space (48.67 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1013 - General Learning Space (48.15 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1014 - General Learning Space (48.01 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1015 - General Learning Space (48.73 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1016 - Movement (124.58 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1017 - Stairs (26.93 m2)

No Asbestos

B00J - R1018 - Stairs (13.09 m2)

No Asbestos

B00J - R1019 - Staff Study (38.14 m2)

No Asbestos

B00J - R1020 - Tea Room (1.13 m2)

No Asbestos

B00J - R9001 - Maintenance Bulk Store (215.15 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Lecture Learning - 1987 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Tiered Learning Area (66.07 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0002 - General Storeroom (2.45 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0003 - External Movement (2.57 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8215/B00K/R0003/Ceiling Structures/Linings/S53	No Asbestos Detected
----------------------------	------------------	--	-----------------------------

B00K - R0004 - Plant (7.69 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Science Learning - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Laboratory L.S. (95.16 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0002 - Distribution Board Cupboard (0.76 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0003 - Apparatus Storage (41.97 m2)

No Asbestos

B00L - R0004 - Chemical Store (12.05 m2)

No Asbestos

B00L - R0005 - Preparation - Science (78.42 m2)

No Asbestos

B00L - R0006 - Laboratory L.S. (95.15 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Movement (9.17 m2)

No Asbestos

B00L - R0008 - Laboratory L.S. (95.06 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0009 - Staff Study (42.25 m2)

No Asbestos

B00L - R0010 - Laboratory L.S. (95.34 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0011 - Movement (22.99 m2)

No Asbestos

B00L - R0012 - General Storeroom (6.66 m2)

No Asbestos

B00L - R0014 - External Movement (92.16 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00L/R0014/Ceiling Structures/Linings/S54	No Asbestos Detected
Infills Above Windows	Flat AC Sheeting 8215/B00L/R0014/Infills Above Windows/S55	No Asbestos Detected

B00L - R0015 - External Movement (29.86 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8215/B00L/R0014/Ceiling Structures/Linings/S54	No Asbestos Detected
Infills Above Windows	Flat AC Sheeting 8215/B00L/R0014/Infills Above Windows/S55	No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Multi Purpose Facilities - 1984 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00M - M0001 - General Storeroom (6.5 m2)**

No Asbestos

B00M - M0002 - Control Room (5.57 m2)

No Asbestos

B00M - R0001 - Sport Equipment Store (51.88 m2)

No Asbestos

B00M - R0002 - Toilets-Disabled (4.4 m2)

No Asbestos

B00M - R0003 - Distribution Board Cupboard (3.39 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0005 - Change (33.84 m2)

Partition Walls (Cubicles) Compressed AC Sheet
8215/B00M/R0005/Partition Walls (Cubicles)/S26

No Asbestos Detected**B00M - R0007 - Stage (68.78 m2)**

No Asbestos

B00M - R0008 - Movement (6.18 m2)

No Asbestos

B00M - R0009 - Movement (16.55 m2)

No Asbestos

B00M - R0011 - Change (33.48 m2)

Partition Walls (Cubicles) Compressed AC Sheet
8215/B00M/R0005/Partition Walls (Cubicles)/S26

No Asbestos Detected**B00M - R0012 - Cleaning Store - Distributed (3.46 m2)**

No Asbestos

B00M - R0013 - Staff Kitchen (15.24 m2)

No Asbestos

B00M - R0014 - Sport Equipment Store (16.39 m2)

No Asbestos

B00M - R0015 - Sport Equipment Store (1.9 m2)

No Asbestos

B00M - R0016 - Sport Equipment Store (21.12 m2)

No Asbestos

B00M - R0017 - Multi-Purpose Space (520.61 m2)

No Asbestos

B00M - R0018 - External Movement (267.71 m2)

No Asbestos

B00M - R0019 - Toilet - Lobby (3.03 m2)

No Asbestos

B00M - R0020 - Toilets-Girls (15.05 m2)

No Asbestos

B00M - R0021 - Movement (39.39 m2)

No Asbestos

B00M - R0022 - General Storeroom (3.22 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00M - R0023 - Lift (1.86 m2)

No Asbestos

B00M - R0024 - Toilet - Lobby (2.94 m2)

No Asbestos

B00M - R0025 - Toilets-Boys (15.14 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Library - 1984 - Brick/Veneer (Brick/Veneer)

Exterior

Wall Cladding	Flat AC Sheeting 8215/B00N/Wall Cladding/S21					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 8215/B00N/In-fill-panel/S56					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8215/B00N/R0011/Ceiling Structures/Linings/S22					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00N - R0001 - Main Area (372.23 m2)

No Asbestos

B00N - R0003 - Cleaning Store - Distributed (2.19 m2)

No Asbestos

B00N - R0004 - Printing/Photocopying (40.86 m2)

No Asbestos

B00N - R0005 - Staff - Toilet (3.91 m2)

No Asbestos

B00N - R0006 - Seminar/Technology Space (12.08 m2)

No Asbestos

B00N - R0007 - Seminar (12.01 m2)

No Asbestos

B00N - R0008 - Seminar (11.97 m2)

No Asbestos

B00N - R0009 - Main Entry (11.5 m2)

No Asbestos

B00N - R0010 - Distribution Board Cupboard (0.54 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0011 - External Movement (51.3 m2)

Wall Linings Internal	Flat AC Sheeting 8215/B00N/Wall Cladding/S21					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 8215/B00N/R0011/Ceiling Structures/Linings/S22					No Asbestos Detected

B00N - R0012 - Library Administration (49.06 m2)

No Asbestos

B00N - R0013 - Tea Room (3.04 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Technological & Applied Studies - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B000 - R0001 - Handwashing Facilities (4.88 m2)

No Asbestos

B000 - R0002 - Workshop (195.24 m2)

No Asbestos

B000 - R0003 - Store (6.57 m2)

No Asbestos

B000 - R0004 - Class Tools Storage (6.08 m2)

No Asbestos

B000 - R0005 - Materials Store (33.57 m2)

No Asbestos

B000 - R0006 - Metal Technology L.S. (47.67 m2)

No Asbestos

B000 - R0007 - Covered Area (79.46 m2)

No Asbestos

B000 - R0008 - Toilets-Unisex (4.96 m2)

No Asbestos

B000 - R0009 - Cleaning Store - Distributed (3.91 m2)

No Asbestos

B000 - R0010 - Welding Area (3.63 m2)

No Asbestos

B000 - R0011 - Welding Area (3.67 m2)

No Asbestos

B000 - R0012 - Welding Area (3.67 m2)

No Asbestos

B000 - R0013 - Welding Area (3.67 m2)

No Asbestos

B000 - R0014 - Welding Area (3.67 m2)

No Asbestos

B000 - R0015 - Welding Area (3.67 m2)

No Asbestos

B000 - R0016 - L.P.G. Store (2.02 m2)

No Asbestos

B000 - R0017 - L.P.G. Store (2.48 m2)

No Asbestos

B000 - R0018 - Main Switch Board Cupboard (5.3 m2)

No Asbestos

B000 - R0020 - External Movement (26.93 m2)

No Asbestos

B000 - R0021 - External Movement (4.7 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Agricultural Science - 1958 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - Agriculture Covered Area (49.05 m2)

No Asbestos

B00P - R0002 - Class Tools Storage (23.89 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Storage - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00Q - R0001 - Staff - Toilet (1.53 m2)

No Asbestos

B00Q - R0002 - General Storeroom (6.44 m2)

No Asbestos

B00Q - R0003 - General Storeroom (42.74 m2)

No Asbestos

B00Q - R0004 - External Movement (25.82 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Technological & Applied Studies/Building Services - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - Dust Extraction Space (10.11 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 840 - D10300 - Girls Toilet : Placement Date - 23/10/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 601 - D10798 - Learning Unit - Standard/Withdrawal : Placement Date - 15/12/2010

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D10847 - Learning Unit - Standard/Withdrawal : Placement Date - 15/12/2010

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 600 - D10866 - Learning Unit - Small : Placement Date - 30/11/2012

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 600 - D10945 - Learning Unit - Small : Placement Date - 11/11/2009

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

OS 840 - D11922 - Girls Toilet : Placement Date - 23/10/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
No Asbestos Found.						
Interior						
R1 - Toilets-Girls						
No Asbestos Found.						
OS 601 - D12392 - Learning Unit - Standard/Withdrawal : Placement Date - 22/09/2011						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 521 - D12451 - Staff Study : Placement Date - 30/11/2012						
Exterior						
No Asbestos Found.						
Interior						
R1 - Staff Room						
No Asbestos Found.						
R2 - Staff Toilet						
No Asbestos Found.						
R3 - Staff Toilet						
No Asbestos Found.						
R4 - Lobby						
No Asbestos Found.						
OS 601 - D12733 - Learning Unit - Standard/Withdrawal : Placement Date - 5/05/2011						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 600 - D13132 - Learning Unit - Small : Placement Date - 16/01/2010						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
OS 710 - D13413 - Home Science/Pantry/Laundry : Placement Date - 16/03/1999						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				14.4 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
R2 - Food Technology L.S.						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				73 m2
R3 - Laundry						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
OS 600 - D13996 - Learning Unit - Small : Placement Date - 23/02/1998						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
OS 600 - D16317 - Learning Unit - Small : Placement Date - 30/01/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
OS 600 - D17677 - Learning Unit - Small : Placement Date - 11/11/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017