


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Plumpton High School (8514)
Region : Western Sydney
State Electorate : Mount DrUITt
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 12 - May - 2008
Reviewed By : Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Computer Learning - 1972 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00A - R0001 - Laboratory L.S. (88.64 m2)

No Asbestos

B00A - R0002 - Security Store (27.87 m2)

No Asbestos

B00A - R0003 - Toilets-Boys (18.39 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0004 - General Learning Space (52.19 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0005 - Secure Storeroom (13.19 m2)

No Asbestos

B00A - R0006 - Interview/Office - Type 1 (15.05 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0007 - General Learning Space (51.68 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0008 - General Learning Space (51.83 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0009 - General Learning Space (51.26 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00A/R0004/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0010 - Security Store (18.01 m2)

No Asbestos

B00A - R0011 - Cleaning Store - Distributed (5.67 m2)

No Asbestos

B00A - R0012 - Laboratory L.S. (90.31 m2)

No Asbestos

B00A - R0013 - Preparation (49.1 m2)

No Asbestos

B00A - R0014 - Main Switchroom (0.76 m2)

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
 8514/B00A/R0017/Ceiling Structures/Linings/S12 **Chrysotile (white asbestos)**

B00A - R0015 - Distribution Board Cupboard (0.73 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0017 - Lift (0.27 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00A - R0018 - Cleaning Store - Distributed (0.42 m2)						
No Asbestos						
B00A - R0020 - Distribution Board Cupboard (0.51 m2)						
						Note: No inspection of live electrical installation.
No Asbestos						
B00A - R0021 - Lift (1.93 m2)						
No Asbestos						
B00A - R0022 - Movement (173.83 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0023 - Stairs (0.48 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0024 - External Movement (20.58 m2)						
No Asbestos						
B00A - R0025 - External Movement (26.2 m2)						
No Asbestos						
B00A - R0026 - External Stairs (18.13 m2)						
No Asbestos						
B00A - R1001 - Laboratory L.S. (88.95 m2)						
No Asbestos						
B00A - R1002 - Staff Study (27.94 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1003 - Toilets-Girls (18.34 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00A - R1004 - General Learning Space (51.82 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1005 - Cleaning Store - Distributed (0.42 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00A - R1007 - Distribution Board Cupboard (0.51 m2)						
						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00A - R1008 - Staff Study (29.02 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1009 - General Learning Space (52.04 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1010 - General Learning Space (51.83 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1011 - General Learning Space (51.25 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1012 - Toilets-Girls (18.43 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8514/B00A/R0017/Ceiling Structures/Linings/S12	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 8514/B00A/R1012/Partition Walls (Cubicles)/S13	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1013 - Laboratory L.S. (90.32 m2)						
No Asbestos						
B00A - R1014 - Lift (0.27 m2)						
No Asbestos						
B00A - R1015 - Cleaning Store - Distributed (0.65 m2)						
No Asbestos						
B00A - R1016 - Preparation (49.73 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00A/R0012/Floor Coverings Res/Textile/S2	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1017 - Distribution Board Cupboard (0.73 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1019 - Lift (1.93 m2)						
No Asbestos						
B00A - R1020 - Staff Study (38.86 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1021 - Movement (133.08 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1022 - Stairs (6.23 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1023 - Movement (20.58 m2)						
No Asbestos						
B00A - R1024 - Movement (26.2 m2)						
No Asbestos						
B00A - R1025 - Stairs (18.13 m2)						
No Asbestos						
B00A - R2001 - Laboratory L.S. (88.94 m2)						
No Asbestos						
B00A - R2002 - Distribution Board Cupboard (0.66 m2)						
					Note: No inspection of live electrical installation.	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
---------	----------------------	--------	--------------------	--------------------	-------------	------------------

Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)		

B00A - R2003 - Staff Study (19.42 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R2004 - Staff - Toilet (2.28 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R2005 - Staff - Toilet (2.28 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R2007 - Laboratory L.S. (90.68 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R2008 - Lift (0.62 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R2009 - Cleaning Store - Distributed (0.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)		

B00A - R2010 - Preparation (49.72 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		

B00A - R2011 - Distribution Board Cupboard (0.71 m2)

				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)		

B00A - R2012 - Lift (1.93 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R2013 - Movement (20.1 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R2014 - Stairs (5.08 m2)

Ceiling Structures/Linings	Vermiculite	8514/B00A/R0004/Ceiling Structures/Linings/S1		Limited Samples Taken		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Technological & Applied Studies - 1972 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - Wood Technology L.S. (81.67 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0002 - Cleaning Store - Distributed (3.7 m2)

No Asbestos

B00B - R0003 - Cleaning Store - Distributed (0.69 m2)

No Asbestos

B00B - R0004 - Materials Store (34.18 m2)

No Asbestos

B00B - R0005 - Metal Technology L.S. (70.79 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0006 - Distribution Board Cupboard (0.84 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
<i>Assumed Asbestos - Electrical Hazard</i>						

B00B - R0007 - Metal Technology Bay (35.14 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0008 - Welding Area (14.49 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0009 - Metal Technology L.S. (75.34 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00A/R0004/Ceiling Structures/Linings/S1					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0010 - Design L.S. (54.39 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0011 - Darkroom Space (19.74 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00B - R0012 - Design L.S. (32.08 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00B/R0023/Ceiling Structures/Linings/S6					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0013 - Distribution Board Cupboard (0.7 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority	
Sample No				Test Result			
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	
8514/B00A/R0017/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)			
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)	
Assumed Asbestos - Electrical Hazard							
B00B - R0014 - Design L.S. (53.79 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
B00B - R0015 - Cleaning Store - Distributed (3.89 m2)							
No Asbestos							
B00B - R0016 - Art Learning Space (65.96 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
B00B - R0017 - Bulk Store (16.6 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
B00B - R0018 - Distribution Board Cupboard (0.5 m2)							
				Note: No inspection of live electrical installation.			
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	
8514/B00A/R0017/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)			
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)	
Assumed Asbestos - Electrical Hazard							
B00B - R0019 - Art Learning Space (61.34 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected	
8514/B00B/R0020/Wall Linings Internal/S7							
B00B - R0020 - Resources Space (30.99 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected	
8514/B00B/R0020/Wall Linings Internal/S7							
B00B - R0021 - Art Learning Space (60.02 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected	
8514/B00B/R0020/Wall Linings Internal/S7							
B00B - R0023 - Wood Technology L.S. (82.25 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
B00B - R0024 - Materials Store (19.15 m2)							
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8514/B00B/R0023/Ceiling Structures/Linings/S6				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works			
B00B - R0025 - Wood Technology Bay (6.3 m2)							

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0026 - Wood Technology Bay (6.3 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0027 - Distribution Board Cupboard (0.9 m2)					Note: No inspection of live electrical installation.	
Electrical Backing Board	Resinous Membrane	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00B - R0028 - General Storeroom (20.91 m2)						
No Asbestos						
B00B - R0029 - External Movement (39.27 m2)						
No Asbestos						
B00B - R0030 - Dust Extraction Space (9.68 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0031 - Movement (6.87 m2)						
No Asbestos						
B00B - R0032 - Bulk Store (8.58 m2)						
No Asbestos						
B00B - R0033 - Movement (120.91 m2)						
No Asbestos						
B00B - R0034 - Bulk Store (7.45 m2)						
No Asbestos						
B00B - R0035 - Uniform Shop (21.78 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0036 - Shower/Change (0.95 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0037 - Shower/Change (0.95 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0038 - Stairs (10.31 m2)						
No Asbestos						
B00B - R0039 - Stairs (8.97 m2)						
No Asbestos						
B00B - R0040 - Art Learning Space (42.67 m2)						
No Asbestos						
B00B - R0041 - External Movement (31.48 m2)						
No Asbestos						
B00B - R1001 - Staff Study (24.59 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1002 - Movement (2.3 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1003 - Staff Change (4.11 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1009 - Food Technology L.S. (93.31 m2)						
No Asbestos						
B00B - R1010 - Design L.S. (74.02 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1011 - Cleaning Store - Distributed (0.49 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00B - R1012 - Food/Research Space (8.78 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1013 - Design L.S. (5.79 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1014 - Design L.S. - Type 8 (72.87 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1015 - Distribution Board Cupboard (0.54 m2) Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	0.6m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00B - R1016 - Music Learning Space (66.61 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1017 - Music Store (30.63 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1018 - Cleaning Store - Distributed (0.65 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
B00B - R1019 - Music Learning Space (62.97 m2)						
Ceiling Structures/Linings	Vermiculite					
8514/B00B/R0023/Ceiling Structures/Linings/S6					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1020 - Distribution Board Cupboard (0.47 m2)						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
Electrical Mounting Board	Resinous Board	1Unit	West	Good Condition (1)	Medium (2)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00B - R1022 - Stairs (14.69 m2)						
No Asbestos						
B00B - R1023 - Stairs (15.55 m2)						
No Asbestos						
B00B - R1024 - General Storeroom (6.22 m2)						
Ceiling Structures/Linings	Vermiculite					
8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1025 - Movement (150.78 m2)						
No Asbestos						
B00B - R1026 - Store (3.29 m2)						
No Asbestos						
B00B - R1027 - Preparation (25.02 m2)						
No Asbestos						
B00B - R1028 - General Storeroom (0.43 m2)						
No Asbestos						
B00B - R1029 - Laundry (1.26 m2)						
No Asbestos						
B00B - R1030 - External Movement (31.48 m2)						
No Asbestos						
B00B - R1031 - Food Technology L.S. (109.38 m2)						
Ceiling Structures/Linings	Vermiculite					
8514/B00A/R0004/Ceiling Structures/Linings/S1					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Multi Purpose Facilities - 1972 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Chair Store (9.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00C - R0002 - Shower/Change (2.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00C - R0003 - Sport Equipment Store (56.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

B00C - R0004 - Movement (14.13 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

B00C - R0005 - Shower/Change (2.61 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

B00C - R0006 - Staff Study (8.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00C - R0007 - Staff Study (14.99 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R1012/Partition Walls (Cubicles)/S13				Chrysotile (white asbestos)	


B00C - R0008 - Staff Study (3.43 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

B00C - R0009 - Shower/Change (54.3 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting	8m2	Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
B00C - R0010 - Multi-Purpose Space (466.6 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8514/B00C/R1007/Ceiling Structures/Linings/S11					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00C - R0011 - Maintenance Bulk Store (10.46 m2)						
No Asbestos						
B00C - R0012 - Main Switchroom (8.74 m2)						
No Asbestos						
B00C - R0013 - General Storeroom (18.4 m2)						
No Asbestos						
B00C - R0015 - Staff - Toilet (1.85 m2)						
No Asbestos						
B00C - R0016 - General Storeroom (4.95 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00C - R0017 - Shower/Change (2.45 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00C - R0018 - Student Canteen (48.51 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00C - R0020 - Shower/Change (46.15 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R1012/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)
B00C - R0021 - Cleaning Store - Distributed (2.37 m2)						
No Asbestos						
B00C - R0022 - Toilets-Girls (14.16 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R1012/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)
B00C - R0023 - Movement (14.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
B00C - R0024 - Chair Store (12.39 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0026 - Plant (1.81 m2)						
No Asbestos						
B00C - R0027 - Movement (87.99 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00C - R0028 - External Movement (128.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	north/adjacent to canteen	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00C/R0018/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00C - R1001 - Toilets-Girls (22.93 m2)						
No Asbestos						
B00C - R1002 - General Storeroom (5.84 m2)						
No Asbestos						
B00C - R1003 - Staff - Toilet (2.77 m2)						
No Asbestos						
B00C - R1004 - Shower/Change (1.6 m2)						
No Asbestos						
B00C - R1005 - Shower/Change (1.6 m2)						
No Asbestos						
B00C - R1006 - Movement (17.19 m2)						
No Asbestos						
B00C - R1007 - Cleaning Supplies Store (11.69 m2)						
Ceiling Structures/Linings	Vermiculite					
8514/B00C/R1007/Ceiling Structures/Linings/S11					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
B00C - R1008 - Music Store (25.82 m2)						
Ceiling Structures/Linings	Vermiculite					
8514/B00C/R1007/Ceiling Structures/Linings/S11					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00C - R1009 - Movement (66.62 m2)						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - Administration/Staff Facilities - 1968 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00D - R0001 - Ancillary Staff (22.63 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0002 - Security Store (19.84 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00D/R0002/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
B00D - R0003 - Cleaning Store - Distributed (0.46 m2)						
No Asbestos						
B00D - R0004 - Distribution Board Cupboard (0.76 m2)						
					Note: No inspection of live electrical installation.	
Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00D - R0007 - Deputy Principal Office (10.24 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0008 - Deputy Principal Office (14.44 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0009 - Principal Office (21.79 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0011 - Cleaning Store - Distributed (6.33 m2)						
No Asbestos						
B00D - R0013 - Administration - Clerical (26.88 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0015 - Interview/Office - Type 1 (9.56 m2)						
No Asbestos						
B00D - R0016 - External Movement (14.07 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8514/B00D/R0016/Ceiling Structures/Linings/S16					No Asbestos Detected
B00D - R0017 - Stairs (3.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0018 - Toilet - Lobby (1.53 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0019 - Staff - Toilet (1.51 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0020 - Toilet - Lobby (1.84 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0021 - Staff - Toilet (1.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0022 - External Movement (41.45 m2)						
No Asbestos						
B00D - R0023 - Movement (20.37 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0024 - Entry (44.9 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1002 - Distribution Board Cupboard (0.63 m2)				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00D - R1003 - Cleaning Store - Distributed (0.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00D - R1004 - Movement (4.58 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1005 - Staff - Toilet (3.62 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1006 - Staff - Toilet (3.13 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1007 - Leading Teacher (7.77 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00D/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1008 - Interview/Office - Type 1 (12.52 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1009 - Staff - Toilet (3.45 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1010 - Interview/Office - Type 1 (11.36 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1011 - Ancillary Staff (11.62 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1012 - Movement (21.14 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1013 - Movement (41.51 m2)						
No Asbestos						
B00D - R1014 - Movement (11.77 m2)						
No Asbestos						
B00D - R1015 - Stairs (8.81 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1016 - Commonroom (85.87 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1017 - Staff Kitchen (3.12 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1018 - Movement (3.27 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1019 - Staff Study (19.78 m2)						
Ceiling Structures/Linings	Vermiculite	8514/B00D/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 1972 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00E - R0001 - Seminar (15.44 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0002 - Staff - Toilet (3.88 m2)

Ceiling Structures/Linings Flat AC Sheeting 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
 8514/B00A/R0017/Ceiling Structures/Linings/S12 **Chrysotile (white asbestos)**

B00E - R0003 - Secure Storeroom (3.64 m2)

No Asbestos

B00E - R0004 - Audio Visual Workroom (30.6 m2)

Ceiling Structures/Linings Flat AC Sheeting 31m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
 8514/B00A/R0017/Ceiling Structures/Linings/S12 **Chrysotile (white asbestos)**

B00E - R0005 - Librarian (8.79 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0006 - Workroom (23.55 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0007 - Entry (11.92 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0008 - Distribution Board Cupboard (0.68 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - Workroom (64.24 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0010 - Toilets-Girls (3.89 m2)

Ceiling Structures/Linings Flat AC Sheeting 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
 8514/B00A/R0017/Ceiling Structures/Linings/S12 **Chrysotile (white asbestos)**

B00E - R0011 - Distribution Board Cupboard (0.63 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0012 - Seminar (15.21 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0013 - Seminar (15.99 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0015 - Seminar (15.75 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0016 - Movement (3.01 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0017 - Stairs (4.33 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0018 - Stairs (0.25 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0019 - External Movement (63.41 m2)						
No Asbestos						
B00E - R0020 - Library Administration (247.99 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0021 - Lift (1.53 m2)						
No Asbestos						
B00E - R1001 - Main Area (179.04 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1002 - Toilets-Boys (27.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00E - R1004 - Senior Seminar (14.15 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1005 - Senior Seminar (14.15 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1006 - Distribution Board Cupboard (0.52 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<i>Assumed Asbestos - Electrical Hazard</i>						
B00E - R1007 - Stairs (4.46 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1008 - Stairs (4.18 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00E/R1003/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1009 - Movement (63.41 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R1010 - Careers Advisers Office (29.24 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R1011 - Seminar/Study (58.92 m2)

Ceiling Structures/Linings Vermiculite
 8514/B00E/R1003/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00F - General Learning - 1972 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior**B00F - R0001 - General Learning Space (50.72 m2)**

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0002 - General Learning Space (51.98 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0003 - Staff Study (22.06 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0004 - General Storeroom (5.79 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles 6m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00F - R0005 - General Storeroom (5.4 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles 6m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00F - R0006 - Security Store (20.11 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles 21m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00F - R0007 - General Storeroom (4.53 m2)

Floor Coverings Res/Textile Vinyl Tiles 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8514/B00A/R0012/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00F - R0008 - Staff - Toilet (5.11 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Partition Walls (Cubicles) Compressed AC Sheet 3m2 North Good Condition (1) Low (1) Low Priority (2-3)
8514/B00A/R1012/Partition Walls (Cubicles)/S13 **Chrysotile (white asbestos)**

B00F - R0009 - Interview/Office - Type 1 (12.42 m2)

Ceiling Structures/Linings Vermiculite
8514/B00F/R0017/Ceiling Structures/Linings/S5 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00F - R0010 - General Learning Space (50.82 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0011 - General Learning Space (56.16 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0012 - General Learning Space (50.25 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0013 - Staff Study (34.15 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0014 - General Learning Space (51.04 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0015 - Cleaning Store - Distributed (3.39 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00F/R0015/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00F - R0016 - Entry (12.83 m2)						
No Asbestos						
B00F - R0017 - Toilets-Girls (28.18 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0018 - General Learning Space (51.11 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0019 - Cleaning Store - Distributed (0.79 m2)						
No Asbestos						
B00F - R0021 - Distribution Board Cupboard (0.78 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R0022 - General Storeroom (28.07 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0023 - General Learning Space (37.9 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0024 - General Learning Space (49.89 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00F - R0025 - Sport Equipment Store (4.27 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00A/R0012/Floor Coverings Res/Textile/S2	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R0026 - Movement (143.9 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Ceiling Structures/Linings	Flat AC Sheeting 8514/B00A/R0017/Ceiling Structures/Linings/S12	1m2	Next to FR0019	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R0027 - Movement (4.73 m2)						
No Asbestos						
B00F - R0028 - General Assistants (17.48 m2)						
No Asbestos						
B00F - R0029 - Covered Area (27.3 m2)						
No Asbestos						
B00F - R0030 - Stairs (12.4 m2)						
No Asbestos						
B00F - R0031 - Stairs (13.83 m2)						
No Asbestos						
B00F - R0032 - External Movement (34.81 m2)						
No Asbestos						
B00F - R1001 - General Learning Space (51.81 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1002 - General Learning Space (51.69 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1003 - General Storeroom (22.51 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1004 - General Storeroom (3.83 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00A/R0012/Floor Coverings Res/Textile/S2	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R1005 - General Storeroom (3.64 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00A/R0012/Floor Coverings Res/Textile/S2	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R1006 - Staff - Toilet (23.59 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 8514/B00A/R1012/Partition Walls (Cubicles)/S13	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R1007 - Staff - Toilet (5.2 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 8514/B00A/R1012/Partition Walls (Cubicles)/S13	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R1008 - General Learning Space (12.03 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1009 - General Learning Space (50.82 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1010 - General Learning Space (57.13 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1011 - General Learning Space (51.13 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1012 - Staff Study (33.6 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1013 - General Learning Space (50.9 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1014 - Movement (8.06 m2)						
No Asbestos						
B00F - R1015 - Movement (3.91 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1016 - Study Space (9.96 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1017 - Staff Study (13.87 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1018 - General Learning Space (49.48 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R1019 - Cleaning Store - Distributed (0.79 m2)						
No Asbestos						
B00F - R1021 - Distribution Board Cupboard (0.79 m2)						
No Asbestos				Note: No inspection of live electrical installation.		
B00F - R1023 - Study Space (38.34 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R1024 - General Learning Space (50.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R1025 - Movement (144.69 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Adjacent R1019	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)
B00F - R1026 - Stairs (18.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R1027 - Stairs (8.06 m2)						
No Asbestos						
B00F - R1028 - Stairs (17.34 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R1029 - Movement (34.81 m2)						
No Asbestos						
B00F - R1030 - General Learning Space (26.07 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R1031 - Staff Kitchen (2.87 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R2001 - General Learning Space (50.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R2002 - Interview/Office - Type 1 (14.22 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R2003 - General Storeroom (22.41 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R2004 - General Storeroom (3.85 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0012/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00F - R2005 - General Storeroom (3.65 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8514/B00A/R0012/Floor Coverings Res/Textile/S2	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R2006 - Staff - Toilet (23.59 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 8514/B00A/R1012/Partition Walls (Cubicles)/S13	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R2007 - General Learning Space (40.47 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2008 - General Learning Space (57.18 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2009 - General Learning Space (50.83 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2010 - Staff Study (33.96 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2011 - General Learning Space (51.11 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2012 - Movement (6.59 m2)						
No Asbestos						
B00F - R2013 - General Learning Space (50.75 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2014 - Cleaning Store - Distributed (0.79 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2016 - Distribution Board Cupboard (0.79 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2017 - General Storeroom (28.18 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00F - R2018 - General Learning Space (38.96 m2)						
Ceiling Structures/Linings	Vermiculite 8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R2019 - Movement (112.44 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Adjacent R2014	Good Condition (1)	Low (1)	Low Priority (2-3)
	8514/B00A/R0017/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)

B00F - R2020 - Stairs (8.88 m2)						
No Asbestos						

B00F - R2021 - Stairs (17.34 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00F - R2022 - Stairs (18.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	8514/B00F/R0017/Ceiling Structures/Linings/S5					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Performing Arts - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - M0001 - Plant (20.53 m2)

No Asbestos

B00G - M0002 - Stairs (2.47 m2)

No Asbestos

B00G - R0003 - Control Room (2.02 m2)

No Asbestos

B00G - R0004 - Cleaning Store - Distributed (2.28 m2)

No Asbestos

B00G - R0005 - Performing Arts Store (21.74 m2)

No Asbestos

B00G - R0006 - Performing Arts Store (32.2 m2)

No Asbestos

B00G - R0007 - External Movement (7.83 m2)

No Asbestos

B00G - R0008 - Lift (2.36 m2)

No Asbestos

B00G - R0009 - Stairs (0.95 m2)

No Asbestos

B00G - R0010 - Performing Arts Changeroom (20.56 m2)

No Asbestos

B00G - R0011 - Stage (102.2 m2)

No Asbestos

B00G - R0012 - Multi-Purpose Space (413.9 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Agricultural Science - 2005 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Class Tools Storage (25.41 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Performing Arts/Multi Purpose Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00P - M0001 - Tiered Learning Area (151.69 m2)

No Asbestos

B00P - M0002 - Control Room (18.32 m2)

No Asbestos

B00P - R0001 - External Movement (14.92 m2)

No Asbestos

B00P - R0002 - Public Reception (31.46 m2)

No Asbestos

B00P - R0003 - Administration - Clerical (9.58 m2)

No Asbestos

B00P - R0004 - Performing Arts Store (24.91 m2)

No Asbestos

B00P - R0005 - Student Canteen (15.96 m2)

No Asbestos

B00P - R0006 - Toilets - Boys (12.36 m2)

No Asbestos

B00P - R0007 - Toilet - Lobby (1.73 m2)

No Asbestos

B00P - R0008 - Cleaning Store - Distributed (2.85 m2)

No Asbestos

B00P - R0009 - Access Student Shower/Toilet/Change (6.89 m2)

No Asbestos

B00P - R0010 - Toilet - Lobby (1.62 m2)

No Asbestos

B00P - R0011 - Toilets - Girls (13.9 m2)

No Asbestos

B00P - R0012 - Performing Arts Store (42.32 m2)

No Asbestos

B00P - R0013 - Movement (29.81 m2)

No Asbestos

B00P - R0014 - Performing Arts Store (34.73 m2)

No Asbestos

B00P - R0015 - Movement (134.06 m2)

No Asbestos

B00P - R0016 - Performance Workspace (70.78 m2)

No Asbestos

B00P - R0017 - Performing Arts Changeroom (14.63 m2)

No Asbestos

B00P - R0018 - Toilets-Unisex (1.99 m2)

No Asbestos

B00P - R0019 - Performing Arts Store (8.88 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00P - R0020 - Performing Arts Changeroom (14.66 m2)						
No Asbestos						
B00P - R0021 - Performing Arts Store (4.57 m2)						
No Asbestos						
B00P - R0022 - Toilets-Unisex (1.97 m2)						
No Asbestos						
B00P - R0023 - Distribution Board Cupboard (3.98 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00P - R0024 - Utility Space (0.47 m2)						
No Asbestos						
B00P - R0025 - Tiered Learning Area (24.48 m2)						
No Asbestos						
B00P - R0026 - Tiered Learning Area (24.16 m2)						
No Asbestos						
B00P - R0027 - Tiered Learning Area (33.79 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Mechanical Services - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00Q - R0001 - General Storeroom (49.62 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Agricultural Science/Other - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00R - R0001 - Garden Store Room (7.64 m2)

No Asbestos

B00R - R0002 - General Learning Space (51.8 m2)

No Asbestos

B00R - R0003 - Garden Store Room (19.35 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11621 - Learning Unit - Standard With P.A.A. : Placement Date - 23/09/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 710 - D12301 - Home Science/Pantry/Laundry : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

R2 - Food Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

R3 - Laundry

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

OS 601 - D14803 - Learning Unit - Standard/Withdrawal : Placement Date - 12/12/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017