


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Quakers Hill Public School (2918)
Region : Western Sydney
State Electorate : Blacktown
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 12 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 21 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Pupil Facilities/Communal Facilities - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2918/B00K/Wall Cladding/S1					No Asbestos Detected

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Sports Store

No Asbestos

B00A - R0003 - Canteen Office/Store

No Asbestos

B00A - R0004 - Canteen Office/Store

No Asbestos

B00A - R0005 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles 2918/B00A/R0005/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00A - R0006 - Communal Space

No Asbestos

B00A - R0007 - Communal/Performance Store

No Asbestos

B00A - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2918/B00A/R0008/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

B00A - R0009 - Staff Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2918/B00A/R0008/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

B00A - R0010 - Cleaning Distributed Store

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Raised Platform

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - Distribution Board Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 2918/B00K/R0013/Wall Linings Internal/S10					No Asbestos Detected
Electrical Backing Board	Resinous Board 2918/B00A/R0015/Electrical Backing Board/S11					No Asbestos Detected

B00A - R0016 - Staff Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2918/B00A/R0008/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

B00A - R0017 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2918/B00A/R0008/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0018 - Hall Chair Store						
No Asbestos						
B00A - R0019 - Movement						
No Asbestos						
B00A - R0020 - General Storeroom						
No Asbestos						
B00A - R0021 - Disabled Toilet						
No Asbestos						
B00A - R0022 - Plant						
Flue Pipe	Fibre Cement Pipe	1m	From Boiler Unit	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	2918/B00A/R0022/Flue Pipe/S12				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1987 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00B - R0001 - Garden Store

No Asbestos

B00B - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Cleaning Distributed Store

No Asbestos

B00B - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Practical Activities - 1hb

No Asbestos

B00B - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0017 - Toilets - Boys

Wall Linings Internal Flat AC Sheeting
2918/B00D/R0009/Wall Linings Internal/S9

No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
2918/B00D/R0009/Ceiling Structures/Linings/S8

No Asbestos Detected

B00B - R0018 - Toilets - Girls

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting		2918/B00D/R0009/Ceiling Structures/Linings/S8			No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting		2918/B00D/R0009/Wall Linings Internal/S9			No Asbestos Detected
B00B - R0019 - General Assistant/Bulk Store						
No Asbestos						
B00B - R0020 - P.E. Store						
Ceiling Structures/Linings	Flat AC Sheeting		2918/B00D/R0009/Ceiling Structures/Linings/S8			No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting		2918/B00D/R0009/Wall Linings Internal/S9			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1987 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - Practical Activities - 1hb

No Asbestos

B00C - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting 2918/B00D/R0009/Ceiling Structures/Linings/S8	No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Practical Activities - 1hb

No Asbestos

B00D - R0007 - Practical Activities - 1hb

No Asbestos

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0009 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 2918/B00D/R0009/Ceiling Structures/Linings/S8	No Asbestos Detected

B00D - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting 2918/B00D/R0009/Ceiling Structures/Linings/S8	No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected

B00E - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0007 - Practical Activities - 1hb

No Asbestos

B00E - R0008 - Practical Activities - 1hb

No Asbestos

B00E - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0012 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 2918/B00D/R0009/Ceiling Structures/Linings/S8	No Asbestos Detected

B00E - R0013 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 2918/B00D/R0009/Ceiling Structures/Linings/S8	No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Administration - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - Cleaning Distributed Store

No Asbestos

B00F - R0004 - Home Base Store

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0006 - Home Base

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0007 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0008 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0009 - Home Base

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0010 - Withdrawal Space - 1hb

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0013 - Cleaning Supplies

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0014 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0015 - Home Base

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0016 - Home Base

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

B00F - R0017 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2918/B00D/R0009/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0018 - Withdrawal Space - 1hb						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
			2918/B00D/R0009/Wall Linings Internal/S9			
B00F - R0019 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0020 - Toilets - Girls						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
			2918/B00D/R0009/Wall Linings Internal/S9			
B00F - R0021 - Toilets - Boys						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
			2918/B00D/R0009/Wall Linings Internal/S9			
B00F - R0022 - Community Clinic						
No Asbestos						
B00F - R0023 - Community Clinic						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0024 - Community Clinic						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0025 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1914 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00H - R0001 - Uniform Shop

No Asbestos

B00H - R0008 - Kiln Room

No Asbestos

B00H - R0009 - Staff Room

No Asbestos

B00H - R0010 - Movement

No Asbestos

B00H - R0011 - Home Base Store

No Asbestos

B00H - R0013 - Toilets-Unisex

No Asbestos

B00H - R0014 - Toilets-Unisex

No Asbestos

B00H - R0015 - Toilet - Lobby

No Asbestos

B00H - R0016 - Practical Activities

No Asbestos

B00H - R0017 - Home Base

No Asbestos

B00H - R0018 - Movement

No Asbestos

B00H - R0019 - Interview

No Asbestos

B00H - R0020 - Practical Activities

No Asbestos

B00H - R0021 - Home Base

No Asbestos

B00H - R0022 - General Storeroom

No Asbestos

B00H - R0023 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1950 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2918/B00K/Wall Cladding/S1					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00I - R0003 - Movement

Wall Linings Internal	Flat AC Sheeting 2918/B00I/R0003/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00I - R0004 - Home Base Store

No Asbestos

B00I - R0005 - Home Base

No Asbestos

B00I - R0006 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library/Tiered Learning - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2918/B00K/Wall Cladding/S1					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00J - R0002 - Distribution Board Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 2918/B00J/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00J - R0003 - Cleaning Distributed Store

No Asbestos

B00J - R0004 - Reading Area

No Asbestos

B00J - R0005 - Movement

No Asbestos

B00J - R0006 - Movement

No Asbestos

B00J - R0007 - Library Office/Workroom

No Asbestos

B00J - R0008 - Library Office/Workroom

No Asbestos

B00J - R0009 - Special Programs Room

No Asbestos

B00J - R0010 - Special Programs Store

No Asbestos

B00J - R0011 - General Storeroom

No Asbestos

B00J - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Administration/Staff Facilities - 1984 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2918/B00K/Wall Cladding/S1					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00K - R0001 - Movement						
No Asbestos						
B00K - R0002 - Duplicating Workroom						
No Asbestos						
B00K - R0003 - Deputy Principal						
No Asbestos						
B00K - R0004 - Interview						
No Asbestos						
B00K - R0005 - Deputy Principal						
No Asbestos						
B00K - R0006 - Staff Room						
No Asbestos						
B00K - R0007 - Movement						
No Asbestos						
B00K - R0008 - Staff Room						
No Asbestos						
B00K - R0009 - Staff Toilet						
No Asbestos						
B00K - R0010 - Staff Toilet						
No Asbestos						
B00K - R0011 - Movement						
No Asbestos						
B00K - R0012 - Cleaning Distributed Store						
No Asbestos						
B00K - R0013 - Distribution Board					Note: No inspection of live electrical installation.	
Wall Linings Internal	Flat AC Sheeting 2918/B00K/R0013/Wall Linings Internal/S10					No Asbestos Detected
B00K - R0014 - Security Store						
No Asbestos						
B00K - R0015 - Principal						
No Asbestos						
B00K - R0016 - Sick Bay						
No Asbestos						
B00K - R0017 - Clerical Office						
No Asbestos						
B00K - R0018 - Movement						
No Asbestos						
B00K - R0019 - Entry Vestibule						
No Asbestos						
B00K - R0020 - Movement						
No Asbestos						
B00K - R0021 - Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - Practical Activities - 1hb

No Asbestos

B00L - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - Practical Activities - 1hb

No Asbestos

B00M - R0002 - Home Base Store

No Asbestos

B00M - R0003 - Withdrawal Space - 1hb

No Asbestos

B00M - R0004 - Practical Activities - 1hb

No Asbestos

B00M - R0005 - Home Base Store

No Asbestos

B00M - R0006 - Home Base

No Asbestos

B00M - R0007 - Home Base

No Asbestos

B00M - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Practical Activities - 1hb

No Asbestos

B00N - R0002 - Home Base Store

No Asbestos

B00N - R0003 - Withdrawal Space - 2hb

No Asbestos

B00N - R0004 - Practical Activities - 1hb

No Asbestos

B00N - R0005 - Home Base Store

No Asbestos

B00N - R0006 - Practical Activities - 1hb

No Asbestos

B00N - R0007 - Home Base Store

No Asbestos

B00N - R0008 - Withdrawal Space - 2hb

No Asbestos

B00N - R0009 - Practical Activities - 1hb

No Asbestos

B00N - R0010 - Home Base Store

No Asbestos

B00N - R0011 - Home Base

No Asbestos

B00N - R0012 - Home Base

No Asbestos

B00N - R0013 - Home Base

No Asbestos

B00N - R0014 - Home Base

No Asbestos

B00N - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Other - After School Care - 2013 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B000 - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - Wesley Out Of School Care

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+2 - SIMULA Building

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 750 - D11211 - Learning Unit - ESL : Placement Date - 10/01/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

OS 602 - D11412 - Learning Unit - Standard With P.A.A. : Placement Date - 4/10/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12580 - Learning Unit - Standard With P.A.A. : Placement Date - 12/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12691 - Learning Unit - Standard With P.A.A. : Placement Date - 12/11/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14598 - Learning Unit - Standard With P.A.A. : Placement Date - 23/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14670 - Learning Unit - Standard With P.A.A. : Placement Date - 12/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14672 - Learning Unit - Standard With P.A.A. : Placement Date - 19/12/2015						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14716 - Learning Unit - Standard With P.A.A. : Placement Date - 22/10/1996						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D14902 - Learning Unit - Standard With P.A.A. : Placement Date - 10/01/2008						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 750 - D15716 - Learning Unit - ESL : Placement Date - 10/07/2015						
Exterior						
No Asbestos Found.						
Interior						
R1 - Esl						
No Asbestos Found.						
OS 602 - D15792 - Learning Unit - Standard With P.A.A. : Placement Date - 28/10/2013						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D15859 - Learning Unit - Standard With P.A.A. : Placement Date - 20/03/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16276 - Learning Unit - Standard With P.A.A. : Placement Date - 22/04/2014						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16840 - Learning Unit - Standard With P.A.A. : Placement Date - 21/11/2014						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017