


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Quakers Hill East Public School (4212)
Region : Western Sydney
State Electorate : Riverstone
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 12 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-Community Use/Support Unit - 2001 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 4212/B00G/Wall Cladding/S1					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Community Clinic

No Asbestos

B00G - R0003 - Toilets - Boys/Girls

No Asbestos

B00G - R0004 - Community Clinic

No Asbestos

B00G - R0005 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0AA - Administration/Staff Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0AA - R0001 - External Movement

No Asbestos

B0AA - R0002 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0003 - Cleaning Distributed Store

No Asbestos

B0AA - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0AA - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0006 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0007 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0008 - Access Shower/Toilet

No Asbestos

B0AA - R0009 - Sick Bay

No Asbestos

B0AA - R0010 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0011 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0012 - Duplicating Workroom

No Asbestos

B0AA - R0013 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0014 - Security Store

No Asbestos

B0AA - R0015 - Staff Toilet

No Asbestos

B0AA - R0016 - Staff Toilet

No Asbestos

B0AA - R0017 - Staff Toilet

No Asbestos

B0AA - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0019 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0BB - Communal Facilities/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0BB - R0001 - Covered Outdoor Learning Area**

No Asbestos

B0BB - R0002 - Toilets - Girls

No Asbestos

B0BB - R0003 - Cleaning Supplies

No Asbestos

B0BB - R0004 - K.L.A. Store

No Asbestos

B0BB - R0005 - General Assistant/Bulk Store

No Asbestos

B0BB - R0006 - Garden Store

No Asbestos

B0BB - R0007 - Communal Space

No Asbestos

B0BB - R0008 - Movement

No Asbestos

B0BB - R0009 - Raised Platform

No Asbestos

B0BB - R0010 - Movement

No Asbestos

B0BB - R0011 - External Movement

No Asbestos

B0BB - R0012 - Sports Store

No Asbestos

B0BB - R0013 - P.E. Store

No Asbestos

B0BB - R0014 - Hall Chair Store

No Asbestos

B0BB - R0015 - Cleaning Distributed Store

No Asbestos

B0BB - R0016 - Main Switch Board

No Asbestos

B0BB - R0017 - Communications Room

No Asbestos

B0BB - R0018 - Toilets - Boys

No Asbestos

B0BB - R0019 - Access Shower/Toilet

No Asbestos

B0BB - R0020 - Canteen Office/Store

No Asbestos

B0BB - R0021 - Canteen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0CC - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0CC - R0001 - External Movement

No Asbestos

B0CC - R0002 - Home Base Store

No Asbestos

B0CC - R0003 - Practical Activities - 1hb

No Asbestos

B0CC - R0004 - External Movement

No Asbestos

B0CC - R0005 - Toilets - Girls

No Asbestos

B0CC - R0006 - Kiln Room

No Asbestos

B0CC - R0007 - Toilets - Boys

No Asbestos

B0CC - R0008 - Practical Activities - 1hb

No Asbestos

B0CC - R0009 - Home Base Store

No Asbestos

B0CC - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0011 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0013 - Practical Activities - 1hb

No Asbestos

B0CC - R0014 - Home Base Store

No Asbestos

B0CC - R0015 - External Movement

No Asbestos

B0CC - R0016 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B0CC - R0017 - Home Base Store

No Asbestos

B0CC - R0018 - Practical Activities - 1hb

No Asbestos

B0CC - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0020 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0021 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R0022 - Practical Activities - 1hb						
No Asbestos						
B0CC - R0023 - Home Base Store						
No Asbestos						
B0CC - R0024 - External Movement						
No Asbestos						
B0CC - R0025 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0CC - R0026 - Home Base Store						
No Asbestos						
B0CC - R0027 - Practical Activities - 1hb						
No Asbestos						
B0CC - R0028 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R0029 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R0030 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0DD - Library/General Learning - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0DD - R0001 - External Movement

No Asbestos

B0DD - R0002 - Practical Activities - 1hb

No Asbestos

B0DD - R0003 - Home Base Store

No Asbestos

B0DD - R0004 - Movement

No Asbestos

B0DD - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0006 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0008 - Practical Activities - 1hb

No Asbestos

B0DD - R0009 - Home Base Store

No Asbestos

B0DD - R0010 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B0DD - R0011 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0012 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0013 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0014 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0EE - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0EE - R0001 - External Movement

No Asbestos

B0EE - R0002 - Practical Activities - 1hb

No Asbestos

B0EE - R0003 - Home Base Store

No Asbestos

B0EE - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0007 - Practical Activities - 1hb

No Asbestos

B0EE - R0008 - Home Base Store

No Asbestos

B0EE - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0010 - Home Base Store

No Asbestos

B0EE - R0011 - Practical Activities - 1hb

No Asbestos

B0EE - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0013 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0015 - Practical Activities - 1hb

No Asbestos

B0EE - R0016 - Home Base Store

No Asbestos

B0EE - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0018 - Toilets - Boys

No Asbestos

B0EE - R0019 - Access Shower/Toilet

No Asbestos

B0EE - R0020 - Toilets - Girls

No Asbestos

B0EE - R0021 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B0EE - R0022 - Practical Activities - 1hb

No Asbestos

B0EE - R0023 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0024 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0025 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0026 - Practical Activities - 1hb

No Asbestos

B0EE - R0027 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0FF - Special Purpose - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0FF - R0001 - Cleaning Distributed Store

No Asbestos

B0FF - R0002 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0003 - Toilets - Boys/Girls

No Asbestos

B0FF - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0GG - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0GG - R0001 - External Movement

No Asbestos

B0GG - R0002 - Practical Activities - 1hb

No Asbestos

B0GG - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0HH - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0HH - R0001 - External Movement

No Asbestos

B0HH - R0002 - Toilets - Girls

No Asbestos

B0HH - R0003 - Toilets - Boys

No Asbestos

B0HH - R0004 - Practical Activities

No Asbestos

B0HH - R0005 - Home Base Store

No Asbestos

B0HH - R0006 - Home Base

No Asbestos

B0HH - R0007 - Withdrawal Space - 2hb

No Asbestos

B0HH - R0008 - Home Base

No Asbestos

B0HH - R0009 - Home Base Store

No Asbestos

B0HH - R0010 - Practical Activities

No Asbestos

B0HH - R0011 - Practical Activities

No Asbestos

B0HH - R0012 - Home Base Store

No Asbestos

B0HH - R0013 - Home Base

No Asbestos

B0HH - R0014 - Withdrawal Space - 2hb

No Asbestos

B0HH - R0015 - Home Base

No Asbestos

B0HH - R0016 - Home Base Store

No Asbestos

B0HH - R0017 - Practical Activities

No Asbestos

B0HH - R0018 - Practical Activities

No Asbestos

B0HH - R0019 - Home Base

No Asbestos

B0HH - R0020 - Home Base Store

No Asbestos

B0HH - R0021 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10249 - Learning Unit - Standard With P.A.A. : Placement Date - 28/11/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10266 - Learning Unit - Standard With P.A.A. : Placement Date - 17/01/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D12210 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 6/08/2003

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12379 - Learning Unit - Standard With P.A.A. : Placement Date - 13/03/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 840 - D12503 - Girls Toilet : Placement Date - 5/07/2008

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

OS 602 - D13323 - Learning Unit - Standard With P.A.A. : Placement Date - 10/04/2006

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

OS 841 - D13806 - Boys Toilet : Placement Date - 5/07/2008

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Boys

No Asbestos Found.

OS 602 - D13860 - Learning Unit - Standard With P.A.A. : Placement Date - 24/02/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 750 - D15133 - Learning Unit - ESL : Placement Date - 28/01/2004

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2

Interior

R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017