


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Uranquinty Public School (1499)
Region : Riverina
State Electorate : Wagga Wagga
Local Government Area : Wagga Wagga

Initial Survey : Noel Arnold & Associates : 01 - May - 2008
Reviewed By : Greencap-NAA : 02 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Library - 1900 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1499/B00D/Eaves Linings/S3					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - General Storeroom**

Floor Coverings Res/Textile	Adhesive					
	1499/B00A/R0007/Floor Coverings Res/Textile/S6					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)
	1499/B00A/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0002 - Home Base

Floor Coverings Res/Textile	Adhesive					
	1499/B00A/R0007/Floor Coverings Res/Textile/S6					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)
	1499/B00A/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0003 - Reading Area

Floor Coverings Res/Textile	Adhesive					
	1499/B00A/R0007/Floor Coverings Res/Textile/S6					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)
	1499/B00A/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0004 - Canteen

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Movement

Floor Coverings Res/Textile	Compressed AC Sheet					
	1499/B00A/R0006/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00A - R0007 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)
	1499/B00A/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	1499/B00A/R0007/Floor Coverings Res/Textile/S6					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00B - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Movement

Flooring	Compressed AC Sheet 1499/B00A/R0006/Floor Coverings Res/Textile/S1	No Asbestos Detected
----------	---	-----------------------------

B00B - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - Movement

Flooring	Compressed AC Sheet 1499/B00A/R0006/Floor Coverings Res/Textile/S1	No Asbestos Detected
----------	---	-----------------------------

B00B - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Movement

Flooring	Compressed AC Sheet 1499/B00A/R0006/Floor Coverings Res/Textile/S1	No Asbestos Detected
----------	---	-----------------------------

B00B - R0009 - Practical Activities - 1hb

No Asbestos

B00B - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Staff Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00C - R0001 - Toilets - Boys

No Asbestos

B00C - R0002 - Toilets - Girls

No Asbestos

B00C - R0003 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Special Purpose - 2005 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1499/B00D/Eaves Linings/S3					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					

Interior

B00E - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Home Base

No Asbestos

B00F - R0002 - Home Base/Practical Activities

No Asbestos

B00F - R0003 - Withdrawal Space - 1hb

No Asbestos

B00F - R0004 - Home Base Store

No Asbestos

B00F - R0005 - External Movement

No Asbestos

B00F - R0006 - Main Switch Board

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 2014 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Canteen

No Asbestos

B00G - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 503 - D13676 - Admin Lib Staff/Principal/Clerk/Store : Placement Date - 21/09/2000

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				24 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

R3 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R4 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R5 - Reading Area

Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
---------	---------------	------------------	--	--	--	-------

R6 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
---------	---------------	------------------	--	--	--	------

R7 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				27 m2
---------	---------------	------------------	--	--	--	-------

R8 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				6 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017