


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Uki Public School (3298)
Region : North Coast
State Electorate : Lismore
Local Government Area : Tweed

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Reviewed By : Grencap-NAA : 04 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1906 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height restricted, greater 4m					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Millboard 3298/B00A/Eaves Linings/S2	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - General Storeroom

No Asbestos

B00A - R0003 - Kiln Room

No Asbestos

B00A - R0004 - Home Base Store

No Asbestos

B00A - R0005 - Home Base

Wall Linings Internal	Flat AC Sheeting 3298/B00A/R0005/Wall Linings Internal/S1	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	------	------------	--------------------	---------	--

B00A - R0006 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 3298/B00A/R0005/Wall Linings Internal/S1	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	------	------------	--------------------	---------	--

B00A - R0007 - External Movement

No Asbestos

B00A - R0010 - Sports Store

Floor Coverings Res/Textile	Vinyl Tiles 3298/B00A/R0012/Floor Coverings Res/Textile/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3298/B00A/R0005/Wall Linings Internal/S1	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 3298/B00A/R0010/Floor Coverings Res/Textile/S12					No Asbestos Detected

B00A - R0011 - Drinking Facilities

No Asbestos

B00A - R0012 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3298/B00A/R0012/Floor Coverings Res/Textile/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3298/B00A/R0005/Wall Linings Internal/S1	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration - 1978 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Millboard	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00B/Eaves Linings/S10					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting					
	3298/B00B/Gable Verge Lining/S11					No Asbestos Detected

Interior**B00B - R0001 - Staff Room**

Ceiling Structures/Linings	Millboard	15m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00B/Eaves Linings/S10					Chrysotile (white asbestos)

B00B - R0009 - General Assistant/Bulk Store

No Asbestos

B00B - R0010 - External Movement

Ceiling Structures/Linings	Millboard	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00B/Eaves Linings/S10					Chrysotile (white asbestos)

B00B - R0011 - Duplicating Workroom

No Asbestos

B00B - R0012 - Sick Bay

No Asbestos

B00B - R0013 - Clerical Office

Ceiling Structures/Linings	Millboard	6m2	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00B/Eaves Linings/S10					Chrysotile (white asbestos)

B00B - R0014 - Security Store

No Asbestos

B00B - R0015 - Deputy Principal

No Asbestos

B00B - R0016 - Staff Toilet

No Asbestos

B00B - R0017 - Staff Toilet

No Asbestos

B00B - R0018 - General Storeroom

No Asbestos

B00B - R0019 - Principal

No Asbestos

B00B - R0020 - Interview

No Asbestos

B00B - R0021 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1991 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	3298/B00C/Eaves Linings/S5					No Asbestos Detected

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Toilets - Boys

No Asbestos

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Home Base Store

No Asbestos

B00C - R0005 - Withdrawal Space - 1hb

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Practical Activities - 1hb

No Asbestos

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Withdrawal Space - 1hb

No Asbestos

B00C - R0011 - General Storeroom

Wall Linings Internal	Flat AC Sheeting					
	3298/B00C/R0012/Wall Linings Internal/S4					No Asbestos Detected

B00C - R0012 - Distribution Board Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting					
	3298/B00C/R0012/Wall Linings Internal/S4					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1970 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - no manhole					
Eaves Linings	Millboard	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/Eaves Linings/S7					Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting	12m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/Gable Ends/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
Downpipes	Fibre Cement Pipe	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/Downpipes/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00D - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Millboard	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0002 - Shower/Change

Ceiling Structures/Linings	Millboard	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0003 - Shower/Change

Ceiling Structures/Linings	Millboard	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0004 - Toilets - Girls

Ceiling Structures/Linings	Millboard	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0005 - Cleaning Distributed Store

Ceiling Structures/Linings	Millboard	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3298/B00D/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 3298/B00C/Eaves Linings/S5					No Asbestos Detected

Interior

B00E - R0001 - External Movement	No Asbestos					
B00E - R0002 - Toilets - Girls	No Asbestos					
B00E - R0003 - Practical Activities - 1hb	No Asbestos					
B00E - R0004 - Home Base Store	No Asbestos					
B00E - R0005 - Withdrawal Space - 1hb	No Asbestos					
B00E - R0006 - Home Base	No Asbestos					
B00E - R0007 - Practical Activities - 1hb	No Asbestos					
B00E - R0008 - Home Base	No Asbestos					
B00E - R0009 - Home Base Store	No Asbestos					
B00E - R0010 - Withdrawal Space - 1hb	No Asbestos					
B00E - R0011 - General Storeroom	No Asbestos					
B00E - R0012 - Distribution Board	No Asbestos					Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00G - R0003 - Practical Activities - 1hb**

No Asbestos

B00G - R0004 - Home Base Store

No Asbestos

B00G - R0005 - Withdrawal Space - 1hb

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Withdrawal Space - 1hb

No Asbestos

B00G - R0009 - Home Base Store

No Asbestos

B00G - R0010 - Practical Activities - 1hb

No Asbestos

B00G - R0011 - Practical Activities - 1hb

No Asbestos

B00G - R0012 - Home Base Store

No Asbestos

B00G - R0013 - Withdrawal Space - 1hb

No Asbestos

B00G - R0014 - Home Base

No Asbestos

B00G - R0015 - Home Base

No Asbestos

B00G - R0016 - Withdrawal Space - 1hb

No Asbestos

B00G - R0017 - Home Base Store

No Asbestos

B00G - R0018 - Practical Activities - 1hb

No Asbestos

B00G - R0019 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0020 - External Movement

No Asbestos

B00G - R0021 - Disabled Shower/Toilet

No Asbestos

B00G - R0022 - Toilets - Girls

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Special Purpose/General Learning - 2006 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B00H - R0001 - Special Programs Store

No Asbestos

B00H - R0002 - Special Programs Room - Type 1

No Asbestos

B00H - R0003 - External Movement

No Asbestos

B00H - R0004 - Special Programs Room - Type 1

No Asbestos

B00H - R0005 - Special Programs Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Reading Area

No Asbestos

B00I - R0003 - Communications Room

No Asbestos

B00I - R0004 - K.L.A. Store

No Asbestos

B00I - R0005 - Library Office/Workroom

No Asbestos

B00I - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 801 - D12276 - FSU : Placement Date - 6/03/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		8.64 m2

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		45 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017