


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ultimo Public School (3305)
Region : Sydney
State Electorate : Balmain
Local Government Area : Sydney

Initial Survey : Noel Arnold & Associates : 05 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00A - R0017 - Home Base

No Asbestos

B00A - R0018 - Home Base Store

No Asbestos

B00A - R0019 - Disabled Toilet

No Asbestos

B00A - R0020 - Toilets - Boys/Girls

No Asbestos

B00A - R0021 - Stairs

No Asbestos

B00A - R0022 - Movement

No Asbestos

B00A - R0023 - Home Base Store

No Asbestos

B00A - R0024 - Practical Activities - 1hb

No Asbestos

B00A - R0025 - Withdrawal Space - 1hb

No Asbestos

B00A - R0026 - Home Base

No Asbestos

B00A - R0027 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0028 - Home Base

No Asbestos

B00A - R0029 - Stairs

No Asbestos

B00A - R0030 - Practical Activities - 1hb

No Asbestos

B00A - R0031 - Home Base Store

No Asbestos

B00A - R0032 - General Assistant/Bulk Store

No Asbestos

B00A - R0033 - Movement

No Asbestos

B00A - R0034 - General Assistant/Bulk Store

No Asbestos

B00A - R0035 - Stairs

No Asbestos

B00A - R0036 - Cleaning Distributed Store

No Asbestos

B00A - R0037 - Special Programs Store

No Asbestos

B00A - R0038 - Special Programs Room

No Asbestos

B00A - R0039 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00A - R0040 - Plant					
	No Asbestos					
	B00A - R0041 - Lift					
	No Asbestos					
	B00A - R0042 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R0043 - Home Base Store					
	No Asbestos					
	B00A - R0044 - Home Base					
	No Asbestos					
	B00A - R0045 - Withdrawal Space - 1hb					
	No Asbestos					
	B00A - R0046 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R1025 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R1026 - Withdrawal Space - 2hb					
	No Asbestos					
	B00A - R1027 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R1028 - Home Base					
	No Asbestos					
	B00A - R1029 - Movement					
	No Asbestos					
	B00A - R1030 - Home Base Store					
	No Asbestos					
	B00A - R1031 - Stairs					
	No Asbestos					
	B00A - R1032 - Movement					
	No Asbestos					
	B00A - R1033 - Stairs					
	No Asbestos					
	B00A - R1034 - Special Programs Room					
	No Asbestos					
	B00A - R1035 - Special Programs Store					
	No Asbestos					
	B00A - R1036 - Cleaning Distributed Store					
	No Asbestos					
	B00A - R1037 - Movement					
	No Asbestos					
	B00A - R1038 - Lift					
	No Asbestos					
	B00A - R1039 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R1040 - Home Base Store					
	No Asbestos					
	B00A - R1041 - Home Base					
	No Asbestos					
	B00A - R1042 - Withdrawal Space - 2hb					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1043 - Home Base						
No Asbestos						
B00A - R1044 - Practical Activities - 1hb						
No Asbestos						
B00A - R1045 - Home Base Store						
No Asbestos						
B00A - R1046 - Staff Toilet						
No Asbestos						
B00A - R1047 - Staff Toilet						
No Asbestos						
B00A - R1048 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R1049 - Home Base Store						
No Asbestos						
B00A - R1050 - Home Base						
No Asbestos						
B00A - R1051 - Stairs						
No Asbestos						
B00A - R2019 - Movement						
No Asbestos						
B00A - R2020 - Staff Toilet						
No Asbestos						
B00A - R2021 - Staff Toilet						
No Asbestos						
B00A - R2022 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R2023 - Home Base						
No Asbestos						
B00A - R2024 - Home Base Store						
No Asbestos						
B00A - R2025 - Practical Activities - 1hb						
No Asbestos						
B00A - R2026 - Withdrawal Space - 2hb						
No Asbestos						
B00A - R2027 - Practical Activities - 1hb						
No Asbestos						
B00A - R2028 - Home Base						
No Asbestos						
B00A - R2029 - Movement						
No Asbestos						
B00A - R2030 - Home Base Store						
No Asbestos						
B00A - R2031 - Stairs						
No Asbestos						
B00A - R2032 - Stairs						
No Asbestos						
B00A - R2033 - Special Programs Room						
No Asbestos						
B00A - R2034 - Special Programs Store						
No Asbestos						
B00A - R2035 - Communications Cupboard						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R2036 - Main Switch Board

No Asbestos

B00A - R2037 - Lift

No Asbestos

B00A - R2038 - Home Base Store

No Asbestos

B00A - R2039 - Practical Activities - 1hb

No Asbestos

B00A - R2040 - Home Base

No Asbestos

B00A - R2041 - Withdrawal Space - 2hb

No Asbestos

B00A - R2042 - Practical Activities - 1hb

No Asbestos

B00A - R2043 - Home Base

No Asbestos

B00A - R2044 - Home Base Store

No Asbestos

B00A - R3001 - Lift

No Asbestos

B00A - R3002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/Library - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Canteen Office/Store

No Asbestos

B00D - R0002 - Cleaning Distributed Store

No Asbestos

B00D - R0003 - Canteen

No Asbestos

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Communal Space

No Asbestos

B00D - R0006 - Raised Platform

No Asbestos

B00D - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0008 - Communications Room

No Asbestos

B00D - R0009 - General Assistant/Bulk Store

No Asbestos

B00D - R0010 - P.E. Store

No Asbestos

B00D - R0011 - Hall Chair Store

No Asbestos

B00D - R0012 - Communal/Performance Store

No Asbestos

B00D - R0013 - General Assistant/Bulk Store

No Asbestos

B00D - R0014 - Movement

No Asbestos

B00D - R0015 - Plant

No Asbestos

B00D - R0016 - External Movement

No Asbestos

B00D - R0017 - Plant

No Asbestos

B00D - R0018 - Stairs

No Asbestos

B00D - R0019 - External Movement

No Asbestos

B00D - R1001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R1002 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R1003 - Communications Room

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1004 - K.L.A. Store						
No Asbestos						
B00D - R1005 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1006 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1007 - Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1008 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1009 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1010 - External Movement						
No Asbestos						
B00D - R1011 - Duplicating Workroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1012 - Sick Bay						
No Asbestos						
B00D - R1013 - Deputy Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1014 - Deputy Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1015 - Staff Toilet						
No Asbestos						
B00D - R1016 - Staff Toilet						
No Asbestos						
B00D - R1017 - Staff Toilet						
No Asbestos						
B00D - R1018 - Security Store						
No Asbestos						
B00D - R1019 - Cleaning Distributed Store						
No Asbestos						
B00D - R1020 - Disabled Toilet						
No Asbestos						
B00D - R1021 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1022 - Plant						
No Asbestos						
B00D - R1023 - Distribution Board						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1024 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R1025 - External Movement						

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R1026 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0CC - General Learning/Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0CC - R0001 - Home Base

No Asbestos

B0CC - R0002 - Practical Activities - 1hb

No Asbestos

B0CC - R0003 - Withdrawal Space - 1hb

No Asbestos

B0CC - R0004 - Home Base Store

No Asbestos

B0CC - R0005 - Toilets - Girls

No Asbestos

B0CC - R0006 - Toilets - Boys

No Asbestos

B0CC - R0007 - Garden Store

No Asbestos

B0CC - R0008 - General Assistant/Bulk Store

No Asbestos

B0CC - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D17725 - Learning Unit - Standard With P.A.A. : Placement Date - 22/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017