

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Urunga Public School (3318)
Region : North Coast
State Electorate : Oxley
Local Government Area : Bellingen

Initial Survey : Noel Arnold & Associates : 03 - May - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Administration/General Learning - 1954 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction. Space partially visible, no asbestos identified, no safe access due to height (3.2m)					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 3318/B001/Eaves Linings/S11	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Covering	Compressed AC Sheet 3318/B001/Floor Covering/S13					No Asbestos Detected

Interior

B001 - R0001 - Security Store

No Asbestos

B001 - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/Eaves Linings/S11	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	------	------------	--------------------	---------	---

B001 - R0005 - Cleaning Supplies

No Asbestos

B001 - R0006 - Disabled Toilet

Wall Linings Internal	Compressed AC Sheet 3318/B001/R0014/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B001 - R0007 - Sick Bay

No Asbestos

B001 - R0010 - Duplicating Workroom

Wall Linings Internal	Compressed AC Sheet 3318/B001/R0014/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/R0012/Ceiling Structures/Linings/S9	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0011 - Practical Activities - 1hb

Wall Linings Internal	Compressed AC Sheet 3318/B001/R0014/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/R0012/Ceiling Structures/Linings/S9	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0012 - Home Base

Wall Linings Internal	Compressed AC Sheet 3318/B001/R0018/Wall Linings Internal/S2	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/R0012/Ceiling Structures/Linings/S9	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0013 - Staff Room

Wall Linings Internal	Compressed AC Sheet 3318/B001/R0018/Wall Linings Internal/S2	70m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos)
-----------------------	---	------	------------	----------------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0012/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0014 - Practical Activities - 1hb						
Wall Linings Internal	Compressed AC Sheet					No Asbestos Detected
	3318/B001/R0014/Wall Linings Internal/S3					
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0012/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0015 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/Eaves Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0018 - Home Base						
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3318/B001/R0019/Floor Coverings Res/Textile/S7					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0019/Floor Coverings Res/Textile/S6			Chrysotile (white asbestos)		
B001 - R0019 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0019/Floor Coverings Res/Textile/S6			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3318/B001/R0019/Floor Coverings Res/Textile/S7					
B001 - R0022 - Deputy Principal						
No Asbestos						
B001 - R0026 - General Storeroom						
Wall Linings Internal	Compressed AC Sheet					No Asbestos Detected
	3318/B001/R0014/Wall Linings Internal/S3					
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3318/B001/R0019/Floor Coverings Res/Textile/S7					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0019/Floor Coverings Res/Textile/S6			Chrysotile (white asbestos)		
B001 - R0027 - Withdrawal Space - 1hb						
Wall Linings Internal	Compressed AC Sheet					No Asbestos Detected
	3318/B001/R0014/Wall Linings Internal/S3					
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3318/B001/R0019/Floor Coverings Res/Textile/S7					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B001/R0019/Floor Coverings Res/Textile/S6			Chrysotile (white asbestos)		
B001 - R0028 - Movement						
No Asbestos						
B001 - R0029 - Principal						
No Asbestos						
B001 - R0032 - External Movement						
No Asbestos						
B001 - R0033 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Wall Linings Internal	Compressed AC Sheet 3318/B001/R0014/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/R0012/Ceiling Structures/Linings/S9	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B001 - R0034 - Interview						
Ceiling Structures/Linings	Flat AC Sheeting 3318/B001/R0012/Ceiling Structures/Linings/S9	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B001 - R0035 - Toilets-Unisex						
Wall Linings Internal	Flat AC Sheeting 3318/B001/R0035/Wall Linings Internal/S12					No Asbestos Detected
B001 - R0036 - Toilet - Lobby						
No Asbestos						
B001 - R0037 - Toilet - Lobby						
No Asbestos						
B001 - R0038 - Toilets - Girls						
No Asbestos						
B001 - R0039 - Toilet - Lobby						
No Asbestos						
B001 - R0040 - Toilets-Unisex						
No Asbestos						
B001 - R0041 - Interview/Office - Type 3						
No Asbestos						
B001 - R0042 - Clerical Office						
Floor Coverings Res/Textile	Adhesive 3318/B001/R0019/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3318/B001/R0019/Floor Coverings Res/Textile/S6	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0043 - Distribution Board						
Note: No inspection of live electrical installation.						
Infill Panel	Flat AC Sheeting 3318/B001/R0043/Infill Panel/S8	1m2	Variable positions	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0044 - Entry Vestibule						
Floor Coverings Res/Textile	Adhesive 3318/B001/R0019/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3318/B001/R0019/Floor Coverings Res/Textile/S6	14m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R9001 - Canteen						
Wall Linings Internal	Compressed AC Sheet 3318/B001/R9001/Wall Linings Internal/S4					No Asbestos Detected
B001 - R9003 - External Movement						
No Asbestos						
B001 - R9005 - Special Programs Room						
Wall Linings Internal	Compressed AC Sheet 3318/B001/R9001/Wall Linings Internal/S4					No Asbestos Detected
B001 - R9006 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B002 - Library - 1982 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Wall Cladding	Flat AC Sheeting 3318/B002/Wall Cladding/S10					No Asbestos Detected
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B002 - R0001 - External Movement

No Asbestos

B002 - R0002 - Library Office/Workroom

No Asbestos

B002 - R0003 - Reading Area

In-fill-panel	Compressed AC Sheet	3m	Lower Door Panels	Good Condition (1)	Low (1)	Low Priority (2-3)
	3318/B002/R0003/In-fill-panel/S1					Chrysotile (white asbestos)

B002 - R0004 - External Movement

No Asbestos

B002 - R0005 - Communications Room

No Asbestos

B002 - R0006 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B002 - R0007 - Cleaning Supplies

Wall Linings Internal	Flat AC Sheeting 3318/B002/R0007/Wall Linings Internal/S14					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B003 - General Learning - 1991 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Area inaccessible. Metal awning,

Interior**B003 - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B003 - R0004 - Kiln Room

Kiln	Encapsulated Insulation material within unit	1Unit	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
------	--	-------	-------	----------------------	---------	--------------------

Assumed Asbestos - Area inaccessible

B003 - R0005 - External Movement

No Asbestos

B003 - R0006 - Practical Activities - 1hb

No Asbestos

B003 - R0007 - Home Base

No Asbestos

B003 - R0008 - Home Base

No Asbestos

B003 - R0009 - Practical Activities - 1hb

No Asbestos

B003 - R0010 - Withdrawal Space - 1hb

No Asbestos

B003 - R0011 - Home Base Store

No Asbestos

B003 - R0012 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - Building Services - 1991 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B005 - R0003 - Sports Store

No Asbestos

B005 - R0004 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B006 - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B006 - R0001 - Home Base Store

No Asbestos

B006 - R0002 - Communications Room

No Asbestos

B006 - R0003 - Practical Activities - 1hb

No Asbestos

B006 - R0004 - Home Base

No Asbestos

B006 - R0005 - Withdrawal Space - 1hb

No Asbestos

B006 - R0006 - Practical Activities - 1hb

No Asbestos

B006 - R0007 - Home Base

No Asbestos

B006 - R0008 - Practical Activities - 1hb

No Asbestos

B006 - R0009 - Home Base

No Asbestos

B006 - R0010 - Home Base Store

No Asbestos

B006 - R0011 - Home Base Store

No Asbestos

B006 - R0012 - Practical Activities - 1hb

No Asbestos

B006 - R0013 - Home Base

No Asbestos

B006 - R0014 - Home Base Store

No Asbestos

B006 - R0015 - External Movement

No Asbestos

B006 - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B006 - R9001 - General Storeroom

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B007 - Communal Facilities - 2008 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B007 - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B008 - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B008 - R0001 - External Movement**

No Asbestos

B008 - R0002 - Practical Activities - 1hb

No Asbestos

B008 - R0003 - Home Base

No Asbestos

B008 - R0004 - Home Base Store

No Asbestos

B008 - R0005 - Withdrawal Space - 1hb

No Asbestos

B008 - R0006 - Main Switch Board

No Asbestos

B008 - R0007 - Practical Activities - 1hb

No Asbestos

B008 - R0008 - Home Base Store

No Asbestos

B008 - R0009 - Home Base

No Asbestos

B008 - R0010 - Withdrawal Space - 2hb

No Asbestos

B008 - R0011 - Home Base

No Asbestos

B008 - R0012 - Home Base Store

No Asbestos

B008 - R0013 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B009 - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B009 - R0001 - External Movement

No Asbestos

B009 - R0002 - Toilets - Boys

No Asbestos

B009 - R0003 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B010 - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B010 - R0001 - Sports Store

No Asbestos

B010 - R0002 - Movement

No Asbestos

B010 - R0003 - Raised Platform

No Asbestos

B010 - R0004 - Communal/Performance Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017