


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Upper Coopers Creek Public School (3760)
Region : North Coast
State Electorate : Ballina
Local Government Area : Byron

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Library - 1949 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Clerical Office

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Reading Area

No Asbestos

B00A - R0004 - General Storeroom

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1949 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Cleaning Distributed Store

No Asbestos

B00B - R0002 - Staff Toilet

No Asbestos

B00B - R0003 - Staff Shower/Change

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Toilets - Boys

No Asbestos

B00B - R0006 - Practical Activities - 1hb

No Asbestos

B00B - R0007 - Garden Store

No Asbestos

B00B - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1987 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Canteen Covered Area

No Asbestos

B00C - R0002 - Canteen Covered Area

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Practical Activities - 1hb

No Asbestos

B00D - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017