

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Ulladulla High School (8495)  
**Region :** Illawarra and South East  
**State Electorate :** South Coast  
**Local Government Area :** Shoalhaven

**Initial Survey :** Noel Arnold & Associates : 07 - May - 2008  
**Reviewed By :** Greencap-NAA : 26 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1974 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Ceiling Voids	No Asbestos Found					

**Interior****B00A - R0001 - Leading Teacher (12.32 m2)**

No Asbestos

**B00A - R0006 - Staff - Toilet (4.99 m2)**

No Asbestos

**B00A - R0007 - Cleaning Store - Distributed (1.71 m2)**

No Asbestos

**B00A - R0008 - Staff - Toilet (5.04 m2)**

No Asbestos

**B00A - R0010 - Principal Office (19.1 m2)**

No Asbestos

**B00A - R0016 - Distribution Board Cupboard (0.91 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting					
	8495/B00A/R0016/Ceiling Structures/Linings/S12					<b>No Asbestos Detected</b>

**B00A - R0026 - Movement (123.16 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	124m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0027 - Entry (26.34 m2)**

Wall Linings Internal	Compressed AC Sheet					
	8495/B00A/R0027/Wall Linings Internal/S11					<b>No Asbestos Detected</b>

**B00A - R0028 - Administration - Clerical (100.4 m2)**

No Asbestos

**B00A - R0029 - Administration - Executive (12.35 m2)**

No Asbestos

**B00A - R0030 - Secure Storeroom (12.46 m2)**

No Asbestos

**B00A - R0031 - Student Reception (46.06 m2)**

No Asbestos

**B00A - R0032 - Access Staff Shower/Toilet (5.08 m2)**

No Asbestos

**B00A - R0033 - Deputy Principal Office (13.65 m2)**

No Asbestos

**B00A - R0034 - Tea Room (3.55 m2)**

No Asbestos

**B00A - R0035 - Deputy Principal Office (13.25 m2)**

No Asbestos

**B00A - R0036 - Clinic - Boys (12.59 m2)**

No Asbestos

**B00A - R0037 - Clinic - Girls (12.96 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0038 - Principal Office (12.89 m2)</b>						
No Asbestos						
<b>B00A - R0039 - Principal Office (13.46 m2)</b>						
No Asbestos						
<b>B00A - R0040 - Movement (22.71 m2)</b>						
No Asbestos						
<b>B00A - R0041 - Interview/Office - Type 2 (10.26 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library - 1974 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00B - R0001 - Main Area (144.83 m2)**

No Asbestos

**B00B - R0008 - Staff - Toilet (4.1 m2)**

No Asbestos

**B00B - R0009 - Distribution Board Cupboard (0.49 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting					
	8495/B00A/R0016/Ceiling Structures/Linings/S12					<b>No Asbestos Detected</b>

**B00B - R0010 - Staff - Toilet (4.1 m2)**

No Asbestos

**B00B - R0011 - Cleaning Store - Distributed (0.92 m2)**

No Asbestos

**B00B - R0015 - Communication Space (15.97 m2)**

Wall Linings Internal	Compressed AC Sheet					
	8495/B00B/R0015/Wall Linings Internal/S13					<b>No Asbestos Detected</b>

**B00B - R0016 - Entry (15.95 m2)**

No Asbestos

**B00B - R0017 - Movement (19.47 m2)**

No Asbestos

**B00B - R0018 - Librarian (64.41 m2)**

No Asbestos

**B00B - R0019 - Staff Study (14.18 m2)**

No Asbestos

**B00B - R0020 - Audio Visual Workroom (13.88 m2)**

No Asbestos

**B00B - R0021 - Seminar (13.61 m2)**

No Asbestos

**B00B - R0022 - Seminar (13.96 m2)**

No Asbestos

**B00B - R0023 - Seminar (13.84 m2)**

No Asbestos

**B00B - R0024 - System Administrators Office (13.68 m2)**

No Asbestos

**B00B - R0025 - Main Area (244.82 m2)**

No Asbestos

**B00B - R0026 - Access Staff Shower/Toilet (8.13 m2)**

No Asbestos

**B00B - R0027 - Entry (31.62 m2)**

No Asbestos

**B00B - R0028 - Movement (51.5 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	51.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Technological & Applied Studies - 1974 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 8495/B00C/R1001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

**Interior****B00C - R0001 - Wood Technology L.S. (88.28 m2)**

No Asbestos

**B00C - R0002 - Wood Technology Bay (36.11 m2)**

No Asbestos

**B00C - R0003 - Dust Extraction Space (7.39 m2)**

No Asbestos

**B00C - R0004 - Wood Technology L.S. (94.51 m2)**

Floor Coverings Res/Textile	Vinyl Sheet 8495/B00C/R0004/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
-----------------------------	--	--	--	--	--	-----------------------------

**B00C - R0005 - Resource/Project Store (9.28 m2)**

No Asbestos

**B00C - R0006 - General Storeroom (2.39 m2)**

No Asbestos

**B00C - R0007 - Workshop Area (48.19 m2)**

No Asbestos

**B00C - R0008 - Welding Area (13.02 m2)**

No Asbestos

**B00C - R0009 - Metal Technology L.S. (91.53 m2)**

Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

**B00C - R0010 - Metal Technology Bay (37.67 m2)**

No Asbestos

**B00C - R0011 - Design L.S. (94.1 m2)**

Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

**B00C - R0012 - Materials Store (14.04 m2)**

No Asbestos

**B00C - R0013 - General Assistants (14.01 m2)**

No Asbestos

**B00C - R0014 - Staff Study (32.35 m2)**

Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8495/B00C/R0016/Floor Coverings Res/Textile/S19	32.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------------	--	---------	------------	--------------------	---------	--

**B00C - R0015 - Movement (15.44 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00C - R0016 - General Storeroom (9.21 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8495/B00C/R0016/Floor Coverings Res/Textile/S19	9.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00C - R0017 - Staff - Toilet (4.7 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 8495/B00A/R0006/Partition Walls (Cubicles)/S3	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00C - R0018 - Cleaning Store - Distributed (2.19 m2)</b>						
No Asbestos						
<b>B00C - R0019 - Staff - Toilet (4.72 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8495/B00C/R0011/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 8495/B00A/R0006/Partition Walls (Cubicles)/S3	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00C - R0020 - Main Switchroom (8.9 m2)</b>						
Electrical Backing Board	Resinous Board 8495/B00C/R0020/Electrical Backing Board/S20	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00C - R0021 - Movement (83.19 m2)</b>						
No Asbestos						
<b>B00C - R0022 - L.P.G. Store (0.93 m2)</b>						
No Asbestos						
<b>B00C - R0023 - Cleaning Supplies Store (8.39 m2)</b>						
No Asbestos						
<b>B00C - R0024 - Materials Store (32.02 m2)</b>						
No Asbestos						
<b>B00C - R0025 - Distribution Board Cupboard (0.8 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00C - R0027 - Stairs (9.34 m2)</b>						
No Asbestos						
<b>B00C - R0028 - Movement (13.02 m2)</b>						
No Asbestos						
<b>B00C - R0029 - Stairs (1.26 m2)</b>						
No Asbestos						
<b>B00C - R0030 - Movement (14.3 m2)</b>						
No Asbestos						
<b>B00C - R0031 - Stairs (1.26 m2)</b>						
No Asbestos						
<b>B00C - R0032 - Resource/Project Store (3.61 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0033 - Movement (61.91 m2)</b>						
No Asbestos						
<b>B00C - R1001 - Design L.S. (57.31 m2)</b>						
No Asbestos						
<b>B00C - R1002 - Design L.S. (56.75 m2)</b>						
No Asbestos						
<b>B00C - R1003 - Resource/Project Store (26.07 m2)</b>						
No Asbestos						
<b>B00C - R1004 - Food Technology L.S. (104.27 m2)</b>						
No Asbestos						
<b>B00C - R1005 - Food/Research Space (16.58 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8495/B00C/R1001/Ceiling Structures/Linings/S4				<b>No Asbestos Detected</b>	
<b>B00C - R1006 - Design L.S. (65.21 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1007 - Materials Store (4.8 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1008 - Laundry (16.14 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1009 - Pantry (4.69 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	4.69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1010 - Food/Research Space (10.78 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1011 - Food/Research Space (11 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1012 - Food Technology L.S. (99.74 m2)</b>						
No Asbestos						
<b>B00C - R1013 - Distribution Board Cupboard (0.84 m2)</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R1014 - Design L.S. (64.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	64.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1015 - Resource/Project Store (9.06 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	9.06m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1016 - Cleaning Store - Distributed (0.54 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00C - R1017 - Resource/Project Store (4.7 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	4.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0023/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1018 - Movement (51.45 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1019 - Interview/Office - Type 1 (12.93 m2)</b>						
No Asbestos						
<b>B00C - R1020 - Staff Study (28.8 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8495/B00C/R1001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
<b>B00C - R1021 - Distribution Board Cupboard (0.97 m2)</b>						
				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00C - R1022 - Movement (53.36 m2)</b>						
No Asbestos						
<b>B00C - R1023 - Stairs (13.38 m2)</b>						
No Asbestos						
<b>B00C - R1024 - Movement (14.27 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8495/B00C/R1001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
<b>B00C - R1025 - Movement (14.91 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Computer Learning - 1974 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

**Interior****B00E - R0001 - Toilets-Girls (10.32 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0002 - Distribution Board Cupboard (0.74 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0003 - Cleaning Store - Distributed (0.65 m2)**

No Asbestos

**B00E - R0004 - Toilets-Boys (12.28 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0005 - Movement (19.19 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0006 - Computer Learning Space (52.48 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00E/R0008/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

**B00E - R0007 - Computer Learning Space (52.48 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00E/R0008/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

**B00E - R0008 - General Learning Space (51.97 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00E/R0006/Ceiling Structures/Linings/S9					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00E/R0008/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

**B00E - R0010 - Stairs (17.72 m2)**

No Asbestos

**B00E - R0011 - Toilets-Girls (34.01 m2)**

Ceiling Structures/Linings No Asbestos Found

**B00E - R0012 - Archive Store (23.71 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Ceiling lined with gyprock / suspect vermiculite above					
	8495/B00E/R0006/Ceiling Structures/Linings/S9				<b>No Asbestos Detected</b>	
<b>B00E - R0013 - Movement (71.12 m2)</b>						
No Asbestos						
<b>B00E - R1002 - General Learning Space (52.55 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00E/R1002/Floor Coverings Res/Textile/S10				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1003 - General Learning Space (52.63 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1004 - General Learning Space (52.11 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1005 - Movement (52 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1006 - Stairs (17.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1007 - Store (19.05 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1008 - General Learning Space - Type 1 (61.61 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	61.61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00E - Room+1 - R1006</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Science Learning - 1974 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - Laboratory L.S. (89.94 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>
Heat-proof Mat	Compressed AC Sheet					<b>No Asbestos Detected</b>
	8495/B00F/R0003/Heat-proof Mat/S15					

**B00F - R0002 - Preparation (49.22 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0003 - Laboratory L.S. (90.95 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>
Heat-proof Mat	Compressed AC Sheet					<b>No Asbestos Detected</b>
	8495/B00F/R0003/Heat-proof Mat/S15					

**B00F - R0004 - Movement (9.21 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0005 - Distribution Board Cupboard (0.78 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0006 - Growing/Breeding (25.53 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R0007 - Apparatus Store (27.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite				<b>Limited Samples Taken</b>	
8495/B00F/R0001/Ceiling Structures/Linings/S6					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R0009 - Stairs (4.59 m2)</b>						
No Asbestos						
<b>B00F - R0010 - Stairs (4.58 m2)</b>						
No Asbestos						
<b>B00F - R0012 - Movement (101.63 m2)</b>						
No Asbestos						
<b>B00F - R1001 - Laboratory L.S. (90.03 m2)</b>						
No Asbestos						
<b>B00F - R1002 - Preparation (49.27 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles				<b>No Asbestos Detected</b>	
8495/B00F/R1002/Floor Coverings Res/Textile/S8						
<b>B00F - R1003 - Laboratory L.S. (91.14 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	91.14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0023/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1004 - Staff Study (39.46 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1005 - Movement (9.24 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	9.24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1006 - Distribution Board Cupboard (0.76 m2)</b>						
Note: No inspection of live electrical installation.						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00F/R0001/Floor Coverings Res/Textile/S7					<b>Chrysotile (white asbestos)</b>	
Electrical Backing Board	Resinous Board	.350m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00F/R1006/Electrical Backing Board/S16					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1007 - Cleaning Store - Distributed (0.45 m2)</b>						
No Asbestos						
<b>B00F - R1008 - Staff - Toilet (4.25 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0006/Partition Walls (Cubicles)/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1009 - Staff - Toilet (4.25 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0006/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	
<b>B00F - R1011 - Stairs (9.16 m2)</b>						
No Asbestos						
<b>B00F - R1012 - Stairs (4.59 m2)</b>						
No Asbestos						
<b>B00F - R1013 - Movement (96.63 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	96.63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1974 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Distribution Board Cupboard (0.93 m2)** Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0008 - General Learning Space (50.54 m2)**

Ceiling Structures/Linings	Vermiculite 8495/B00F/R0001/Ceiling Structures/Linings/S6	<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

**B00G - R0009 - Movement (62.21 m2)**

No Asbestos

**B00G - R0010 - Stairs (16.71 m2)**

No Asbestos

**B00G - R0011 - Stairs (16.62 m2)**

No Asbestos

**B00G - R0012 - Senior Study (75.56 m2)**

No Asbestos

**B00G - R0013 - Movement (6.32 m2)**

No Asbestos

**B00G - R0014 - Careers Advisers Office (16.58 m2)**

No Asbestos

**B00G - R0015 - Computer Resource (65.99 m2)**

No Asbestos

**B00G - R0016 - Computer Store (12.13 m2)**

No Asbestos

**B00G - R0017 - Seminar (13.03 m2)**

No Asbestos

**B00G - R0018 - Seminar (12.9 m2)**

No Asbestos

**B00G - R1001 - Staff - Toilet (3.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0006/Partition Walls (Cubicles)/S3				<b>Chrysotile (white asbestos)</b>	

**B00G - R1002 - Study Space (24.87 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	

**B00G - R1003 - General Learning Space (51.26 m2)**

Ceiling Structures/Linings	Vermiculite					
	8495/B00F/R0001/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	1m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R0001/Floor Coverings Res/Textile/S7				<b>Chrysotile (white asbestos)</b>	

**B00G - R1004 - General Learning Space (51.26 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00G - R1005 - General Learning Space (51.25 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00G - R1006 - General Learning Space (50.75 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00G - R1007 - Staff - Toilet (3.19 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0006/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	
<b>B00G - R1008 - Movement (51.83 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00G - R1009 - Stairs (16.71 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
8495/B00F/R0001/Ceiling Structures/Linings/S6					No Asbestos Detected	
<b>B00G - R1010 - Stairs (16.62 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
8495/B00F/R0001/Ceiling Structures/Linings/S6					No Asbestos Detected	
<b>B00G - R1011 - Seminar (12.49 m2)</b>						
No Asbestos						
<b>B00G - R1012 - Seminar (12.45 m2)</b>						
No Asbestos						
<b>B00G - Room+1 - R1009</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00G - Room+2 - R1010</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Art/Pupil Facilities - 1989 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground  
Non Accessible Area  
- Area inaccessible

Ceiling Voids - Raked Ceiling  
No Asbestos Found

**Interior****B00H - R0001 - Toilets-Girls (10.44 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10.44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00H - R0002 - Toilets-Boys (10.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10.54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00H - R0003 - Distribution Board Cupboard (0.9 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0004 - Resources Store (5.81 m2)**

No Asbestos

**B00H - R0007 - General Learning Space - Bd/Cd/Ed (59.1 m2)**

No Asbestos

**B00H - R0010 - General Learning Space - Bd/Cd/Ed (59.76 m2)**

No Asbestos

**B00H - R0011 - General Learning Space - Bd/Cd/Ed (58.93 m2)**

No Asbestos

**B00H - R0012 - Movement (84.6 m2)**

Lower infill panel South		3.m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	--	------	-------	--------------------	---------	--------------------

**B00H - R0013 - Kiln Space (9.61 m2)**

No Asbestos

**B00H - R0014 - Staff Study (20.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	20.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00H - R0015 - Staff Study (18.94 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	18.94m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00H - R0016 - Staff Kitchen (28.18 m2)**

No Asbestos

**B00H - R0017 - Laundry (23.76 m2)**

Wall Linings Internal	Compressed AC Sheet					
8495/B00H/R0017/Wall Linings Internal/S18					<b>No Asbestos Detected</b>	

**B00H - R0018 - No Access (6.37 m2)**

No Asbestos

**B00H - R0019 - Movement (42.22 m2)**

Lower infill panel South	Compressed AC Sheet					
8495/B00H/R0017/Wall Linings Internal/S18					<b>No Asbestos Detected</b>	

**B00H - R0020 - Access Student Shower/Toilet - Type 2 (9.15 m2)**

No Asbestos

**B00H - R0021 - Cleaning Store - Distributed (2.75 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00H - R0022 - Store (5.26 m2)**

No Asbestos

**B00H - R0023 - General Learning Space - Bd/Cd/Ed (60.23 m2)**

No Asbestos

**B00H - R0024 - Seminar - Type 1 (14.28 m2)**

No Asbestos

**B00H - R0025 - Store (7.29 m2)**

No Asbestos

**B00H - R0026 - External Movement (12.81 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Tiered Learning/Art - 1990 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00J - R0001 - Darkroom Space (31.34 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	31.34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0002 - Tiered Learning Area (65.9 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	65.9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0003 - Tiered Learning Store (2.94 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2.94m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0004 - Distribution Board Cupboard (1.14 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1.14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0005 - Sport Equipment Store (11.81 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	11.81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0006 - Plant (5.78 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5.78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00J - R0008 - Movement (48.53 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning/Pupil Facilities - 1990 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00K - R0001 - Toilets-Boys (12.99 m2)**

No Asbestos

**B00K - R0002 - Cleaning Store - Distributed (1.66 m2)**

No Asbestos

**B00K - R0003 - Toilets-Girls (10.65 m2)**

No Asbestos

**B00K - R0004 - Distribution Board Cupboard (1.71 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00K - R0005 - General Learning Space (51.42 m2)**

No Asbestos

**B00K - R0006 - General Learning Space (51.58 m2)**

No Asbestos

**B00K - R0007 - General Storeroom (21.47 m2)**

No Asbestos

**B00K - R0008 - General Learning Space (51.5 m2)**

No Asbestos

**B00K - R0011 - Movement (78.84 m2)**

No Asbestos

**B00K - R0012 - Stairs (17.05 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00K - R0013 - Staff Study (36.15 m2)**

No Asbestos

**B00K - R1001 - Careers Advisers Office (13.95 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	13.95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00K - R1002 - Interview/Office - Type 1 (12 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00K - R1003 - Distribution Board Cupboard (1.77 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00K - R1004 - General Learning Space (51.44 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	51.44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00K - R1005 - General Learning Space (51.35 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	51.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

**B00K - R1006 - Cleaning Store - Distributed (2.58 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00K - R1007 - General Storeroom (18.54 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	18.54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1009 - General Learning Space (58.33 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	58.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1011 - Movement (74.37 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	74.37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1012 - Stairs (17.05 m2)</b>						
No Asbestos						
<b>B00K - R1013 - Seminar (29.12 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	29.12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Music - 1990 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00L - R0003 - Staff - Toilet (5.66 m2)**

No Asbestos

**B00L - R0004 - Distribution Board Cupboard (1.57 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1.57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0005 - Movement (37.23 m2)**

No Asbestos

**B00L - R0006 - Practice/Seminar (28.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	28.54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0007 - Music Learning Space (57.5 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	57.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0010 - Music Store (18.3 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	18.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0011 - Movement (68.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	68.28m2	North East & South East	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0012 - Movement (17.1 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0013 - Disabled Toilet (7.82 m2)**

No Asbestos

**B00L - R0014 - Music Learning Space (53.86 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	53.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

**B00L - R0015 - Music Learning Space (53.69 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	53.69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8495/B00A/R0001/Ceiling Structures/Linings/S1						<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - General Learning - 1974 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior****B00M - R0001 - Laboratory L.S. (95 m2)**

No Asbestos

**B00M - R0005 - Distribution Board Cupboard (0.82 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00M - R0007 - Movement (50.83 m2)**

No Asbestos

**B00M - R0008 - Stairs (18.19 m2)**

No Asbestos

**B00M - R0009 - Stairs (16.62 m2)**

No Asbestos

**B00M - R0010 - Laboratory L.S. (91.38 m2)**

No Asbestos

**B00M - R0011 - Preparation (30.69 m2)**

No Asbestos

**B00M - R1003 - General Learning Space (55.01 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1004 - General Learning Space (47.08 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1005 - General Learning Space (55 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1006 - Cleaning Store - Distributed (1.83 m2)**

No Asbestos

**B00M - R1007 - Distribution Board Cupboard (0.77 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	77m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00F/R1006/Electrical Backing Board/S16					Chrysotile (white asbestos)

**B00M - R1008 - General Storeroom (16.96 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1009 - Movement (55.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1010 - Stairs (18.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1011 - Stairs (16.62 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

**B00M - R1012 - Staff Study (32.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8495/B00M/R1009/Ceiling Structures/Linings/S17	No Asbestos Detected
----------------------------	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Multi Purpose Facilities/Pupil Facilities - 1974 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					

**Interior****B00N - R0006 - Distribution Board Cupboard (1.27 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Electrical Mounting Board	Resinous Board	1Unit	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8495/B00C/R0020/Electrical Backing Board/S20					<b>Chrysotile (white asbestos)</b>

**B00N - R0011 - Staff - Toilet (4.79 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0006/Partition Walls (Cubicles)/S3					<b>Chrysotile (white asbestos)</b>

**B00N - R0012 - Toilets-Girls (8.96 m2)**

No Asbestos

**B00N - R0013 - Toilets-Boys (9.07 m2)**

No Asbestos

**B00N - R0023 - Store - Coolroom (4.85 m2)**

No Asbestos

**B00N - R0024 - Student Canteen (84.46 m2)**

No Asbestos

**B00N - R0025 - Store (7.12 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	7.12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0006/Partition Walls (Cubicles)/S3					<b>Chrysotile (white asbestos)</b>

**B00N - R0026 - Movement (5.77 m2)**

No Asbestos

**B00N - R0027 - Store (2.21 m2)**

No Asbestos

**B00N - R0028 - Student Change - Type 2 (40.93 m2)**

No Asbestos

**B00N - R0029 - Store (12.07 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	12.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0006/Partition Walls (Cubicles)/S3					<b>Chrysotile (white asbestos)</b>

**B00N - R0030 - Store (12.07 m2)**

No Asbestos

**B00N - R0031 - Stairs (7.82 m2)**

No Asbestos

**B00N - R0032 - Student Change - Type 2 (39.73 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00N - R0033 - Store (12.33 m2)</b>						
No Asbestos						
<b>B00N - R0034 - Movement Studio Store (38.08 m2)</b>						
No Asbestos						
<b>B00N - R0035 - Movement Studio (125.81 m2)</b>						
No Asbestos						
<b>B00N - R0036 - Movement (5.48 m2)</b>						
No Asbestos						
<b>B00N - R0037 - Control Room (9.66 m2)</b>						
No Asbestos						
<b>B00N - R0038 - Movement Studio (176.41 m2)</b>						
No Asbestos						
<b>B00N - R0039 - Movement Studio Store (6.54 m2)</b>						
No Asbestos						
<b>B00N - R0040 - External Movement (340.16 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	340.16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8495/B00A/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
Lower infill panels	Compressed AC Sheet					<b>No Asbestos Detected</b>
	8495/B00H/R0017/Wall Linings Internal/S18					
<b>B00N - Room+1 - R0020</b>						
Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	8495/B00M/R1009/Ceiling Structures/Linings/S17					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Agricultural Science - 1989 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00P - R0004 - General Learning Space (41.18 m2)**

No Asbestos

**B00P - R0005 - Toilets-Unisex (2.62 m2)**

No Asbestos

**B00P - R0006 - Machine Storage (38.44 m2)**

No Asbestos

**B00P - R0007 - Class Tools Storage (27.55 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00Q - General Learning/Staff Facilities - 2007 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00Q - R0001 - General Learning Space - Type 5 (59.49 m2)**

No Asbestos

**B00Q - R0002 - General Learning Space - Type 5 (59.47 m2)**

No Asbestos

**B00Q - R0003 - General Learning Space - Type 4 (59.47 m2)**

No Asbestos

**B00Q - R0004 - General Learning Space - Type 4 (63.54 m2)**

No Asbestos

**B00Q - R0005 - General Learning Space - Type 1 (59.39 m2)**

No Asbestos

**B00Q - R0006 - General Learning Space - Type 1 (59.71 m2)**

No Asbestos

**B00Q - R0007 - Practice/Seminar (20.54 m2)**

No Asbestos

**B00Q - R0008 - Performance Workshop (94.93 m2)**

No Asbestos

**B00Q - R0009 - Performance Store (15.13 m2)**

No Asbestos

**B00Q - R0010 - Practice/Seminar (8.7 m2)**

No Asbestos

**B00Q - R0011 - Visual Arts Workshop (104.17 m2)**

No Asbestos

**B00Q - R0012 - Visual Arts Store (18.49 m2)**

No Asbestos

**B00Q - R0013 - Visual Arts Store (18.55 m2)**

No Asbestos

**B00Q - R0014 - Multi Media Studio (24.5 m2)**

No Asbestos

**B00Q - R0015 - Project Store - Type 3 (24.5 m2)**

No Asbestos

**B00Q - R0016 - Visual Arts Workshop (99.95 m2)**

No Asbestos

**B00Q - R0017 - Kiln Space (12.33 m2)**

No Asbestos

**B00Q - R0018 - Pottery Store (13.03 m2)**

No Asbestos

**B00Q - R0019 - Cleaning Store - Distributed (3.63 m2)**

No Asbestos

**B00Q - R0020 - Distribution Board Cupboard (0.8 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00Q - R0021 - External Stairs (5.45 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00Q - R0022 - External Movement (106.96 m2)</b>					
	No Asbestos					
	<b>B00Q - R0023 - Movement (3.76 m2)</b>					
	No Asbestos					
	<b>B00Q - R0024 - Lift (1.89 m2)</b>					
	No Asbestos					
	<b>B00Q - R0025 - Stairs (14.47 m2)</b>					
	No Asbestos					
	<b>B00Q - R0026 - External Stairs (5.47 m2)</b>					
	No Asbestos					
	<b>B00Q - R0027 - External Movement (26.2 m2)</b>					
	No Asbestos					
	<b>B00Q - R0028 - External Movement (26.2 m2)</b>					
	No Asbestos					
	<b>B00Q - R0029 - External Movement (7.08 m2)</b>					
	No Asbestos					
	<b>B00Q - R0030 - External Movement (10.88 m2)</b>					
	No Asbestos					
	<b>B00Q - R0031 - External Movement (26.52 m2)</b>					
	No Asbestos					
	<b>B00Q - R0032 - External Movement (3.39 m2)</b>					
	No Asbestos					
	<b>B00Q - R1001 - Movement (102.67 m2)</b>					
	No Asbestos					
	<b>B00Q - R1002 - Store (24.35 m2)</b>					
	No Asbestos					
	<b>B00Q - R1003 - General Learning Space - Type 2 (63.41 m2)</b>					
	No Asbestos					
	<b>B00Q - R1004 - Seminar - Type 1 (28.92 m2)</b>					
	No Asbestos					
	<b>B00Q - R1005 - Shared Learning Space (77.49 m2)</b>					
	No Asbestos					
	<b>B00Q - R1006 - Cleaning Store - Distributed (3.58 m2)</b>					
	No Asbestos					
	<b>B00Q - R1007 - Distribution Board Cupboard (0.59 m2)</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00Q - R1008 - Practical Activity Area (8.67 m2)</b>					
	No Asbestos					
	<b>B00Q - R1009 - General Learning Space - Type 1 (58.57 m2)</b>					
	No Asbestos					
	<b>B00Q - R1010 - Seminar - Type 1 (30.33 m2)</b>					
	No Asbestos					
	<b>B00Q - R1011 - General Learning Space - Type 1 (58.67 m2)</b>					
	No Asbestos					
	<b>B00Q - R1012 - General Learning Space - Type 1 (58.91 m2)</b>					
	No Asbestos					
	<b>B00Q - R1013 - General Learning Space - Type 1 (58.82 m2)</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00Q - R1014 - General Learning Space - Type 2 (63.82 m2)</b>					
	No Asbestos					
	<b>B00Q - R1015 - General Learning Space - Type 1 (58.75 m2)</b>					
	No Asbestos					
	<b>B00Q - R1016 - General Learning Space - Type 1 (58.75 m2)</b>					
	No Asbestos					
	<b>B00Q - R1017 - General Learning Space - Type 1 (58.75 m2)</b>					
	No Asbestos					
	<b>B00Q - R1018 - Plant (11.14 m2)</b>					
	No Asbestos					
	<b>B00Q - R1019 - Plant (11.14 m2)</b>					
	No Asbestos					
	<b>B00Q - R1020 - External Stairs (14.34 m2)</b>					
	No Asbestos					
	<b>B00Q - R1021 - External Stairs (14.37 m2)</b>					
	No Asbestos					
	<b>B00Q - R1022 - Movement (12.32 m2)</b>					
	No Asbestos					
	<b>B00Q - R1023 - Stairs (16.36 m2)</b>					
	No Asbestos					
	<b>B00Q - R1024 - Movement (3.76 m2)</b>					
	No Asbestos					
	<b>B00Q - R1025 - Movement (3.89 m2)</b>					
	No Asbestos					
	<b>B00Q - R1026 - Movement (12.32 m2)</b>					
	No Asbestos					
	<b>B00Q - R1027 - External Movement (15.26 m2)</b>					
	No Asbestos					
	<b>B00Q - R2001 - Preparation/Printing (35.11 m2)</b>					
	No Asbestos					
	<b>B00Q - R2002 - Interview/Meeting (12.49 m2)</b>					
	No Asbestos					
	<b>B00Q - R2003 - Interview/Meeting (12.53 m2)</b>					
	No Asbestos					
	<b>B00Q - R2004 - Movement (66.36 m2)</b>					
	No Asbestos					
	<b>B00Q - R2005 - Cleaning Store - Distributed (3.61 m2)</b>					
	No Asbestos					
	<b>B00Q - R2006 - Distribution Board Cupboard (0.59 m2)</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00Q - R2007 - Interview/Meeting (12.42 m2)</b>					
	No Asbestos					
	<b>B00Q - R2008 - Interview/Meeting (12.36 m2)</b>					
	No Asbestos					
	<b>B00Q - R2009 - Staff - Toilet (5.34 m2)</b>					
	No Asbestos					
	<b>B00Q - R2010 - Staff - Toilet (5.36 m2)</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00Q - R2011 - Access Staff Shower/Toilet (5.11 m2)**

No Asbestos

**B00Q - R2012 - Staff - Toilet (5.33 m2)**

No Asbestos

**B00Q - R2013 - Staff - Toilet (5.39 m2)**

No Asbestos

**B00Q - R2014 - Staff - Toilet (5.33 m2)**

No Asbestos

**B00Q - R2015 - Staff Study (237.49 m2)**

No Asbestos

**B00Q - R2016 - Staff Lounge (119.73 m2)**

No Asbestos

**B00Q - R2017 - Staff Study (256.41 m2)**

No Asbestos

**B00Q - R2018 - Movement (21.13 m2)**

No Asbestos

**B00Q - R2019 - External Stairs (4.6 m2)**

No Asbestos

**B00Q - R2020 - External Stairs (4.61 m2)**

No Asbestos

**B00Q - R2021 - Movement (12.32 m2)**

No Asbestos

**B00Q - R2022 - Stairs (5.65 m2)**

No Asbestos

**B00Q - R2023 - Movement (3.76 m2)**

No Asbestos

**B00Q - R2024 - Movement (12.32 m2)**

No Asbestos

**B00Q - R2025 - External Movement (15.26 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00R - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
- Area inaccessible

Ceiling Voids - Flat Roof      Non Accessible Area  
- Area inaccessible

**Interior****B00R - R0001 - External Movement (6.5 m2)**

No Asbestos

**B00R - R0002 - Movement (4.89 m2)**

No Asbestos

**B00R - R0003 - Lift (2.23 m2)**

No Asbestos

**B00R - R0004 - External Movement (13.85 m2)**

No Asbestos

**B00R - R1001 - Movement (42.4 m2)**

No Asbestos

**B00R - R1002 - Movement (4.89 m2)**

No Asbestos

**B00R - R1003 - Movement (4.86 m2)**

No Asbestos

**B00R - R2001 - Movement (31.15 m2)**

No Asbestos

**B00R - R2002 - Movement (4.89 m2)**

No Asbestos

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B0RR - Multi Purpose Facilities/Physical Education - 2013 - Brick/Veneer (Brick/Veneer)

#### Exterior

Underfloor Voids - Slab on Ground      Non Accessible Area  
- Area inaccessible

#### Interior

##### B0RR - R0001 - External Movement (347.47 m2)

No Asbestos

##### B0RR - R0002 - Multi-Purpose Space (618.34 m2)

No Asbestos

##### B0RR - R0003 - Control Room (16.59 m2)

No Asbestos

##### B0RR - R0004 - No Access (0.93 m2)

No Asbestos

##### B0RR - R0005 - First Aid (22.36 m2)

No Asbestos

##### B0RR - R0006 - Ramp (14.04 m2)

No Asbestos

##### B0RR - R0007 - Store (26.56 m2)

No Asbestos

##### B0RR - R0008 - Chair Store (35.31 m2)

No Asbestos

##### B0RR - R0009 - Store (36.24 m2)

No Asbestos

##### B0RR - R0010 - Communications Cupboard (2.51 m2)

No Asbestos

##### B0RR - R0011 - Movement (16.57 m2)

No Asbestos

##### B0RR - R0012 - Movement (8.86 m2)

No Asbestos

##### B0RR - R0013 - External Movement (37.68 m2)

No Asbestos

##### B0RR - R0014 - Stage (120.76 m2)

No Asbestos

##### B0RR - R0015 - No Access (0.46 m2)

No Asbestos

##### B0RR - R0016 - Movement (12.24 m2)

No Asbestos

##### B0RR - R0017 - Lift (2.41 m2)

No Asbestos

##### B0RR - R0018 - No Access (2.79 m2)

No Asbestos

##### B0RR - R0019 - Movement (15.55 m2)

No Asbestos

##### B0RR - R0020 - External Movement (12.38 m2)

No Asbestos

##### B0RR - R0021 - Movement (77.77 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0RR - R0022 - Student Change - Type 2 (22.5 m2)</b>						
No Asbestos						
<b>B0RR - R0023 - Student Change - Type 2 (21.54 m2)</b>						
No Asbestos						
<b>B0RR - R0024 - Student Shower (17.22 m2)</b>						
No Asbestos						
<b>B0RR - R0025 - Student Change - Type 2 (21.93 m2)</b>						
No Asbestos						
<b>B0RR - R0026 - Student Change - Type 2 (21.16 m2)</b>						
No Asbestos						
<b>B0RR - R0027 - Student Shower (18.07 m2)</b>						
No Asbestos						
<b>B0RR - R0028 - Staff - Toilet (7.68 m2)</b>						
No Asbestos						
<b>B0RR - R0029 - Access Student Shower/Toilet - Type 2 (7.64 m2)</b>						
No Asbestos						
<b>B0RR - R0030 - Cleaning Store - Distributed (3.73 m2)</b>						
No Asbestos						
<b>B0RR - R0031 - Outdoor Equipment Store (18.8 m2)</b>						
No Asbestos						
<b>B0RR - R0032 - Toilets-Boys (25.04 m2)</b>						
No Asbestos						
<b>B0RR - R0033 - Toilets-Girls (41.53 m2)</b>						
No Asbestos						
<b>B0RR - R9001 - External Movement (40.68 m2)</b>						
No Asbestos						
<b>B0RR - R9002 - Outdoor Workshop (61.95 m2)</b>						
No Asbestos						
<b>B0RR - R9003 - No Access (9.24 m2)</b>						
No Asbestos						
<b>B0RR - R9004 - No Access (0.81 m2)</b>						
No Asbestos						
<b>B0RR - R9005 - Materials Technology L.S. (189.35 m2)</b>						
No Asbestos						
<b>B0RR - R9006 - Materials Store (68.27 m2)</b>						
No Asbestos						
<b>B0RR - R9007 - Bulk Store (16.41 m2)</b>						
No Asbestos						
<b>B0RR - R9008 - Store (12.05 m2)</b>						
No Asbestos						
<b>B0RR - R9009 - Uniform Shop (12.38 m2)</b>						
No Asbestos						
<b>B0RR - R9010 - Utility Space (0.83 m2)</b>						
No Asbestos						
<b>B0RR - R9011 - No Access (65.86 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**OS 601 - D12359 - Learning Unit - Standard/Withdrawal : Placement Date - 20/09/2016**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

**OS 601 - D12477 - Learning Unit - Standard/Withdrawal : Placement Date - 20/09/2016**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

**OS 600 - D13081 - Learning Unit - Small : Placement Date - 20/02/2003**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

### Interior

#### R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

**OS 971 - D80082 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Garden Store

No Asbestos Found.

**OS 971 - D80083 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Garden Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017