

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wooli Public School (2841)  
**Region :** North Coast  
**State Electorate :** Clarence  
**Local Government Area :** Clarence Valley

**Initial Survey :** Noel Arnold & Associates : 27 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - General Learning/Administration - 1942 - Timber (Timber)</b>						
<b>Exterior</b>						
Eaves Linings	Flat AC Sheeting 2841/B00D/Eaves Linings/S2					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					
<b>Interior</b>						
<b>B00A - R0002 - Personal Effects Storage</b>						
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0002/Wall Linings Internal/S5	3m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0003 - Entry Vestibule</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0004 - Staff Room</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	15m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0005 - General Storeroom</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	7m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0006 - Clerical Office</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0007 - General Storeroom</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	18m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles 2841/B00A/R0007/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00A - R0008 - Principal</b>						
Wall Linings Internal	Flat AC Sheeting 2841/B00A/R0007/Wall Linings Internal/S3	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2841/B00A/R0007/Wall Linings Internal/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0009 - Clerical Office</b>						
Wall Linings Internal	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2841/B00A/R0007/Wall Linings Internal/S3					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2841/B00A/R0007/Wall Linings Internal/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0010 - Staff Room Annexe</b>						
Wall Linings Internal	Flat AC Sheeting	25m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2841/B00A/R0007/Wall Linings Internal/S3					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2841/B00A/R0007/Wall Linings Internal/S3					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1971 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior****B00B - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0003 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0004 - Cleaning Distributed Store**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0005 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0006 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0007 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2841/B00B/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Shed - 1942 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1942 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting 2841/B00D/Eaves Linings/S2					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior****B00D - R0003 - Canteen**

Wall Linings Internal	Flat AC Sheeting 2841/B00D/R0003/Wall Linings Internal/S1					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00D - R0004 - General Assistant/Bulk Store**

No Asbestos

**B00D - R0005 - General Storeroom**

No Asbestos

**B00D - R0006 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2841/B00D/R0003/Wall Linings Internal/S1					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Administration - 1965 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - Staff Room**

No Asbestos

**B00E - R0003 - Staff Kitchen**

No Asbestos

**B00E - R0004 - General Storeroom**

No Asbestos

**B00E - R0005 - General Storeroom**

No Asbestos

**B00E - R0006 - Clerical Office**

No Asbestos

**B00E - R0007 - Clerical Office**

No Asbestos

**B00E - R0008 - Movement**

No Asbestos

**B00E - R0009 - Staff Toilet**

No Asbestos

**B00E - R0010 - Staff Shower/Change**

No Asbestos

**B00E - R0011 - General Storeroom**

No Asbestos

**B00E - R0012 - General Storeroom**

No Asbestos

**B00E - R0013 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Practical Activities - 1hb**

No Asbestos

**B00F - R0003 - Home Base Store**

No Asbestos

**B00F - R0004 - Home Base**

No Asbestos

**B00F - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0006 - Home Base**

No Asbestos

**B00F - R0007 - Home Base Store**

No Asbestos

**B00F - R0008 - Practical Activities - 1hb**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D12358 - Learning Unit - Standard With P.A.A. : Placement Date - 3/03/2015**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 531 - D12502 - Library : Placement Date - 22/04/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry/classroom**

No Asbestos Found.

**R2 - Reading Area/workroom**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

2841\_ASB\_010713\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017