

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** West Ryde Public School (3023)  
**Region :** Northern Sydney  
**State Electorate :** Ryde  
**Local Government Area :** Ryde

**Initial Survey :** Noel Arnold & Associates : 18 - Jan - 2008  
**Reviewed By :** Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1917 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 3023/B00A/Eaves Linings/S14	160m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
gable verge lining	Flat AC Sheeting 3023/B00A/gable verge lining/S15	60m	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Wall Cladding	Flat AC Sheeting 3023/B00A/Wall Cladding/S4					<b>No Asbestos Detected</b>
Ceiling Voids	Compressed AC Sheet 3023/B00A/Ceiling Voids/S16					<b>No Asbestos Detected</b>
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Compressed AC Sheet 3023/B00A/Ceiling Voids/S13	1m2	Variable positions	Minimal Damage (2)	Medium (2)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00A - R0002 - Staff Room (47.48 m2)**

No Asbestos

**B00A - R0003 - Security Store (6.85 m2)**

No Asbestos

**B00A - R0004 - Movement (5.23 m2)**

Wall Linings Internal	Flat AC Sheeting 3023/B00A/R0004/Wall Linings Internal/S10					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0005 - Staff Room Annexe (9.33 m2)**

Wall Linings Internal	Flat AC Sheeting 3023/B00A/R0004/Wall Linings Internal/S10					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0006 - Staff Room Annexe (14.08 m2)**

Wall Linings Internal	Flat AC Sheeting 3023/B00A/R0004/Wall Linings Internal/S10					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0007 - Security Store (9 m2)**

Wall Linings Internal	Flat AC Sheeting 3023/B00A/R0004/Wall Linings Internal/S10					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0008 - Staff Toilet (3.4 m2)**

Wall Linings Internal	Compressed AC Sheet 3023/B00A/R0008/Wall Linings Internal/S9					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0009 - Staff Toilet (3.4 m2)**

Wall Linings Internal	Compressed AC Sheet 3023/B00A/R0008/Wall Linings Internal/S9					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00A - R0011 - External Movement (2.79 m2)**

No Asbestos

**B00A - R0012 - Sick Bay (12.19 m2)**

No Asbestos

**B00A - R0013 - Movement (1.36 m2)**

No Asbestos

**B00A - R0014 - External Movement (3.79 m2)**

No Asbestos

**B00A - R0015 - Cleaning Distributed Store (4.88 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00A - R0016 - Entry Vestibule (9.73 m2)</b>						
No Asbestos						
<b>B00A - R0017 - Entry Vestibule (12.15 m2)</b>						
No Asbestos						
<b>B00A - R0018 - Clerical Office (12.55 m2)</b>						
No Asbestos						
<b>B00A - R0019 - Duplicating Workroom (18.15 m2)</b>						
No Asbestos						
<b>B00A - R0020 - Principal (25.3 m2)</b>						
No Asbestos						
<b>B00A - R0021 - Movement (9.88 m2)</b>						
No Asbestos						
<b>B00A - R0022 - External Movement (2.44 m2)</b>						
No Asbestos						
<b>B00A - R0023 - Movement (2.17 m2)</b>						
No Asbestos						
<b>B00A - R0024 - General Storeroom (4.91 m2)</b>						
No Asbestos						
<b>B00A - R0028 - Garden Store (4.99 m2)</b>						
Wall Linings Internal	Flat AC Sheeting 3023/B00A/Wall Cladding/S4					<b>No Asbestos Detected</b>
<b>B00A - R0029 - Toilets - Girls (61.54 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00A/R0029/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0030 - General Storeroom (39.85 m2)</b>						
Wall Linings Internal	Flat AC Sheeting 3023/B00A/Wall Cladding/S4					<b>No Asbestos Detected</b>
<b>B00A - R0031 - Toilets - Boys (61.54 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00A/R0029/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0032 - External Movement (33.77 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 3023/B00A/R0032/Ceiling Structures/Linings/S11					<b>No Asbestos Detected</b>
<b>B00A - R0033 - Security Store (6.44 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Reading Area (40.49 m2)</b>						
No Asbestos						
<b>B00A - R0039 - Movement (2.87 m2)</b>						
No Asbestos						
<b>B00A - R0040 - External Movement (14.08 m2)</b>						
No Asbestos						
<b>B00A - R0041 - Stairs (7.63 m2)</b>						
No Asbestos						
<b>B00A - R0042 - Stairs (7.65 m2)</b>						
No Asbestos						
<b>B00A - R0043 - Movement (24.52 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0044 - Library Office/Workroom (22.11 m2)</b>						
No Asbestos						
<b>B00A - R0045 - Reading Area (95.59 m2)</b>						
No Asbestos						
<b>B00A - R0046 - Cleaning Distributed Store (5 m2)</b>						
No Asbestos						
<b>B00A - R0047 - Movement (5.2 m2)</b>						
No Asbestos						
<b>B00A - R0048 - General Assistant/Bulk Store (12.46 m2)</b>						
No Asbestos						
<b>B00A - R0049 - K.L.A. Store (18.44 m2)</b>						
No Asbestos						
<b>B00A - R0050 - Reading Area (33.09 m2)</b>						
No Asbestos						
<b>B00A - R0051 - External Movement (26.88 m2)</b>						
Ceiling Structures/Linings No Asbestos Found						
<b>B00A - R0052 - Movement (73.15 m2)</b>						
No Asbestos						
<b>B00A - R0054 - General Storeroom (6.03 m2)</b>						
No Asbestos No Asbestos Found						
<b>B00A - R1001 - Home Base (49.78 m2)</b>						
No Asbestos						
<b>B00A - R1002 - Home Base (49.51 m2)</b>						
No Asbestos						
<b>B00A - R1003 - Home Base (50.19 m2)</b>						
No Asbestos						
<b>B00A - R1004 - Home Base (50.53 m2)</b>						
No Asbestos						
<b>B00A - R1005 - Home Base (50.12 m2)</b>						
No Asbestos						
<b>B00A - R1006 - Home Base (49.85 m2)</b>						
No Asbestos						
<b>B00A - R1007 - Interview (8.2 m2)</b>						
No Asbestos						
<b>B00A - R1008 - Movement (109.19 m2)</b>						
No Asbestos						
<b>B00A - R1009 - Movement (7.78 m2)</b>						
No Asbestos						
<b>B00A - R1010 - Special Programs Room (9.14 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00A/R1010/Floor Coverings Res/Textile/S5				<b>Chrysotile (white asbestos)</b>	
Ceiling Hatch cover	Compressed AC Sheet	1m2	Ceiling	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00A/R1010/Ceiling Hatch cover/S12				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1011 - Teachers Aide Special Ed (18.42 m2)</b>						
No Asbestos						
<b>B00A - R1012 - General Storeroom (8.37 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3023/B00A/R1010/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

**B00A - R1013 - Movement (9.26 m2)**

No Asbestos

**B00A - R1014 - Stairs (10.61 m2)**

No Asbestos

**B00A - R1015 - Stairs (11.74 m2)**

No Asbestos

**B00A - R9001 - General Storeroom (3.7 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1965 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	50m2	South Eastern	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	3023/B00B/Underfloor Voids/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior**

**B00B - R0001 - Home Base (47.24 m2)**

No Asbestos

**B00B - R0002 - Home Base (47.24 m2)**

No Asbestos

**B00B - R0003 - External Movement (25.44 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Communal Facilities - 1963 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	200m2	Throughout	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	3023/B00C/Underfloor Voids/S18			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Underfloor Voids	Packers on piers	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00C/Underfloor Voids/S19			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**Interior**

**B00C - M0001 - Plant (11.68 m2)**

No Asbestos

**B00C - M0002 - Hall Chair Store (11.17 m2)**

No Asbestos

**B00C - R0001 - Movement (1.51 m2)**

No Asbestos

**B00C - R0002 - Movement (6.76 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3023/B00C/R0002/Floor Coverings Res/Textile/S3			<b>No Asbestos Detected</b>		

**B00C - R0003 - Communal Space (207.93 m2)**

No Asbestos

**B00C - R0004 - Movement (6.76 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3023/B00C/R0002/Floor Coverings Res/Textile/S3			<b>No Asbestos Detected</b>		

**B00C - R0005 - Raised Platform (55.59 m2)**

No Asbestos

**B00C - R0006 - Staff Kitchen (11.17 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3023/B00C/R0002/Floor Coverings Res/Textile/S3			<b>No Asbestos Detected</b>		

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00C/R0012/Ceiling Structures/Linings/S2			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0007 - Movement (0.39 m2)**

No Asbestos

**B00C - R0008 - Movement (0.39 m2)**

No Asbestos

**B00C - R0009 - Uniform Shop (11.17 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00C/R0012/Ceiling Structures/Linings/S2			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0010 - Movement (1.51 m2)**

No Asbestos

**B00C - R0011 - Toilets - Boys/Girls (2.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3023/B00C/R0012/Ceiling Structures/Linings/S2			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0012 - Toilets - Boys/Girls (2.26 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3023/B00C/R0012/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R0013 - Movement (15.1 m2)</b>						
No Asbestos	No Asbestos Found					
<b>B00C - R0014 - External Movement (5.21 m2)</b>						
No Asbestos	No Asbestos Found					

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1917 - Brick/Block (Brick/Block)**

**Exterior**

Wall Cladding	Flat AC Sheeting 3023/B00A/Wall Cladding/S4					<b>No Asbestos Detected</b>
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

**Interior**

**B00F - R0001 - Staff Toilet (8.31 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3023/B00F/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>	

**B00F - R0002 - Movement (1.24 m2)**

No Asbestos

**B00F - R0003 - Cleaning Distributed Store (2.7 m2)**

No Asbestos

**B00F - R0004 - Movement (6.93 m2)**

No Asbestos

**B00F - R0005 - Movement (4.57 m2)**

No Asbestos

**B00F - R0006 - Practical Activities - 1hb (30.29 m2)**

No Asbestos

**B00F - R0007 - Home Base (47.53 m2)**

No Asbestos

**B00F - R0008 - Withdrawal Space - 1hb (15.45 m2)**

No Asbestos

**B00F - R0009 - Home Base Store (2.38 m2)**

No Asbestos

**B00F - R0010 - Home Base Store (12.18 m2)**

No Asbestos

**B00F - R0011 - Withdrawal Space - 1hb (15.65 m2)**

No Asbestos

**B00F - R0012 - Home Base (47.53 m2)**

No Asbestos

**B00F - R0013 - Movement (5.82 m2)**

No Asbestos

**B00F - R0014 - Special Programs Room (12.49 m2)**

No Asbestos

**B00F - R0015 - Sports Store (10.63 m2)**

No Asbestos

**B00F - R0016 - Cleaning Supplies (5.66 m2)**

No Asbestos

**B00F - R0017 - Movement (10.37 m2)**

No Asbestos

**B00F - R0018 - Cleaning Distributed Store (7.63 m2)**

Ceiling Structures/Linings	Vermiculite 3023/B00F/R0018/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0019 - Toilets - Boys (51.51 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3023/B00A/R0029/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
3023/B00F/R0018/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R0021 - External Movement (33.76 m2)</b>						
No Asbestos						
<b>B00F - R0023 - Toilets - Girls (52.93 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3023/B00A/R0029/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
3023/B00F/R0018/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R0024 - General Assistant/Bulk Store (9.67 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
3023/B00F/R0018/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R0025 - Movement (1.99 m2)</b>						
No Asbestos						
<b>B00F - R0026 - Movement (1.99 m2)</b>						
No Asbestos						
<b>B00F - R0027 - Stairs (7.67 m2)</b>						
No Asbestos	No Asbestos Found					
<b>B00F - R0028 - Stairs (6.01 m2)</b>						
Na Asbestos	No Asbestos Found					
<b>B00F - R1001 - Home Base (47.73 m2)</b>						
No Asbestos						
<b>B00F - R1002 - Home Base (47.08 m2)</b>						
No Asbestos						
<b>B00F - R1003 - Home Base (47.73 m2)</b>						
No Asbestos						
<b>B00F - R1005 - Practical Activities - 1hb (37.67 m2)</b>						
No Asbestos						
<b>B00F - R1006 - Interview (9.81 m2)</b>						
No Asbestos						
<b>B00F - R1007 - Movement (14.71 m2)</b>						
No Asbestos						
<b>B00F - R1009 - General Storeroom (2.68 m2)</b>						
No Asbestos						
<b>B00F - R1010 - Movement (6.06 m2)</b>						
No Asbestos	No Asbestos Found					
<b>B00F - R1011 - Special Programs Room (9.54 m2)</b>						
No Asbestos	No Asbestos Found					
<b>B00F - R1012 - Stairs (16.04 m2)</b>						
No Asbestos						
<b>B00F - R1013 - Movement (4.15 m2)</b>						
No Asbestos						
<b>B00F - R1014 - Personal Effects Storage (10.51 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00F - R1015 - Stairs (11.69 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Other-After School Care - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Home Base (66.36 m2)**

No Asbestos

**B00G - R0002 - Other-After School Care (56.87 m2)**

No Asbestos

**B00G - R0003 - Staff Kitchen (8.18 m2)**

No Asbestos

**B00G - R0004 - External Movement (31.5 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

<b>B00H - R0001 - Home Base (60 m2)</b>	No Asbestos
<b>B00H - R0002 - Home Base (59.47 m2)</b>	No Asbestos
<b>B00H - R0003 - Home Base (60.19 m2)</b>	No Asbestos
<b>B00H - R0004 - Home Base (60.3 m2)</b>	No Asbestos
<b>B00H - R0005 - Practical Activities - 1hb (19.49 m2)</b>	No Asbestos
<b>B00H - R0006 - Practical Activities - 1hb (19.53 m2)</b>	No Asbestos
<b>B00H - R0007 - Practical Activities - 1hb (19.58 m2)</b>	No Asbestos
<b>B00H - R0008 - Practical Activities - 1hb (19.63 m2)</b>	No Asbestos
<b>B00H - R0009 - Withdrawal Space - 2hb (11.57 m2)</b>	No Asbestos
<b>B00H - R0010 - Withdrawal Space - 2hb (11.57 m2)</b>	No Asbestos
<b>B00H - R0011 - Home Base Store (6.09 m2)</b>	No Asbestos
<b>B00H - R0012 - Home Base Store (6.13 m2)</b>	No Asbestos
<b>B00H - R0013 - Home Base Store (6.13 m2)</b>	No Asbestos
<b>B00H - R0014 - Home Base Store (6.23 m2)</b>	No Asbestos
<b>B00H - R0015 - External Movement (85.74 m2)</b>	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B01C - Pupil Facilities - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof    Non Accessible Area  
 - Area inaccessible No roof void

Underfloor Voids - Slab    No Asbestos Found  
 on Ground

**Interior**

**B01C - R0001 - Canteen (18.48 m2)**

No Asbestos

**B01C - R0002 - Canteen Office/Store (2.52 m2)**

No Asbestos

**B01C - R0003 - Canteen Office/Store (2.69 m2)**

No Asbestos

**B01C - R0004 - Movement (48.89 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

3023/B01C/R0004/Ceiling Structures/Linings/S20

**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D11518 - Learning Unit - Standard With P.A.A. : Placement Date - 25/09/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D12064 - Learning Unit - Standard With P.A.A. : Placement Date - 23/07/2015**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D12088 - Learning Unit - Standard With P.A.A. : Placement Date - 5/12/2015**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D12197 - Learning Unit - Standard With P.A.A. : Placement Date - 1/12/2014**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

#### R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 602 - D12489 - Learning Unit - Standard With P.A.A. : Placement Date - 20/10/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D14479 - Learning Unit - Standard With P.A.A. : Placement Date - 25/09/2015</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D15262 - Learning Unit - Standard With P.A.A. : Placement Date - 8/10/2016</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D15653 - Learning Unit - Standard With P.A.A. : Placement Date - 5/12/2015</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D17432 - Learning Unit - Standard With P.A.A. : Placement Date - 14/09/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

3023\_ASB\_010713\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017