


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Waitara Public School (3334)
Region : Northern Sydney
State Electorate : Ku-ring-gai
Local Government Area : Hornsby

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1991 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Non Accessible Area
Packing to Floor Joists
- Area inaccessible - internal confined space entry.

Ceiling Voids No Asbestos Found

Interior**B00A - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction >3m.

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
3334/B00A/R0003/Floor Coverings Res/Textile/S15						

B00A - R0004 - Library Office/Workroom

No Asbestos

B00A - R0005 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
3334/B00A/R0005/Floor Coverings Res/Textile/S16						

B00A - R0006 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction >3m.

B00A - R0007 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction >3m.

B00A - R0008 - Duplicating Workroom

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction >3m.

B00A - R0009 - External Movement

No Asbestos

B00A - R0010 - Practical Activities - 1hb

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - External Movement

No Asbestos

B00A - R0013 - Home Base

Chalk Board	Compressed AC Sheet	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
-------------	---------------------	-----	----------------	--------------------	---------	--------------------

3334/B00J/R0003/Chalk Board/S13

Chrysotile (white asbestos)

B00A - R0016 - Staff Room

No Asbestos

B00A - R0017 - Deputy Principal

No Asbestos

B00A - R0018 - Staff Toilet

No Asbestos

B00A - R0019 - General Storeroom

No Asbestos

B00A - R0020 - Principal

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0021 - Security Store

No Asbestos

B00A - R0022 - Movement

No Asbestos

B00A - R0023 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1959 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction <0.3m.					
Eaves Linings	Flat AC Sheeting 3334/B00B/Eaves Linings/S4	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00B - R0001 - Withdrawal Space - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting 3334/B00B/R0004/Ceiling Structures/Linings/S2	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00B - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting 3334/B00B/R0002/Wall Linings Internal/S1	2m2	Adjacent heater South East corner	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
-----------------------	--	-----	-----------------------------------	--------------------	---------	---

B00B - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting 3334/B00B/R0002/Wall Linings Internal/S1	2m2	Adjacent heater South East corner	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
-----------------------	--	-----	-----------------------------------	--------------------	---------	---

B00B - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3334/B00B/R0004/Ceiling Structures/Linings/S2	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting 3334/B00B/R0004/Wall Linings Internal/S3	2m2	South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1963 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible - Internal confined space entry.					
Gable end strips	Flat AC Sheeting	16m	East and West elevations	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/Eaves Linings/S5					Chrysotile (white asbestos)

Interior**B00C - R0001 - Home Base**

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0004 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	3334/B00C/R0004/Wall Linings Internal/S7					No Asbestos Detected

B00C - R0005 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0007 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Home Base

No Asbestos

B00C - R0010 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Library - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00E - R0001 - Cleaning Distributed Store**

No Asbestos

B00E - R0002 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Plant

No Asbestos

B00E - R0005 - Cleaning Distributed Store

No Asbestos

B00E - R0006 - External Movement

No Asbestos

B00E - R0007 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities - 1985 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 3334/B00G/Wall Cladding/S8					No Asbestos Detected

Interior**B00F - R0001 - Cleaning Distributed Store**

No Asbestos

B00F - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0005 - Hall Chair Store

No Asbestos

B00F - R0006 - Movement

No Asbestos

B00F - R0007 - External Movement

No Asbestos

B00F - R0008 - Raised Platform

No Asbestos

B00F - R0009 - Movement

No Asbestos

B00F - R0010 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0011 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0012 - Hall Chair Store

No Asbestos

B00F - R0013 - Communal Space

No Asbestos

B00F - R0014 - External Movement

No Asbestos

B00F - R0015 - No Access

No Asbestos

B00F - R0016 - P.E. Store

No Asbestos

B00F - R0017 - Canteen Office/Store

No Asbestos

B00F - R0019 - Canteen Office/Store

No Asbestos

B00F - R0020 - Music Store

No Asbestos

B00F - R0021 - Canteen

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00F - R0022 - External Movement

No Asbestos

B00F - R0023 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1963 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Slab on Ground	Non Accessible Area - Height Restriction <0.3m.					
Gable verge lining	Flat AC Sheeting	15m	East and West elevations	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/Eaves Linings/S5					Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting					
	3334/B00G/Wall Cladding/S8					No Asbestos Detected

Interior**B00G - R0001 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00G/R0001/Wall Linings Internal/S9					Chrysotile (white asbestos)

B00G - R0002 - Special Programs Room

No Asbestos

B00G - R0003 - Special Programs Room

No Asbestos

B00G - R0004 - General Storeroom

No Asbestos

B00G - R0005 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00G/R0001/Wall Linings Internal/S9					Chrysotile (white asbestos)

B00G - R0006 - Personal Effects Storage

No Asbestos

B00G - R0007 - Movement

No Asbestos

B00G - R0008 - Home Base

No Asbestos

B00G - R0009 - Special Programs Room

No Asbestos

B00G - R0010 - Practical Activities - 1hb

No Asbestos

B00G - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00G/R0011/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-Regional Use - 1951 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists
 Non Accessible Area
 - Area inaccessible - access sealed.

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Height Restriction >3m.

Interior

B00H - R0001 - Uniform Shop

No Asbestos

B00H - R0002 - External Movement

No Asbestos

B00H - R0003 - General Storeroom

No Asbestos

B00H - R0004 - No Access

Floor Coverings Res/Textile Vinyl Tiles
 3334/B00H/R0004/Floor Coverings Res/Textile/S11 **No Asbestos Detected**

B00H - R0005 - No Access

Floor Coverings Res/Textile Vinyl Tiles
 3334/B00H/R0004/Floor Coverings Res/Textile/S11 **No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1991 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction <0.3m
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Home Base

No Asbestos

B00I - R0002 - External Movement

No Asbestos

B00I - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1991 - Timber (Timber)**Exterior**

Underfloor Voids - Non Accessible Area
Packing to Floor Joists
- Height Restriction <0.3m

Ceiling Voids No Asbestos Found

Interior**B00J - R0001 - General Storeroom**

No Asbestos

B00J - R0002 - Home Base Store

No Asbestos

B00J - R0003 - Home Base

Chalk Board	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0004 - Home Base

Chalk Board	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0005 - Personal Effects Storage

Floor Coverings Vinyl Tiles
Res/Textile
3334/B00J/R0005/Floor Coverings Res/Textile/S12

No Asbestos Detected

B00J - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0007 - Practical Activities - 1hb

No Asbestos

B00J - R0008 - Home Base

Chalk Board	Compressed AC Sheet	11m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0009 - General Storeroom

No Asbestos

B00J - R0010 - Movement

No Asbestos

B00J - R0011 - Staff Toilet

No Asbestos

B00J - R0012 - General Storeroom

No Asbestos

B00J - R0013 - Library Office/Workroom

No Asbestos

B00J - R0014 - Staff Room Annexe

No Asbestos

B00J - R0015 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00G/R0011/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 1951 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists
 Non Accessible Area
 - Height Restriction <0.3m

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Height Restriction >3m.

Interior

B00K - R0001 - Special Programs Room

No Asbestos

B00K - R0002 - General Storeroom

No Asbestos

B00K - R0003 - Cleaning Supplies

Wall Linings Internal	Flat AC Sheeting	8m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

B00K - R0004 - External Movement

Wall Linings Internal	Flat AC Sheeting	2m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

B00K - R0005 - Personal Effects Storage

Wall Linings Internal	Flat AC Sheeting	6m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1991 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - Toilets - Girls

No Asbestos

B00L - R0002 - General Assistant/Bulk Store

No Asbestos

B00L - R0003 - Toilets - Boys

No Asbestos

B00L - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - General Learning/Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - Home Base

No Asbestos

B00M - R0002 - Home Base

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

No Asbestos

B00M - R0006 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - General Assistant/Bulk Store

No Asbestos

B00M - R0009 - Toilets - Girls

No Asbestos

B00M - R0010 - Toilets - Boys

No Asbestos

B00M - R0011 - Access Shower/Toilet/Change

No Asbestos

B00M - R0012 - General Storeroom

No Asbestos

B00M - R0013 - General Storeroom

No Asbestos

B00M - R0014 - External Movement

No Asbestos

B00M - R0015 - External Stairs

No Asbestos

B00M - R0016 - External Stairs

No Asbestos

B00M - R1001 - Home Base

No Asbestos

B00M - R1002 - Home Base

No Asbestos

B00M - R1003 - Home Base

No Asbestos

B00M - R1004 - Home Base Store

No Asbestos

B00M - R1005 - Practical Activities/Movement - 1hb

No Asbestos

B00M - R1006 - Withdrawal Space - 2hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00M - R1007 - Practical Activities/Movement - 1hb						
No Asbestos						
B00M - R1008 - Home Base Store						
No Asbestos						
B00M - R1009 - Withdrawal Space - 1hb						
No Asbestos						
B00M - R1010 - Home Base Store						
No Asbestos						
B00M - R1011 - Practical Activities/Movement - 1hb						
No Asbestos						
B00M - R1012 - External Movement						
No Asbestos						
B00M - R1013 - External Stairs						
No Asbestos						
B00M - R1014 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10229 - Learning Unit - Standard With P.A.A. : Placement Date - 13/04/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10265 - Learning Unit - Standard With P.A.A. : Placement Date - 29/09/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D11409 - Learning Unit - Standard/Withdrawal : Placement Date - 29/05/1998

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D11771 - Learning Unit - Standard With P.A.A. : Placement Date - 25/01/2017

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12132 - Learning Unit - Standard With P.A.A. : Placement Date - 20/02/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 750 - D12469 - Learning Unit - ESL : Placement Date - 13/03/1996						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 601 - D12609 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 602 - D13138 - Learning Unit - Standard With P.A.A. : Placement Date - 2/02/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D13630 - Learning Unit - Standard/Withdrawal : Placement Date - 19/01/2015						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D13760 - Learning Unit - Standard/Withdrawal : Placement Date - 6/06/2007						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 602 - D14094 - Learning Unit - Standard With P.A.A. : Placement Date - 13/04/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14143 - Learning Unit - Standard With P.A.A. : Placement Date - 31/08/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14254 - Learning Unit - Standard With P.A.A. : Placement Date - 18/09/2008						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14580 - Learning Unit - Standard With P.A.A. : Placement Date - 29/12/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D14959 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017