


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Walhallow Public School (3343)
Region : New England
State Electorate : Upper Hunter
Local Government Area : Liverpool Plains

Initial Survey : Noel Arnold & Associates : 05 - Apr - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Pupil Facilities - 1922 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3343/B00A/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids - Flat Roof	Non Accessible Area - No manhole height approximately 3.5m					
Underfloor Voids - Slab on Ground						

Interior

B00A - R0001 - Staff Toilet

No Asbestos

B00A - R0002 - Toilets - Girls

No Asbestos

B00A - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3343/B00A/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0004 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/General Learning - 1922 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	4m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3343/B00B/Eaves Linings/S5					Chrysotile (white asbestos)
Ceiling Void - Flat ceiling, pitched roof.	Non Accessible Area					
	- Height restricted - 4m					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					

Interior

B00B - R0001 - General Storeroom	No Asbestos
B00B - R0002 - General Storeroom	No Asbestos
B00B - R0003 - Staff Room	No Asbestos
B00B - R0004 - Principal	No Asbestos
B00B - R0005 - Movement	No Asbestos
B00B - R0006 - Home Base	No Asbestos
B00B - R0007 - Home Base Store	No Asbestos
B00B - R0010 - Movement	No Asbestos
B00B - R0013 - Clerical Office	No Asbestos
B00B - R0014 - Withdrawal Space - 1hb	No Asbestos
B00B - R0015 - P.E. Store	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1922 - Timber (Timber)

Exterior

Ceiling Void - Flat Ceiling, pitched roof	Non Accessible Area					
	- Height restricted - Approximately 4m high.					
Eaves Linings	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Stairs	Compressed AC Sheet					
	3343/B00C/Stairs/S7					No Asbestos Detected

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Movement

Electrical Mounting Board	Fibrous Membrane	1Unit	Southern wall eastern end	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	------------------	-------	---------------------------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Special Programs Room

No Asbestos

B00C - R0007 - Special Programs Room

No Asbestos

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - General Storeroom

No Asbestos

B00C - R0011 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3343/B00C/R0011/Floor Coverings Res/Textile/S6					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	3343/B00C/R0011/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00C - R0012 - General Storeroom

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Building Services - 2009 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
No Ceiling Void	No Asbestos Found

Interior

B00D - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
No Ceiling Void	No Asbestos Found

Interior

B00E - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017