


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wallabadah Public School (3345)
Region : New England
State Electorate : Upper Hunter
Local Government Area : Liverpool Plains

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1958 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 3345/B00A/Eaves Linings/S1	12m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Void - Flat ceiling, pitched roof	Non Accessible Area - Height restricted approx 4m high					

Interior

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - External Movement

Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Staff Facilities - 1983 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Void - Flat ceiling, pitted roof	Non Accessible Area - Height restricted approx 4m

Interior

B00B - R0004 - Staff Kitchen

No Asbestos

B00B - R0005 - Clerical Office

No Asbestos

B00B - R0006 - Principal

No Asbestos

B00B - R0007 - Entry Vestibule

No Asbestos

B00B - R0008 - Interview

No Asbestos

B00B - R0009 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1920 - Brick/Block (Brick/Block)

Exterior

Window beading	Caulking 3345/B00C/Window beading/S7					No Asbestos Detected
Ceiling Void - Mostly flat ceiling, pitched roof	Non Accessible Area - Height restricted, ceiling height approx 4m					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					

Interior

B00C - R0001 - External Movement

Electrical Mounting Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B00C - R0002 - Reading Area

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0006 - General Assistant/Bulk Store

No Asbestos

B00C - R0007 - Library Office/Workroom

No Asbestos

B00C - R0008 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Staff Facilities - 1983 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/Eaves Linings/S3					Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - No manhole, ceiling height measured at 2.6m					

Interior**B00D - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/R0001/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00D - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/R0001/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00D - R0003 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/R0001/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Incinerette	Encapsulated Insulation material within unit	1Unit(s)	North facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00D - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/R0001/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Incinerette	Encapsulated Insulation material within unit	1Unit(s)	North facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00D - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	7m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00D/R0001/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities - 2003 - Timber (Timber)**Exterior**

Wall Cladding	Flat AC Sheeting	75m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00F/Wall Cladding/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	14m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3345/B00F/Eaves Linings/S6				Chrysotile (white asbestos)	

Interior**B00F - R0001 - Garage/Carport**

No Asbestos

B00F - R0002 - Garage/Carport

Wall Linings Internal	Fibre Cement Casting (Monocrete)	40m2	North, South, East & West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3345/B00F/Wall Cladding/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 2007 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning/Library - 2011 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Sub floor completely sealed.

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B001 - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D11740 - Learning Unit - Standard/Withdrawal : Placement Date - 7/07/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017