

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wallendbeen Public School (3353)  
**Region :** Riverina  
**State Electorate :** Cootamundra  
**Local Government Area :** Cootamundra

**Initial Survey :** Noel Arnold & Associates : 14 - May - 2008  
**Reviewed By :** Greencap-NAA : 15 - Jun - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1911 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior**

**B00A - R0001 - Home Base**

Heater Backing	Flat AC Sheeting 3353/B00A/R0001/Heater Backing/S4					<b>No Asbestos Detected</b>
----------------	---	--	--	--	--	-----------------------------

**B00A - R0003 - Staff Kitchen**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0004 - Duplicating Workroom**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0005 - Personal Effects Storage**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0006 - Clerical Office**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0007 - Staff Room Annexe**

Heater Backing	Flat AC Sheeting 3353/B00A/R0001/Heater Backing/S4					<b>No Asbestos Detected</b>
----------------	---	--	--	--	--	-----------------------------

**B00A - R0008 - Staff Kitchen**

No Asbestos						
-------------	--	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library - 1930 - Timber (Timber)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction 4m height
Underfloor Voids	No Asbestos Found

**Interior**

**B00B - R0001 - Movement**

Flooring	Compressed AC Sheet 3353/B00B/R0001/Floor Coverings Res/Textile/S1	<b>No Asbestos Detected</b>
----------	---	-----------------------------

**B00B - R0002 - Reading Area**

No Asbestos

**B00B - R0003 - General Storeroom**

In-fill-panel	Flat AC Sheeting	1m2	Behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	3353/B00B/R0003/Infill panel/S2				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Building Services - 1960 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0001 - Movement**

Flooring	Compressed AC Sheet 3353/B00B/R0001/Floor Coverings Res/Textile/S1	<b>No Asbestos Detected</b>
----------	---	-----------------------------

**B00C - R0002 - General Storeroom**

Flooring	Compressed AC Sheet 3353/B00B/R0001/Floor Coverings Res/Textile/S1	<b>No Asbestos Detected</b>
----------	---	-----------------------------

**B00C - R0003 - Garden Store**

Flooring	Compressed AC Sheet 3353/B00B/R0001/Floor Coverings Res/Textile/S1	<b>No Asbestos Detected</b>
----------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00D - R0002 - Toilets - Boys**

No Asbestos

**B00D - R0003 - Toilets - Girls**

No Asbestos

**B00D - R0004 - Staff Toilet**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Gable Ends	Flat AC Sheeting  3353/B00E/Gable Ends/S3	4m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00E - R0001 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00F - R0001 - Reading Area**

No Asbestos

**B00F - R0002 - K.L.A. Store**

No Asbestos

**B00F - R0003 - Practical Activities**

No Asbestos

**B00F - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017