


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wallerawang Public School (3354)
Region : Western NSW
State Electorate : Bathurst
Local Government Area : Lithgow

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Sick Bay**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0003 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Cleaning Supplies

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Staff Toilet

No Asbestos

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Duplicating Workroom

No Asbestos

B00A - R0015 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Movement

No Asbestos

B00A - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0020 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)

No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Library - 1995 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0006 - General Assistant/Bulk Store

No Asbestos

B00B - R0007 - Kiln Room

No Asbestos

B00B - R0008 - Plant

No Asbestos

B00B - R0009 - General Assistant/Bulk Store

No Asbestos

B00B - R0010 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - Stairs

No Asbestos

B00B - R1001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R1007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1008 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1009 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1010 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1011 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1012 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1013 - Movement						
No Asbestos						
B00B - R1014 - Practical Activities - 1hb						
No Asbestos						
B00B - R1015 - Practical Activities - 1hb						
No Asbestos						
B00B - R1016 - Practical Activities - 1hb						
No Asbestos						
B00B - R1017 - Practical Activities - 1hb						
No Asbestos						
B00B - R1018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Communal Facilities/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0002 - Canteen

No Asbestos

B00C - R0003 - Canteen Office/Store

No Asbestos

B00C - R0004 - General Assistant/Bulk Store

No Asbestos

B00C - R0005 - Staff Room Annexe

No Asbestos

B00C - R0006 - Cleaning Supplies

No Asbestos

B00C - R0007 - Plant

No Asbestos

B00C - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - Garden Store

No Asbestos

B00C - R0010 - Toilets - Girls

No Asbestos

B00C - R0011 - Shower/Change

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Communal Space

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Communal Space

No Asbestos

B00C - R0018 - Toilets - Boys

No Asbestos

B00C - R0019 - P.E. Store

No Asbestos

B00C - R0020 - Sports Store

No Asbestos

B00C - R0021 - Hall Chair Store

No Asbestos

B00C - R0024 - Main Switch Board

No Asbestos

B00C - R0025 - Disabled Toilet

No Asbestos

B00C - R0026 - Movement

No Asbestos

B00C - R0027 - Lift

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0028 - Communal Space

No Asbestos

B00C - R0029 - External Movement

No Asbestos

B00C - R0030 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1995 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Toilets - Girls**

No Asbestos

B00D - R0002 - Toilets - Boys

No Asbestos

B00D - R0004 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0005 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0006 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0007 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0008 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0009 - General Storeroom**

No Asbestos

B00D - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Movement

No Asbestos

B00D - R0012 - Personal Effects Storage

No Asbestos

B00D - R0013 - Practical Activities - 1hb

No Asbestos

B00D - R0014 - Practical Activities - 1hb

No Asbestos

B00D - R0015 - Personal Effects Storage

No Asbestos

B00D - R0016 - Stairs

No Asbestos

B00D - R0017 - Staff Toilet

No Asbestos

B00D - R1001 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R1002 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R1003 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R1004 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1005 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1006 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R1007 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1008 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1009 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1010 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1011 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1012 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1013 - Movement						
No Asbestos						
B00D - R1014 - Practical Activities - 1hb						
No Asbestos						
B00D - R1015 - Practical Activities - 1hb						
No Asbestos						
B00D - R1016 - Practical Activities - 1hb						
No Asbestos						
B00D - R1017 - Practical Activities - 1hb						
No Asbestos						
B00D - R1018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 2006 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Storage - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Special Programs Room - Type 1

No Asbestos

B00G - R0002 - Special Programs Store

No Asbestos

B00G - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13882 - Learning Unit - Standard With P.A.A. : Placement Date - 17/03/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14709 - Learning Unit - Standard With P.A.A. : Placement Date - 14/05/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017