


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Warners Bay Public School (3384)  
**Region :** Hunter/Central Coast  
**State Electorate :** Charlestown  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 14 - Jan - 2010  
**Reviewed By :** Grencap-NAA : 26 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Communal Facilities/Pupil Facilities - 1985 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00A - R0001 - Cleaning Distributed Store (0.96 m2)**

Wall Linings Internal	Flat AC Sheeting 3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected

**B00A - R0002 - Plant (0.86 m2)**

Wall Linings Internal	Flat AC Sheeting 3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected

**B00A - R0003 - Shower/Change (2.27 m2)**

Wall Linings Internal	Flat AC Sheeting 3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected

**B00A - R0004 - Movement (6.51 m2)**

Wall Linings Internal	Flat AC Sheeting 3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0004/Ceiling Structures/Linings/S6					No Asbestos Detected

**B00A - R0005 - Toilets - Girls (10.99 m2)**

Wall Linings Internal	Flat AC Sheeting 3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet 3384/B00A/R0005/Partition Walls (Cubicles)/S24					No Asbestos Detected

**B00A - R0006 - Movement (95.69 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

**B00A - R0007 - Hall Chair Store (2.55 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0008 - Communal Space (186.68 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0009 - Canteen (43.47 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0010 - Canteen Office/Store (5.7 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0011 - Canteen Office/Store (5.65 m2)**

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard**

**B00A - R0012 - Sports Store (14.16 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00A - R0013 - Disabled Toilet (3.33 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0014 - Movement (31.65 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00A - R0015 - Hall Chair Store (2.5 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00A - R0016 - Raised Platform (53.96 m2)</b>						
No Asbestos						
<b>B00A - R0017 - Toilets - Boys (10.97 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet					
	3384/B00A/R0005/Partition Walls (Cubicles)/S24					No Asbestos Detected
<b>B00A - R0018 - Shower/Change (2.77 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00A - R0019 - Movement (4.35 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0001/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00A - R0020 - No Access (2.23 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0004/Ceiling Structures/Linings/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0004/Ceiling Structures/Linings/S6					No Asbestos Detected
<b>B00A - R0021 - Movement (16.68 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00A - R0022 - Distribution Board (1.57 m2)</b>						
					Note: No inspection of live electrical installation.	
Wall Linings Internal	Flat AC Sheeting					
	3384/B00A/R0022/Wall Linings Internal/S2					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00A/R0003/Ceiling Structures/Linings/S23					No Asbestos Detected
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00A - R0023 - Music Store (15.45 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Library - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>

**Interior**

**B00C - R0001 - External Movement (41.43 m2)**

No Asbestos

**B00C - R0002 - Movement (8.92 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

**B00C - R0003 - Home Base Store (7.12 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

**B00C - R0004 - Home Base (57.82 m2)**

Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Home Base (57.98 m2)**

Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Home Base Store (7.08 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

**B00C - R0007 - Movement (8.93 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3384/B00C/R0006/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

**B00C - R0008 - Distribution Board (4.51 m2)**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Resinous Board	12Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0008/Electrical Backing Board/S8					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	1m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00C/R0008/Wall Linings Internal/S25					<b>Chrysotile (white asbestos)</b>
<b>B00C - R0009 - Movement (8.62 m2)</b>						
In-fill-panel	Flat AC Sheeting					
	3384/B00C/R0009/In-fill-panel/S9					<b>No Asbestos Detected</b>
<b>B00C - R0010 - Sports Store (13.42 m2)</b>						
No Asbestos						
<b>B00C - R0011 - Stairs (4.57 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
<b>B00C - R1001 - Movement (53.17 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
<b>B00C - R1002 - K.L.A. Store (9.04 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Infil panel	Flat AC Sheeting					
	3384/B00C/R0009/In-fill-panel/S9					<b>No Asbestos Detected</b>
<b>B00C - R1003 - K.L.A. Store (7.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1005 - K.L.A. Store (7.1 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1006 - Movement (8.86 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Infil panel	Flat AC Sheeting					
	3384/B00C/R0009/In-fill-panel/S9					<b>No Asbestos Detected</b>
<b>B00C - R1007 - Home Base (58.06 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1008 - Home Base (58.21 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00C - R1009 - Stairs (15.25 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 1935 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00D/R0009/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0009 - Reading Area (179.93 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	180m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00D/R0009/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00D - R0010 - Library Office/Workroom (25.34 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00D/R0009/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00D - R0011 - Staff Toilet (6.74 m2)**

No Asbestos

**B00D - R0012 - Communications Room (7.74 m2)**

No Asbestos

**B00D - R0013 - K.L.A. Store (15.8 m2)**

No Asbestos

**B00D - R0014 - Movement (20.34 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Building Services - 1935 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00E/Eaves Linings/S26					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00E - R0001 - Cleaning Supplies (9.83 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00E/R0004/Ceiling Structures/Linings/S12					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00E - R0002 - Cleaning Supplies (2.7 m2)**

No Asbestos

**B00E - R0003 - Home Base (46.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00E/R0003/Floor Coverings Res/Textile/S27					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	3384/B00E/R0003/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>

**B00E - R0004 - Practical Activities - 1hb (53.59 m2)**

Wall Linings Internal	Flat AC Sheeting					
	3384/B00E/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>

**B00E - R0005 - Staff Room Annexe (11.59 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00E/R0003/Floor Coverings Res/Textile/S27					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	3384/B00E/R0003/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>

**B00E - R0006 - Home Base (47.75 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3384/B00E/R0003/Floor Coverings Res/Textile/S27					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	3384/B00E/R0003/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>

**B00E - R0007 - Home Base (47.81 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3384/B00E/R0003/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	3384/B00E/R0003/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>

**B00E - R0008 - General Storeroom (2.59 m2)**

No Asbestos

**B00E - R0009 - General Assistant/Bulk Store (10 m2)**

No Asbestos

**B00E - R0010 - Garden Store (4.56 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00F - General Learning - 1965 - Brick/Veneer (Brick/Veneer)****Exterior**

In-fill-panel	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/In-fill-panel/S14					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00F - R0001 - Home Base (56.78 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B001/R0002/Floor Coverings Res/Textile/S30					

**B00F - R0002 - Home Base Store (4.65 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0003 - Movement (9.36 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B001/R0002/Floor Coverings Res/Textile/S30					

**B00F - R0004 - Movement (3.39 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0008/Ceiling Structures/Linings/S32					<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>

**B00F - R0005 - Home Base (56.25 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B001/R0002/Floor Coverings Res/Textile/S30					

**B00F - R0006 - Home Base Store (4.73 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B00F/R0006/Ceiling Structures/Linings/S13				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0007 - Movement (9.41 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B00F/R0006/Ceiling Structures/Linings/S13				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0008 - Movement (5.87 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B00F/R0008/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Pupil Facilities - 1968 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00G/R0018/Ceiling Structures/Linings/S34				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00G - R0001 - Home Base (52.94 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive				<b>No Asbestos Detected</b>	
	3384/B001/R0002/Floor Coverings Res/Textile/S30					

**B00G - R0002 - Practical Activities - 1hb (18.55 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	

**B00G - R0003 - Home Base Store (6.04 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	

**B00G - R0004 - Personal Effects Storage (2.77 m2)**

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Assumed Asbestos - Electrical Hazard</b>	

**B00G - R0005 - Movement (5.54 m2)**

No Asbestos

**B00G - R0006 - Personal Effects Storage (2.75 m2)**

No Asbestos

**B00G - R0007 - Home Base Store (6.05 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	

**B00G - R0008 - Home Base (57.03 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive				<b>No Asbestos Detected</b>	
	3384/B001/R0002/Floor Coverings Res/Textile/S30					

**B00G - R0009 - Practical Activities - 1hb (18.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	

**B00G - R0010 - Home Base (52.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>	

**B00G - R0011 - Home Base Store (6.05 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0012 - Personal Effects Storage (2.75 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0013 - Movement (5.52 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0014 - Personal Effects Storage (2.73 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0015 - Home Base Store (5.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0016 - Home Base (56.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					
3384/B001/R0002/Floor Coverings Res/Textile/S30				<b>No Asbestos Detected</b>		
<b>B00G - R0017 - Movement (11.07 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B00G/R0018/Ceiling Structures/Linings/S34				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0018 - Movement (11.04 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B00G/R0018/Ceiling Structures/Linings/S34				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0019 - Movement (4.41 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0020 - Toilets - Boys (22.35 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0021 - Toilets - Girls (15.87 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3384/B001/R0002/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R9001 - Garden Store (45.75 m2)</b>						
No Asbestos						
<b>B00G - R9002 - General Assistant/Bulk Store (38.96 m2)</b>						
No Asbestos						
<b>B00G - R9003 - General Storeroom (116.86 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning/Staff Facilities - 1965 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting 3384/B00H/R0021/Ceiling Structures/Linings/S15					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 3384/B00H/R0021/Ceiling Structures/Linings/S15					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00H - R0002 - General Storeroom (3.71 m2)**

No Asbestos

**B00H - R0003 - Movement (3.07 m2)**

No Asbestos

**B00H - R0004 - Staff Toilet (2.99 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00H - R0005 - Staff Room Annexe (18.04 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B00I/R0002/Floor Coverings Res/Textile/S29	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B00I/R0002/Floor Coverings Res/Textile/S30					No Asbestos Detected

**B00H - R0006 - Movement (19.75 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B00I/R0002/Floor Coverings Res/Textile/S29	20NA	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B00I/R0002/Floor Coverings Res/Textile/S30					No Asbestos Detected

**B00H - R0007 - Staff Room Annexe (17.4 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B00I/R0002/Floor Coverings Res/Textile/S29	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B00I/R0002/Floor Coverings Res/Textile/S30					No Asbestos Detected

**B00H - R0008 - General Storeroom (2.71 m2)**

No Asbestos

**B00H - R0009 - Personal Effects Storage (5.99 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B00I/R0002/Floor Coverings Res/Textile/S29	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B00I/R0002/Floor Coverings Res/Textile/S30					No Asbestos Detected

**B00H - R0010 - Home Base Store (5.97 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 3384/B00I/R0002/Floor Coverings Res/Textile/S29	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00H - R0011 - Home Base (65.63 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30				<b>No Asbestos Detected</b>	
<b>B00H - R0012 - Home Base (74.56 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30				<b>No Asbestos Detected</b>	
<b>B00H - R0013 - Practical Activities - 1hb (20.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00H - R0014 - Personal Effects Storage (3.78 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30				<b>No Asbestos Detected</b>	
<b>B00H - R0015 - Cleaning Distributed Store (2.3 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00H - R0016 - Movement (10.16 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00H - R0017 - General Storeroom (29.27 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30				<b>No Asbestos Detected</b>	
<b>B00H - R0018 - Toilet - M (3.01 m2)</b>						
Wall Linings Internal	Flat AC Sheeting 3384/B00H/R0018/Wall Linings Internal/S16				<b>No Asbestos Detected</b>	
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00H/R0021/Ceiling Structures/Linings/S15				<b>No Asbestos Detected</b>	
<b>B00H - R0019 - Toilet - M (3.05 m2)</b>						
No Asbestos						
<b>B00H - R0021 - Movement (105.79 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00H/R0021/Ceiling Structures/Linings/S15				<b>No Asbestos Detected</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B001 - Administration/General Learning - 1949 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00I/In-fill-panel/S14					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B001 - R0001 - Movement (6.21 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0008/Ceiling Structures/Linings/S32					<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>

**B001 - R0002 - Movement (9.85 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00I/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B00I/R0002/Floor Coverings Res/Textile/S30					

**B001 - R0003 - Home Base Store (4.35 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00C/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B001 - R0004 - Home Base (56.61 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00I/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B00I/R0002/Floor Coverings Res/Textile/S30					

**B001 - R0005 - Clerical Office (37.75 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00I/R0002/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	3384/B00I/R0002/Floor Coverings Res/Textile/S30					

**B001 - R0006 - Entry Vestibule (9.32 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
<b>B001 - R0007 - Movement (12.5 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0008/Ceiling Structures/Linings/S32	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>
<b>B001 - R0008 - Staff Toilet (3.17 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B001 - R0009 - Principal (18.79 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
<b>B001 - R0010 - General Storeroom (4.17 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B001 - R0011 - Distribution Board (0.44 m2)</b>						
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Assumed Asbestos - Electrical Hazard</b>
Wall Linings Internal	Flat AC Sheeting 3384/B001/R0011/Wall Linings Internal/S31	10m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B001 - R0012 - General Storeroom (4.62 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3384/B001/R0002/Floor Coverings Res/Textile/S29	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B001 - R0013 - Duplicating Workroom (18.05 m2)</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3384/B001/R0002/Floor Coverings Res/Textile/S29	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting 3384/B00F/R0006/Ceiling Structures/Linings/S13	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 3384/B001/R0002/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	4m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00J - R0001 - Toilets - Boys (24.71 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00J - R0002 - Toilets - Girls (24.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00F/R0006/Ceiling Structures/Linings/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Other-After School Care - 1965 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00K - R0003 - No Access (2.19 m2)**

No Asbestos

**B00K - R0004 - Movement (3.53 m2)**

No Asbestos

**B00K - R0005 - Out Of School Hours Care Centre (76.14 m2)**

No Asbestos

**B00K - R0006 - No Access (9.48 m2)**

No Asbestos

**B00K - R0007 - Out Of School Hours Care Centre (7.45 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00L - Pupil Facilities - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Wall Cladding/S33			<b>Chrysotile (white asbestos)</b>		

**Interior**

**B00L - R0001 - Movement (2.83 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00L - R0002 - Toilets - Girls (20.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00L - R0003 - General Storeroom (33.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Wall Linings Internal	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Wall Cladding/S33			<b>Chrysotile (white asbestos)</b>		

**B00L - R0004 - Toilets - Boys (20.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00L - R0005 - Movement (2.79 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3384/B00L/Eaves Linings/S20			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 1955 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 3384/B00M/Eaves Linings/S21					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00M - R0001 - Toilets - Boys (30.96 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North	Good Condition (1)	Low (1) Low Priority (2-3)	
	3384/B00M/R0003/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>

**B00M - R0002 - Movement (21.42 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00M - R0003 - Toilets - Girls (24.26 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3384/B00M/R0002/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North	Good Condition (1)	Low (1) Low Priority (2-3)	
	3384/B00M/R0003/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00P - Administration - 2003 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00P - R0001 - Entry Vestibule (23.06 m2)**

No Asbestos

**B00P - R0002 - Clerical Office (27.83 m2)**

No Asbestos

**B00P - R0003 - Duplicating Workroom (22.14 m2)**

No Asbestos

**B00P - R0004 - Sick Bay (9.78 m2)**

No Asbestos

**B00P - R0005 - Access Shower/Toilet (5.17 m2)**

No Asbestos

**B00P - R0006 - Staff Toilet (4.79 m2)**

No Asbestos

**B00P - R0007 - Cleaning Distributed Store (2.66 m2)**

No Asbestos

**B00P - R0008 - Main Switch Board (2.78 m2)**

No Asbestos

**B00P - R0009 - Interview (16.76 m2)**

No Asbestos

**B00P - R0010 - Security Store (13.8 m2)**

No Asbestos

**B00P - R0011 - Staff Room Annexe (19.68 m2)**

No Asbestos

**B00P - R0012 - Staff Room (48.78 m2)**

No Asbestos

**B00P - R0013 - Staff Toilet (4.82 m2)**

No Asbestos

**B00P - R0014 - Staff Toilet (4.82 m2)**

No Asbestos

**B00P - R0015 - Deputy Principal (13.08 m2)**

No Asbestos

**B00P - R0016 - Principal (16.49 m2)**

No Asbestos

**B00P - R0017 - Interview (13.26 m2)**

No Asbestos

**B00P - R0018 - Movement (56.36 m2)**

No Asbestos

**B00P - R0019 - Movement (34.28 m2)**

No Asbestos

**B00P - R0020 - Movement (6.06 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00Q - General Learning - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

**Interior****B00Q - R0001 - External Movement (49.84 m2)**

No Asbestos

**B00Q - R0002 - Practical Activities - 1hb (19.75 m2)**

No Asbestos

**B00Q - R0003 - Home Base Store (6.18 m2)**

No Asbestos

**B00Q - R0004 - Home Base (60.3 m2)**

No Asbestos

**B00Q - R0005 - Withdrawal Space - 2hb (11.67 m2)**

No Asbestos

**B00Q - R0006 - Practical Activities - 1hb (19.75 m2)**

No Asbestos

**B00Q - R0007 - Home Base (60.3 m2)**

No Asbestos

**B00Q - R0008 - Home Base Store (6.18 m2)**

No Asbestos

**B00Q - R0009 - External Stairs (18.56 m2)**

No Asbestos

**B00Q - R1001 - External Movement (49.84 m2)**

No Asbestos

**B00Q - R1002 - Practical Activities - 1hb (19.73 m2)**

No Asbestos

**B00Q - R1003 - Home Base Store (6.18 m2)**

No Asbestos

**B00Q - R1004 - Home Base (60.12 m2)**

No Asbestos

**B00Q - R1005 - Withdrawal Space - 2hb (11.64 m2)**

No Asbestos

**B00Q - R1006 - Practical Activities - 1hb (19.73 m2)**

No Asbestos

**B00Q - R1007 - Home Base (60.12 m2)**

No Asbestos

**B00Q - R1008 - Home Base Store (6.18 m2)**

No Asbestos

**B00Q - R1009 - External Stairs (18.56 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017