


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Warren Central School (3392)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Warren

**Initial Survey :** Noel Arnold & Associates : 29 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1980 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00A - R0001 - Movement (66.19 m2)**

No Asbestos

**B00A - R0002 - Plant (7.72 m2)**

No Asbestos

**B00A - R0003 - Home Base Store (6.37 m2)**

No Asbestos

**B00A - R0004 - Sports Store (11.14 m2)**

No Asbestos

**B00A - R0005 - Staff Room Annexe (7.28 m2)**

No Asbestos

**B00A - R0006 - Movement (2.66 m2)**

No Asbestos

**B00A - R0007 - Practical Activities - 1hb (236.15 m2)**

No Asbestos

**B00A - R0008 - Distribution Board (0.81 m2)**

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles						
		3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00A - R0009 - Cleaning Distributed Store (1.16 m2)**

Floor Coverings Res/Textile	Vinyl Tiles						
		3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00A - R0010 - General Storeroom (3.12 m2)**

Floor Coverings Res/Textile	Vinyl Tiles						
		3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00A - R0011 - Toilets - Boys (8.02 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
							<b>Chrysotile (white asbestos)</b>
		3392/B00A/R0077/Partition Walls (Cubicles)/S1					

**B00A - R0012 - Toilets - Girls (7.99 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
							<b>Chrysotile (white asbestos)</b>
		3392/B00A/R0077/Partition Walls (Cubicles)/S1					

**B00A - R0013 - Personal Effects Storage (1.11 m2)**

No Asbestos

**B00A - R0014 - Home Base (59.01 m2)**

No Asbestos

**B00A - R0015 - Home Base (58.02 m2)**

No Asbestos

**B00A - R0016 - Withdrawal Space - 1hb (11.4 m2)**

No Asbestos

**B00A - R0017 - Home Base Store (6.41 m2)**

No Asbestos

**B00A - R0018 - Disabled Shower/Toilet (15.23 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
<b>B00A - R0019 - Special Programs Room (45.37 m2)</b>						
No Asbestos						
<b>B00A - R0020 - Staff Toilet (3.05 m2)</b>						
No Asbestos						
<b>B00A - R0021 - Staff Toilet (4.29 m2)</b>						
No Asbestos						
<b>B00A - R0022 - General Storeroom (7.23 m2)</b>						
No Asbestos						
<b>B00A - R0023 - Plant (6.13 m2)</b>						
No Asbestos						
<b>B00A - R0024 - Movement (73.39 m2)</b>						
No Asbestos						
<b>B00A - R0025 - Special Learning Space (59.17 m2)</b>						
No Asbestos						
<b>B00A - R0026 - Withdrawal Space - 1hb (11.19 m2)</b>						
No Asbestos						
<b>B00A - R0027 - Plant (7.74 m2)</b>						
No Asbestos						
<b>B00A - R0028 - Movement (42.78 m2)</b>						
No Asbestos						
<b>B00A - R0029 - Home Base (59.07 m2)</b>						
No Asbestos						
<b>B00A - R0030 - Staff Room Annexe (21.49 m2)</b>						
No Asbestos						
<b>B00A - R0031 - Home Base Store (5.79 m2)</b>						
No Asbestos						
<b>B00A - R0032 - Home Base Store (5.84 m2)</b>						
No Asbestos						
<b>B00A - R0033 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00A - R0035 - Cleaning Distributed Store (1.02 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0036 - General Storeroom (2.73 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0037 - Toilets - Boys (8.32 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0038 - Toilets - Girls (8.32 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0039 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00A - R0040 - Personal Effects Storage (1.11 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00A - R0041 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00A - R0042 - Cleaning Distributed Store (1.12 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0043 - Craft Store (2.96 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0044 - Toilets - Boys (8.05 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0045 - Toilets - Girls (7.99 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0046 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00A - R0047 - Personal Effects Storage (1.11 m2)</b>						
No Asbestos						
<b>B00A - R0048 - Distribution Board (0.62 m2)</b>						
						Note: No inspection of live electrical installation.
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0049 - Home Base (58.83 m2)</b>						
No Asbestos						
<b>B00A - R0050 - Withdrawal Space - 1hb (11.31 m2)</b>						
No Asbestos						
<b>B00A - R0051 - Home Base (58.69 m2)</b>						
No Asbestos						
<b>B00A - R0052 - Home Base Store (6.27 m2)</b>						
No Asbestos						
<b>B00A - R0053 - Security Store (18.88 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0054 - Plant (7.73 m2)</b>						
No Asbestos						
<b>B00A - R0055 - Movement (186.37 m2)</b>						
No Asbestos						
<b>B00A - R0056 - Interview (5.86 m2)</b>						
No Asbestos						
<b>B00A - R0057 - Staff Room Annexe (17.96 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0058 - Staff Toilet (2.08 m2)</b>						
No Asbestos						
<b>B00A - R0059 - General Storeroom (0.98 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0060 - Principal (18.23 m2)</b>						
No Asbestos						
<b>B00A - R0061 - Duplicating Workroom (25.09 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0062 - Clerical Office (16.61 m2)</b>						
No Asbestos						
<b>B00A - R0063 - Movement (40.2 m2)</b>						
No Asbestos						
<b>B00A - R0064 - Staff Room Annexe (12.32 m2)</b>						
No Asbestos						
<b>B00A - R0065 - Security Store (25.1 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0066 - Deputy Principal (16.28 m2)</b>						
No Asbestos						
<b>B00A - R0067 - Plant (8.85 m2)</b>						
No Asbestos						
<b>B00A - R0068 - Cleaning Distributed Store (2.85 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0069 - Distribution Board (1.87 m2)</b>						
						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00A - R0070 - Sick Bay (8.79 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0071 - Entry Vestibule (18.63 m2)</b>						
No Asbestos						
<b>B00A - R0072 - Movement (5.84 m2)</b>						
No Asbestos						
<b>B00A - R0073 - Clerical Office/Workroom (10.63 m2)</b>						
No Asbestos						
<b>B00A - R0074 - Security Store (4.78 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0075 - Staff Toilet (9.21 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0076 - Disabled Toilet (3.04 m2)</b>						
No Asbestos						
<b>B00A - R0077 - Staff Toilet (9.23 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - R0078 - Movement (11.18 m2)**

No Asbestos

**B00A - R0079 - Staff Room (87.27 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
		3392/B00A/R0079/Floor Coverings Res/Textile/S2				

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Library - 1980 - Brick/Block (Brick/Block)**

**Exterior**

Gable Verge Lining	Flat AC Sheeting 3392/B00F/Gable Verge Lining/S7					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Movement (66.29 m2)**

No Asbestos

**B00B - R0002 - Plant (7.81 m2)**

No Asbestos

**B00B - R0003 - Home Base Store (6.31 m2)**

No Asbestos

**B00B - R0004 - Security Store (18.92 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 3392/B00A/R0079/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00B - R0005 - Distribution Board (0.62 m2)**

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles 3392/B00A/R0079/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00B - R0006 - Practical Activities - 1hb (248.79 m2)**

No Asbestos

**B00B - R0007 - Movement (2.71 m2)**

No Asbestos

**B00B - R0008 - Cleaning Distributed Store (1.09 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 3392/B00A/R0079/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00B - R0009 - General Storeroom (3.01 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 3392/B00A/R0079/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00B - R0010 - Toilets - Boys (7.97 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

**B00B - R0011 - Toilets - Girls (7.94 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

**B00B - R0012 - Personal Effects Storage (1.11 m2)**

No Asbestos

**B00B - R0013 - Home Base (58.76 m2)**

No Asbestos

**B00B - R0014 - Withdrawal Space - 1hb (11.48 m2)**

No Asbestos

**B00B - R0015 - Home Base (58.29 m2)**

No Asbestos

**B00B - R0016 - Movement (42.48 m2)**

No Asbestos

**B00B - R0017 - Home Base Store (5.7 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00B - R0018 - Home Base Store (5.7 m2)</b>						
No Asbestos						
<b>B00B - R0019 - Staff Room Annexe (21.6 m2)</b>						
No Asbestos						
<b>B00B - R0020 - Home Base (58.25 m2)</b>						
No Asbestos						
<b>B00B - R0021 - Withdrawal Space - 1hb (11.32 m2)</b>						
No Asbestos						
<b>B00B - R0022 - Home Base (58.5 m2)</b>						
No Asbestos						
<b>B00B - R0023 - Plant (7.93 m2)</b>						
No Asbestos						
<b>B00B - R0024 - Movement (34.64 m2)</b>						
No Asbestos						
<b>B00B - R0025 - Plant (3.84 m2)</b>						
No Asbestos						
<b>B00B - R0026 - Home Base Store (6.44 m2)</b>						
No Asbestos						
<b>B00B - R0027 - General Storeroom (6.32 m2)</b>						
No Asbestos						
<b>B00B - R0028 - Special Programs Room (43.2 m2)</b>						
No Asbestos						
<b>B00B - R0029 - General Learning Space (58.83 m2)</b>						
No Asbestos						
<b>B00B - R0030 - Movement (2.78 m2)</b>						
No Asbestos						
<b>B00B - R0031 - Movement (2.97 m2)</b>						
No Asbestos						
<b>B00B - R0032 - Cleaning Distributed Store (1 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00B - R0033 - General Storeroom (2.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00B - R0034 - Toilets - Boys (8.02 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0035 - Toilets - Girls (7.94 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0036 - Movement (2.8 m2)</b>						
No Asbestos						
<b>B00B - R0037 - Personal Effects Storage (1.11 m2)</b>						
No Asbestos						
<b>B00B - R0038 - Kiln Room (0.73 m2)</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00B - R0039 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00B - R0040 - Cleaning Distributed Store (1.09 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00B - R0041 - General Storeroom (3.01 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00B - R0042 - Toilets - Boys (8.13 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0043 - Toilets - Girls (8.08 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0044 - Movement (2.66 m2)</b>						
No Asbestos						
<b>B00B - R0045 - Personal Effects Storage (1.11 m2)</b>						
No Asbestos						
<b>B00B - R0046 - Distribution Board (0.66 m2)</b>						
					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00B - R0047 - Withdrawal - M (11.53 m2)</b>						
No Asbestos						
<b>B00B - R0048 - Home Base - M (58.78 m2)</b>						
No Asbestos						
<b>B00B - R0049 - Staff Room Annexe (7.33 m2)</b>						
No Asbestos						
<b>B00B - R0050 - Home Base Store - M (6.31 m2)</b>						
No Asbestos						
<b>B00B - R0051 - Staff Toilet (5.48 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0052 - Staff Toilet (5.5 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0053 - Plant (7.68 m2)</b>						
No Asbestos						
<b>B00B - R0054 - Movement (203.45 m2)</b>						
No Asbestos						
<b>B00B - R0055 - Security Store (11.23 m2)</b>						
No Asbestos						
<b>B00B - R0058 - Distribution Board (2.14 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00B - R0059 - General Storeroom (4.39 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00B - R0060 - General Storeroom (2.09 m2)**

No Asbestos

**B00B - R0061 - K.L.A. Store (13.58 m2)**

No Asbestos

**B00B - R0062 - K.L.A. Store (13.53 m2)**

No Asbestos

**B00B - R0063 - Plant (19.77 m2)**

No Asbestos

**B00B - R0064 - Communications Room (8.9 m2)**

No Asbestos

**B00B - R0065 - Staff Kitchen (3.47 m2)**

No Asbestos

**B00B - R0066 - Staff Room (23.96 m2)**

No Asbestos

**B00B - R0067 - K.L.A. Store (18.96 m2)**

No Asbestos

**B00B - R0068 - Reading Area (230.77 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Communal Facilities/Pupil Facilities - 1981 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting 3392/B00F/Gable Verge Lining/S7					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00C - R0001 - Movement (139.96 m2)**

No Asbestos

**B00C - R0002 - Plant (6.72 m2)**

No Asbestos

**B00C - R0003 - No Access (26.57 m2)**

No Asbestos

**B00C - R0004 - Cleaning Distributed Store (1.62 m2)**

No Asbestos

**B00C - R0005 - Distribution Board (1.09 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0006 - Communal Space (280.33 m2)**

No Asbestos

**B00C - R0007 - Raised Platform (71.16 m2)**

No Asbestos

**B00C - R0008 - Hall Chair Store (18.05 m2)**

No Asbestos

**B00C - R0009 - Hall Chair Store (9.09 m2)**

No Asbestos

**B00C - R0010 - Plant (6.69 m2)**

No Asbestos

**B00C - R0011 - Movement (85.05 m2)**

No Asbestos

**B00C - R0012 - Shower/Change (31.5 m2)**

No Asbestos

**B00C - R0013 - Movement (7.37 m2)**

No Asbestos

**B00C - R0014 - Staff Shower/Change (7.83 m2)**

No Asbestos

**B00C - R0015 - Plant (1.17 m2)**

Flue Pipe	AC Pipe	1m	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00C/R0015/Flue Pipe/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0016 - Toilets - Boys (21.15 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>

**B00C - R0017 - Canteen (42.78 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00C - R0018 - Canteen Office/Store (3.22 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

Floor Coverings  
Res/Textile

Vinyl Tiles

3392/B00A/R0079/Floor Coverings Res/Textile/S2

**No Asbestos Detected**

**B00C - R0019 - Staff Toilet (3.18 m2)**

No Asbestos

**B00C - R0020 - Plant (1.12 m2)**

No Asbestos

**B00C - R0021 - Toilets - Girls (17.64 m2)**

No Asbestos

**B00C - R0022 - Movement (5.2 m2)**

No Asbestos

**B00C - R0023 - Staff Shower/Change (7.48 m2)**

No Asbestos

**B00C - R0024 - No Access (1.09 m2)**

No Asbestos

**B00C - R0025 - Shower/Change (31.39 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Science Learning - 1980 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00D - R0001 - Cleaning Supplies (14.71 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00D - R0002 - Staff Toilet (4.2 m2)**

No Asbestos

**B00D - R0003 - Staff Toilet (4.2 m2)**

No Asbestos

**B00D - R0004 - General Assistant/Bulk Store (7.37 m2)**

No Asbestos

**B00D - R0005 - Distribution Board (2.8 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0006 - Security Store (54.32 m2)**

No Asbestos

**B00D - R0007 - Laboratory L.S. (96.12 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00D - R0008 - Preparation (57.42 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00D - R0009 - Laboratory L.S. (96.52 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00D - R0010 - Darkroom Space (18.49 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00D - R0011 - Cleaning Distributed Store (1.85 m2)**

No Asbestos

**B00D - R0012 - Plant (11.23 m2)**

No Asbestos

**B00D - R0013 - Movement (178.78 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Technological & Applied Studies - 1980 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting 3392/B00F/Gable Verge Lining/S7					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00E - R0001 - Music Learning Space (96.31 m2)**

No Asbestos

**B00E - R0002 - Distribution Board (2.14 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0003 - Cleaning Distributed Store (1.72 m2)**

No Asbestos

**B00E - R0004 - Resource/Project Store (18.39 m2)**

No Asbestos

**B00E - R0005 - Security Store (15.47 m2)**

No Asbestos

**B00E - R0006 - Plant (9.93 m2)**

No Asbestos

**B00E - R0007 - T.A.S. Outdoor Area (19.32 m2)**

No Asbestos

**B00E - R0008 - Plant (8.7 m2)**

No Asbestos

**B00E - R0009 - Materials Technology L.S. (79.83 m2)**

No Asbestos

**B00E - R0010 - Materials Technology L.S. (36.52 m2)**

No Asbestos

**B00E - R0011 - Metal Technology Bay (11.98 m2)**

No Asbestos

**B00E - R0012 - Welding Area (5.17 m2)**

No Asbestos

**B00E - R0013 - Materials Technology L.S. (63.97 m2)**

No Asbestos

**B00E - R0014 - T.A.S. Outdoor Area (20.79 m2)**

No Asbestos

**B00E - R0015 - Materials Store (33.1 m2)**

No Asbestos

**B00E - R0016 - Staff Room Annexe (23.35 m2)**

No Asbestos

**B00E - R0017 - Resources Store (21.15 m2)**

No Asbestos

**B00E - R0018 - Distribution Board (1.5 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0019 - Art Learning Space (51.13 m2)**

No Asbestos

**B00E - R0020 - Plant (12.53 m2)**

No Asbestos

**B00E - R0021 - Art Learning Space (56.44 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00E - R0022 - Kiln Room (6.4 m2)</b>						
No Asbestos						
<b>B00E - R0023 - Art Learning Space (50.7 m2)</b>						
No Asbestos						
<b>B00E - R0024 - Cleaning Distributed Store (1.75 m2)</b>						
No Asbestos						
<b>B00E - R0025 - Security Store (5.04 m2)</b>						
No Asbestos						
<b>B00E - R0026 - General Learning Space (33.5 m2)</b>						
No Asbestos						
<b>B00E - R0027 - Cleaning Distributed Store (1.62 m2)</b>						
No Asbestos						
<b>B00E - R0028 - General Learning Space (51.26 m2)</b>						
No Asbestos						
<b>B00E - R0029 - Plant (9.92 m2)</b>						
No Asbestos						
<b>B00E - R0030 - General Learning Space (51.19 m2)</b>						
No Asbestos						
<b>B00E - R0031 - Plant (1.57 m2)</b>						
No Asbestos						
<b>B00E - R0032 - Security Store (4.97 m2)</b>						
No Asbestos						
<b>B00E - R0033 - General Learning Space (33.58 m2)</b>						
No Asbestos						
<b>B00E - R0034 - Cleaning Distributed Store (1.68 m2)</b>						
No Asbestos						
<b>B00E - R0035 - General Learning Space (51.12 m2)</b>						
No Asbestos						
<b>B00E - R0036 - Plant (9.82 m2)</b>						
No Asbestos						
<b>B00E - R0037 - General Learning Space (51.19 m2)</b>						
No Asbestos						
<b>B00E - R0038 - Distribution Board (1.67 m2)</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00E - R0039 - Staff Toilet (3.46 m2)</b>						
No Asbestos						
<b>B00E - R0040 - Staff Toilet (3.42 m2)</b>						
No Asbestos						
<b>B00E - R0041 - General Learning Space (31.9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00E - R0042 - Toilets - Boys (13.36 m2)</b>						
No Asbestos						
<b>B00E - R0043 - Toilets - Girls (13.11 m2)</b>						
No Asbestos						
<b>B00E - R0044 - Movement (357.9 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - R0045 - Art Outdoor Area (51.62 m2)

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Senior Learning - 1992 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting 3392/B00F/Gable Verge Lining/S7					No Asbestos Detected
Gable Ends	Flat AC Sheeting 3392/B00F/Gable Ends/S9					No Asbestos Detected
Underfloor Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - Seminar/Study (52.47 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0002 - Design L.S. (75.06 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0003 - Food/Research Space (114.56 m2)**

No Asbestos

**B00F - R0004 - Pantry (22.91 m2)**

No Asbestos

**B00F - R0006 - Laundry (6.52 m2)**

No Asbestos

**B00F - R0008 - Distribution Board (0.42 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0009 - Staff Room Annexe (31.2 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0010 - Security Store (32.72 m2)**

No Asbestos

**B00F - R0011 - Laboratory L.S. (92.09 m2)**

No Asbestos

**B00F - R0012 - General Learning Space (48.7 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0013 - General Learning Space (48.7 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0014 - General Learning Space (48.79 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0015 - General Storeroom (31.66 m2)**

No Asbestos

**B00F - R0016 - Movement (11.12 m2)**

No Asbestos

**B00F - R0017 - Cleaning Distributed Store (6.14 m2)**

No Asbestos

**B00F - R0018 - Main Switch Board (10.56 m2)**

No Asbestos

**B00F - R0019 - General Learning Space (64.24 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0020 - General Learning Space (64.31 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0021 - Staff Room (67.97 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0022 - Interview (13.67 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0023 - Interview (13.63 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0024 - Cleaning Distributed Store (8.84 m2)</b>						
No Asbestos						
<b>B00F - R0025 - Staff Toilet (6.16 m2)</b>						
No Asbestos						
<b>B00F - R0026 - Staff Toilet (6.16 m2)</b>						
No Asbestos						
<b>B00F - R0027 - General Storeroom (20.33 m2)</b>						
No Asbestos						
<b>B00F - R0028 - General Storeroom (20.29 m2)</b>						
No Asbestos						
<b>B00F - R0029 - Staff Room Annexe (43.73 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0030 - Movement (2.03 m2)</b>						
No Asbestos						
<b>B00F - R0031 - Movement (185.36 m2)</b>						
No Asbestos						
<b>B00F - R0032 - Pantry (12.74 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Senior Learning - 1969 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	5m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00G/Gable Verge Lining/S8					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00G/Eaves Linings/S6					<b>Chrysotile (white asbestos)</b>

**Interior****B00G - R0001 - Computer Learning Space (52.41 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00G - R0002 - Computer Store (6.07 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00G - R0003 - Personal Effects Storage (12.63 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00G - R0004 - Other-Vacant (6.12 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00G - R0005 - Seminar/Study (52.27 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00G - R0006 - General Storeroom (8.21 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00G - R0007 - General Storeroom (8.12 m2)**

Ceiling Structures/Linings	Vermiculite					
	3392/B00G/R0007/Ceiling Structures/Linings/S5					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	3392/B00A/R0079/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00G - R0008 - Senior Seminar (54.02 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite		3392/B00G/R0007/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0009 - Special Learning Space (31.58 m2)</b>						
Ceiling Structures/Linings	Vermiculite		3392/B00G/R0007/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0010 - Distribution Board (0.89 m2)</b>					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite		3392/B00G/R0007/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0011 - Movement (61.5 m2)</b>						
No Asbestos						
Ceiling Void	Non Accessible Area - No Access - No manhole in building					
Underfloor Voids	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Agricultural Science - 1968 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Corrugated AC Sheeting 3392/B00H/Wall Cladding/S3					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior****B00H - R0001 - General Storeroom (9.44 m2)**

Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00H/R0001/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>

**B00H - R0002 - Garden Store (40.45 m2)**

Wall Linings Internal	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00H/R0001/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>

**B00H - R0003 - Movement (16.12 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00H/R0003/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

**B00H - R0004 - Plant Space (7.94 m2)**

Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00H/R0001/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3392/B00H/R0003/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Building Services - 1968 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior**

**B001 - R0001 - Cleaning Supplies (13.69 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Agricultural Science - 1968 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00J - R0001 - Garden Store (13.23 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Science Learning - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00K - R0001 - General Learning Space - Type 10 (59.94 m2)**

No Asbestos

**B00K - R0002 - Science Laboratory (60.09 m2)**

No Asbestos

**B00K - R0003 - Preparation (30.29 m2)**

No Asbestos

**B00K - R0004 - Staff Room (21.07 m2)**

No Asbestos

**B00K - R0005 - Seminar - Type 2 (21.07 m2)**

No Asbestos

**B00K - R0006 - Chemical Store (12.2 m2)**

No Asbestos

**B00K - R0007 - Apparatus Storage (13.93 m2)**

No Asbestos

**B00K - R0008 - Movement (6.14 m2)**

No Asbestos

**B00K - R0009 - Main Switch Board (0.59 m2)**

No Asbestos

**B00K - R0010 - Outdoor Learning Space - Type 4 (41.27 m2)**

No Asbestos

**B00K - R0011 - External Movement (43.51 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00L - R0001 - Sport Equipment Store (16.19 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017