


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wattle Flat Public School (3402)  
**Region :** Western NSW  
**State Electorate :** Bathurst  
**Local Government Area :** Bathurst

**Initial Survey :** Noel Arnold & Associates : 21 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Communal Facilities - 1883 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00A - R0001 - Communal Space**

No Asbestos

**B00A - R0002 - External Movement**

No Asbestos

**B00A - R0003 - Staff Room**

No Asbestos

**B00A - R0004 - Practical Activities - 1hb**

No Asbestos

**B00A - R0005 - Canteen Covered Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library/Administration - 1960 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0001 - Clerical Office**

No Asbestos

**B00B - R0002 - Reading Area**

No Asbestos

**B00B - R0003 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - Home Base Store**

No Asbestos

**B00C - R0003 - Practical Activities**

No Asbestos

**B00C - R0004 - External Movement**

No Asbestos

**B00C - R0005 - Ramp**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Storage - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Building Services - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Building Services - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 842 - D10413 - Country Toilet - Relta - Boys/Girls : Placement Date - 25/02/1999**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Toilets-Girls**

No Asbestos Found.

**R2 - Staff Toilet**

No Asbestos Found.

**R3 - Toilets-Boys**

No Asbestos Found.

**R4 - Staff Toilet**

No Asbestos Found.

**OS 603 - D12267 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 22/03/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017