

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Weethalle Public School (3415)
Region : Riverina
State Electorate : Cootamundra
Local Government Area : Bland

Initial Survey : Noel Arnold & Associates : 07 - May - 2008
Reviewed By : Greencap-NAA : 15 - Jun - 2016



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Library/General Learning - 1929 - Timber (Timber)

Exterior

| | | | | | | |
|---|---|----------|-------------|--------------------|---------|-----------------------------|
| Eaves Linings | Flat AC Sheeting 3415/B00A/Eaves Linings/S3 | | | | | No Asbestos Detected |
| Electrical mounting board | Resinous Board | 1Unit(s) | East facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
| Assumed Asbestos - Electrical Hazard | | | | | | |
| Ceiling Voids | Non Accessible Area - Height Restriction 4m height | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0005 - Library Office/Workroom

No Asbestos

B00A - R0006 - K.L.A. Store

| | | | | | | |
|--------------------------------|---|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles 3415/B00A/R0006/Floor Coverings Res/Textile/S1 | | | | | No Asbestos Detected |
|--------------------------------|---|--|--|--|--|-----------------------------|

B00A - R0007 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Reading Area

No Asbestos

B00A - R0013 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Administration/General Learning - 1926 - Timber (Timber)

Exterior

| | | | | | | |
|---------------------------|---|----------|---|--------------------|------------------------------------|--------------------|
| Eaves Linings | Flat AC Sheeting | 25m2 | North facing, South facing, East facing, West facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00B/R0001/Ceiling Structures/Linings/S2 | | | | Chrysotile (white asbestos) | |
| Electrical mounting board | Resinous Board | 1Unit(s) | East facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | Assumed Asbestos - Electrical Hazard | | | | | |
| Ceiling Voids | Non Accessible Area - Height Restriction 4m height | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00B - R0001 - Staff Room

| | | | | | | |
|----------------------------|---|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00B/R0001/Ceiling Structures/Linings/S2 | | | | Chrysotile (white asbestos) | |

B00B - R0004 - General Storeroom

No Asbestos

B00B - R0005 - Home Base Store

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - External Movement

| | | | | | | |
|----------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 23m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00B/R0001/Ceiling Structures/Linings/S2 | | | | Chrysotile (white asbestos) | |

B00B - R0009 - Clerical Office/Workroom

No Asbestos

B00B - R0010 - Staff Kitchen

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - Pupil Facilities - 1950 - Timber (Timber)

Exterior

| | |
|---------------------------|--|
| Ceiling Voids - Flat Roof | Non Accessible Area - Area inaccessible |
| Underfloor Voids | No Asbestos Found |

Interior

B00C - R0002 - Sports Store

No Asbestos

B00C - R0003 - General Assistant/Bulk Store

No Asbestos

B00C - R0004 - Canteen

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - Pupil Facilities/Staff Facilities - 1926 - Brick/Block (Brick/Block)

Exterior

| | | | | | | |
|-----------------------------------|--|------|---|--------------------|---------|------------------------------------|
| Underfloor Voids - Slab on Ground | Non Accessible Area - Area inaccessible | | | | | |
| Ceiling Voids - Flat Roof | Non Accessible Area - Area inaccessible | | | | | |
| Eaves Linings | Flat AC Sheeting | 20m2 | North facing, South facing, East facing, West facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00D/Eaves Linings/S4 | | | | | Chrysotile (white asbestos) |

Interior

B00D - R0001 - Staff Toilet

| | | | | | | |
|-------------|--|----------|--------------|----------------------|---------|--------------------|
| Incinerator | Encapsulated Insulation material within unit | 1Unit(s) | South facing | Friable Asbestos (5) | Low (1) | Low Priority (2-3) |
| | Assumed Asbestos - Area inaccessible | | | | | |

B00D - R0002 - Toilets - Girls

| | | | | | | |
|----------------------------|---|----------|------------|----------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 18m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00D/R0005/Ceiling Structures/Linings/S5 | | | | | Chrysotile (white asbestos) |
| Incinerator | Encapsulated Insulation material within unit | 1Unit(s) | North | Friable Asbestos (5) | Low (1) | Low Priority (2-3) |
| | Assumed Asbestos - item inaccessible | | | | | |

B00D - R0003 - Toilets - Boys

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 20m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00D/R0005/Ceiling Structures/Linings/S5 | | | | | Chrysotile (white asbestos) |

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Cleaning Supplies

| | | | | | | |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3415/B00D/R0005/Ceiling Structures/Linings/S5 | | | | | Chrysotile (white asbestos) |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - Pupil Facilities/Staff Facilities - 1926 - Timber (Timber)

Exterior

| | |
|-----------------------------------|--|
| Underfloor Voids - Slab on Ground | Non Accessible Area - Area inaccessible |
|-----------------------------------|--|

| | |
|---------------|-------------------|
| Ceiling Voids | No Asbestos Found |
|---------------|-------------------|

Interior

B00E - R0001 - Drinking Facilities

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - Building Services - 2007 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - Residential Facilities - 1960 - Timber (Timber)

Exterior

| | |
|-----------------|---------------------|
| Ceiling Void | Requires Inspection |
| Underfloor Void | Requires Inspection |

Interior

B00G - R0001 - Residence - Movement

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0002 - Residence - Movement

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0003 - Residence - Bedroom

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0004 - Residence - Bedroom

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0005 - Residence - Movement

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0006 - Residence - Dining

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0007 - Residence - Lounge

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0008 - Residence - Kitchen

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0009 - Residence - Pantry

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0010 - Residence - Bathroom

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0011 - Residence - Bedroom

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0012 - Residence - Movement

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0013 - Residence - Laundry

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

B00G - R0014 - Residence - Toilet

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B0G1 - Residential Facilities - 1970 - Metal Shed (Metal Shed)

Exterior

| | |
|-----------------|---------------------|
| Ceiling Void | Requires Inspection |
| Underfloor Void | Requires Inspection |

Interior

B0G1 - R0001 - Residence - Garage

| | |
|-------------------------|---------------------|
| Recently Modified Space | Requires Inspection |
|-------------------------|---------------------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 837 - D16034 - Hcap Shower/Change/Toilet : Placement Date - 5/09/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017