


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wellington Public School (3420)  
**Region :** Western NSW  
**State Electorate :** Dubbo  
**Local Government Area :** Wellington

**Initial Survey :** Noel Arnold & Associates : 19 - Mar - 2008  
**Reviewed By :** : 24 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1881 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids	Non Accessible Area - Area inaccessible
Ceiling Voids	Non Accessible Area - Height Restriction

**Interior**

**B00A - R0001 - Home Base (57.35 m2)**

No Asbestos

**B00A - R0002 - Movement (11.3 m2)**

No Asbestos

**B00A - R0003 - Movement (46.96 m2)**

No Asbestos

**B00A - R0004 - General Storeroom (11.81 m2)**

No Asbestos

**B00A - R0005 - Home Base (75.52 m2)**

No Asbestos

**B00A - R0006 - Practical Activities - 1hb (20.16 m2)**

No Asbestos

**B00A - R0007 - Home Base Store (6.32 m2)**

No Asbestos

**B00A - R0008 - General Storeroom (15.57 m2)**

No Asbestos

**B00A - R0009 - Home Base Store (7.8 m2)**

No Asbestos

**B00A - R0010 - Practical Activities - 1hb (21.46 m2)**

No Asbestos

**B00A - R0011 - Home Base (65.32 m2)**

No Asbestos

**B00A - R0012 - General Storeroom (19.56 m2)**

No Asbestos

**B00A - R0013 - Interview (11.01 m2)**

No Asbestos

**B00A - R0014 - Distribution Board (0.39 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0015 - Movement (34.66 m2)**

No Asbestos

**B00A - R0016 - Practical Activities - 1hb (29.61 m2)**

No Asbestos

**B00A - R0017 - Security Store (7.5 m2)**

No Asbestos

**B00A - R0018 - Clerical Office/Workroom (50.5 m2)**

No Asbestos

**B00A - R0019 - Home Base (95.94 m2)**

No Asbestos

**B00A - R0020 - General Storeroom (11.12 m2)**

No Asbestos

**B00A - R0021 - Movement (13.67 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R0022 - Withdrawal Space - 1hb (20.08 m2)**

No Asbestos

**B00A - R0023 - Toilets - Boys (2.76 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2.76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00A/R0024/Ceiling Structures/Linings/S17					<b>Chrysotile (white asbestos)</b>	

**B00A - R0024 - Toilets - Girls (2.74 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2.74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00A/R0024/Ceiling Structures/Linings/S17					<b>Chrysotile (white asbestos)</b>	

**B00A - R0025 - Movement (11.71 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00A/R0025/Ceiling Structures/Linings/S18					<b>Chrysotile (white asbestos)</b>	

**B00A - R0026 - Movement (41.12 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00A/R0025/Ceiling Structures/Linings/S18					<b>Chrysotile (white asbestos)</b>	

**B00A - R0027 - Drinking Facilities (10.19 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - Pupil Facilities - 1965 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/Eaves Linings/S19					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground						
Gable Verge Lining	Non Accessible Area - Height Restriction					
Ceiling Voids	No Asbestos Found					

**Interior****B00B - R0001 - Toilets - Boys (22.66 m2)**

Wall Linings Internal	Flat AC Sheeting	40m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Partition Walls (Cubicles)/S10					<b>Chrysotile (white asbestos)</b>

**B00B - R0002 - Toilets - Girls (22.34 m2)**

Wall Linings Internal	Flat AC Sheeting	40m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Partition Walls (Cubicles)/S10					<b>Chrysotile (white asbestos)</b>

**B00B - R0003 - Movement (104.94 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	105m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0003/Ceiling Structures/Linings/S20					<b>Chrysotile (white asbestos)</b>

**B00B - R0004 - Canteen (36.32 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>

**B00B - R0005 - Staff Toilet (5.02 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0001/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>

**B00B - R0006 - No Access (5.47 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00B/R0003/Ceiling Structures/Linings/S20					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Support Unit - 1971 - Brick/Veneer (Brick/Veneer)****Exterior**

Gable Verge Lining	Non Accessible Area - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					
infill pannels under windows	Compressed AC Sheet 3420/B00C/infill pannels under windows/S23	44Unit	north/south	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**Interior****B00C - R0001 - Home Base Store (3.14 m2)**

No Asbestos

**B00C - R0002 - Personal Effects Storage (6.32 m2)**

No Asbestos

**B00C - R0003 - Home Base (86.51 m2)**

No Asbestos

**B00C - R0004 - Toilets - Boys/Girls (3.83 m2)**

No Asbestos

**B00C - R0005 - Toilets - Girls (26.98 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3420/B00C/R0020/Ceiling Structures/Linings/S22	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	------	--------------	--------------------	---------	--

Partition Walls (Cubicles)	Compressed AC Sheet 3420/B00C/R0011/Partition Walls (Cubicles)/S8	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	------	--------------	--------------------	---------	--

**B00C - R0006 - Home Base (86.67 m2)**

No Asbestos

**B00C - R0007 - Personal Effects Storage (6.25 m2)**

No Asbestos

**B00C - R0008 - Home Base Store (3.1 m2)**

No Asbestos

**B00C - R0009 - Toilets - Boys/Girls (3.75 m2)**

No Asbestos

**B00C - R0010 - Distribution Board (1.4 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 3420/B00C/R0010/Ceiling Structures/Linings/S21	1.4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	-------	------------	--------------------	---------	--

Electrical Backing Board	Non Accessible Area - Electrical Hazard					
--------------------------	--	--	--	--	--	--

**B00C - R0011 - Toilets - Boys (26.06 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 3420/B00C/R0020/Ceiling Structures/Linings/S22	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	------	--------------	--------------------	---------	--

Partition Walls (Cubicles)	Compressed AC Sheet 3420/B00C/R0011/Partition Walls (Cubicles)/S8	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	-----	--------------	--------------------	---------	--

**B00C - R0015 - Home Base - M (72.03 m2)**

No Asbestos

**B00C - R0016 - Home Base (86.03 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0017 - Toilets - Boys/Girls (3.79 m2)</b>						
No Asbestos						
<b>B00C - R0018 - Home Base Store (3.1 m2)</b>						
No Asbestos						
<b>B00C - R0019 - Personal Effects Storage (6.23 m2)</b>						
No Asbestos						
<b>B00C - R0020 - Movement (57.23 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00C/R0020/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R0021 - Movement (60.08 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	57m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00C/R0020/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R0022 - Toilet - M (5.72 m2)</b>						
No Asbestos						
<b>B00C - R0023 - Laundry - Type 2 (6.48 m2)</b>						
No Asbestos						
<b>B00C - R0024 - Sports Store (10.58 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
3420/B00C/R0024/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1914 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids	Non Accessible Area - Area inaccessible
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction

**Interior****B00E - R0001 - Home Base (47.68 m2)**

No Asbestos

**B00E - R0002 - Home Base (47.71 m2)**

No Asbestos

**B00E - R0003 - Home Base (47.54 m2)**

No Asbestos

**B00E - R0004 - Home Base (52.3 m2)**

No Asbestos

**B00E - R0005 - Home Base (47.07 m2)**

No Asbestos

**B00E - R0006 - Home Base (47.21 m2)**

No Asbestos

**B00E - R0007 - Movement (2.25 m2)**

No Asbestos

**B00E - R0008 - Movement (18.97 m2)**

Floor Coverings Res/Textile	Vinyl Sheet
3420/B00E/R0008/Floor Coverings Res/Textile/S11	

**No Asbestos Detected****B00E - R0009 - Movement (2.24 m2)**

No Asbestos

**B00E - R0010 - Staff Room Annexe (8.52 m2)**

No Asbestos

**B00E - R0011 - General Storeroom (19.35 m2)**

Floor Coverings Res/Textile	Vinyl Sheet
3420/B00E/R0008/Floor Coverings Res/Textile/S11	

**No Asbestos Detected****B00E - R0012 - Withdrawal Space - 1hb (19.35 m2)**

No Asbestos

**B00E - R0013 - Movement (137.13 m2)**

No Asbestos

**B00E - R0014 - Practical Activities - 1hb (12.96 m2)**

Floor Coverings Res/Textile	Vinyl Sheet
3420/B00E/R0008/Floor Coverings Res/Textile/S11	

**No Asbestos Detected****B00E - R0015 - Movement (1.51 m2)**

No Asbestos

**B00E - R0016 - Movement (1.66 m2)**

No Asbestos

**B00E - R0018 - Movement (8.4 m2)**

Floor Coverings Res/Textile	Vinyl Sheet
3420/B00E/R0008/Floor Coverings Res/Textile/S11	

**No Asbestos Detected****B00E - R0019 - Movement (8.51 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings  
Res/Textile

Vinyl Sheet

3420/B00E/R0008/Floor Coverings Res/Textile/S11

**No Asbestos Detected**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1925 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids	Non Accessible Area - Area inaccessible
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction

**Interior****B00F - R0001 - Special Programs Room (46.43 m2)**

No Asbestos

**B00F - R0002 - Movement (16.25 m2)**

No Asbestos

**B00F - R0003 - Home Base (52.66 m2)**

No Asbestos

**B00F - R0004 - Interview (24.94 m2)**

Floor Coverings Res/Textile	Vinyl Sheet 3420/B00E/R0008/Floor Coverings Res/Textile/S11	<b>No Asbestos Detected</b>
membrane pad under sink	Resinous Membrane 3420/B00F/R0004/membrane pad under sink/S12	<b>No Asbestos Detected</b>

**B00F - R0005 - Movement (10.25 m2)**

No Asbestos

**B00F - R0006 - Movement (158.1 m2)**

No Asbestos

**B00F - R0007 - Movement (43.56 m2)**

No Asbestos

**B00F - R0008 - Home Base (51.37 m2)**

No Asbestos

**B00F - R0009 - Home Base (51.5 m2)**

No Asbestos

**B00F - R0010 - Practical Activities - 1hb (10.31 m2)**

Floor Coverings Res/Textile	Vinyl Sheet 3420/B00E/R0008/Floor Coverings Res/Textile/S11	<b>No Asbestos Detected</b>
-----------------------------	--	-----------------------------

**B00F - R0011 - Withdrawal Space - 1hb (24.78 m2)**

No Asbestos

**B00F - R0012 - Home Base (52.35 m2)**

No Asbestos

**B00F - R0013 - Special Programs Room (46.35 m2)**

No Asbestos

**B00F - R0014 - Movement (16.5 m2)**

Floor Coverings Res/Textile	Vinyl Sheet 3420/B00E/R0008/Floor Coverings Res/Textile/S11	<b>No Asbestos Detected</b>
-----------------------------	--	-----------------------------

**B00F - R0015 - Movement (7.34 m2)**

No Asbestos

**B00F - R0016 - Movement (4.98 m2)**

No Asbestos

**B00F - R0017 - Sports Store (12.09 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - R0018 - Cleaning Distributed Store (2.79 m2)**

No Asbestos

**B00F - R0019 - Cleaning Supplies (8.33 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Administration/Library - 1971 - Brick/Block (Brick/Block)****Exterior**

Infill panels	Compressed AC Sheet	36Unit(s)	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/Infill panels/S13					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground						
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R1011/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00G - R0001 - Resource/Toy Space (59.36 m2)**

Ceiling Structures/Linings	Vermiculite					
	3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00G - R0003 - Movement (14.07 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00G - R0004 - Staff Room (59.36 m2)**

Ceiling Structures/Linings	Vermiculite					
	3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00G - R0006 - Staff Room Annexe (36.86 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00G - R0007 - Clerical Office/Workroom (25.55 m2)**

Ceiling Structures/Linings	Vermiculite					
	3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00G - R0008 - Security Store (13.27 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0009 - Deputy Principal (13.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3420/B00G/R0015/Floor Coverings Res/Textile/S1	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0010 - Deputy Principal (10.21 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3420/B00G/R0015/Floor Coverings Res/Textile/S1	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0011 - General Storeroom (1.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3420/B00G/R0015/Floor Coverings Res/Textile/S1	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0012 - Staff Toilet (3.36 m2)</b>						
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0013 - Principal (16.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3420/B00G/R0015/Floor Coverings Res/Textile/S1	16.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00G - R0014 - Movement (6.49 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3420/B00G/R0015/Floor Coverings Res/Textile/S1	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0015 - Entry Vestibule (17.83 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 3420/B00G/R0015/Floor Coverings Res/Textile/S1	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0016 - Staff Toilet (2.21 m2)</b>						
Ceiling Structures/Linings	Vermiculite 3420/B00G/R0015/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00G - R0017 - Sick Bay (8.8 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00G - R0018 - Movement (8.07 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00G - R0019 - Staff Toilet (5.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00G - R0020 - Distribution Board (0.44 m2)</b>						
Note: No inspection of live electrical installation.						
Door backing sheet	Flat AC Sheeting	2Unit(s)	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00G/R0020/Door backing sheet/S3					<b>Chrysotile (white asbestos)</b>	
Electrical Mounting Board	Non Accessible Area - Electrical Hazard					
<b>B00G - R0021 - Staff Toilet (4.49 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00G - R0022 - Cleaning Distributed Store (1.5 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
3420/B00G/R0015/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00G - R0023 - Movement (70.47 m2)</b>						
No Asbestos						
<b>B00G - R0024 - Stairs (7.13 m2)</b>						
No Asbestos						
<b>B00G - R0025 - Clerical Office (11.36 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3420/B00G/R0015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00G - R1001 - Reading Area (212.52 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					<b>No Asbestos Detected</b>
3420/B00G/R1001/Floor Coverings Res/Textile/S14						
<b>B00G - R1002 - Withdrawal Space - 2hb (53.05 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					<b>No Asbestos Detected</b>
3420/B00G/R1001/Floor Coverings Res/Textile/S14						
<b>B00G - R1003 - Communications Room (6.07 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					<b>No Asbestos Detected</b>
3420/B00G/R1001/Floor Coverings Res/Textile/S14						
<b>B00G - R1004 - Library Office/Workroom (19.22 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					<b>No Asbestos Detected</b>
3420/B00G/R1001/Floor Coverings Res/Textile/S14						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R1005 - Library Office/Workroom (13.08 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3420/B00G/R1001/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>
<b>B00G - R1006 - K.L.A. Store (12.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3420/B00G/R1001/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>
<b>B00G - R1007 - Toilets - Boys (5.45 m2)</b>						
No Asbestos						
<b>B00G - R1008 - Cleaning Distributed Store (1.53 m2)</b>						
No Asbestos						
<b>B00G - R1009 - Distribution Board (0.54 m2)</b>				Note: No inspection of live electrical installation.		
Door backing sheet	Flat AC Sheeting	2Unit(s)	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R0020/Door backing sheet/S3					<b>Chrysotile (white asbestos)</b>
Electrical Mounting Board	Non Accessible Area - Electrical Hazard					
<b>B00G - R1010 - Toilets - Girls (4.69 m2)</b>						
No Asbestos						
<b>B00G - R1011 - Movement (18.23 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R1011/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00G - R1012 - Stairs (9.11 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00G/R1011/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Special Purpose - 1980 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

**Interior**

**B00K - R0001 - Kiln Room (3.96 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00L - R0001 - Practical Activities - 1hb (20.09 m2)**

No Asbestos

**B00L - R0002 - Home Base Store (7.34 m2)**

No Asbestos

**B00L - R0003 - Home Base (58.11 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0004 - Withdrawal Space - 2hb (11.48 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0005 - Home Base (57.89 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0006 - Home Base Store (8 m2)**

No Asbestos

**B00L - R0007 - Practical Activities - 1hb (20.03 m2)**

No Asbestos

**B00L - R0008 - Distribution Board (0.55 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R0009 - Movement (2.43 m2)**

No Asbestos

**B00L - R0010 - Movement (38.37 m2)**

No Asbestos

**B00L - R0011 - Movement (2.38 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Building Services - 1990 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00M - R0001 - Sports Store (48.56 m2)**

No Asbestos

**B00M - R0002 - General Assistant/Bulk Store (23.9 m2)**

No Asbestos

**B00M - R0003 - Staff Toilet (1.67 m2)**

No Asbestos

**B00M - R0004 - No Access (13.82 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00N - R0001 - Movement (2.23 m2)**

No Asbestos

**B00N - R0002 - Entry Vestibule (13.9 m2)**

No Asbestos

**B00N - R0003 - Security Store (8.6 m2)**

No Asbestos

**B00N - R0004 - General Storeroom - Pre (12.4 m2)**

No Asbestos

**B00N - R0005 - Home Base - Pre (69 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00N - R0006 - Practical Activities - Pre (46.36 m2)**

No Asbestos

**B00N - R0007 - Toilets - Boys/Girls - Pre (12.81 m2)**

No Asbestos

**B00N - R0008 - Laundry - Pre (4.54 m2)**

No Asbestos

**B00N - R0009 - Access Shower/Toilet - Type 2 (5.56 m2)**

No Asbestos

**B00N - R0010 - Cleaning Distributed Store (3.54 m2)**

No Asbestos

**B00N - R0011 - Kitchen - Pre (12.91 m2)**

No Asbestos

**B00N - R0012 - Clerical Office - Pre (12.44 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00N - R0013 - Clerical Office - Pre (8.66 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00N - R0014 - General Storeroom - Pre (20.56 m2)**

No Asbestos

**B00N - R0015 - Movement (69.38 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Other - 2007 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids                      Non Accessible Area  
 - Building is shed - no ceiling voids detected at time of inspection.

Underfloor Voids - Slab on Ground

Ceiling Voids                      Non Accessible Area  
 - Height Restriction - Building is shed - no ceiling voids detected at time of inspection.

**Interior**

**B00P - R0001 - General Assistant/Bulk Store (8.93 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	Non Accessible Area - Non Accessible Area
Underfloor Voids	Non Accessible Area - Height Restriction

**Interior**

**B00Q - R0001 - Practical Activities (19.56 m2)**

No Asbestos

**B00Q - R0002 - Home Base (58.73 m2)**

No Asbestos

**B00Q - R0003 - Home Base Store (5.64 m2)**

No Asbestos

**B00Q - R0004 - Withdrawal Space - 2hb (10.72 m2)**

No Asbestos

**B00Q - R0005 - Home Base (58.72 m2)**

No Asbestos

**B00Q - R0006 - Practical Activities (19.56 m2)**

No Asbestos

**B00Q - R0007 - Home Base Store (5.64 m2)**

No Asbestos

**B00Q - R0008 - External Movement (38.44 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00R - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

**Interior**

**B00R - R0001 - Access Shower/Toilet/Change (6.88 m2)**

No Asbestos

**B00R - R0002 - Main Switch Board (3.24 m2)**

No Asbestos

**B00R - R0003 - Cleaning Distributed Store (3.51 m2)**

No Asbestos

**B00R - R0004 - Other (1.6 m2)**

No Asbestos

**B00R - R0005 - Movement (3.31 m2)**

No Asbestos

**B00R - R0006 - Toilets - Boys (5.71 m2)**

No Asbestos

**B00R - R0007 - Sound Cupboard (2.06 m2)**

No Asbestos

**B00R - R0008 - Toilets - Girls (7.32 m2)**

No Asbestos

**B00R - R0009 - Movement (2.37 m2)**

No Asbestos

**B00R - R0010 - P.E. Store (12.85 m2)**

No Asbestos

**B00R - R0011 - Communal/Performance Store (9.6 m2)**

No Asbestos

**B00R - R0012 - Hall Chair Store (9.6 m2)**

No Asbestos

**B00R - R0013 - Communal Space (141.9 m2)**

No Asbestos

**B00R - R0014 - Raised Platform (63.69 m2)**

No Asbestos

**B00R - R0015 - Other (18.52 m2)**

No Asbestos

**B00R - R0016 - Covered Outdoor Learning Area (154.15 m2)**

No Asbestos

**B00R - R0017 - Movement (6.85 m2)**

No Asbestos

**B00R - R0018 - Movement (12.67 m2)**

No Asbestos

**B00R - R0019 - Movement (11.97 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00S - General Learning - 2015 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00S - R0001 - Home Base (88.27 m2)**

No Asbestos

**B00S - R0002 - Home Base Store (5.92 m2)**

No Asbestos

**B00S - R0003 - Movement (3.51 m2)**

No Asbestos

**B00S - R0004 - External Movement (26.12 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00T - Administration/Pupil Facilities - 1887 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	Flat AC Sheeting	80m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	3420/B00T/Ceiling Voids/S23			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	10m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	3420/B00T/Ceiling Voids/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Eaves Linings	Flat AC Sheeting	20m2	North, South & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00T/Eaves Linings/S25			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Non Accessible Area - No manhole in building					

**Interior****B00T - R0001 - Interview (23.15 m2)**

Infill panel to Fireplace	Flat AC Sheeting					
	3420/B00T/R0001/Infill panel to Fireplace/S28					<b>No Asbestos Detected</b>

**B00T - R0002 - Staff Room Annexe (20.96 m2)**

No Asbestos

**B00T - R0003 - Resource/Toy Space (14.81 m2)**

No Asbestos

**B00T - R0004 - Movement (16.49 m2)**

No Asbestos

**B00T - R0005 - Special Programs Room (20.86 m2)**

No Asbestos

**B00T - R0006 - Interview (11.81 m2)**

No Asbestos

**B00T - R0007 - Staff Room Annexe (11.8 m2)**

No Asbestos

**B00T - R0008 - Movement (11.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00T/R0011/Ceiling Structures/Linings/S27			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00T - R0009 - Staff Toilet (5.67 m2)**

No Asbestos

**B00T - R0010 - Staff Shower/Change (9.97 m2)**

No Asbestos

**B00T - R0011 - Practical Activities (13.37 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00T/R0011/Ceiling Structures/Linings/S27			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00T - R0012 - General Storeroom (3.12 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B00T/R0011/Ceiling Structures/Linings/S27			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00T - R0013 - Staff Toilet (1.66 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00T - R0014 - Laundry - P (7.78 m2)**

No Asbestos

**B00T - R0015 - External Movement (21.18 m2)**

Electrical Backing Board    Resinous Board  
 3420/B00T/R0015/Electrical Backing Board/S26

**No Asbestos Detected**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00U - Storage - 1971 - Fibre Clad Shed (Fibre Clad Shed)**

**Exterior**

Wall Cladding	Flat AC Sheeting 3420/B00U/Wall Cladding/S29					<b>No Asbestos Detected</b>
---------------	---	--	--	--	--	-----------------------------

**Interior**

**B00U - R0001 - Garden Store (29.98 m2)**

Wall Linings Internal	Flat AC Sheeting 3420/B00U/Wall Cladding/S29					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00V - Building Services - 2014 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00V - R0001 - Garage/Carport (50.94 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0H1 - Pupil Facilities - 1971 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	4m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/Eaves Linings/S15					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground						
Gable Verge Lining	Non Accessible Area - Height Restriction					
Ceiling Voids	No Asbestos Found					

**Interior**

**B0H1 - R0001 - Movement (13.07 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>

**B0H1 - R0002 - Toilets - Boys (51.61 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>

**B0H1 - R0003 - Movement (18.71 m2)**

No Asbestos

**B0H1 - R0004 - Covered Area (88.78 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0H2 - Pupil Facilities - 1971 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/Eaves Linings/S15					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground						
Ceiling Voids	No Asbestos Found					

**Interior**

**B0H2 - R0001 - Drinking Facilities (5.57 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>

**B0H2 - R0002 - Toilets - Girls (62.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	63m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>

**B0H2 - R0003 - Covered Area (8.08 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3420/B0H1/R0002/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10511 - Learning Unit - Standard With P.A.A. : Placement Date - 25/11/2008**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D13059 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/11/2007**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D15228 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 20/03/2006**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017