

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wentworth Public School (3421)  
**Region :** Western NSW  
**State Electorate :** Murray  
**Local Government Area :** Wentworth

**Initial Survey :** Noel Arnold & Associates : 13 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016

3421 - Wentworth Public School  
Site Plan (All Sites)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1967 - Brick/Veneer (Brick/Veneer)****Exterior**

Wall Cladding	Flat AC Sheeting	80m2	North facing, South facing, Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	60m2	North facing, South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00B/Eaves Linings/S14					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00A - R0001 - Home Base**

Window In-fill-panel	Flat AC Sheeting	1m2	North at duct penetration	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00A/R0003/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>

**B00A - R0004 - Home Base**

Window In-fill-panel	Flat AC Sheeting	1m2	North at duct penetration	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0006 - Home Base Store**

No Asbestos

**B00A - R0007 - Home Base Store**

No Asbestos

**B00A - R0008 - Movement**

No Asbestos

**B00A - R0009 - Practical Activities - 1hb**

No Asbestos

**B00A - R0010 - Practical Activities - 1hb**

No Asbestos

**B00A - R0011 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library/General Learning - 1964 - Brick/Block (Brick/Block)****Exterior**

Window In-fill-panel	Flat AC Sheeting	100m2	East facing, West facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	120m2	East facing, West facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00B/Eaves Linings/S14					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Void	No Asbestos Found					

**Interior****B00B - R0001 - Canteen Office/Store**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0017/Ceiling Structures/Linings/S21					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0003 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0017/Ceiling Structures/Linings/S21					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0004 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0017/Ceiling Structures/Linings/S21					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0005 - Home Base Store**

No Asbestos

**B00B - R0006 - Home Base**

Window In-fill-panel	Flat AC Sheeting	1m2	East at duct penetration	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>

**B00B - R0007 - Home Base**

Window In-fill-panel	Flat AC Sheeting	1m2	East at duct penetration	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>

**B00B - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0015 - Sports Store**

Wall Linings Internal	Flat AC Sheeting	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0015/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>

**B00B - R0016 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0017 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0017/Ceiling Structures/Linings/S21					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00B/R0017/Ceiling Structures/Linings/S21					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0019 - Practical Activities - 1hb**

No Asbestos

**B00B - R0020 - Practical Activities - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00B - R0021 - Reading Area**

No Asbestos

**B00B - R0022 - Entry Vestibule**

No Asbestos

**B00B - R0023 - Special Programs Room**

No Asbestos

**B00B - R0024 - Library Office/Workroom**

No Asbestos

**B00B - R0025 - Movement**

No Asbestos

**B00B - R0030 - Canteen**

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------------	--------------------	---------	--------------------

3421/B00B/R0017/Ceiling Structures/Linings/S21

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00C - Administration - 1965 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Flat AC Sheeting	36m2	North facing, South facing, Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00A/Wall Cladding/S4					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00B/Eaves Linings/S14					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00C - R0001 - Staff Room**

Window Sill	Compressed AC Sheet	2m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0002 - Duplicating Workroom**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0003 - Sick Bay**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0004 - Staff Toilet**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0005 - Movement**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0006 - Staff Toilet**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0007 - General Storeroom**

Window Sill	Compressed AC Sheet	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0008 - Principal**

Window Sill	Compressed AC Sheet	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0009 - Clerical Office**

Window Sill	Compressed AC Sheet	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00C/R0003/Window ledge/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0010 - General Storeroom**

No Asbestos

**B00C - R0011 - No Access**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Door Lining	Flat AC Sheeting	3m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
3421/B00C/R0011/Door lining/S3					Chrysotile (white asbestos)	
<b>B00C - R0012 - General Storeroom</b>						
No Asbestos						
<b>B00C - R0013 - Movement</b>						
No Asbestos						
<b>B00C - R0014 - Entry Vestibule</b>						
Window Sill	Compressed AC Sheet	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3421/B00C/R0003/Window ledge/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities - 1967 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00B/Eaves Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Voids	Flat AC Sheeting	12m2	Ceiling edging	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3421/B00D/Underfloor Voids/S18				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior****B00D - R0001 - General Storeroom**

No Asbestos

**B00D - R0002 - Communal Space**

No Asbestos

**B00D - R0003 - Cleaning Supplies**

No Asbestos

Ceiling Void No Asbestos Found

**B00D - R0004 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0005 - Staff Toilet**

No Asbestos

**B00D - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0007 - Shower/Change**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0008 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0009 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0011 - Shower/Change**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0012 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00D/R0004/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0013 - Staff Toilet**

No Asbestos

**B00D - R0014 - Raised Platform**

No Asbestos

**B00D - R0016 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00D - R0017 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

3421/B00E/Eaves Linings/S15

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1950 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	15m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00E/Eaves Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

**Interior**

**B00E - R0001 - Home Base**

No Asbestos

**B00E - R0002 - Toilets - Boys/Girls**

Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00E/R0002/Wall Linings Internal/S6				<b>Chrysotile (white asbestos)</b>	

**B00E - R0003 - Home Base Store**

No Asbestos

**B00E - R0004 - External Movement**

Floor Coverings Res/Textile	Compressed AC Sheet					<b>No Asbestos Detected</b>
	3421/B00E/R0004/Floor Coverings Res/Textile/S12					
Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00E/R0004/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	8m2	East facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00E/R0002/Wall Linings Internal/S6				<b>Chrysotile (white asbestos)</b>	

**B00E - R0005 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1886 - Brick/Block (Brick/Block)****Exterior**

Window In-fill-panel	Flat AC Sheeting 3421/B00A/Wall Cladding/S4	3m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting 3421/B00F/Eaves Linings/S16	50m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Voids	AC Fragments/Debris 3421/B00F/Ceiling Voids/S19	5m2	Middle portion	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Underfloor Voids	AC Fragments/Debris 3421/B00F/Underfloor Voids/S20	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>

**Interior****B00F - R0001 - Home Base**

No Asbestos

**B00F - R0002 - Home Base**

No Asbestos

**B00F - R0003 - Home Base**

No Asbestos

**B00F - R0004 - Kiln Room**

External kiln lining	Flat AC Sheeting 3421/B00F/R0004/External kiln lining/S9	1Unit(s)	Variable positions	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Workbench	Compressed AC Sheet 3421/B00F/R0004/Workbench/S27					<b>No Asbestos Detected</b>
In-fill-panel	Flat AC Sheeting 3421/B00F/R0011/Wall Linings Internal/S10	4m2	To doorway	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**B00F - R0005 - Craft Store**

No Asbestos

**B00F - R0006 - Home Base**

No Asbestos

**B00F - R0007 - Home Base**

No Asbestos

**B00F - R0008 - Movement**

No Asbestos

**B00F - R0009 - Staff Room Annexe**

No Asbestos

**B00F - R0010 - General Assistant/Bulk Store**

Ceiling Structures/Linings	Flat AC Sheeting 3421/B00F/R0010/Ceiling Structures/Linings/S25					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00F - R0011 - Sick Bay**

Wall Linings Internal	Flat AC Sheeting 3421/B00F/R0011/Wall Linings Internal/S10	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles 3421/B00F/R0011/Floor Coverings Res/Textile/S11					<b>No Asbestos Detected</b>

**B00F - R0012 - Staff Room Annexe**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00F - R0013 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
	3421/B00F/R0013/Floor Coverings Res/Textile/S28					<b>No Asbestos Detected</b>

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3421/B00F/R0015/Ceiling Structures/Linings/S24					<b>Chrysotile (white asbestos)</b>

**B00F - R0016 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00F/R0017/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00F - R0017 - No Access**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00F/R0017/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

Wall Linings Internal	Flat AC Sheeting	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00F/R0017/Wall Linings Internal/S26					<b>Chrysotile (white asbestos)</b>

**B00F - R0018 - Practical Activities - 1hb**

No Asbestos

**B00F - R0019 - Practical Activities - 1hb**

No Asbestos

**B00F - R0020 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Special Purpose - 1870 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	45m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00G/Eaves Linings/S17					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	No Asbestos Found					
Ceiling Void	Non Accessible Area - No Manhole located					

**Interior**

**B00G - R0001 - General Storeroom**

No Asbestos

**B00G - R0002 - Home Base**

No Asbestos

**B00G - R0003 - Home Base**

No Asbestos

**B00G - R0004 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00G/R0007/Floor Coverings Res/Textile/S13					<b>Chrysotile (white asbestos)</b>

**B00G - R0005 - Sick Bay**

No Asbestos

**B00G - R0006 - Staff Kitchen**

No Asbestos

**B00G - R0007 - Staff Room Annexe**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3421/B00G/R0007/Floor Coverings Res/Textile/S13					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017