

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Werris Creek Public School (3425)
Region : New England
State Electorate : Tamworth
Local Government Area : Liverpool Plains

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - Pupil Facilities - 1928 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00A/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling void height restricted 4metres	No Asbestos Found					

Interior

B00A - R0001 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00A/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00A/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00A/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0004 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00A/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00B - General Learning - 1963 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0001/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Void - Flat ceiling pitched roof	Non Accessible Area - Height restricted approximately 4m					

Interior

B00B - R0001 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0001/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	4m2	South, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0002/Wall Linings Internal/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	4m2	South, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0002/Wall Linings Internal/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0004 - Staff Kitchen

No Asbestos

B00B - R0005 - Darkroom Space

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0001/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0008 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0001/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1928 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	64m2	North , South, East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00C/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Void - Flat ceiling, pitched roof	Non Accessible Area - No manhole - Ceiling height approx 3.5m					

Interior

B00C - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00C/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00C - R0002 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00C/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00C - R0003 - General Assistant/Bulk Store

No Asbestos

B00C - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00C/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00C - R0005 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00C/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00C - R0006 - Cleaners Room

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3425/B00B/R0001/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities/Pupil Facilities - 1982 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 3425/B00D/Wall Cladding/S3					No Asbestos Detected
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior**B00D - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0002 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3425/B00D/R0003/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3425/B00D/R0003/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - Disabled Toilet

No Asbestos

B00D - R0006 - Sports Store

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - P.E. Store

No Asbestos

B00D - R0009 - Canteen Office/Store

Electrical Mounting Board	Resinous Membrane	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	-------------------	-------	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard**B00D - R0010 - Canteen Office/Store**

No Asbestos

B00D - R0011 - Canteen

No Asbestos

B00D - R0012 - Communal Space

No Asbestos

B00D - R0013 - Hall Chair Store

No Asbestos

B00D - R0014 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3425/B00D/R0003/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0015 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 3425/B00D/R0003/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0016 - Cleaning Distributed Store

No Asbestos

B00D - R0017 - Movement

No Asbestos

B00D - R0018 - Movement

No Asbestos

B00D - R0019 - Raised Platform

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0020 - Movement

No Asbestos

B00D - R0021 - Plant

No Asbestos

B00D - R0022 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1963 - Timber (Timber)

Exterior

Eaves Linings	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
Assumed Asbestos - Joist packing. Cannot sample -						
Ceiling Void - Flat ceiling, pitched roof	No Asbestos Found					

Interior

B00E - R0001 - Principal

No Asbestos

B00E - R0002 - Movement

No Asbestos

B00E - R0003 - Clerical Office

No Asbestos

B00E - R0004 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Sheet					
	3425/B00E/R0005/Floor Coverings Res/Textile/S8					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	3425/B00E/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00E - R0005 - Sick Bay

Floor Coverings Res/Textile	Vinyl Sheet					
	3425/B00E/R0005/Floor Coverings Res/Textile/S8					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	3425/B00E/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00E - R0006 - Staff Toilet

No Asbestos

B00E - R0007 - Security Store

No Asbestos

B00E - R0008 - Deputy Principal

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities - 1928 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Void - Flat ceiling, pitched roof	Non Accessible Area - No manhole. Ceiling height approx 4m

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Staff Room

Electrical Mounting Board	Fibrous Membrane	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

Floor Coverings Res/Textile	Vinyl Sheet					
	3425/B00E/R0005/Floor Coverings Res/Textile/S8					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	3425/B00E/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00F - R0003 - Staff Room Annexe

No Asbestos

B00F - R0004 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Library - 1927 - Timber (Timber)**Exterior**

Storm Water Cover	Compressed AC Sheet	2m2	North, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3425/B00G/Storm Water Cover/S1				Chrysotile (white asbestos)	
Above ground drainage pipe (protruding from building)	Fibre Cement Pipe	0.5m2	Southern side western end	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3425/B00G/Above ground drainage pipe (protruding from building)/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					
	3425/B00G/Underfloor Voids - Packing to Floor Joists/S11				No Asbestos Detected	
Ceiling Void - Flat ceiling, pitched roof	Non Accessible Area					
	- Height restricted approx 4m high.					

Interior**B00G - R0001 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3425/B00G/R0001/Floor Coverings Res/Textile/S12				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	3425/B00G/R0001/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00G - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3425/B00G/R0001/Floor Coverings Res/Textile/S12				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	3425/B00G/R0001/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3425/B00G/R0001/Floor Coverings Res/Textile/S12				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	3425/B00G/R0001/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00G - R0005 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3425/B00G/R0001/Floor Coverings Res/Textile/S12				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	3425/B00G/R0001/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00G - R0006 - Library Office/Workroom

No Asbestos

B00G - R0007 - Library Office/Workroom

No Asbestos

B00G - R0008 - Reading Area

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0012 - Movement						
No Asbestos						
B00G - R0013 - Movement						
No Asbestos						
B00G - R0014 - Cleaning Distributed Store						
No Asbestos						
B00G - R0015 - Cleaning Supplies						
No Asbestos						
B00G - R0016 - Security Store						
No Asbestos						
B00G - R0017 - Movement						
No Asbestos						
B00G - R0018 - Movement						
No Asbestos						
B00G - R0019 - Movement						
No Asbestos						
B00G - R0020 - Home Base						
No Asbestos						
B00G - R9001 - No Access						
No Asbestos						
B00G - R9002 - Movement						
No Asbestos						
B00G - R9003 - Practical Activities - 1hb						
No Asbestos						
B00G - R9004 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00H - R0001 - Lift

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017