


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Westdale Public School (3428)
Region : New England
State Electorate : Tamworth
Local Government Area : Tamworth

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Reviewed By : AECOM : 29 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area

- Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Hall Chair Store

No Asbestos

B00A - R0003 - Garden Store

No Asbestos

B00A - R0004 - Sports Store

No Asbestos

B00A - R0005 - P.E. Store

No Asbestos

B00A - R0006 - Communal Space

No Asbestos

B00A - R0007 - Raised Platform

No Asbestos

B00A - R0008 - Plant

No Asbestos

B00A - R0009 - Toilets - Boys

No Asbestos

B00A - R0010 - Toilets - Girls

No Asbestos

B00A - R0011 - Shower/Change

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Outdoor Learning Area

No Asbestos

B00A - R0014 - Canteen Office/Store

No Asbestos

B00A - R0015 - Canteen

No Asbestos

B00A - R0016 - Disabled Toilet

No Asbestos

B00A - R0017 - General Assistant/Bulk Store

No Asbestos

B00A - R0018 - Cleaning Supplies

No Asbestos

B00A - R0019 - Uniform Shop

No Asbestos

B00A - R0020 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Tiered Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00B - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0007 - Cleaning Distributed Store

No Asbestos

B00B - R0008 - Plant

No Asbestos

B00B - R0009 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Support Unit - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Toilets - Girls

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0010 - General Storeroom

No Asbestos

B00C - R0011 - Toilets - Boys

No Asbestos

B00C - R0012 - Practical Activities - M - 1hb

No Asbestos

B00C - R0013 - Home Base Store - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0014 - Home Base - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/Staff Facilities - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Staff Shower/Change

No Asbestos

B00D - R0009 - Sick Bay

No Asbestos

B00D - R0010 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Duplicating Workroom

No Asbestos

B00D - R0013 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - Security Store

No Asbestos

B00D - R0015 - Staff Toilet

No Asbestos

B00D - R0016 - Staff Toilet

No Asbestos

B00D - R0017 - Staff Toilet

No Asbestos

B00D - R0018 - Cleaning Distributed Store

No Asbestos

B00D - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00E - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0009 - Practical Activities - 1hb

No Asbestos

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0014 - Practical Activities - 1hb

No Asbestos

B00E - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0017 - Practical Activities - 1hb

No Asbestos

B00E - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0019 - Main Switch Board

No Asbestos

B00E - R0020 - Practical Activities - 1hb

No Asbestos

B00E - R0021 - Access Shower/Toilet - Type 2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0022 - Laundry - Type 2

No Asbestos

B00E - R0024 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0017 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0018 - Practical Activities - 1hb

No Asbestos

B00F - R0019 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00F - R0020 - General Storeroom

No Asbestos

B00F - R0021 - Toilets - Girls

No Asbestos

B00F - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1962 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.3M GR0005					
Eaves Linings	Flat AC Sheeting	200m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction >3M						
Underfloor Voids	AC Fragments/Debris	2m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
3428/B00G/Underfloor Voids/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00G - R0001 - Practical Activities - 1hb**

No Asbestos

B00G - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	4m2	South, East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3428/B00G/R0002/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Staff Room Annexe

No Asbestos

B00G - R0005 - Craft Store

No Asbestos

B00G - R0006 - Movement

No Asbestos

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
3428/B00G/R0008/Floor Coverings Res/Textile/S5				No Asbestos Detected		

B00G - R0009 - Withdrawal Space - 1hb

No Asbestos

B00G - R0010 - General Storeroom

No Asbestos

B00G - R0011 - Movement

No Asbestos

B00G - R0012 - External Movement

No Asbestos

B00G - R0015 - External Movement

No Asbestos

B00G - R0016 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities/General Learning - 1950 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00H - R0001 - Drinking Facilities

No Asbestos

B00H - R0002 - Drinking Facilities

No Asbestos

B00H - R0003 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B001 - Support Unit - 1968 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 3428/B001/Eaves Linings/S8	50m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	AC Fragments/Debris 3428/B001/Ceiling Voids/S9	1Unit	Variable positions	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B001 - R0001 - Movement

No Asbestos

B001 - R0002 - Staff Kitchen

Ceiling Structures/Linings	Flat AC Sheeting 3428/B001/R0003/Ceiling Structures/Linings/S3	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Sheet 3428/B001/R0002/Floor Coverings Res/Textile/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3428/B001/R0003/Wall Linings Internal/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0003 - Laundry - Type 2

Wall Linings Internal	Flat AC Sheeting 3428/B001/R0003/Wall Linings Internal/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 3428/B001/R0003/Ceiling Structures/Linings/S3	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0004 - Home Base Store - M

Wall Linings Internal	Flat AC Sheeting 3428/B001/R0003/Wall Linings Internal/S2	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 3428/B001/R0003/Ceiling Structures/Linings/S3	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0005 - Staff Room

No Asbestos

B001 - R0006 - Withdrawal Space - 1hb

No Asbestos

B001 - R0007 - Withdrawal Space - 1hb

No Asbestos

B001 - R0008 - Staff Room

No Asbestos

B001 - R0009 - Toilet - M

Wall Linings Internal	Flat AC Sheeting 3428/B001/R0003/Wall Linings Internal/S2	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
-----------------------	--	-----	------------	--------------------	---------	---

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3428/B001/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0010 - Shower/Change						
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3428/B001/R0003/Wall Linings Internal/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3428/B001/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0011 - Movement						
No Asbestos						
B001 - R0012 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3428/B001/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 2002 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Hall Chair Store

No Asbestos

B00J - R0002 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2006 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					
Packing to ramp	Flat AC Sheeting 3428/B00K/Packing to ramp/S6					No Asbestos Detected

Interior

B00K - R0001 - Special Programs Room

No Asbestos

B00K - R0002 - General Storeroom

No Asbestos

B00K - R0003 - Ramp

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Cleaning Distributed Store

No Asbestos

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Special Programs Room - Type 1

No Asbestos

B00L - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0006 - Home Base Store

No Asbestos

B00L - R0007 - Practical Activities - 1hb

No Asbestos

B00L - R0008 - Home Base

No Asbestos

B00L - R0009 - Withdrawal Space - 2hb

No Asbestos

B00L - R0010 - Home Base

No Asbestos

B00L - R0011 - Practical Activities - 1hb

No Asbestos

B00L - R0012 - Home Base Store

No Asbestos

B00L - R0013 - Sports Store

No Asbestos

B00L - R0014 - General Storeroom

No Asbestos

B00L - R0015 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Canteen

No Asbestos

B00M - R0002 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Storage - 2014 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Sports Store

No Asbestos

B00N - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10915 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 26/11/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11008 - Learning Unit - Standard With P.A.A. : Placement Date - 22/01/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D12273 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/02/2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14156 - Learning Unit - Standard With P.A.A. : Placement Date - 3/02/2004

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D14339 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 4/10/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14679 - Learning Unit - Standard With P.A.A. : Placement Date - 28/06/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15921 - Learning Unit - Standard With P.A.A. : Placement Date - 2/06/2009

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017