


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wiangaree Public School (3439)
Region : North Coast
State Electorate : Lismore
Local Government Area : Kyogle

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1915 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3439/B00A/R0009/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	4m2	Behind water fountains	Good Condition (1)	Low (1)	Low Priority (2-3)
	3439/B00A/In-fill-panel/S2				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3439/B00A/Electrical Backing Board/S7				Chrysotile (white asbestos)	

Interior**B00A - R0001 - Principal Office**

Inspection hatch	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3439/B00A/R0001/Inspection hatch/S6				Chrysotile (white asbestos)	

B00A - R0002 - Clerical Office

No Asbestos

B00A - R0003 - Entry Vestibule

No Asbestos

B00A - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3439/B00A/R0004/Floor Coverings Res/Textile/S1				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	3439/B00A/R0004/Floor Coverings Res/Textile/S5				No Asbestos Detected	

B00A - R0005 - Home Base

Floor Coverings Res/Textile	Adhesive					
	3439/B00A/R0004/Floor Coverings Res/Textile/S5				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3439/B00A/R0004/Floor Coverings Res/Textile/S1				No Asbestos Detected	

B00A - R0006 - Home Base

Floor Coverings Res/Textile	Adhesive					
	3439/B00A/R0004/Floor Coverings Res/Textile/S5				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3439/B00A/R0004/Floor Coverings Res/Textile/S1				No Asbestos Detected	

B00A - R0007 - Practical Activities - 1hb

No Asbestos

B00A - R0008 - Staff Room

No Asbestos

B00A - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3439/B00A/R0009/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00A - R0011 - External Movement

No Asbestos

B00A - R9001 - Special Programs Room

No Asbestos

B00A - R9002 - Kiln Room

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R9003 - General Storeroom

No Asbestos

B00A - R9004 - Movement

No Asbestos

B00A - R9005 - Movement

No Asbestos

B00A - R9006 - P.E. Store

No Asbestos

B00A - R9007 - General Assistant/Bulk Store

No Asbestos

B00A - R9008 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1977 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 3439/B00B/Eaves Linings/S8	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Downpipes	Fibre Cement Pipe 3439/B00B/Downpipes/S3	4m	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Area inaccessible no access point					

Interior

B00B - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

B00B - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0004 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0007 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00B - R0008 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3439/B00B/R0005/Ceiling Structures/Linings/S9	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 2006 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Reading Area

No Asbestos

B00D - R0002 - K.L.A. Store

No Asbestos

B00D - R0003 - Practical Activities

No Asbestos

B00D - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017