


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Willow Tree Public School (3451)
Region : New England
State Electorate : Upper Hunter
Local Government Area : Liverpool Plains

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : AECOM : 29 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1917 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.6M AR 0001					
Electrical Backing Board	Resinous Board	1Unit(s)	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
Eaves Linings	Flat AC Sheeting 3451/B00A/Eaves Linings/S1					No Asbestos Detected
Underfloor Voids	AC Fragments/Debris 3451/B00A/Underfloor Voids/S14					No Asbestos Detected
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 3451/B00A/Underfloor Voids/S14					No Asbestos Detected
Underfloor Voids - Packing to Floor Joists	Packing 3451/B00A/Underfloor Voids/S14					No Asbestos Detected

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	3451/B00A/R0007/Floor Coverings Res/Textile/S2				No Asbestos Detected
-----------------------------	-------------	--	--	--	--	-----------------------------

B00A - R0004 - Clerical Office/Workroom

No Asbestos

B00A - R0005 - External Movement

No Asbestos

B00A - R0006 - Entry Vestibule

No Asbestos

B00A - R0007 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles	3451/B00A/R0007/Floor Coverings Res/Textile/S2				No Asbestos Detected
-----------------------------	-------------	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1962 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.3M					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 3451/B00B/Eaves Linings/S3					No Asbestos Detected

Interior

B00B - R0001 - External Movement

Wall Linings Internal	Flat AC Sheeting 3451/B00B/R0001/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00B - R0002 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Staff Facilities - 1962 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.3M CR0003					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 3451/B00B/Eaves Linings/S3					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 3451/B00C/Wall Cladding/S6					No Asbestos Detected
Wall Sign/Mural	Flat AC Sheeting 3451/B00C/Wall Sign/Mural/S13					No Asbestos Detected

Interior

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Staff Room

No Asbestos

B00C - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1900 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/Eaves Linings/S10					Chrysotile (white asbestos)

Interior

B00D - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/R0003/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/R0004/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/R0003/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/R0004/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0004 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3451/B00D/R0004/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pre-School Facilities - 1975 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.5M					
Eaves Linings	Flat AC Sheeting 3451/B00E/Eaves Linings/S15					No Asbestos Detected
Gable Ends	Flat AC Sheeting	8m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction 4M						
Underfloor Voids	Packing	2Unit	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
Assumed Asbestos - Area inaccessible						

Interior

B00E - R0001 - Home Base - Pre

No Asbestos

B00E - R0002 - External Movement

Floor Coverings Res/Textile	Corrugated AC Sheeting 3451/B00E/R0002/Floor Coverings Res/Textile/S9					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3451/B00E/R0002/Wall Linings Internal/S8					No Asbestos Detected

B00E - R0003 - Clerical Office - Pre

No Asbestos

B00E - R0004 - Kitchen - Pre

No Asbestos

B00E - R0005 - Toilets - Boys/Girls - Pre

No Asbestos

B00E - R0006 - Staff Toilet - Pre

No Asbestos

B00E - R0007 - Handwashing Facilities

No Asbestos

B00E - R0008 - Staff Shower/Change

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other - 2006 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - Canteen

No Asbestos

B00G - R0002 - Ramp

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pre-School Facilities - 2009 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B001 - R0001 - P.E. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017