


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Windellama Public School (3457)
Region : Illawarra and South East
State Electorate : Goulburn
Local Government Area : Goulburn Mulwaree

Initial Survey : Noel Arnold & Associates : 07 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1955 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00A/Eaves Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3457/B00A/Underfloor Voids/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					

Interior

B00A - R0001 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00A/R0002/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00A - R0002 - Withdrawal Space - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00A/R0002/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00A - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	3m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00A/R0003/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0004 - Home Base Store

No Asbestos

B00A - R0005 - Clerical Office

No Asbestos

B00A - R0006 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Entry Steps	Compressed AC Sheet 3457/B00B/Entry Steps/S3					No Asbestos Detected
Ceiling Void	Non Accessible Area - No Manhole in Building					

Interior

B00B - R0001 - Canteen

No Asbestos

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1926 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof Non Accessible Area
- No manhole in Building

Interior

B00C - R0001 - Special Programs Room

Wall Linings Internal Flat AC Sheeting
3457/B00C/R0001/Wall Linings Internal/S4 **No Asbestos Detected**

B00C - R0002 - Sports Store

No Asbestos

B00C - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	8m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00D/Eaves Linings/S2					Chrysotile (white asbestos)
Ceiling Void	Non Accessible Area - No Manhole in Building					

Interior

B00D - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00D/R0002/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00D/R0002/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0003 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00D/R0002/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00D - R0004 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00D/R0002/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities/Multi Purpose Facilities - 2010 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - Communal Space

No Asbestos

B00E - R0002 - Student Kitchen

No Asbestos

B00E - R0003 - General Storeroom

No Asbestos

B00E - R0004 - Chair Storeroom

No Asbestos

B00E - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Storage - 2013 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - Administration - 1965 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00A/Eaves Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Wall Cladding	Flat AC Sheeting	110m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3457/B00G/Wall Cladding/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	3457/B00G/Ceiling Void/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Void	AC Fragments/Debris	2m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	3457/B00G/Underfloor Void/S13			Chrysotile (white asbestos)		

Interior**B00G - R0001 - Clerical Office**

Wood Burner	Rope Seal to door					No Asbestos Detected
	3457/B00G/R0001/Wood Burner/S18					

B00G - R0002 - Staff Kitchen

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Wall Linings Internal/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0003 - Other

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Wall Linings Internal/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Ceiling Structures/Linings/S14			Chrysotile (white asbestos)		

B00G - R0004 - Clerical Office

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Wall Linings Internal/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Ceiling Structures/Linings/S14			Chrysotile (white asbestos)		

B00G - R0005 - Principal

No Asbestos

B00G - R0006 - Sick Bay

No Asbestos

B00G - R0007 - Clerical Office

No Asbestos

B00G - R0008 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Ceiling Structures/Linings/S14			Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3457/B00G/R0008/Wall Linings Internal/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0009 - Staff Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

3457/B00G/R0011/Ceiling Structures/Linings/S16

Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Storage Shed (West of Building G)

Exterior

Wall Cladding	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3457/B00H/Exterior/Wall Cladding/S17			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Void	No Asbestos Found					
	3457/B00H/Exterior/Wall Cladding/S17			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - Room+1 - Added Room

Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3457/B00H/Exterior/Wall Cladding/S17			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 844 - D10626 - Country Toilet - Reltc - Boys/Girls : Placement Date - 1/08/2000

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		2.88 m2

Interior

R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		9 m2

R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		9 m2

OS 601 - D15097 - Learning Unit - Standard/Withdrawal : Placement Date - 21/04/1999

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017