


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wollar Public School (3473)
Region : Western NSW
State Electorate : Upper Hunter
Local Government Area : Mid-Western

Initial Survey : Noel Arnold & Associates : 16 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1930 - Timber (Timber)

Exterior

Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior

B00A - R0001 - Clerical Office

No Asbestos

B00A - R0002 - General Storeroom

No Asbestos

B00A - R0003 - Reading Area

No Asbestos

B00A - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
		3473/B00A/R0005/Floor Coverings Res/Textile/S3				No Asbestos Detected

B00A - R0005 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Sheet					
		3473/B00A/R0005/Floor Coverings Res/Textile/S3				No Asbestos Detected

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Entry Vestibule

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/Building Services - 1960 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 3473/B00B/Wall Cladding/S1					No Asbestos Detected
Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos						
Wall Cladding	Flat AC Sheeting 3473/B00B/Wall Cladding/S2					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00B - R0001 - Outdoor Learning Area

No Asbestos

B00B - R0002 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Practical Activities

No Asbestos

B00C - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Storage - 2009 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 2007 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 842 - D16233 - Country Toilet - Relta - Boys/Girls : Placement Date - 26/02/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

R2 - Staff Toilet

No Asbestos Found.

R3 - Toilets-Boys

No Asbestos Found.

R4 - Staff Toilet

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017