

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Woodburn Public School (3490)
Region : North Coast
State Electorate : Clarence
Local Government Area : Richmond Valley

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1952 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 3490/B00B/Eaves Linings/S11	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00B - R0010 - Withdrawal Space - 1hb

No Asbestos

B00B - R0011 - Home Base Store

No Asbestos

B00B - R0012 - Home Base

No Asbestos

B00B - R0013 - Practical Activities - 1hb

No Asbestos

B00B - R0014 - Practical Activities - 1hb

No Asbestos

B00B - R0015 - Home Base

No Asbestos

B00B - R0016 - Withdrawal Space - 2hb

No Asbestos

B00B - R0017 - Home Base Store

No Asbestos

B00B - R0018 - Home Base Store

No Asbestos

B00B - R0019 - Disabled Toilet

No Asbestos

B00B - R0020 - Home Base

No Asbestos

B00B - R0021 - Practical Activities - 1hb

No Asbestos

B00B - R0022 - External Movement

No Asbestos

B00B - R0023 - External Stairs

No Asbestos

B00B - R9001 - Garden Store

No Asbestos

B00B - R9002 - General Assistant/Bulk Store

No Asbestos

B00B - R9003 - General Assistant/Bulk Store

No Asbestos

B00B - R9007 - General Assistant/Bulk Store

Wall Linings Internal	Flat AC Sheeting 3490/B00B/R9007/Wall Linings Internal/S1	50m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	--	------	--------------------	--------------------	---------	--------------------

Chrysotile (white asbestos)

B00B - R9008 - Movement

No Asbestos

B00B - R9009 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1965 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 3490/B00C/Eaves Linings/S12	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0007 - Practical Activities - 1hb**

No Asbestos

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Home Base Store

No Asbestos

B00C - R0011 - Withdrawal Space - 2hb

No Asbestos

B00C - R0012 - Home Base

No Asbestos

B00C - R0013 - Practical Activities - 1hb

No Asbestos

B00C - R0014 - External Movement

Wall Linings Internal	Flat AC Sheeting 3490/B00C/R0014/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00C - R9001 - General Storeroom

No Asbestos

B00C - R9002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R9003 - Cleaning Supplies

No Asbestos

B00C - R9004 - Sports Store

Wall Linings Internal	Flat AC Sheeting 3490/B00C/R9004/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00C - R9005 - Craft Store

Floor Coverings Res/Textile	Vinyl Tiles 3490/B00C/R9005/Floor Coverings Res/Textile/S4	26m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00C - R9006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles 3490/B00C/R9005/Floor Coverings Res/Textile/S4	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00C - R9007 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles 3490/B00C/R9005/Floor Coverings Res/Textile/S4	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00C - R9008 - General Storeroom

Debris on floor	AC Fragments/Debris 3490/B00C/R9008/Debris on floor/S19	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00C - R9009 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1952 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris 3490/B00E/Underfloor Voids/S15	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior**B00E - R0001 - Home Base Store**

No Asbestos

B00E - R0002 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00E - R0003 - Special Programs Room

Wall Linings Internal	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00E - R0004 - Staff Room Annexe

Wall Linings Internal	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00E - R0005 - Special Programs Room

Wall Linings Internal	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00E - R0006 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3490/B00E/R0005/Wall Linings Internal/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1952 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 3490/B00G/Eaves Linings/S13					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris 3490/B00G/Underfloor Voids/S16	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B00G - R0007 - Home Base

Wall Linings Internal	Flat AC Sheeting 3490/B00J/R0001/Wall Linings Internal/S7	30m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	------	---------------	--------------------	---------	--

B00G - R0008 - Withdrawal Space - 2hb

No Asbestos

B00G - R0009 - Home Base

Wall Linings Internal	Flat AC Sheeting 3490/B00J/R0001/Wall Linings Internal/S7	30m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	------	---------------	--------------------	---------	--

B00G - R0010 - Home Base Store

No Asbestos

B00G - R0011 - Practical Activities - 1hb

No Asbestos

B00G - R0012 - Practical Activities - 1hb

No Asbestos

B00G - R0013 - Home Base Store

No Asbestos

B00G - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Library - 1881 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 3490/B00I/R0011/Ceiling Structures/Linings/S5					No Asbestos Detected
Ceiling Void	Non Accessible Area - No Access - Ceiling too high >5m					
Underfloor Voids	AC Fragments/Debris 3490/B00I/Underfloor Voids/S17	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B00I - R0002 - Reading Area

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos - Ceiling too high						

B00I - R0003 - Reading Area

Ceiling Structures/Linings	Flat AC Sheeting	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos - Ceiling too high						

B00I - R0004 - Library Office/Workroom

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos - Ceiling too high						

B00I - R0005 - Seminar/Study

No Asbestos

B00I - R0006 - Library Office/Workroom

No Asbestos

B00I - R0007 - Communications Room

No Asbestos

B00I - R0010 - Librarian

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos - Ceiling too high						

B00I - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 3490/B00I/R0011/Ceiling Structures/Linings/S5					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3490/B00I/R0011/Ceiling Structures/Linings/S5					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00J - General Learning - 1958 - Timber (Timber)						
Exterior						
Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/Eaves Linings/S14					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	3490/B00J/Underfloor Voids/S18					Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior						
B00J - R0001 - Laundry - Type 2						
Wall Linings Internal	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0002 - Change - Type 2						
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0003 - Access Shower/Toilet - Type 2						
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0005 - Withdrawal Space - 1hb						
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0009 - Home Base Store						
Wall Linings Internal	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0010 - Home Base						
Wall Linings Internal	Flat AC Sheeting	40m2	Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0011 - Practical Activities - 1hb						
Wall Linings Internal	Flat AC Sheeting	30m2	Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3490/B00J/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)
B00J - R0012 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3490/B00J/R0012/Ceiling Structures/Linings/S6					
B00J - R9001 - General Storeroom						
Wall Linings Internal	Compressed AC Sheet	8m2	Variable positions	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	3490/B00J/R9003/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)
B00J - R9002 - General Storeroom						
Wall Linings Internal	Compressed AC Sheet					No Asbestos Detected
	3490/B00J/R9002/Wall Linings Internal/S20					
B00J - R9003 - General Storeroom						
Ceiling Structures/Linings	Compressed AC Sheet	10m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	3490/B00J/R9003/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)
B00J - R9004 - Main Switch Board						
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Administration - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Q - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0002 - Duplicating Workroom

No Asbestos

B00Q - R0003 - Security Store

No Asbestos

B00Q - R0004 - Cleaning Distributed Store

No Asbestos

B00Q - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0009 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0011 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0012 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0013 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0014 - Disabled Toilet

No Asbestos

B00Q - R0015 - Sick Bay

No Asbestos

B00Q - R0016 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00Q - R0018 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00Q - R0019 - External Movement

No Asbestos

B00Q - R0020 - External Movement

No Asbestos

B00Q - R0021 - Toilet - Lobby

No Asbestos

B00Q - R0022 - Toilet - Lobby

No Asbestos

B00Q - R0023 - Toilet - Lobby

No Asbestos

B00Q - R0024 - Staff Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00Q - R0025 - Staff Toilet

No Asbestos

B00Q - R0026 - Staff Toilet

No Asbestos

B00Q - R0027 - Staff Kitchen

No Asbestos

B00Q - R0028 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Communal Facilities - 2003 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00R - R0001 - Disabled Toilet**

No Asbestos

B00R - R0004 - Security Store

No Asbestos

B00R - R0005 - Cleaning Distributed Store

No Asbestos

B00R - R0006 - Movement

No Asbestos

B00R - R0007 - Raised Platform

No Asbestos

B00R - R0008 - Movement

No Asbestos

B00R - R0009 - P.E. Store

No Asbestos

B00R - R0010 - Hall Chair Store

No Asbestos

B00R - R0011 - Canteen

No Asbestos

B00R - R0012 - Canteen Office/Store

No Asbestos

B00R - R0013 - Communal Space

No Asbestos

B00R - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00R - R0015 - Plant

No Asbestos

B00R - R0016 - External Movement

No Asbestos

B00R - R0017 - Movement

No Asbestos

B00R - R0018 - Toilets - Girls

No Asbestos

B00R - R0019 - Movement

No Asbestos

B00R - R0020 - Toilets - Boys

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00S - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	3490/B00S/R0002/Ceiling Structures/Linings/S9					No Asbestos Detected

B00S - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting					
	3490/B00S/R0002/Ceiling Structures/Linings/S9					No Asbestos Detected

B00S - R0003 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting					
	3490/B00S/R0002/Ceiling Structures/Linings/S9					No Asbestos Detected

B00S - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting					
	3490/B00S/R0002/Ceiling Structures/Linings/S9					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017