

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wyangala Dam Public School (3521)


Region : Western NSW

State Electorate : Cootamundra

Local Government Area : Cowra

Initial Survey : Noel Arnold & Associates : 13 - May - 2008

Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1929 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 3521/B00A/R0001/Ceiling Structures/Linings/S3	No Asbestos Detected				
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3521/B00A/R0001/Ceiling Structures/Linings/S3	No Asbestos Detected				
----------------------------	---	-----------------------------	--	--	--	--

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities - 1929 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1929 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior

B00C - R0001 - General Storeroom

No Asbestos

B00C - R0002 - Sports Store

No Asbestos

B00C - R0003 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1968 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior

B00D - R0001 - Reading Area

No Asbestos

B00D - R0002 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Special Purpose - 1929 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Home Base

In-fill-panel	Flat AC Sheeting	3m	North east corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	3521/B00E/R0001/In-fill-panel/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0002 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/Building Services - 1929 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior

B00F - R0001 - Toilets - Boys

No Asbestos

B00F - R0002 - Toilets - Girls

No Asbestos

B00F - R0003 - Staff Toilet

Non Accessible

B00F - R0004 - General Assistant/Bulk Store

Wall Linings Internal	Flat AC Sheeting					
	3521/B00F/R0004/Wall Linings Internal/S2					No Asbestos Detected

B00F - R0005 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017