

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wyong Public School (3527)
Region : Hunter/Central Coast
State Electorate : Wyong
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 31 - Mar - 2008
Reviewed By : Greencap-NAA : 20 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1979 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00A/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00A - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	3527/B00A/R0001/Ceiling Structures/Linings/S21					No Asbestos Detected

B00A - R0002 - Movement

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00A/R0015/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00A - R0003 - Staff Toilet

No Asbestos

B00A - R0006 - General Storeroom

No Asbestos

B00A - R0007 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00A/R0007/Partition Walls (Cubicles)/S26					Chrysotile (white asbestos)

B00A - R0008 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00A/R0007/Partition Walls (Cubicles)/S26					Chrysotile (white asbestos)

B00A - R0010 - Deputy Principal

No Asbestos

B00A - R0014 - Principal

No Asbestos

B00A - R0017 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00A/R0017/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00A - R0018 - Distribution Board

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00A/R0017/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00A - R0019 - Communications Cupboard

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00A/R0017/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00A - R0020 - Staff Room

No Asbestos

B00A - R0021 - Interview

No Asbestos

B00A - R0022 - Movement

No Asbestos

B00A - R0024 - Entry Vestibule

No Asbestos

B00A - R0025 - Interview

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0026 - Principal						
No Asbestos						
B00A - R0027 - Deputy Principal						
No Asbestos						
B00A - R0028 - Clerical Office/Workroom						
No Asbestos						
B00A - R0029 - Movement						
No Asbestos						
B00A - R0030 - Access Shower/Toilet						
No Asbestos						
B00A - R0031 - Staff Toilet						
No Asbestos						
B00A - R0032 - External Movement						
No Asbestos						
B00A - R0033 - General Storeroom						
No Asbestos						
B00A - R0034 - Uniform Shop						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1979 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00A/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Communications Room

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - General Storeroom

No Asbestos

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0005/Acoustic wall & ceiling lining/S30					Chrysotile (white asbestos)

B00B - R0007 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R1002/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos)

B00B - R0009 - Distribution Board

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected

B00B - R0010 - Cleaning Distributed Store

No Asbestos

B00B - R0011 - K.L.A. Store

No Asbestos

B00B - R0012 - K.L.A. Store

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Library Office/Workroom

No Asbestos

B00B - R0015 - Library Office/Workroom

No Asbestos

B00B - R0016 - Library Office/Workroom

No Asbestos

B00B - R0019 - Communications Room

Wall Linings Internal	Flat AC Sheeting					
	3527/B00B/R0019/Wall Linings Internal/S33					No Asbestos Detected

B00B - R0020 - Movement

No Asbestos

B00B - R0021 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00B - R0022 - Movement						
No Asbestos						
B00B - R0023 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28					Chrysotile (white asbestos)
B00B - R0024 - Special Programs Room						
Wall Linings Internal	AIB					
	3527/B00B/R0024/Wall Linings Internal/S32					No Asbestos Detected
B00B - R0027 - Stairs						
No Asbestos						
B00B - R0028 - External Movement						
No Asbestos						
B00B - R0029 - Stairs						
No Asbestos						
B00B - R0030 - Stairs						
No Asbestos						
B00B - R0031 - Ramp						
No Asbestos						
B00B - R0032 - Ramp						
No Asbestos						
B00B - R0033 - General Storeroom						
No Asbestos						
B00B - R0034 - Reading Area						
Acoustic wall & ceiling lining	Flat AC Sheeting	220m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R0034/Acoustic wall & ceiling lining/S34					Chrysotile (white asbestos)
B00B - R1001 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00B - R1002 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R1002/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos)
B00B - R1004 - Kiln Room						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R0034/Acoustic wall & ceiling lining/S34					Chrysotile (white asbestos)
B00B - R1005 - Plant						
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R1005/Ceiling Structures/Linings/S25					Chrysotile (white asbestos)
B00B - R1006 - Security Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00B - R1008 - Distribution Board						
					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

3527/B00B/R1005/Ceiling Structures/Linings/S25

Chrysotile (white asbestos)

B00B - R1009 - Cleaning Distributed Store

No Asbestos

B00B - R1010 - MovementFloor Coverings
Res/Textile Vinyl Tiles

3527/B00B/R0009/Floor Coverings Res/Textile/S31

No Asbestos Detected

B00B - R1011 - General Assistant/Bulk StoreFloor Coverings
Res/Textile Vinyl Tiles

3527/B00B/R0009/Floor Coverings Res/Textile/S31

No Asbestos Detected

B00B - R1012 - Toilets - Boys/Girls

No Asbestos

B00B - R1013 - Communications Room

No Asbestos

B00B - R1014 - RampFloor Coverings
Res/Textile Vinyl Tiles

3527/B00B/R0009/Floor Coverings Res/Textile/S31

No Asbestos Detected

B00B - R1015 - Stairs

No Asbestos

B00B - R1016 - Stairs

No Asbestos

B00B - R1017 - RampFloor Coverings
Res/Textile Vinyl Tiles

3527/B00B/R0009/Floor Coverings Res/Textile/S31

No Asbestos Detected

B00B - R1018 - Stairs

No Asbestos

B00B - R1020 - Deputy PrincipalFloor Coverings
Res/Textile Vinyl Tiles (Under Floor
Covering/Carpet)

3527/B00B/R0009/Floor Coverings Res/Textile/S31

No Asbestos Detected

B00B - R2001 - PlantCeiling Structures/Linings Flat AC Sheeting 36m2 Variable
positions

Good Condition (1)

Low (1) Low Priority (2-3)

3527/B00B/R2001/Ceiling Structures/Linings/S10

Chrysotile (white asbestos)

B00B - R2002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1979 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00C - M0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28					Chrysotile (white asbestos)

B00C - M0002 - Stairs

No Asbestos

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Garden Store

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0004 - P.E. Store

Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00C - R0005 - Communal Space

Acoustic wall & ceiling lining	Flat AC Sheeting	320m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0005/Acoustic wall & ceiling lining/S30					Chrysotile (white asbestos)

B00C - R0006 - Hall Chair Store

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00C - R0007 - Hall Chair Store

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00C - R0008 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00C - R0009 - Main Switch Board

Electrical Backing Board	Resinous Board	2Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard**B00C - R0010 - Cleaning Distributed Store**

No Asbestos

B00C - R0011 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00C - R0012 - Raised Platform

No Asbestos

B00C - R0013 - Canteen Office/Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00C/R0013/Floor Coverings Res/Textile/S17				No Asbestos Detected	
B00C - R0014 - Canteen						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00C/R0013/Floor Coverings Res/Textile/S17				No Asbestos Detected	
B00C - R0015 - Canteen Office/Store						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00C/R0013/Floor Coverings Res/Textile/S17				No Asbestos Detected	
B00C - R0016 - Staff Toilet						
No Asbestos						
B00C - R0017 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0017/Partition Walls (Cubicles)/S19				Chrysotile (white asbestos)	
B00C - R0018 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/R0017/Partition Walls (Cubicles)/S19				Chrysotile (white asbestos)	
B00C - R0019 - Sports Store						
No Asbestos						
B00C - R0020 - Cleaning Distributed Store						
No Asbestos						
B00C - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28				Chrysotile (white asbestos)	
B00C - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	97m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28				Chrysotile (white asbestos)	
B00C - R0023 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00C/Eaves Linings/S28				Chrysotile (white asbestos)	
B00C - R0024 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00A/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00D - M1001 - Withdrawal Space - 1hb

No Asbestos

B00D - M1002 - Withdrawal Space - 1hb

No Asbestos

B00D - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1023/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)

B00D - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00A/R0017/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00D - R0003 - Kiln Room

No Asbestos

B00D - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - Withdrawal Space - 1hb

No Asbestos

B00D - R0007 - Home Base

No Asbestos

B00D - R0008 - Withdrawal Space - 1hb

No Asbestos

B00D - R0009 - Home Base

No Asbestos

B00D - R0010 - Withdrawal Space - 1hb

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0012 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected

B00D - R0013 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1023/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)

B00D - R0014 - Movement

No Asbestos

B00D - R0015 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0016 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0017 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0018 - Movement						
No Asbestos						
B00D - R0019 - Cleaning Distributed Store						
No Asbestos						
B00D - R0020 - Distribution Board						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R0021 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0022 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0023 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1004 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1005 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1006 - Home Base						
No Asbestos						
B00D - R1007 - Home Base						
No Asbestos						
B00D - R1008 - Staff Room Annexe						
No Asbestos						
B00D - R1009 - Home Base						
No Asbestos						
B00D - R1010 - Home Base						
No Asbestos						
B00D - R1011 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1012 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1023/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)
B00D - R1013 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1013/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)
B00D - R1014 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1015 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1016 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1017 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	58m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1013/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	3527/B00B/R0019/Wall Linings Internal/S33					No Asbestos Detected
B00D - R1018 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1013/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	3527/B00B/R0019/Wall Linings Internal/S33					No Asbestos Detected
B00D - R1019 - Distribution Board						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1013/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	3527/B00B/R0019/Wall Linings Internal/S33					No Asbestos Detected
B00D - R1020 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1021 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1022 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00D/R1014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R1023 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00D/R1023/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1979 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00E/R1017/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00E - M1001 - Withdrawal Space - 1hb**

No Asbestos

B00E - M1002 - Withdrawal Space - 1hb

No Asbestos

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Withdrawal Space - 1hb

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Staff Room Annexe

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Withdrawal Space - 1hb

No Asbestos

B00E - R0008 - Home Base

No Asbestos

B00E - R0009 - Home Base Store

No Asbestos

B00E - R0010 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R1002/Partition Walls (Cubicles)/S12				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00E/R1017/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

B00E - R0011 - Movement

No Asbestos

B00E - R0012 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14				No Asbestos Detected	

B00E - R0013 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14				No Asbestos Detected	

B00E - R0014 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14				No Asbestos Detected	

B00E - R0015 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0016 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0017 - Cleaning Distributed Store						
No Asbestos						
B00E - R0018 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00E - R0019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00E - R0020 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00E - R0024 - Home Base Store						
No Asbestos						
B00E - R1004 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00E - R1010 - Home Base						
No Asbestos						
B00E - R1011 - Home Base						
No Asbestos						
B00E - R1012 - Staff Room Annexe						
No Asbestos						
B00E - R1013 - Home Base						
No Asbestos						
B00E - R1014 - Home Base						
No Asbestos						
B00E - R1015 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00E - R1016 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00B/R1002/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos)
B00E - R1017 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3527/B00E/R1017/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
B00E - R1018 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00E - R1019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00E - R1020 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	58m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
3527/B00E/R1017/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00E - R1022 - Cleaning Distributed Store						
No Asbestos						
B00E - R1023 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1024 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00E - R1025 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00E - R1026 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Sheet					
3527/B00E/R1024/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00E - R1027 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles					
3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 3527/B00F/Eaves Linings/S2					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00F - M0002 - Withdrawal Space - 1hb

No Asbestos

B00F - M0003 - Other-Non Government Pre-Sch

No Asbestos

B00F - M0004 - Movement

No Asbestos

B00F - M0005 - Stairs

No Asbestos

B00F - M0006 - Stairs

No Asbestos

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3527/B00F/R0002/Partition Walls (Cubicles)/S24					Chrysotile (white asbestos)	

B00F - R0003 - Craft Store

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
3527/B00B/R0009/Floor Coverings Res/Textile/S31						

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Home Base

No Asbestos

B00F - R0006 - Staff Room Annexe

No Asbestos

B00F - R0007 - General Storeroom

No Asbestos

B00F - R0008 - Movement

No Asbestos

B00F - R0009 - Staff Room Annexe

No Asbestos

B00F - R0010 - Staff Room Annexe

No Asbestos

B00F - R0011 - Home Base

No Asbestos

B00F - R0012 - Home Base

No Asbestos

B00F - R0013 - Withdrawal Space - 1hb

No Asbestos

B00F - R0014 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00F/R0014/Floor Coverings Res/Textile/S23					No Asbestos Detected
B00F - R0015 - Home Base						
No Asbestos						
B00F - R0016 - Toilets - Boys/Girls						
No Asbestos						
B00F - R0017 - Toilets - Boys/Girls						
No Asbestos						
B00F - R0019 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00F/R0019/Floor Coverings Res/Textile/S22					No Asbestos Detected
B00F - R0020 - Toilets - Boys/Girls						
No Asbestos						
B00F - R0021 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00F - R0022 - Movement						
No Asbestos						
B00F - R0023 - Cleaning Distributed Store						
No Asbestos						
B00F - R0024 - Distribution Board					Note: No inspection of live electrical installation.	
Electrical Backing Board	Resinous Board					
	3527/B00F/R0024/Electrical Backing Board/S35					No Asbestos Detected
B00F - R0025 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00F/R0019/Floor Coverings Res/Textile/S22					No Asbestos Detected
B00F - R0026 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
	3527/B00B/R0009/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00F - R0027 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	3527/B00F/R0019/Floor Coverings Res/Textile/S22					No Asbestos Detected
B00F - R0028 - Personal Effects - E						
Wall Linings Internal	Flat AC Sheeting					
	3527/B00F/R0028/Wall Linings Internal/S36					No Asbestos Detected
B00F - R0029 - Personal Effects - E						
Wall Linings Internal	Flat AC Sheeting					
	3527/B00F/R0028/Wall Linings Internal/S36					No Asbestos Detected
B00F - R0030 - Stairs						
No Asbestos						
B00F - R0031 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-Community Use - 1979 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Other-Community Use

Ceiling Structures/Linings	Flat AC Sheeting	3527/B00G/R0001/Ceiling Structures/Linings/S1	No Asbestos Detected
----------------------------	------------------	---	-----------------------------

B00G - R0002 - Other-Community Use

No Asbestos

B00G - R0003 - Other-Community Use

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 534 - D13471 - Library/Group Study/Office/A V Store : Placement Date - 9/10/2013

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
---------	---------------	------------------	--	--	--	-------

R3 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
---------	---------------	------------------	--	--	--	------

R4 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

R5 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R6 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R7 - Reading Area

Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2
---------	---------------	------------------	--	--	--	-------

R8 - Entry

Ceiling	Flat AC Sheet	Assumed Asbestos				14 m2
---------	---------------	------------------	--	--	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017