

Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Warragamba Public School (3744)
Region : Western Sydney
State Electorate : Wollondilly
Local Government Area : Wollondilly

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting 3744/B00A/Gable Verge Lining/S14	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 3744/B00A/Eaves Linings/S13	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 3744/B00A/In-fill-panel/S11					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 3744/B00A/In-fill-panel/S10	11m2	West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Staff Toilet

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0012 - General Storeroom

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3744/B00A/R0030/Ceiling Structures/Linings/S12	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	------------	--------------------	---------	--

B00A - R0016 - General Storeroom

No Asbestos

B00A - R0020 - Withdrawal Space - 1hb

No Asbestos

B00A - R0021 - Home Base Store

No Asbestos

B00A - R0022 - Home Base Store

No Asbestos

B00A - R0025 - Staff Room Annexe

No Asbestos

B00A - R0026 - Staff Room Annexe

No Asbestos

B00A - R0027 - General Storeroom

No Asbestos

B00A - R0028 - Movement

No Asbestos

B00A - R0029 - Staff Room

No Asbestos

B00A - R0031 - Personal Effects Storage

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
B00A - R0032 - Practical Activities - 1hb						
No Asbestos						
B00A - R0033 - Personal Effects Storage						
No Asbestos						
B00A - R0034 - Practical Activities - 1hb						
No Asbestos						
B00A - R0035 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	165.03m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
3744/B00A/R0035/Ceiling Structures/Linings/S15						Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	4m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00B/Gable Verge Lining/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0006 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00B/R0011/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00B - R0007 - Cleaning Distributed Store

No Asbestos

B00B - R0008 - Cleaning Supplies

No Asbestos

B00B - R0009 - Sports Store

No Asbestos

B00B - R0010 - Main Switch Board

No Asbestos

B00B - R0011 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	22m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00B/R0011/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00B - R0013 - Practical Activities - 1hb

No Asbestos

B00B - R0014 - Practical Activities - 1hb

No Asbestos

B00B - R0015 - Home Base Store

No Asbestos

B00B - R0016 - Home Base Store

No Asbestos

B00B - R0017 - Withdrawal Space - 1hb

No Asbestos

B00B - R0018 - Movement

No Asbestos

B00B - R0019 - Home Base

No Asbestos

B00B - R0020 - Home Base

No Asbestos

B00B - R0021 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00B/R0022/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00B - R0022 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00B/R0022/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	4m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00C/Gable Verge Lining/S18				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	7m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00C/Eaves Linings/S17				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	5m2	Under Eastern end of R0011	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3744/B00C/Underfloor Voids/S19				Chrysotile (white asbestos)	

Interior

B00C - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00C/R0007/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00C - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00C/R0007/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - Practical Activities - 1hb

No Asbestos

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base

No Asbestos

B00C - R0012 - Home Base Store

No Asbestos

B00C - R0013 - Home Base Store

No Asbestos

B00C - R0014 - Withdrawal Space - 1hb

No Asbestos

B00C - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00C/R0007/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Tiered Learning - 1969 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Eaves Linings	Flat AC Sheeting	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
3744/B00D/Eaves Linings/S20					Chrysotile (white asbestos)	

Interior

B00D - R0001 - Plant

No Asbestos

B00D - R0002 - Special Programs Store

No Asbestos

B00D - R0003 - Special Programs Room

No Asbestos

B00D - R0004 - Music Store

No Asbestos

B00D - R0005 - Staff Toilet

No Asbestos

B00D - R0006 - Staff Toilet

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Distribution Board Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
3744/B00D/R0008/Wall Linings Internal/S2					Chrysotile (white asbestos)	

B00D - R0009 - External Movement

No Asbestos

B00D - R0010 - Library Office/Workroom

No Asbestos

B00D - R0011 - Communications Room

No Asbestos

B00D - R0013 - External Movement

No Asbestos

B00D - R0014 - External Movement

No Asbestos

B00D - R0016 - Special Programs Room

No Asbestos

B00D - R0017 - Reading Area

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Staff Facilities - 1944 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
In-fill-panel	Flat AC Sheeting	16m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00E/In-fill-panel/S21			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Staff Room

No Asbestos

B00E - R0002 - General Storeroom

No Asbestos

B00E - R0003 - General Storeroom

No Asbestos

B00E - R0004 - Special Programs Room

In-fill-panel	Flat AC Sheeting	2m	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00E/R0004/In-fill-panel/S3			Chrysotile (white asbestos)		

B00E - R0005 - External Movement

No Asbestos

B00E - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities/Communal Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3744/B00G/Gable Verge Lining/S22					Chrysotile (white asbestos)	

Interior

B00G - R0001 - Canteen

No Asbestos

B00G - R0002 - Canteen Office/Store

No Asbestos

B00G - R0003 - Canteen Office/Store

No Asbestos

B00G - R0004 - Communal Space

No Asbestos

B00G - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3744/B00G/Eaves Linings/S9					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1979 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00H - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0002 - Outdoor Learning Area

No Asbestos

B00H - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0004 - Practical Activities - 1hb

No Asbestos

B00H - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0006 - Outdoor Learning Area

No Asbestos

B00H - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Practical Activities - 1hb

No Asbestos

B00H - R0010 - External Movement

No Asbestos

B00H - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Personal Effects Storage

No Asbestos

B00J - R0003 - Practical Activities - 1hb

No Asbestos

B00J - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Movement

No Asbestos

B00J - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Movement

No Asbestos

B00J - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0011 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0012 - Personal Effects Storage

No Asbestos

B00J - R0013 - External Movement

No Asbestos

B00J - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1997 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - External Movement

No Asbestos

B00K - R0002 - Drinking Facilities

No Asbestos

B00K - R0003 - Toilets - Girls

No Asbestos

B00K - R0004 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Administration - 1944 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00M/Eaves Linings/S5					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					

Interior**B00M - R0001 - External Movement**

No Asbestos

B00M - R0010 - General Storeroom

Wall Linings Internal	Flat AC Sheeting					
	3744/B00M/R0011/Wall Linings Internal/S4					No Asbestos Detected

B00M - R0015 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0016 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0017 - Clerical/Printing

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0018 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0019 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0020 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0021 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0022 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0023 - Security Store

No Asbestos

B00M - R0024 - Access Shower/Toilet

No Asbestos

B00M - R0025 - Sick Bay

No Asbestos

B00M - R0026 - Staff Toilet

No Asbestos

B00M - R0027 - Staff Kitchen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Building Services - 1969 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Eaves Linings	Flat AC Sheeting	8m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00N/Eaves Linings/S6				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3744/B00N/Eaves Linings/S6				Chrysotile (white asbestos)	

Interior

B00N - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B000 - R0001 - External Movement

No Asbestos

B000 - R0003 - Movement

No Asbestos

B000 - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B000 - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B000 - R0007 - Movement

No Asbestos

B000 - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B000 - R0009 - External Movement

No Asbestos

B000 - R0010 - Practical Activities - 1hb

No Asbestos

B000 - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B000 - R0012 - Practical Activities - 1hb

No Asbestos

B000 - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00P - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00P - R0004 - Withdrawal Space - 1hb

No Asbestos

B00P - R0005 - Movement

No Asbestos

B00P - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00P - R0008 - External Movement

No Asbestos

B00P - R0009 - External Movement

No Asbestos

B00P - R0010 - Practical Activities - 1hb

No Asbestos

B00P - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00P - R0012 - Practical Activities - 1hb

No Asbestos

B00P - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior**B00Q - R0001 - Communal Space**

No Asbestos

B00Q - R0002 - Raised Platform

No Asbestos

B00Q - R0003 - Hall Chair Store

No Asbestos

B00Q - R0004 - Communal/Performance Store

No Asbestos

B00Q - R0005 - P.E. Store

No Asbestos

B00Q - R0006 - Toilet - Lobby

No Asbestos

B00Q - R0007 - Toilets - Girls

No Asbestos

B00Q - R0008 - Sound Cupboard

No Asbestos

B00Q - R0009 - Toilet - Lobby

No Asbestos

B00Q - R0010 - Toilets - Boys

No Asbestos

B00Q - R0011 - Cleaning Distributed Store

No Asbestos

B00Q - R0012 - General Storeroom

No Asbestos

B00Q - R0013 - Main Switch Board

No Asbestos

B00Q - R0014 - Disabled Shower/Toilet

No Asbestos

B00Q - R0015 - Covered Outdoor Learning Area

No Asbestos

B00Q - R0016 - Movement

No Asbestos

B00Q - R0017 - Ramp

No Asbestos

B00Q - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10005 - Learning Unit - Standard With P.A.A. : Placement Date - 24/11/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3744_ASB_010313_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017