

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wyrallah Road Public School (3856)
Region : North Coast
State Electorate : Lismore
Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 24 - Feb - 2015



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Administration - 1952 - Brick/Block (Brick/Block)

Exterior

| | | | | | | |
|-----------------------------|-------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |
| Eaves Linings | Flat AC Sheeting | 40m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00A/Eaves Linings/S12 | | | | | Chrysotile (white asbestos) | |

Interior

B00A - R0001 - Interview (20.85 m2)

No Asbestos

B00A - R0002 - Clerical Office/Workroom (17.07 m2)

No Asbestos

B00A - R0003 - Clerical Office (12.78 m2)

No Asbestos

B00A - R0004 - Entry Vestibule (12.47 m2)

No Asbestos

B00A - R0005 - Deputy Principal (12.81 m2)

No Asbestos

B00A - R0008 - Movement (20.95 m2)

| | | | | | | |
|---|-------------|---|--|--|--|------------------------------|
| Ceiling Structures/Linings | Vermiculite | 3856/B00A/R0015/Ceiling Structures/Linings/S9 | | | | Limited Samples Taken |
| Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works | | | | | | |

B00A - R0009 - Cleaning Supplies (2.01 m2)

| | | | | | | |
|---|-------------|---|--|--|--|------------------------------|
| Ceiling Structures/Linings | Vermiculite | 3856/B00A/R0015/Ceiling Structures/Linings/S9 | | | | Limited Samples Taken |
| Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works | | | | | | |

B00A - R0010 - Security Store (18.5 m2)

No Asbestos

B00A - R0011 - Sick Bay (8.48 m2)

No Asbestos

B00A - R0014 - Staff Toilet (2.02 m2)

No Asbestos

B00A - R0015 - Movement (4.44 m2)

| | | | | | | |
|---|-------------|---|--|--|--|------------------------------|
| Ceiling Structures/Linings | Vermiculite | 3856/B00A/R0015/Ceiling Structures/Linings/S9 | | | | Limited Samples Taken |
| Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works | | | | | | |

B00A - R0016 - Main Switch Board (3.96 m2)

| | | | | | | |
|--------------------------|----------------|---|--|--|--|-----------------------------|
| Electrical Backing Board | Resinous Board | 3856/B00A/R0016/Electrical Backing Board/S8 | | | | No Asbestos Detected |
|--------------------------|----------------|---|--|--|--|-----------------------------|

B00A - R0017 - Movement (22.83 m2)

No Asbestos

B00A - R0018 - Movement (2.37 m2)

| | | | | | | |
|--|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00A/R1006/Ceiling Structures/Linings/S10 | | | | | Chrysotile (white asbestos) | |

B00A - R0019 - General Storeroom (4.7 m2)

No Asbestos

B00A - R0020 - Movement (6.47 m2)

| | | | | | | |
|--|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00A/R1006/Ceiling Structures/Linings/S10 | | | | | Chrysotile (white asbestos) | |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|--------------------|--------------------|------------------------------------|--------------------|
| Sample No | | | | | Test Result | |
| B00A - R0021 - Movement (4.37 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00A/R1006/Ceiling Structures/Linings/S10 | | | | | Chrysotile (white asbestos) | |
| B00A - R0022 - Stairs (2.83 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0023 - Principal (26.04 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0024 - Staff Room Annexe (28.72 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1001 - Staff Room (55.93 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1002 - Movement (12.82 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1003 - Deputy Principal (13.57 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1004 - Staff Toilet (6.44 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1005 - Staff Toilet (6.48 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00A - R1006 - Movement (24.85 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 20m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00A/R1006/Ceiling Structures/Linings/S10 | | | | | Chrysotile (white asbestos) | |
| B00A - R1007 - Stairs (3.59 m2) | | | | | | |
| No Asbestos | | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - General Learning - 1954 - Timber (Timber)

Exterior

| | | | | | | |
|------------------|-----------------------------|------|------------|---|---------|--------------------|
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |
| Eaves Linings | Flat AC Sheeting | 80m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/Eaves Linings/S13 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos) | | |

Interior

B00B - R0001 - Home Base Store (8.35 m2)

No Asbestos

B00B - R0002 - Cleaning Distributed Store (4.93 m2)

No Asbestos

B00B - R0003 - Withdrawal Space - 1hb (12.71 m2)

No Asbestos

B00B - R0004 - Home Base (53.51 m2)

No Asbestos

B00B - R0005 - Practical Activities - 1hb (77.4 m2)

| | | | | | | |
|----------------------------|---|------|------------|------------------------------------|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 77m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R0005/Ceiling Structures/Linings/S3 | | | Chrysotile (white asbestos) | | |

B00B - R0006 - Home Base (53.51 m2)

No Asbestos

B00B - R0007 - Home Base Store (9.62 m2)

No Asbestos

B00B - R0008 - Home Base Store (16.73 m2)

No Asbestos

B00B - R0009 - Home Base (53.72 m2)

No Asbestos

B00B - R0010 - Home Base (53.79 m2)

No Asbestos

B00B - R0011 - Home Base Store (13.87 m2)

No Asbestos

B00B - R0012 - General Storeroom (12.45 m2)

No Asbestos

B00B - R0013 - Movement (10.04 m2)

No Asbestos

B00B - R0014 - Movement (17.89 m2)

No Asbestos

B00B - R9001 - Staff Toilet (1.81 m2)

| | | | | | | |
|----------------------------|---|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R9006 - Uniform Shop (18.35 m2)

| | | | | | | |
|----------------------------|---|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 18m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R9007 - General Storeroom (3.43 m2)

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---|----------------------|--------|--------------------|---|-------------|--------------------|
| Sample No | | | | Test Result | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9008 - Movement (3.94 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9009 - Movement (103.43 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 103m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9010 - Drinking Facilities (12.22 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 12m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9011 - Garden Store (6.03 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9012 - Garden Store (6 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R9014 - External Stairs (0.63 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00B - R9015 - External Stairs (0.62 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00B - R9016 - Entry Vestibule (4.5 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00B - R9017 - Canteen Office/Store (11.23 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00B - R9018 - Canteen (50.4 m2) | | | | | | |
| No Asbestos | | | | | | |
| B00B - R9019 - Canteen Covered Area (50.37 m2) | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 40m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3856/B00B/R9019/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) | | |
| B00B - R9020 - External Movement (103.25 m2) | | | | | | |
| Recently Modified Space | Requires Inspection | | | | | |
| B00B - R9021 - External Movement (14.05 m2) | | | | | | |
| Recently Modified Space | Requires Inspection | | | | | |
| B00B - R9022 - External Movement (50.27 m2) | | | | | | |
| Recently Modified Space | Requires Inspection | | | | | |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - General Learning - 1952 - Timber (Timber)

Exterior

| | | | | | | |
|------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Eaves Linings | Flat AC Sheeting | 40m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00C/R0001/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) | |
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00C - R0001 - Movement (34.95 m2)

| | | | | | | |
|----------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 35m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00C/R0001/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) | |

B00C - R0002 - Home Base (53.65 m2)

No Asbestos

B00C - R0003 - Home Base (53.79 m2)

No Asbestos

B00C - R9001 - Special Programs Room (51.01 m2)

No Asbestos

B00C - R9002 - Movement (4.96 m2)

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - General Learning - 1952 - Timber (Timber)**Exterior**

| | | | | | | |
|------------------|---|------|------------|--------------------|---------|---|
| Eaves Linings | Flat AC Sheeting | 80m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Underfloor Voids | No Asbestos Found | | | | | |
| Ceiling Voids | No Asbestos Found | | | | | |

Interior**B00D - R0001 - General Storeroom (8.39 m2)**

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R0005/Ceiling Structures/Linings/S3 | | | | | Chrysotile (white asbestos) |
| Wall Linings Internal | Flat AC Sheeting | 30m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00D/R0001/Wall Linings Internal/S14 | | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) |

B00D - R0002 - General Storeroom (3.1 m2)

| | | | | | | |
|----------------------------|--|------|------------|--------------------|---------|---|
| Wall Linings Internal | Flat AC Sheeting | 20m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00D/R0002/Wall Linings Internal/S16 | | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00D/R0002/Ceiling Structures/Linings/S15 | | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) |

B00D - R0003 - Movement (7.9 m2)

| | | | | | | |
|----------------------------|--|-----|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00D/R0003/Ceiling Structures/Linings/S18 | | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) |

B00D - R0004 - Movement (84.38 m2)

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 84m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R0005/Ceiling Structures/Linings/S3 | | | | | Chrysotile (white asbestos) |
| In-fill-panel | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 3856/B00D/R0004/In-fill-panel/S5 | | | | | |

B00D - R0005 - General Assistant/Bulk Store (12.51 m2)

No Asbestos

B00D - R0006 - Reading Area (107.89 m2)

No Asbestos

B00D - R0007 - Withdrawal Space - 1hb (16.7 m2)

No Asbestos

B00D - R0008 - General Storeroom (9.66 m2)

No Asbestos

B00D - R0009 - Home Base (53.57 m2)

No Asbestos

B00D - R0010 - Home Base (53.37 m2)

No Asbestos

B00D - R0011 - Home Base Store (13.88 m2)

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - General Learning - 1952 - Timber (Timber)

Exterior

| | | | | | | |
|------------------|---|------|------------|---|---------|--------------------|
| Eaves Linings | Flat AC Sheeting | 50m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R9009/Ceiling Structures/Linings/S4 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00E - R0001 - Home Base (66.91 m2)

No Asbestos

B00E - R0002 - Movement (79.54 m2)

| | | | | | | |
|----------------------------|---|------|------------|------------------------------------|---------|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 53m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00B/R0005/Ceiling Structures/Linings/S3 | | | Chrysotile (white asbestos) | | |
| In-fill-panel | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 3856/B00D/R0004/In-fill-panel/S5 | | | | | |

B00E - R0003 - Home Base Store (6.78 m2)

No Asbestos

B00E - R0004 - Home Base Store (3.35 m2)

No Asbestos

B00E - R0005 - Toilets - Boys/Girls (3.44 m2)

No Asbestos

B00E - R0006 - Withdrawal Space - 2hb (22.53 m2)

No Asbestos

B00E - R0007 - Home Base (67.07 m2)

No Asbestos

B00E - R9001 - General Storeroom (28.94 m2)

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - Pupil Facilities - 1952 - Brick/Block (Brick/Block)

Exterior

| | | | | | | |
|------------------|---|------|------------|--------------------|---------|------------------------------------|
| Eaves Linings | Flat AC Sheeting | 10m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00F/R0003/Ceiling Structures/Linings/S6 | | | | | Chrysotile (white asbestos) |
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00F - R0001 - Toilets - Boys (18.25 m2)

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 18m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00F/R0003/Ceiling Structures/Linings/S6 | | | | | Chrysotile (white asbestos) |

B00F - R0002 - Toilets - Girls (18.31 m2)

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 18m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00F/R0003/Ceiling Structures/Linings/S6 | | | | | Chrysotile (white asbestos) |

B00F - R0003 - Movement (21.46 m2)

| | | | | | | |
|----------------------------|---|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 21m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00F/R0003/Ceiling Structures/Linings/S6 | | | | | Chrysotile (white asbestos) |

B00F - R0004 - Disabled Toilet (8.16 m2)

| | | | | | | |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00F/R0003/Ceiling Structures/Linings/S6 | | | | | Chrysotile (white asbestos) |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | Test Result | | |

B00G - Communal Facilities - 1952 - Timber (Timber)

Exterior

| | | | | | | |
|------------------|---|------|------------|---|---------|--------------------|
| Eaves Linings | Flat AC Sheeting | 12m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00G - R0001 - Movement (2 m2)

| | | | | | | |
|----------------------------|---|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00G - R0002 - Sports Store (18.15 m2)

| | | | | | | |
|----------------------------|---|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 18m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|-----------------------|---|------|------------|---|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting | 40m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00G - R0003 - Sports Store (1.35 m2)

| | | | | | | |
|----------------------------|---|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 1m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|-----------------------|---|-----|------------|---|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00G - R0004 - Movement (1.99 m2)

| | | | | | | |
|----------------------------|---|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3856/B00G/R0001/Ceiling Structures/Linings/S7 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00L - Library/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

| | |
|------------------|-------------------|
| Underfloor Voids | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior**B00L - R0001 - Reading Area (129.22 m2)**

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0002 - Library Office/Workroom (28.65 m2)

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0003 - Communications Room (13.95 m2)

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0004 - Communications Cupboard (1.23 m2)

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0005 - Movement (33.73 m2)

No Asbestos

B00L - R9001 - Toilets - Girls (33.34 m2)

No Asbestos

B00L - R9002 - Disabled Toilet (4.19 m2)

No Asbestos

B00L - R9003 - Toilets - Boys (18.94 m2)

No Asbestos

B00L - R9004 - Movement (18.81 m2)

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00M - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

| | |
|------------------|-------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

Interior

B00M - R0001 - External Movement (35.91 m2)

No Asbestos

B00M - R0002 - Practical Activities - 1hb (19.77 m2)

No Asbestos

B00M - R0003 - Home Base Store (6.15 m2)

No Asbestos

B00M - R0004 - Home Base (59.28 m2)

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb (10.9 m2)

No Asbestos

B00M - R0006 - Home Base (59.28 m2)

No Asbestos

B00M - R0007 - Practical Activities - 1hb (19.77 m2)

No Asbestos

B00M - R0008 - Home Base Store (6.15 m2)

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B00N - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

| | |
|-----------------|-------------------|
| Ceiling Void | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

Interior**B00N - R0001 - Ramp (11.62 m2)**

No Asbestos

B00N - R0002 - Raised Platform (57.08 m2)

No Asbestos

B00N - R0003 - Communal Space (200.6 m2)

No Asbestos

B00N - R0004 - Distribution Board (3.4 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0005 - Disabled Shower/Toilet (7.19 m2)

No Asbestos

B00N - R0006 - Cleaning Supplies (3.56 m2)

No Asbestos

B00N - R0007 - Other (1.64 m2)

No Asbestos

B00N - R0008 - Entry Vestibule (3.26 m2)

No Asbestos

B00N - R0009 - Sound Cupboard (2.14 m2)

No Asbestos

B00N - R0010 - Toilets - Boys (5.84 m2)

No Asbestos

B00N - R0011 - Entry Vestibule (2.5 m2)

No Asbestos

B00N - R0012 - Toilets - Girls (7.13 m2)

No Asbestos

B00N - R0013 - P.E. Store (16.4 m2)

No Asbestos

B00N - R0014 - Communal/Performance Store (10.37 m2)

No Asbestos

B00N - R0015 - Chair Storeroom (12.75 m2)

No Asbestos

B00N - R0016 - External Movement (79.26 m2)

No Asbestos

B00N - R0017 - Covered Outdoor Learning Area (179.32 m2)

No Asbestos

B00N - R0018 - Movement (18.31 m2)

No Asbestos

B00N - R0019 - Movement (7.09 m2)

No Asbestos

B00N - R9001 - Other (135.3 m2)

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B000 - General Learning/Special Purpose Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------|-------------------|
| Ceiling Void | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

Interior

B000 - R0001 - Home Base Store (6.17 m2)

No Asbestos

B000 - R0002 - Home Base (61.09 m2)

No Asbestos

B000 - R0003 - Home Base (61 m2)

No Asbestos

B000 - R0004 - Home Base Store (5.93 m2)

No Asbestos

B000 - R0005 - Home Base Store (5.79 m2)

No Asbestos

B000 - R0006 - Home Base (57.94 m2)

No Asbestos

B000 - R0007 - Practical Activities (20.22 m2)

No Asbestos

B000 - R0008 - External Stairs (10.5 m2)

No Asbestos

B000 - R0009 - Withdrawal Space - 1hb (8.98 m2)

No Asbestos

B000 - R0010 - Distribution Board (0.71 m2)

Note: No inspection of live electrical installation.

No Asbestos

B000 - R0011 - Practical Activities (18.25 m2)

No Asbestos

B000 - R0012 - External Stairs (10.47 m2)

No Asbestos

B000 - R0013 - Withdrawal Space - 2hb (11.17 m2)

No Asbestos

B000 - R0014 - Practical Activities (18.98 m2)

No Asbestos

B000 - R0015 - General Storeroom (5.07 m2)

No Asbestos

B000 - R0016 - General Storeroom (5.07 m2)

No Asbestos

B000 - R0017 - External Movement (88.97 m2)

No Asbestos

B000 - R0018 - Plant (5.11 m2)

No Asbestos

B000 - R1001 - Home Base Store (6.11 m2)

No Asbestos

B000 - R1002 - Home Base (61.28 m2)

No Asbestos

B000 - R1003 - Home Base (61.12 m2)

No Asbestos

B000 - R1004 - Home Base Store (6.19 m2)

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

No Asbestos

B000 - R1005 - Home Base Store (5.84 m2)

No Asbestos

B000 - R1006 - Home Base (58.92 m2)

No Asbestos

B000 - R1007 - Practical Activities (20.48 m2)

No Asbestos

B000 - R1008 - External Stairs (18.53 m2)

No Asbestos

B000 - R1009 - Withdrawal Space - 1hb (8.94 m2)

No Asbestos

B000 - R1010 - Distribution Board (0.63 m2)

Note: No inspection of live electrical installation.

No Asbestos

B000 - R1011 - Practical Activities (18.23 m2)

No Asbestos

B000 - R1012 - External Stairs (18.52 m2)

No Asbestos

B000 - R1013 - Withdrawal Space - 2hb (11.7 m2)

No Asbestos

B000 - R1014 - Practical Activities (18.99 m2)

No Asbestos

B000 - R1015 - External Movement (89.58 m2)

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13799 - Learning Unit - Standard With P.A.A. : Placement Date - 17/03/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14522 - Learning Unit - Standard With P.A.A. : Placement Date - 2/07/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15145 - Learning Unit - Standard With P.A.A. : Placement Date - 21/05/2014

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017