


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wattle Grove Public School (3871)
Region : South Western Sydney
State Electorate : Holsworthy
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Sick Bay

No Asbestos

B00A - R0004 - Disabled Toilet

No Asbestos

B00A - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Security Store

No Asbestos

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Cleaning Distributed Store

No Asbestos

B00A - R0011 - Main Switch Board

No Asbestos

B00A - R0012 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Movement

No Asbestos

B00A - R0019 - Toilets - Boys

No Asbestos

B00A - R0020 - Cleaning Distributed Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0021 - Toilets - Girls

No Asbestos

B00A - R0022 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0023 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Communal Facilities - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Canteen Covered Area**

No Asbestos

B00B - R0002 - Canteen

No Asbestos

B00B - R0003 - Canteen Office/Store

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Cleaning Supplies

No Asbestos

B00B - R0006 - Garden Store

No Asbestos

B00B - R0007 - P.E. Store

No Asbestos

B00B - R0008 - Hall Chair Store

No Asbestos

B00B - R0009 - Movement

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Raised Platform

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Communal/Performance Store

No Asbestos

B00B - R0015 - Sports Store

No Asbestos

B00B - R0016 - General Assistant/Bulk Store

No Asbestos

B00B - R0017 - Cleaning Distributed Store

No Asbestos

B00B - R0018 - Sound Cupboard

No Asbestos

B00B - R0019 - Toilets - Boys

No Asbestos

B00B - R0020 - Access Shower/Toilet

No Asbestos

B00B - R0021 - General Assistant/Bulk Store

No Asbestos

B00B - R0022 - Communal Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Community Clinic**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Staff Toilet

No Asbestos

B00C - R0003 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Home Base Store

No Asbestos

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base Store

No Asbestos

B00C - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Home Base Store

No Asbestos

B00C - R0015 - Practical Activities - 1hb

No Asbestos

B00C - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0019 - Practical Activities - 1hb

No Asbestos

B00C - R0020 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0021 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R0022 - Home Base Store						
No Asbestos						
B00C - R0023 - Practical Activities - 1hb						
No Asbestos						
B00C - R0024 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0025 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0026 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0027 - Practical Activities - 1hb						
No Asbestos						
B00C - R0028 - Home Base Store						
No Asbestos						
B00C - R0029 - Movement						
No Asbestos						
B00C - R0030 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Library - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Practical Activities - 1hb

No Asbestos

B00D - R0004 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0006 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0007 - Practical Activities - 1hb**

No Asbestos

B00D - R0008 - Home Base Store

No Asbestos

B00D - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - Staff Toilet

No Asbestos

B00D - R0012 - Special Programs StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0013 - Garden Store**

No Asbestos

B00D - R0014 - Special Programs RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0015 - Special Programs Room**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0017 - Communications RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0018 - Library Office/Workroom**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0019 - Reading Area**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0020 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Movement**

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0006 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0007 - Practical Activities - 1hb**

No Asbestos

B00E - R0008 - Home Base Store

No Asbestos

B00E - R0009 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00E - R0012 - Toilets - Boys

No Asbestos

B00E - R0013 - Toilets - Girls

No Asbestos

B00E - R0014 - Disabled Toilet

No Asbestos

B00E - R0015 - Home Base Store

No Asbestos

B00E - R0016 - Practical Activities - 1hb

No Asbestos

B00E - R0017 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0018 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0019 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00E - R0020 - Practical Activities - 1hb**

No Asbestos

B00E - R0021 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0003 - Practical Activities - 1hb

No Asbestos

B00F - R0004 - Home Base

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00F - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

B00F - R0007 - Practical Activities - 1hb

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0010 - Movement

No Asbestos

B00F - R0011 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Practical Activities - 1hb

No Asbestos

B00G - R0002 - Special Programs Room

No Asbestos

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Withdrawal Space - 1hb

No Asbestos

B00G - R0005 - Practical Activities - 1hb

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Withdrawal Space - 2hb

No Asbestos

B00G - R0009 - Practical Activities - 1hb

No Asbestos

B00G - R0010 - Home Base

No Asbestos

B00G - R0011 - Home Base Store

No Asbestos

B00G - R0012 - Main Switch Board

No Asbestos

B00G - R0013 - External Movement

No Asbestos

B00G - R0014 - External Stairs

No Asbestos

B00G - R1001 - Practical Activities - 1hb

No Asbestos

B00G - R1002 - Home Base

No Asbestos

B00G - R1003 - Home Base Store

No Asbestos

B00G - R1004 - Withdrawal Space - 1hb

No Asbestos

B00G - R1005 - Practical Activities - 1hb

No Asbestos

B00G - R1006 - Home Base

No Asbestos

B00G - R1007 - Home Base Store

No Asbestos

B00G - R1008 - Withdrawal Space - 2hb

No Asbestos

B00G - R1009 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R1010 - Home Base

No Asbestos

B00G - R1011 - Home Base Store

No Asbestos

B00G - R1012 - External Movement

No Asbestos

B00G - R1013 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10614 - Learning Unit - Standard With P.A.A. : Placement Date - 16/10/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D13332 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 7/11/2014

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 101 - D15686 - Learning Unit - Double Primary/PAA : Placement Date - 19/01/2002

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Home Base

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Home Base Store

No Asbestos Found.

R6 - Practical Activity Area

No Asbestos Found.

R7 - Entry

No Asbestos Found.

OS 602 - D15927 - Learning Unit - Standard With P.A.A. : Placement Date - 13/02/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 602 - D16245 - Learning Unit - Standard With P.A.A. : Placement Date - 4/01/2003						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017