

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Windale Public School (3893)
Region : Hunter/Central Coast
State Electorate : Charlestown
Local Government Area : Lake Macquarie

Initial Survey : Noel Arnold & Associates : 14 - Jan - 2010
Reviewed By : Greencap-NAA : 26 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1956 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Surround	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0004 - Staff Toilet**

No Asbestos

B00A - R0005 - Staff Toilet

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Principal

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	24m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

B00A - R0013 - Clerical Office/Workroom

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

B00A - R0014 - Interview

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					

B00A - R0015 - Staff Room

Ceiling Structures/Linings	Flat AC Sheeting	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	40m2	West, Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	61.93m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Adhesive					
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00A - R0016 - Sick Bay						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	16m2	South, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0017 - Clerical Office						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	27.38m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00A - R0018 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0019 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 3893/B00B/Eaves Linings/S23					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 3893/B00B/Gable Verge Lining/S7	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior

B00B - R0001 - Reading Area

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3893/B00B/R0002/Floor Coverings Res/Textile/S2	149m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	-------	------------	--------------------	---------	--

B00B - R0002 - Workroom

Floor Coverings Res/Textile	Vinyl Tiles 3893/B00B/R0002/Floor Coverings Res/Textile/S2	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3893/B00B/R0002/Floor Coverings Res/Textile/S2	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00B - R0003 - Security Store

Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 3893/B00B/R0002/Floor Coverings Res/Textile/S2	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00B - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3893/B00B/R0004/Ceiling Structures/Linings/S6	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Special Purpose - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Special Programs Room

No Asbestos

B00C - R0002 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1955 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	3893/B00D/In-fill-panel/S22					

Interior**B00D - R0012 - Disabled Shower/Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0014 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00B/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00D - R0017 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00B/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00D - R0019 - Staff Toilet

No Asbestos

B00D - R0020 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00B/R0004/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Infil panels	Flat AC Sheeting					No Asbestos Detected
	3893/B00D/In-fill-panel/S22					

B00D - R0021 - General Storeroom

No Asbestos

B00D - R0022 - Home Base/Practical Activities

Infil panels	Flat AC Sheeting					No Asbestos Detected
	3893/B00D/In-fill-panel/S22					

B00D - R0023 - Home Base/Practical Activities

Infil panels	Flat AC Sheeting					No Asbestos Detected
	3893/B00D/In-fill-panel/S22					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Other-After School Care - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0002 - Other-After School Care

Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00E/R0002/Floor Coverings Res/Textile/S20				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	3893/B00E/R0002/Floor Coverings Res/Textile/S21					

B00E - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00E/R0002/Floor Coverings Res/Textile/S20				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	3893/B00E/R0002/Floor Coverings Res/Textile/S21					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0006/Wall Linings Internal/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					

B00F - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0006/Wall Linings Internal/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - General Learning/Administration - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	2m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3893/B00A/Eaves Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00G - R0001 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0005 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					

B00G - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0006/Wall Linings Internal/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0007 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00G/R0004/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0011 - General Storeroom

No Asbestos

B00G - R0013 - Home Base/Practical Activities

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	77m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					

B00G - R0014 - Home Base/Practical Activities

No Asbestos

B00G - R0015 - Home Base/Practical Activities

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00H/Eaves Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00H - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3893/B00H/R0001/Ceiling Structures/Linings/S18					

B00H - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3893/B00H/R0001/Ceiling Structures/Linings/S18					

B00H - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3893/B00H/R0001/Ceiling Structures/Linings/S18					

B00H - R0004 - Toilets-Girls

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3893/B00H/R0001/Ceiling Structures/Linings/S18					

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00H/R0004/Partition Walls (Cubicles)/S19				Chrysotile (white asbestos)	

B00H - R0005 - Toilets-Boys

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	3893/B00H/R0001/Ceiling Structures/Linings/S18					

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00H/R0004/Partition Walls (Cubicles)/S19				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00I - Pupil Facilities/General Learning - 1956 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/Eaves Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00I - R0001 - Staff Room**

No Asbestos

B00I - R0004 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00I - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00I - R0007 - Home Base

No Asbestos

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Home Base

No Asbestos

B00I - R0010 - Practical Activities/Movement - 2hb

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00I - R0011 - Home Base

No Asbestos

B00I - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Wall Linings Internal	Flat AC Sheeting	45m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00I - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00I - R0017 - Stage

No Asbestos

B00I - R0019 - Practical Activities/Movement - 2hb

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0020 - Canteen						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	3893/B00I/R0020/Wall Linings Internal/S4					
B00I - R0021 - Home Base						
No Asbestos						
B00I - R0022 - Home Base						
No Asbestos						
B00I - R0023 - Toilets-Unisex						
No Asbestos						
B00I - R0024 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0027 - Practical Activities/Movement - 2hb						
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	15m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0013/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0031 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0032 - Communal Space						
No Asbestos						
B00I - R0033 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0034 - Access Shower/Toilet						
No Asbestos						
B00I - R0035 - External Movement						
No Asbestos						
B00I - R0036 - External Movement						
No Asbestos						
B00I - R0037 - Home Base/Practical Activities						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	77m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					
B00I - R0038 - Home Base/Practical Activities						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	77m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3893/B00G/R0005/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	3893/B00G/R0005/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00I - R0039 - Special Programs Room						
No Asbestos						
B00I - R9001 - Toilets-Girls						
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00D/R0002/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)
B00I - R9002 - Toilets-Boys						
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00H/R0004/Partition Walls (Cubicles)/S19					Chrysotile (white asbestos)
B00I - R9003 - Other-Community Use						
Ceiling Structures/Linings	Flat AC Sheeting	120m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3893/B00A/R0018/Ceiling Structures/Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting					
	3893/B00I/R9003/In-fill-panel/S11					No Asbestos Detected
B00I - R9005 - General Storeroom						
No Asbestos						
B00I - R9007 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Entry Vestibule

No Asbestos

B00J - R0003 - Security Store

No Asbestos

B00J - R0004 - General Storeroom - Pre

No Asbestos

B00J - R0005 - Home Base - Pre

No Asbestos

B00J - R0006 - Practical Activities - Pre

No Asbestos

B00J - R0007 - Toilets - Boys/Girls - Pre

No Asbestos

B00J - R0008 - Laundry - Pre

No Asbestos

B00J - R0009 - Access Shower/Toilet - Type 2

No Asbestos

B00J - R0010 - Cleaning Distributed Store

No Asbestos

B00J - R0011 - Kitchen - Pre

No Asbestos

B00J - R0012 - Clerical Office - Pre

No Asbestos

B00J - R0013 - Clerical Office - Pre

No Asbestos

B00J - R0014 - General Storeroom - Pre

No Asbestos

B00J - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 2010 - Steel (Steel)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00K - R0001 - Sports Store

No Asbestos

B00K - R0002 - General Assistant/Bulk Store

No Asbestos

B00K - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3893_ASB_221112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017