


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Waniora Public School (3960)
Region : Illawarra and South East
State Electorate : Keira
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Reviewed By : Greencap-NAA : 27 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1954 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3960/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00A - R0019 - Practical Activities						
No Asbestos						
B00A - R0020 - Withdrawal Space - 2hb						
No Asbestos						
B00A - R0021 - Practical Activities						
No Asbestos						
B00A - R0022 - Entry Vestibule						
No Asbestos						
B00A - R0023 - Practical Activities						
No Asbestos						
B00A - R0024 - Withdrawal Space - 2hb						
No Asbestos						
B00A - R0025 - Practical Activities						
No Asbestos						
B00A - R0026 - Home Base						
No Asbestos						
B00A - R0027 - Home Base						
No Asbestos						
B00A - R0028 - Home Base Store						
No Asbestos						
B00A - R0029 - Home Base Store						
No Asbestos						
B00A - R0030 - Home Base						
No Asbestos						
B00A - R0031 - Home Base						
No Asbestos						
B00A - R0032 - Home Base Store						
No Asbestos						
B00A - R0034 - Sports Store						
No Asbestos						
B00A - R0035 - Toilets - Boys						
No Asbestos						
B00A - R0036 - Toilets - Girls						
No Asbestos						
B00A - R0037 - Distribution Board						
No Asbestos					Note: No inspection of live electrical installation.	
B00A - R0038 - External Movement						
No Asbestos						
B00A - R0039 - Personal Effects Storage						
No Asbestos						
B00A - R0040 - Personal Effects Storage						
No Asbestos						
B00A - R0041 - Staff Toilet						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0042 - Home Base Store

No Asbestos

B00A - R0043 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1954 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3960/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00B - R0025 - Duplicating Workroom

No Asbestos

B00B - R0026 - Clerical Office

No Asbestos

B00B - R0027 - Entry Vestibule

No Asbestos

B00B - R0028 - Interview

No Asbestos

B00B - R0029 - Movement

No Asbestos

B00B - R0030 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting					
	3960/B00B/R0030/Ceiling Structures/Linings/S11					No Asbestos Detected

B00B - R0031 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting					
	3960/B00B/R0030/Ceiling Structures/Linings/S11					No Asbestos Detected

B00B - R0032 - Staff Room Annexe

No Asbestos

B00B - R0033 - Staff Room

No Asbestos

B00B - R0034 - Movement

No Asbestos

B00B - R0035 - Staff Toilet

No Asbestos

B00B - R0036 - Staff Toilet

No Asbestos

B00B - R0037 - Staff Toilet

No Asbestos

B00B - R0038 - Sick Bay

No Asbestos

B00B - R0039 - Access Shower/Toilet

No Asbestos

B00B - R0040 - Interview/Office - Type 3

No Asbestos

B00B - R0041 - Cleaning Distributed Store

No Asbestos

B00B - R0042 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0043 - Principal

No Asbestos

B00B - R0044 - Deputy Principal

No Asbestos

B00B - R0048 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings	Flat AC Sheeting		3960/B00B/R0030/Ceiling Structures/Linings/S11			No Asbestos Detected
----------------------------	------------------	--	--	--	--	-----------------------------

B00B - R0049 - Staff Kitchen

No Asbestos

B00B - R0050 - Security Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Communications Room

No Asbestos

B00C - R0004 - K.L.A. Store

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Disabled Shower/Toilet

No Asbestos

B00C - R0007 - Cleaning Distributed Store

No Asbestos

B00C - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 3960/B00F/Wall Cladding/S13					No Asbestos Detected

Interior

B00D - R0001 - External Movement

Floor Coverings Res/Textile	Compressed AC Sheet 3960/B00F/R0001/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Withdrawal Space - 2hb

No Asbestos

B00D - R0006 - Home Base

No Asbestos

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 3960/B00F/Wall Cladding/S13					No Asbestos Detected

Interior

B00E - R0001 - External Movement

Floor Coverings Res/Textile	Compressed AC Sheet 3960/B00F/R0001/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base Store

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Withdrawal Space - 2hb

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 3960/B00F/Wall Cladding/S13					No Asbestos Detected

Interior

B00F - R0001 - External Movement

Floor Coverings Res/Textile	Compressed AC Sheet 3960/B00F/R0001/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 2hb

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other - 2008 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior

B00G - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior

B00H - R0001 - Canteen

No Asbestos

B00H - R0002 - Canteen Office/Store

No Asbestos

B00H - R0003 - Communal Space

No Asbestos

B00H - R0004 - Chair Storeroom

No Asbestos

B00H - R0005 - Communal/Performance Store

No Asbestos

B00H - R0006 - P.E. Store

No Asbestos

B00H - R0007 - Toilet - Lobby

No Asbestos

B00H - R0008 - Toilets - Girls

No Asbestos

B00H - R0009 - Sound Cupboard

No Asbestos

B00H - R0010 - Toilet - Lobby

No Asbestos

B00H - R0011 - Toilets - Boys

No Asbestos

B00H - R0012 - Cleaning Distributed Store

No Asbestos

B00H - R0013 - Plant

No Asbestos

B00H - R0014 - Access Shower/Toilet/Change

No Asbestos

B00H - R0015 - Main Switch Board

No Asbestos

B00H - R0016 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D12760 - Learning Unit - Standard With P.A.A. : Placement Date - 13/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12949 - Learning Unit - Standard With P.A.A. : Placement Date - 25/01/2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13723 - Learning Unit - Standard With P.A.A. : Placement Date - 10/01/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D14235 - Learning Unit - Standard With P.A.A. : Placement Date - 27/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 837 - D14955 - Hcap Shower/Change/Toilet : Placement Date - 24/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

OS 601 - D16157 - Learning Unit - Standard/Withdrawal : Placement Date - 17/07/2008

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017