


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Woonona East Public School (4296)  
**Region :** Illawarra and South East  
**State Electorate :** Keira  
**Local Government Area :** Wollongong

**Initial Survey :** Noel Arnold & Associates : 04 - May - 2008  
**Reviewed By :** AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1963 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/Eaves Linings/S8					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00A - R0001 - Home Base (58.91 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00A - R0002 - Home Base Store (4.11 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0003 - Personal Effects Storage (16.99 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00A - R0004 - Movement (3.47 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/Eaves Linings/S8					<b>Chrysotile (white asbestos)</b>

**B00A - R0005 - Home Base (58.95 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00A - R0006 - Home Base Store (4.07 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0007 - Movement (7.4 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0008 - General Storeroom (1.71 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0009 - Staff Toilet (2.94 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 4296/B00A/R0002/Floor Coverings Res/Textile/S4	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0010 - Staff Toilet (3.03 m2)</b>						
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 4296/B00A/R0002/Floor Coverings Res/Textile/S4	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0011 - General Storeroom (21.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Ceiling Structures/Linings	Flat AC Sheeting 4296/B00A/Eaves Linings/S8	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1963 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/Eaves Linings/S6				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00B - R0001 - Movement (9.86 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00B - R0002 - Main Switch Board (0.71 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00B - R0003 - Uniform Shop (6.51 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00B - R0004 - Seminar/Study (10.98 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00B - R0005 - Home Base (57.99 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00B - R0006 - Home Base Store (6.54 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>

**B00B - R0007 - Movement (3.25 m2)**

No Asbestos

**B00B - R0008 - Personal Effects Storage (7.21 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>

**B00B - R0009 - Home Base Store (6.4 m2)**

Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>

**B00B - R0010 - Toilets - Boys/Girls (3.79 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0011 - Home Base (87.48 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0012 - Home Base (58.63 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0013 - Home Base Store (8.07 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00B - R0014 - Personal Effects Storage (10.28 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00B - R0015 - Cleaning Supplies (9.58 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00B/R0013/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00B - R0016 - Movement (33.2 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0001 - Movement (38.48 m2)**

No Asbestos

**B00C - R0002 - Practical Activities - 1hb (19.4 m2)**

No Asbestos

**B00C - R0003 - Home Base Store (6.02 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0004 - Home Base (59.2 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0005 - Withdrawal Space - 2hb (11.36 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0006 - Home Base (59.19 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0007 - Home Base Store (6.02 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0008 - Practical Activities - 1hb (19.4 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1964 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

**Interior****B00D - R0002 - Garden Store (6.71 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0003 - Movement (6.37 m2)**

No Asbestos

**B00D - R0005 - Drinking Facilities (41.59 m2)**

No Asbestos

**B00D - R0006 - Sports Store (31.29 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0007 - Garden Store (8.53 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0008 - General Storeroom (1.73 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0009 - General Storeroom (1.03 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

Electrical Backing Board	Resinous Board	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	------------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard****B00D - R0010 - Movement (11.44 m2)**

No Asbestos

**B00D - R0011 - Movement (6.98 m2)**

No Asbestos

**B00D - R0012 - Toilets - Girls (28.37 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0013 - Staff Toilet (2.58 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00D/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>

**B00D - R0014 - Toilets-Disabled (12.94 m2)**

No Asbestos

**B00D - R0015 - Toilets - Boys (17.99 m2)**

No Asbestos

**B00D - R0016 - Movement (55.49 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Library - 1963 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00E/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00E - R0001 - Movement (3.07 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00E/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00E - R0002 - Movement (6.53 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0003 - Library Office/Workroom (10.64 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0004 - Home Base (56.97 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0005 - General Storeroom (4.08 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00E - R0006 - General Storeroom (4.08 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00E - R0007 - Home Base (60.04 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0008 - Movement (1.7 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00E/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00E - R0009 - Movement (4.35 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4296/B00A/R0001/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00A/R0002/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00E - R0010 - Communications Room (4.62 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 4296/B00A/R0002/Floor Coverings Res/Textile/S4	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R0011 - Communications Room (4.36 m2)</b>						
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 4296/B00A/R0002/Floor Coverings Res/Textile/S4	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R0012 - Distribution Board (0.27 m2)</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Vermiculite 4296/B00A/R0001/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 4296/B00A/R0002/Floor Coverings Res/Textile/S4	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Pupil Facilities - 1964 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B00H/Eaves Linings/S10					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00H - R0001 - Canteen (17.98 m2)**

No Asbestos

**B00H - R0002 - Canteen Office/Store (2.97 m2)**

No Asbestos

**B00H - R0003 - Canteen Office/Store (1.81 m2)**

No Asbestos

**B00H - R0004 - Canteen Office/Store (2.22 m2)**

No Asbestos

**B00H - R0005 - Movement (15.95 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 1964 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B001/Eaves Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B001 - R0001 - Movement (11.32 m2)**

No Asbestos

**B001 - R0002 - Movement (7.5 m2)**

No Asbestos

**B001 - R0003 - Toilets - Boys (31.77 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B001/R0003/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B001/Eaves Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

**B001 - R0004 - Toilets - Girls (31.7 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B001/R0003/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4296/B001/Eaves Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

**B001 - R0005 - Drinking Facilities (25.2 m2)**

No Asbestos

**B001 - R0006 - Movement (8.41 m2)**

No Asbestos

**B001 - R0007 - Special Programs Room (51 m2)**

No Asbestos

**B001 - R0008 - Craft Store (7.67 m2)**

Wall Linings Internal	Flat AC Sheeting					
	4296/B001/R0008/Wall Linings Internal/S2				<b>No Asbestos Detected</b>	

**B001 - R0009 - Movement (11.32 m2)**

No Asbestos

**B001 - R0010 - Movement (7.52 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00J - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00J - R0001 - Communal Space (148.59 m2)**

No Asbestos

**B00J - R0002 - Raised Platform (57.66 m2)**

No Asbestos

**B00J - R0003 - Communal/Performance Store (10.85 m2)**

No Asbestos

**B00J - R0004 - Hall Chair Store (11.02 m2)**

No Asbestos

**B00J - R0005 - Movement (6.35 m2)**

No Asbestos

**B00J - R0006 - P.E. Store (16.87 m2)**

No Asbestos

**B00J - R0007 - Toilet - Lobby (1.88 m2)**

No Asbestos

**B00J - R0008 - Toilets - Boys (11.2 m2)**

No Asbestos

**B00J - R0009 - Sound Cupboard (2.63 m2)**

No Asbestos

**B00J - R0010 - Toilet - Lobby (3.66 m2)**

No Asbestos

**B00J - R0011 - Toilets - Girls (10.98 m2)**

No Asbestos

**B00J - R0012 - Cleaning Distributed Store (4.99 m2)**

No Asbestos

**B00J - R0013 - Movement (6.98 m2)**

No Asbestos

**B00J - R0014 - Ramp (11.27 m2)**

No Asbestos

**B00J - R0015 - Movement (13.45 m2)**

No Asbestos

**B00J - R0016 - Distribution Board (2.89 m2)**

No Asbestos

Note: No inspection of live electrical installation.

**B00J - R0017 - Access Shower/Toilet (7.5 m2)**

No Asbestos

**B00J - R0018 - Canteen (26.53 m2)**

No Asbestos

**B00J - R0019 - Canteen Office/Store (9.06 m2)**

No Asbestos

**B00J - R0020 - Covered Outdoor Learning Area (128.15 m2)**

No Asbestos

**B00J - R0021 - External Movement (56.06 m2)**

No Asbestos

**B00J - R0022 - External Movement (5.63 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 502 - D11861 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 15/04/1996

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

### Interior

#### R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2

#### R10 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				12 m2
---------	---------------	------------------	--	--	--	-------

#### R2 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				1 m2
---------	---------------	------------------	--	--	--	------

#### R3 - Duplicating Wookroom

Ceiling	Flat AC Sheet	Assumed Asbestos				12 m2
---------	---------------	------------------	--	--	--	-------

#### R4 - Clinic-Waiting

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

#### R5 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
---------	---------------	------------------	--	--	--	-------

#### R6 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

#### R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

#### R8 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

#### R9 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				27 m2

OS 534 - D13575 - Library/Group Study/Office/A V Store : Placement Date - 3/05/2006

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Clerical Office</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - Staff Room</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
<b>R3 - Security Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R4 - Principal</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
<b>R5 - Staff Toilet</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
<b>R6 - Staff Toilet</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
<b>R7 - Reading Area</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2
<b>R8 - Entry</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				14 m2
<b>NS 020 - D15236 - Staff Study/Store : Placement Date - 4/03/2004</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Staff Room</b>						
No Asbestos Found.						
<b>R2 - Store</b>						
No Asbestos Found.						
<b>R3 - Entry</b>						
No Asbestos Found.						
<b>OS 602 - D15622 - Learning Unit - Standard With P.A.A. : Placement Date - 8/11/2005</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

4296\_ASB\_010608\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017