

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Woy Woy South Public School (4329)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Reviewed By : Grencap-NAA : 20 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 4329/B00B/Eaves Linings/S59	80m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting 4329/B00F/Gable Verge Lining/S66					No Asbestos Detected
Expansion joint	Mastic 4329/B00A/Expansion joint/S53	5m	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Underfloor Voids	Non Accessible Area - Area inaccessible - Visual from small hatch only					
Ceiling Voids	Non Accessible Area - Area inaccessible					
Awnings	Flat AC Sheeting 4329/B00B/Eaves Linings/S59	15m2	Northwest	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00A - R0001 - External Movement (1.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00A/R0015/Ceiling Structures/Linings/S21	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting 4329/B00A/R0015/In-fill-panel/S22	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0002 - Movement (2.66 m2)

No Asbestos

B00A - R0003 - Personal Effects Storage (4.23 m2)

No Asbestos

B00A - R0004 - Home Base Store (5.29 m2)

No Asbestos

B00A - R0005 - Home Base (57.05 m2)

In-fill panel	Flat AC Sheeting 4329/B00A/R0006/In-fill panel/S54					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00A - R0006 - Home Base (57.8 m2)

In-fill panel	Flat AC Sheeting 4329/B00A/R0006/In-fill panel/S54					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00A - R0007 - Home Base Store (5.05 m2)

No Asbestos

B00A - R0008 - Personal Effects Storage (13.91 m2)

No Asbestos

B00A - R0009 - External Movement (1.5 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00A/R0015/Ceiling Structures/Linings/S21	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting 4329/B00A/R0015/In-fill-panel/S22	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0010 - Home Base Store (5.05 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0011 - Home Base (57.57 m2)

Infill Panel	Flat AC Sheeting					
	4329/B00A/R0006/In-fill panel/S54					No Asbestos Detected

B00A - R0012 - Home Base (56.81 m2)

Infill Panel	Flat AC Sheeting					
	4329/B00A/R0006/In-fill panel/S54					No Asbestos Detected

B00A - R0013 - Home Base Store (5.23 m2)

No Asbestos

B00A - R0014 - Personal Effects Storage (4.18 m2)

No Asbestos

B00A - R0015 - External Movement (1.38 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00A/R0015/Ceiling Structures/Linings/S21					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00A/R0015/In-fill-panel/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0016 - Movement (2.6 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	100m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4329/B00B/Eaves Linings/S59				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00B - R0001 - External Movement (1.01 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/R0001/Ceiling Structures/Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/R0001/In-fill-panel/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00B - R0002 - Plant (50.85 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55				No Asbestos Detected	
Floor covering adhesive	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56				No Asbestos Detected	

B00B - R0003 - Staff Toilet (4.68 m2)

Wall Linings Internal	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/R0003/Wall Linings Internal/S51				Chrysotile (white asbestos)	

B00B - R0004 - Cleaning Distributed Store (2.09 m2)

Wall Linings Internal	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/R0003/Wall Linings Internal/S51				Chrysotile (white asbestos)	

B00B - R0005 - Shower/Change (4.26 m2)

Wall Linings Internal	Flat AC Sheeting	32m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4329/B00B/R0003/Wall Linings Internal/S51				Chrysotile (white asbestos)	

B00B - R0006 - Staff Room Annexe (8.32 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56				No Asbestos Detected	

B00B - R0007 - Distribution Board (0.36 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	0.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/R0007/Floor Coverings Res/Textile/S57				Chrysotile (white asbestos)	

B00B - R0008 - Kiln Room (0.84 m2)

Kiln	Encapsulated Insulation material within unit					
	4329/B00B/R0008/Kiln/S58				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55				No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56					No Asbestos Detected
B00B - R0009 - Movement (12.13 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56					No Asbestos Detected
B00B - R0010 - External Movement (9.45 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/Eaves Linings/S59					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0011 - Movement (12.07 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56					No Asbestos Detected
B00B - R0012 - Craft Store (15.12 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56					No Asbestos Detected
B00B - R0013 - Special Programs Room (22.38 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	4329/B00B/R0002/Floor covering adhesive/S56					No Asbestos Detected
B00B - R0014 - External Movement (11.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4329/B00B/R0014/Ceiling Structures/Linings/S16					No Asbestos Detected
Upstand Panel	Flat AC Sheeting					
	4329/B00B/R0014/Upstand Panel/S52					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1980 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00C - R0001 - External Movement (1.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0002 - Movement (2.55 m2)

No Asbestos

B00C - R0003 - Personal Effects Storage (4.24 m2)

No Asbestos

B00C - R0004 - Home Base Store (5.27 m2)

No Asbestos

B00C - R0005 - Home Base (56.74 m2)

Infill Panel	Flat AC Sheeting	1m2	Wall heater surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0006 - Home Base (57.58 m2)

Infill Panel	Flat AC Sheeting	1m2	Wall heater surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0007 - Home Base Store (5.07 m2)

No Asbestos

B00C - R0008 - Personal Effects Storage (14.12 m2)

No Asbestos

B00C - R0009 - External Movement (1.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0010 - General Storeroom (5.18 m2)

No Asbestos

B00C - R0011 - Home Base (57.53 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Infill Panel	Flat AC Sheeting	1m2	Wall heater surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0012 - Home Base (56.9 m2)						
Infill Panel	Flat AC Sheeting	1m2	Wall heater surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0013 - Home Base Store (5.2 m2)						
No Asbestos						
B00C - R0014 - Personal Effects Storage (4.27 m2)						
No Asbestos						
B00C - R0015 - Movement (2.55 m2)						
No Asbestos						
B00C - R0016 - External Movement (1.38 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00C/R0016/In-fill-panel/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0017 - Cleaning Distributed Store (0.54 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00B/Eaves Linings/S59				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Compressed AC Sheet				No Asbestos Detected	
	4329/B00D/In-fill-panel/S25					
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00D - R0001 - Toilets - Boys (45.29 m2)

Partition Walls (Cubicles)	Compressed AC Sheet				No Asbestos Detected	
	4329/B00D/R0004/Partition Walls (Cubicles)/S38					

B00D - R0002 - Craft Store (5.81 m2)

No Asbestos

B00D - R0003 - General Storeroom (5.91 m2)

No Asbestos

B00D - R0004 - Toilets - Girls (41.04 m2)

Partition Walls (Cubicles)	Compressed AC Sheet				No Asbestos Detected	
	4329/B00D/R0004/Partition Walls (Cubicles)/S38					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 1960 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - Restricted Access - Raked Ceilings
Underfloor Voids	Non Accessible Area - Entrance to sub-floor bolted shut.
Ceiling Voids	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Extreme Access Issue - Restricted Access - Raked Ceilings

Interior

B00E - R0001 - Communal Space (239.87 m2)

No Asbestos

B00E - R0002 - General Storeroom (4.57 m2)

No Asbestos

B00E - R0003 - Toilets - Girls (5.96 m2)

No Asbestos

B00E - R0004 - Distribution Board (0.49 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4329/B00E/R0004/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	1Unit	LHS - To wall	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4329/B00E/R0004/Electrical Backing Board/S60					Chrysotile (white asbestos)	

B00E - R0005 - General Storeroom (4.71 m2)

No Asbestos

B00E - R0006 - Toilets - Boys (6.84 m2)

Wall Linings Internal	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00E/R0006/Wall Linings Internal/S34					Chrysotile (white asbestos)	

B00E - R0007 - Raised Platform (33.12 m2)

No Asbestos

B00E - R0008 - Movement (31.76 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4329/B00E/R0008/Floor Coverings Res/Textile/S33					No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles					
4329/B00E/R0008/Floor Coverings Res/Textile/S62					No Asbestos Detected	

B00E - R0009 - Cleaning Distributed Store (1.79 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4329/B00E/R0008/Floor Coverings Res/Textile/S33					No Asbestos Detected	

B00E - R0010 - Sports Store (15.03 m2)

No Asbestos

B00E - R0011 - Canteen (45.31 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4329/B00E/R0008/Floor Coverings Res/Textile/S33					No Asbestos Detected	

B00E - R0012 - Canteen Office/Store (3.72 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	4329/B00E/R0008/Floor Coverings Res/Textile/S33				No Asbestos Detected	
B00E - R0013 - Staff Toilet (3.74 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4329/B00E/R0008/Floor Coverings Res/Textile/S33				No Asbestos Detected	
B00E - R0014 - Uniform Shop (9 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4329/B00E/R0008/Floor Coverings Res/Textile/S33				No Asbestos Detected	
B00E - R0015 - External Movement (352.47 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	353m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00E/R0015/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1960 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting 4329/B00F/Gable Verge Lining/S66					No Asbestos Detected
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Awnings	AC Fragments/Debris 4329/B00B/Eaves Linings/S59	30m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00F - R0001 - Practical Activities - 1hb (21.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00F/R0007/Floor Coverings Res/Textile/S39	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles 4329/B00F/R0007/Floor Coverings Res/Textile/S39	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor covering adhesive	Vinyl tile adhesive 4329/B00F/R0006/Floor covering adhesive/S65	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0002 - Home Base (51.03 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00F/R0006/Floor Coverings Res/Textile/S64	51.03m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor covering adhesive	Vinyl tile adhesive - Beneath carpet 4329/B00F/R0006/Floor covering adhesive/S65	51.03m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0003 - Home Base (50.86 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00F/R0006/Floor covering adhesive/S65	50.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor covering adhesive	Vinyl tile adhesive beneath carpet 4329/B00F/R0006/Floor Coverings Res/Textile/S64	50.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0004 - Practical Activities - 1hb (21.56 m2)

Floor covering adhesive	Vinyl tile adhesive 4329/B00F/R0006/Floor covering adhesive/S65	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles 4329/B00F/R0006/Floor Coverings Res/Textile/S64	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0005 - Practical Activities - 1hb (21.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00F/R0006/Floor Coverings Res/Textile/S64	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor covering adhesive	Vinyl tile adhesive 4329/B00F/R0006/Floor covering adhesive/S65	21.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00F - R0006 - Home Base (50.86 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00F/R0006/Floor Coverings Res/Textile/S64	50.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	---------	------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor covering adhesive	Vinyl tile adhesive	50.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00F/R0006/Floor covering adhesive/S65					Chrysotile (white asbestos)	
B00F - R0007 - Sports Store (11.13 m2)						
No Asbestos						
B00F - R0008 - Toilets - Girls (10.55 m2)						
No Asbestos						
B00F - R0009 - Toilets - Boys (16.7 m2)						
No Asbestos						
B00F - R0010 - Garden Store (8.7 m2)						
Table top covering	Hessian backed vinyl sheeting					
4329/B00F/R0010/Table top covering/S63					No Asbestos Detected	
B00F - R0011 - External Movement (76.45 m2)						
No Asbestos						
B00F - R0012 - EDB						
Electrical Backing Board	Encapsulated Insulation material within unit	1m2	Southwest	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Green metallic electrical distribution						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1964 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					
Electrical Backing Board	Encapsulated Insulation material within unit Assumed Asbestos - Electrical Hazard	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

Interior

B00G - R0001 - External Movement (24.78 m2)

No Asbestos

B00G - R0002 - Home Base (46.85 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00G/R0002/Floor Coverings Res/Textile/S72	46.85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	---------	------------	--------------------	---------	--

B00G - R0003 - Home Base (46.85 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00G/R0002/Floor Coverings Res/Textile/S72	46.85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	---------	------------	--------------------	---------	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1960 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting 4329/B00F/Gable Verge Lining/S66					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0001 - Toilets - Boys/Girls (3.38 m2)

No Asbestos

B00H - R0002 - Home Base (83.04 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00H/R0004/Floor Coverings Res/Textile/S40	83.04m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0003 - Practical Activities - 1hb (16.16 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00H/R0004/Floor Coverings Res/Textile/S40	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0004 - Practical Activities - 1hb (16.16 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00H/R0004/Floor Coverings Res/Textile/S40	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0005 - Home Base (83.04 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00H/R0004/Floor Coverings Res/Textile/S40	83.04m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0006 - Toilets - Boys/Girls (3.38 m2)

No Asbestos

B00H - R0007 - Distribution Board (0.78 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00H/R0010/Ceiling Structures/Linings/S2	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
						Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board 4329/B00E/R0004/Electrical Backing Board/S60	2Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Electrical Backing Board	Encapsulated Insulation material within unit Assumed Asbestos - Electrical Hazard	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)

B00H - R0008 - Cleaning Distributed Store (0.78 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00H/R0010/Ceiling Structures/Linings/S2	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
						Chrysotile (white asbestos)

B00H - R0009 - External Movement (29.12 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00H/R0010/Ceiling Structures/Linings/S2	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0010 - External Movement (4.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00H/R0010/Ceiling Structures/Linings/S2	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00H - R0011 - External Movement (23.13 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00H/R0010/Ceiling Structures/Linings/S2	23.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - Administration/Library - 1960 - Brick/Block (Brick/Block)						
Exterior						
Eaves Linings	Flat AC Sheeting	30m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00K/R1007/Ceiling Structures/Linings/S45				Chrysotile (white asbestos)	
Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction					
Gable Verge Lining	Flat AC Sheeting	2m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00I/R0021/Gable end - Packer to roof/S71				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	No Asbestos Found					
Interior						
B00I - R0001 - External Movement (46.8 m2)						
No Asbestos						
B00I - R0002 - Deputy Principal (13.31 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0002/Ceiling Structures/Linings/S68				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00I - R0003 - Interview (9.44 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00I - R0004 - Sick Bay (13.43 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00I/R0004/Floor Coverings Res/Textile/S36				Chrysotile (white asbestos)	
B00I - R0005 - Staff Toilet (6.64 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00I - R0006 - Staff Toilet (7.92 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00I/R0006/Partition Walls (Cubicles)/S37				Chrysotile (white asbestos)	
B00I - R0007 - Staff Room Annexe (13.46 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00I - R0008 - Duplicating Workroom (16 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4329/B00I/R0019/Ceiling Structures/Linings/S35				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00I - R0009 - Main Switch Board (9.68 m2)						
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00E/R0004/Electrical Backing Board/S60				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Encapsulated Insulation material within unit	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B001 - R0010 - Hall Chair Store (3.74 m2)						
No Asbestos						
B001 - R0011 - Movement (8.71 m2)						
No Asbestos						
B001 - R0012 - Staff Room (96.54 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B001/R0004/Floor Coverings Res/Textile/S36	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Sheet 4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
B001 - R0013 - Distribution Board (1.17 m2) Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0002/Ceiling Structures/Linings/S68					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Electrical Backing Board	Resinous Board 4329/B00E/R0004/Electrical Backing Board/S60	2Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0014 - Security Store (13.84 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4329/B001/R0004/Floor Coverings Res/Textile/S36	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0015 - Cleaning Distributed Store (3.58 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4329/B001/R0004/Floor Coverings Res/Textile/S36	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0016 - Deputy Principal (13.68 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0017 - Principal (22.69 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0018 - Clerical Office (13.54 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0019 - Entry Vestibule (23.77 m2)						
Ceiling Structures/Linings	Vermiculite 4329/B001/R0019/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0020 - Movement (17.47 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4329/B001/R0019/Ceiling Structures/Linings/S35				Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0021 - External Movement (34.79 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4329/B001/R0021/Ceiling Structures/Linings/S10				No Asbestos Detected	
B001 - R0022 - Stairs (10.48 m2)						
No Asbestos						
B001 - R1001 - Toilets - Girls (6.68 m2)						
No Asbestos						
B001 - R1002 - Cleaning Distributed Store (1.28 m2)						
No Asbestos						
B001 - R1003 - Movement (1.41 m2)						
No Asbestos						
B001 - R1004 - Withdrawal Space - 1hb (15.9 m2)						
No Asbestos						
B001 - R1005 - K.L.A. Store (14.33 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4329/B001/R1005/Floor Coverings Res/Textile/S44				No Asbestos Detected	
Security Door	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Material metal encased						
B001 - R1006 - Library Office/Workroom (23.77 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4329/B001/R1005/Floor Coverings Res/Textile/S44				No Asbestos Detected	
B001 - R1007 - Library Office/Workroom (8.64 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	4329/B001/R1005/Floor Coverings Res/Textile/S44				No Asbestos Detected	
B001 - R1008 - Seminar/Study (15.78 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	4329/B001/R1005/Floor Coverings Res/Textile/S44				No Asbestos Detected	
B001 - R1009 - Seminar/Study (19.97 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	4329/B001/R1005/Floor Coverings Res/Textile/S44				No Asbestos Detected	
B001 - R1010 - Movement (18.39 m2)						
No Asbestos						
B001 - R1011 - Reading Area (243.69 m2)						
No Asbestos						
B001 - R1012 - Stairs (15.47 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4329/B00J/Eaves Linings/S11					No Asbestos Detected
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00J - R0001 - General Storeroom (13.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00J/R0001/Ceiling Structures/Linings/S41	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0002 - Staff Toilet (1.3 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00J/R0001/Ceiling Structures/Linings/S41	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00J/R0005/Floor Coverings Res/Textile/S42	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting 4329/B00J/R0002/Wall Linings Internal/S43	2m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00J - R0003 - General Storeroom (1.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00J/R0001/Ceiling Structures/Linings/S41	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00J/R0005/Floor Coverings Res/Textile/S42	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting 4329/B00J/R0002/Wall Linings Internal/S43	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Electrical Backing Board	Resinous Board 4329/B00E/R0004/Electrical Backing Board/S60	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00J - R0004 - General Storeroom (2.73 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00J/R0001/Ceiling Structures/Linings/S41	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00J/R0005/Floor Coverings Res/Textile/S42	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00J - R0005 - General Assistant/Bulk Store (17.64 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00J/R0001/Ceiling Structures/Linings/S41	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00J/R0005/Floor Coverings Res/Textile/S42	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Table/bench top covering	Vinyl Sheet 4329/B00F/R0010/Table top covering/S63					No Asbestos Detected
--------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4329/B00M/Eaves Linings/S6	18m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 4329/B00M/R0007/In-fill-panel/S30	8m2	South, Upper Portion Adjacent KRI008	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Gable Verge Lining	Flat AC Sheeting 4329/B00I/R0021/Gable end - Packer to roof/S71	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00K - R0001 - External Movement (12.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00K/R1007/Ceiling Structures/Linings/S45	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00K - R0002 - Home Base (58.32 m2)

Ceiling Structures/Linings	Vermiculite 4329/B00K/R0002/Ceiling Structures/Linings/S50 Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00K/R1003/Floor Coverings Res/Textile/S46	58.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00K - R0003 - Practical Activities - 1hb (12.96 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00K/R1003/Floor Coverings Res/Textile/S46	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	------	------------	--------------------	---------	--

B00K - R0004 - P.E. Store (12.38 m2)

No Asbestos

B00K - R0005 - External Movement (12.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4329/B00K/R1007/Ceiling Structures/Linings/S45	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00K - R0006 - Home Base (58.32 m2)

Ceiling Structures/Linings	Vermiculite 4329/B00K/R0002/Ceiling Structures/Linings/S50 Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00K/R1003/Floor Coverings Res/Textile/S46	58.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00K - R0007 - Practical Activities - 1hb (12.94 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00K/R1003/Floor Coverings Res/Textile/S46	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	------	------------	--------------------	---------	--

B00K - R0008 - General Storeroom (3.6 m2)

No Asbestos

B00K - R0009 - External Movement (59.16 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0010 - Movement (3.05 m2)						
No Asbestos						
B00K - R0011 - Lift (2.22 m2)						
No Asbestos						
B00K - R0012 - External Stairs (11.65 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1007/Ceiling Structures/Linings/S45					Chrysotile (white asbestos)	
B00K - R1001 - Toilets - Boys (6.59 m2)						
No Asbestos						
B00K - R1002 - Distribution Board (0.58 m2)						
Note: No inspection of live electrical installation.						
Electrical Backing Board	Resinous Board	2Unit	North & south	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00E/R0004/Electrical Backing Board/S60					Chrysotile (white asbestos)	
Electrical Backing Board	Encapsulated Insulation material within unit	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00K - R1003 - Practical Activities - 1hb (12.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1003/Floor Coverings Res/Textile/S46					Chrysotile (white asbestos)	
B00K - R1004 - Home Base (59.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1003/Floor Coverings Res/Textile/S46					Chrysotile (white asbestos)	
B00K - R1005 - Home Base (59.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1003/Floor Coverings Res/Textile/S46					Chrysotile (white asbestos)	
B00K - R1006 - Practical Activities - 1hb (12.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1003/Floor Coverings Res/Textile/S46					Chrysotile (white asbestos)	
B00K - R1007 - Movement (54.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1007/Ceiling Structures/Linings/S45					Chrysotile (white asbestos)	
B00K - R1008 - Movement (3.05 m2)						
No Asbestos						
B00K - R1009 - Lift (2.22 m2)						
No Asbestos						
B00K - R1010 - Stairs (16.34 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00K/R1007/Ceiling Structures/Linings/S45					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4329/B00L/Eaves Linings/S9	78m2	Throughout	Minimal Damage (2)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4329/B00F/Gable Verge Lining/S66					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 4329/B00L/R0013/Wall Linings Internal/S49	6m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Manhole access blocked with stored items					

Interior

B00L - R0001 - Home Base (56.88 m2)

No Asbestos

B00L - R0002 - Home Base Store (4.2 m2)

No Asbestos

B00L - R0003 - Distribution Board (0.56 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 4329/B00L/R0003/Wall Linings Internal/S47	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board 4329/B00E/R0004/Electrical Backing Board/S60	2Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00L - R0004 - Seminar/Study (10.51 m2)

Floor Coverings Res/Textile	Vinyl Sheet 4329/B00B/R0002/Floor Coverings Res/Textile/S55					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00L - R0005 - Movement (7.5 m2)

No Asbestos

B00L - R0006 - Home Base Store (4.2 m2)

No Asbestos

B00L - R0007 - Home Base (55.93 m2)

No Asbestos

B00L - R0008 - Home Base (84.13 m2)

No Asbestos

B00L - R0009 - General Storeroom (4.41 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00L/R0009/Floor Coverings Res/Textile/S31	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------------	--------------------	---------	--

B00L - R0010 - Toilets - Boys/Girls (1.89 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4329/B00L/R0009/Floor Coverings Res/Textile/S31	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------------	--------------------	---------	--

B00L - R0011 - Home Base Store (6.94 m2)

No Asbestos

B00L - R0012 - Practical Activities - 1hb (10.35 m2)

No Asbestos

B00L - R0013 - Toilets - Girls (22.93 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet 4329/B00L/R0013/Partition Walls (Cubicles)/S48				No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting 4329/B00L/R0016/Ceiling Structures/Linings/S8	3m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting 4329/B00L/R0013/Wall Linings Internal/S49	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00L - R0014 - Garden Store (8.91 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4329/B00L/R0016/Ceiling Structures/Linings/S8	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00L - R0015 - Toilets - Boys (25.59 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4329/B00L/R0013/Partition Walls (Cubicles)/S48				No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting 4329/B00L/R0013/Wall Linings Internal/S49	3m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting 4329/B00L/R0016/Ceiling Structures/Linings/S8	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00L - R0016 - Movement (33.92 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4329/B00L/R0016/Ceiling Structures/Linings/S8	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00L - R0017 - External Movement (63.42 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4329/B00L/R0016/Ceiling Structures/Linings/S8	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00L - R0018 - External Movement (22.53 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/Eaves Linings/S6					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	16m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00I/R0021/Gable end - Packer to roof/S71					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior

B00M - R0001 - Staff Room Annexe (16.52 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)

B00M - R0002 - Special Programs Room (18.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)

B00M - R0003 - General Storeroom (16.95 m2)

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)

B00M - R0004 - No Access (7.54 m2)

No Asbestos

B00M - R0005 - Staff Toilet (3.65 m2)

No Asbestos

B00M - R0006 - Distribution Board (0.53 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)

B00M - R0007 - Movement (8.99 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)

In-fill-panel	Flat AC Sheeting	4m	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4329/B00M/R0007/In-fill-panel/S30					Chrysotile (white asbestos)

B00M - R0008 - External Movement (18.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0008/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

Upstands	Flat AC Sheeting	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00M/R0008/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 1980 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	78m2	Throughout	Minimal Damage (2)	Medium (2)	Low Priority (2-3)
	4329/B00N/Eaves Linings/S4					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00I/R0021/Gable end - Packer to roof/S71					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

Interior

B00N - R0001 - Home Base (57.09 m2)

No Asbestos

B00N - R0002 - Home Base Store (6.24 m2)

No Asbestos

B00N - R0003 - Distribution Board (0.58 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0012/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00E/R0004/Electrical Backing Board/S60					Chrysotile (white asbestos)

B00N - R0004 - Practical Activities - 1hb (13.82 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0012/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)

B00N - R0005 - Home Base Store (6.35 m2)

No Asbestos

B00N - R0006 - Home Base (57.25 m2)

No Asbestos

B00N - R0007 - Home Base (86.28 m2)

No Asbestos

B00N - R0008 - Toilets - Boys/Girls (1.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0012/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)

B00N - R0009 - General Storeroom (1.9 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0012/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)

B00N - R0010 - Toilets - Girls (25.49 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 4329/B00N/R0014/Partition Walls (Cubicles)/S27					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	North, South, Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00N - R0011 - General Storeroom (2.66 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00N - R0012 - Practical Activities - 1hb (6.95 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00N/R0012/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)	

B00N - R0013 - Cleaning Distributed Store (4.15 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

B00N - R0014 - Toilets - Boys (24 m2)

Partition Walls (Cubicles)	Compressed AC Sheet				No Asbestos Detected	
4329/B00N/R0014/Partition Walls (Cubicles)/S27						

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	3m2	North, South, Upper portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

B00N - R0015 - External Movement (97.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4329/B00N/R0015/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 1960 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B000 - R0001 - External Movement (11.97 m2)

No Asbestos

B000 - R0002 - Special Programs Room (47 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4329/B00G/R0002/Floor Coverings Res/Textile/S72	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Building Services - 2000 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/B00P/Eaves Linings/S26					Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior

B00P - R0001 - General Assistant/Bulk Store (7.57 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B00Q - R0001 - Practical Activities - 1hb (14.06 m2)**

No Asbestos

B00Q - R0002 - Personal Effects Storage (4.48 m2)

No Asbestos

B00Q - R0003 - Home Base Store (6.2 m2)

No Asbestos

B00Q - R0004 - Home Base (58.87 m2)

No Asbestos

B00Q - R0005 - Withdrawal Space - 2hb (11.43 m2)

No Asbestos

B00Q - R0006 - Home Base (59.4 m2)

No Asbestos

B00Q - R0007 - Home Base Store (6.34 m2)

No Asbestos

B00Q - R0008 - Personal Effects Storage (4.51 m2)

No Asbestos

B00Q - R0009 - Practical Activities - 1hb (14.3 m2)

No Asbestos

B00Q - R0010 - Practical Activities - 1hb (13.82 m2)

No Asbestos

B00Q - R0011 - Personal Effects Storage (4.52 m2)

No Asbestos

B00Q - R0012 - Home Base Store (6.34 m2)

No Asbestos

B00Q - R0013 - Home Base (58.37 m2)

No Asbestos

B00Q - R0014 - Withdrawal Space - 2hb (11.49 m2)

No Asbestos

B00Q - R0015 - Home Base (59.79 m2)

No Asbestos

B00Q - R0016 - Home Base Store (6.19 m2)

No Asbestos

B00Q - R0017 - Personal Effects Storage (4.73 m2)

No Asbestos

B00Q - R0018 - Practical Activities - 1hb (14.21 m2)

No Asbestos

B00Q - R0019 - Laundry - P (8.67 m2)

No Asbestos

B00Q - R0020 - Access Shower/Toilet/Change (18.87 m2)

No Asbestos

B00Q - R0021 - External Movement (92.19 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - Movement Between B00M & B00N

Exterior

No Asbestos

Interior

Build+1 - Room+1 - Walkway

Ceiling Structures/Linings Flat AC Sheeting
 4329/Build+1/Room+1/Ceiling Structures/Linings/S5

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+2 - Movement Between B00J & B00C

Exterior

No Asbestos

Interior

Build+2 - Room+1 - Walkway

Ceiling Structures/Linings	Flat AC Sheeting	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

4329/Build+2/Room+1/Ceiling Structures/Linings/S12

Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+3 - Movement Between B00C & B00A

Exterior

No Asbestos

Interior

Build+3 - Room+1 - Walkway

Ceiling Structures/Linings	Flat AC Sheeting 4329/Build+3/Room+1/Ceiling Structures/Linings/S15					No Asbestos Detected
Upstand Panel	Flat AC Sheeting 4329/Build+4/Room+1/Upstand Panel/S20					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+4 - Movement Between B00A & B00B

Exterior

No Asbestos

Interior

Build+4 - Room+1 - Walkway

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4329/Build+4/Room+1/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Upstand Panel	Flat AC Sheeting					No Asbestos Detected
	4329/Build+4/Room+1/Upstand Panel/S20					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017