

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Warilla North Public School (4333)
Region : Illawarra and South East
State Electorate : Shellharbour
Local Government Area : Shellharbour

Initial Survey : Noel Arnold & Associates : 04 - May - 2008
Reviewed By : AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00A - R0001 - Staff Room (31.59 m2)

No Asbestos

B00A - R0006 - Entry Vestibule (12.19 m2)

No Asbestos

B00A - R0007 - Principal (14.34 m2)

No Asbestos

B00A - R0008 - General Storeroom (3.03 m2)

No Asbestos

B00A - R0009 - Staff Toilet (3.22 m2)

No Asbestos

B00A - R0010 - General Storeroom (8.59 m2)

No Asbestos

B00A - R0011 - Staff Toilet (5.85 m2)

No Asbestos

B00A - R0012 - Staff Toilet (5.49 m2)

No Asbestos

B00A - R0013 - General Storeroom (4.3 m2)

No Asbestos

B00A - R0014 - Kiln Room (0.92 m2)

No Asbestos

B00A - R0015 - Interview (10.02 m2)

No Asbestos

B00A - R0016 - Movement (27.97 m2)

No Asbestos

B00A - R0017 - Movement (1.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00A - R0018 - Movement (3.39 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00A - R0019 - Cleaning Distributed Store (0.64 m2)

No Asbestos

B00A - R0020 - General Storeroom (9.44 m2)

No Asbestos

B00A - R0021 - General Storeroom (7.87 m2)

No Asbestos

B00A - R0022 - Sick Bay (22.61 m2)

No Asbestos

B00A - R0023 - Clerical Office (29.42 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00B/Eaves Linings/S11					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00B - R0001 - Home Base (59.11 m2)	No Asbestos
B00B - R0002 - Home Base Store (5.68 m2)	No Asbestos
B00B - R0003 - Personal Effects Storage (10.85 m2)	No Asbestos
B00B - R0004 - Movement (5.62 m2)	No Asbestos
B00B - R0005 - Home Base (58.07 m2)	No Asbestos
B00B - R0006 - Home Base Store (5.71 m2)	No Asbestos
B00B - R0007 - Home Base (58.07 m2)	No Asbestos
B00B - R0008 - Home Base Store (5.68 m2)	No Asbestos
B00B - R0009 - Movement (5.65 m2)	No Asbestos
B00B - R0010 - Personal Effects Storage (10.91 m2)	No Asbestos
B00B - R0011 - Home Base (58.95 m2)	No Asbestos
B00B - R0012 - Home Base Store (5.71 m2)	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Staff Facilities/General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00C/Eaves Linings/S12					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0001 - Movement (6.93 m2)	No Asbestos
B00C - R0002 - Main Switch Board (4.76 m2)	No Asbestos
B00C - R0004 - Withdrawal Space - 1hb (18.9 m2)	No Asbestos
B00C - R0005 - Home Base (58.08 m2)	No Asbestos
B00C - R0006 - Toilets - Boys/Girls (2.08 m2)	No Asbestos
B00C - R0007 - Home Base Store (4.51 m2)	No Asbestos
B00C - R0008 - Personal Effects Storage (3.76 m2)	No Asbestos
B00C - R0009 - Movement (3.31 m2)	No Asbestos
B00C - R0010 - Staff Toilet (3.7 m2)	No Asbestos
B00C - R0011 - Staff Kitchen (8.61 m2)	No Asbestos
B00C - R0012 - Home Base (57.04 m2)	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4333/B00H/Eaves Linings/S8					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0003 - Movement (18.42 m2)

No Asbestos

B00H - R0004 - Reading Area (86.34 m2)

No Asbestos

B00H - R0005 - Library Office/Workroom (19.8 m2)

No Asbestos

B00H - R0006 - Communications Room (9.12 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Vermiculite 4333/B00I/Eaves Linings/S9	Limited Samples Taken				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00I - R0001 - Canteen (23.55 m2)	No Asbestos				
B00I - R0002 - Canteen Office/Store (1.99 m2)	No Asbestos				
B00I - R0003 - Canteen Office/Store (3.11 m2)	No Asbestos				
B00I - R0004 - Staff Toilet (1.48 m2)	No Asbestos				
B00I - R0005 - Movement (3.14 m2)	No Asbestos				
B00I - R0006 - General Storeroom (4.28 m2)	No Asbestos				
B00I - R0007 - Toilets - Girls (42.42 m2)	No Asbestos				
B00I - R0008 - Plant (6.61 m2)	No Asbestos				
B00I - R0011 - Toilets - Boys (27.22 m2)	No Asbestos				
B00I - R0012 - Cleaning Distributed Store (3.19 m2)	No Asbestos				
B00I - R0013 - Toilets - Boys (42.38 m2)	No Asbestos				
B00I - R0014 - Plant (6.65 m2)	No Asbestos				
B00I - R0015 - Movement (39.82 m2)	No Asbestos				
B00I - R0016 - General Storeroom (9.82 m2)	No Asbestos				
B00I - R0017 - Disabled Shower/Toilet (10.91 m2)	No Asbestos				
B00I - R0018 - Movement (6.71 m2)	No Asbestos				
B00I - R0019 - Cleaning Distributed Store (12.38 m2)	No Asbestos				

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00J/Eaves Linings/S13					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00J - R0001 - Home Base (58.96 m2)	No Asbestos
B00J - R0009 - Movement (5.59 m2)	No Asbestos
B00J - R0010 - Personal Effects Storage (10.68 m2)	No Asbestos
B00J - R0011 - Home Base (58.33 m2)	No Asbestos
B00J - R0012 - Home Base Store (5.68 m2)	No Asbestos
B00J - R0013 - Communal Space (119.39 m2)	No Asbestos
B00J - R0014 - Communal Space (27.87 m2)	No Asbestos
B00J - R0015 - Communications Room (5.66 m2)	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00K - R0001 - General Storeroom (9.75 m2)

No Asbestos

B00K - R0002 - Cleaning Supplies (13.07 m2)

No Asbestos

B00K - R0003 - Toilets - Girls (42.22 m2)

No Asbestos

B00K - R0004 - Cleaning Distributed Store (6.53 m2)

No Asbestos

B00K - R0005 - Toilets - Boys (32.49 m2)

No Asbestos

B00K - R0006 - Other-Vacant (4.3 m2)

No Asbestos

B00K - R0007 - Movement (37.09 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017