

Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Westport Public School (4411)
Region : North Coast
State Electorate : Port Macquarie
Local Government Area : Port Macquarie-Hastings

Initial Survey : Noel Arnold & Associates : 05 - May - 2008
Reviewed By : Grencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1970 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet	17m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00B/In-fill-panel/S24					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible slab on ground					

Interior**B00A - R0001 - Toilets - Boys (3.11 m2)**

No Asbestos

B00A - R0004 - Interview (10.33 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00A - R0005 - General Storeroom (9.57 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00A - R0010 - Toilets - Boys (3.52 m2)

No Asbestos

B00A - R0011 - Cleaning Supplies (2.35 m2)

No Asbestos

B00A - R0012 - Distribution Board (2.49 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4411/B00B/R0003/Electrical Mounting Board/S25					Chrysotile (white asbestos)

B00A - R0013 - Toilets - Boys (16.62 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00A/R0014/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)

B00A - R0014 - Toilets - Girls (16.61 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00A/R0014/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)

B00A - R0015 - Movement (126.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	127m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0016 - Home Base (77.32 m2)						
No Asbestos						
B00A - R0017 - Practical Activities (14.78 m2)						
No Asbestos						
B00A - R0018 - Withdrawal Space - 1hb (8.27 m2)						
No Asbestos						
B00A - R0019 - Home Base (90.98 m2)						
No Asbestos						
B00A - R0020 - Withdrawal Space - 1hb (8.27 m2)						
No Asbestos						
B00A - R0021 - Practical Activities (20.31 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
In-fill-panel	Compressed AC Sheet	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00B/In-fill-panel/S24				Chrysotile (white asbestos)	
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible slab on ground					

Interior

B00B - R0001 - Toilets - Girls (16.47 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00B/R0001/Partition Walls (Cubicles)/S12				Chrysotile (white asbestos)	

B00B - R0002 - Toilets - Boys (16.46 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00B/R0001/Partition Walls (Cubicles)/S12				Chrysotile (white asbestos)	

B00B - R0003 - Distribution Board (2.51 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4411/B00B/R0003/Electrical Mounting Board/S25				Chrysotile (white asbestos)	

B00B - R0004 - Cleaning Supplies (2.36 m2)

No Asbestos

B00B - R0005 - Toilets - Boys (3.66 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00B - R0014 - Home Base Store (6.86 m2)

No Asbestos

B00B - R0015 - Personal Effects Storage (6.86 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00B/R0008/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	

B00B - R0016 - Movement (126.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	127m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00B - R0017 - Practical Activities (21.68 m2)

No Asbestos

B00B - R0018 - Home Base (96.33 m2)

No Asbestos

B00B - R0019 - Withdrawal Space - 1hb (11.2 m2)

No Asbestos

B00B - R0020 - Home Base (77.52 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0021 - Practical Activities (14.41 m2)

No Asbestos

B00B - R0022 - Withdrawal Space - 1hb (8.15 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground					
Eaves Linings	Flat AC Sheeting	50m	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	50m	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

Interior

B00C - R0001 - Movement (101.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	102m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00C - R0002 - Movement (79.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Staff Facilities/Building Services - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0017/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
Ceiling Voids - Raked Ceiling	Non Accessible Area - no access to ceiling space					
Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground					
Infil panels	Flat AC Sheeting	20m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/In-fill-panel/S21				Chrysotile (white asbestos)	

Interior

B00D - R0001 - Withdrawal - M (14.71 m2)

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17				Chrysotile (white asbestos)	

B00D - R0002 - Cleaning Supplies (4.45 m2)

No Asbestos

B00D - R0003 - Movement (11.15 m2)

No Asbestos

B00D - R0004 - Staff Toilet (4.06 m2)

No Asbestos

B00D - R0005 - Staff Toilet (9.64 m2)

No Asbestos

B00D - R0006 - General Storeroom (9.34 m2)

No Asbestos

B00D - R0007 - Cleaning Supplies (6.16 m2)

No Asbestos

B00D - R0008 - Garden Store (9.73 m2)

No Asbestos

B00D - R0009 - Home Base (42.93 m2)

No Asbestos

B00D - R0010 - Practical Activities - 1hb (13.44 m2)

No Asbestos

B00D - R0011 - Home Base Store (4.26 m2)

No Asbestos

B00D - R0012 - General Assistant/Bulk Store (7.02 m2)

No Asbestos

B00D - R0013 - Main Switch Board (7.02 m2)

Electrical Backing Board	Resinous Board	3Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard assumed live at time						

B00D - R0014 - Staff Room (104.02 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	104m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive	104m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00D - R0015 - General Storeroom (9.05 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00D/R0015/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
B00D - R0016 - General Storeroom (9.49 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00D/R0015/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
B00D - R0017 - Interview (9.6 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00D/R0015/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00D - R0018 - Movement (9.67 m2)						
No Asbestos						
B00D - R0019 - Staff Room Annexe (15.84 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00D - R0020 - Movement (1.26 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00D/R0015/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00D - R0021 - Staff Toilet (1.98 m2)						
No Asbestos						
B00D - R0022 - Movement (116.32 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	117m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0017/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0017/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
In-fill-panel	Compressed AC Sheet	36m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/In-fill-panel/S21				Chrysotile (white asbestos)	
Underfloor Voids - Slab on Ground	Non Accessible Area - no access slab on ground					
Ceiling Voids - Raked Ceiling	Non Accessible Area - no access to ceiling space					

Interior

B00E - R0001 - Home Base (62.91 m2)

No Asbestos

B00E - R0004 - Duplicating Workroom (15.47 m2)

No Asbestos

B00E - R0005 - General Storeroom (12.64 m2)

No Asbestos

B00E - R0006 - General Storeroom (1.58 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17				Chrysotile (white asbestos)	

B00E - R0007 - Toilets - Boys (1.58 m2)

No Asbestos

B00E - R0008 - Community Clinic (9.18 m2)

No Asbestos

B00E - R0009 - Clerical Office (22.08 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17				Chrysotile (white asbestos)	

B00E - R0010 - Entry Vestibule (13.17 m2)

No Asbestos

B00E - R0011 - General Storeroom (10.07 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17				Chrysotile (white asbestos)	

B00E - R0012 - Principal (15.73 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00E - R0013 - Deputy Principal (15.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00E - R0014 - Staff Toilet (3.8 m2)						
No Asbestos						
B00E - R0015 - General Storeroom (1.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	1.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	1.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00E - R0016 - General Storeroom (12.78 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
4411/B00E/R0016/Floor Coverings Res/Textile/S18					No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
4411/B00E/R0016/Floor Coverings Res/Textile/S19					No Asbestos Detected	
B00E - R0017 - Movement (76.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0017/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00E - R0018 - Withdrawal Space - 2hb (12.85 m2)						
No Asbestos						
B00E - R0019 - Practical Activities (14.41 m2)						
No Asbestos						
B00E - R0020 - Home Base (49.26 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0017/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet	64m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/In-fill-panel/S21					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible sealed ceilings					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab to ground					

Interior

B00F - R0001 - Home Base (64.4 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00F - R0002 - Home Base (64.4 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00F - R0003 - Toilets - Girls (54.99 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00F/R0003/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)

B00F - R0004 - Toilets - Boys (55.01 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00F/R0003/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)

B00F - R0005 - Home Base (64.15 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R0006 - Home Base (64.15 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R0007 - Cleaning Supplies (5.13 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4411/B00F/R0001/Ceiling Structures/Linings/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00F - R0008 - Movement (124.06 m2)						
No Asbestos						
B00F - R0009 - Stairs (9.01 m2)						
No Asbestos						
B00F - R1001 - Home Base (63.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R1002 - Home Base (63.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R1003 - Practical Activities - 1hb (24.48 m2)						
No Asbestos						
B00F - R1005 - Home Base (63.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R1006 - Home Base (63.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	
B00F - R1007 - Movement (27.1 m2)						
No Asbestos						
B00F - R1008 - Aboriginal Resource Centre (42.51 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0011/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00F - R1009 - Movement (9.8 m2)

No Asbestos

B00F - R1010 - Stairs (13.68 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4411/B00L/Eaves Linings/S22					No Asbestos Detected
In-fill-panel	Compressed AC Sheet 4411/B00G/Infill panels/S11					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground					

Interior

B00G - R0005 - Movement (71.37 m2)

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B00G - R0006 - Practical Activities (18.31 m2)

No Asbestos

B00G - R0007 - Home Base (51.34 m2)

No Asbestos

B00G - R0008 - Home Base (51.56 m2)

No Asbestos

B00G - R0009 - Practical Activities (18.25 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 1970 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet	54m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/In-fill-panel/S21					Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible slab on ground					

Interior**B00H - R0005 - Toilets - Boys (46.69 m2)**

Ceiling Structures/Linings	Vermiculite					
	4411/B00H/R0006/Ceiling Structures/Linings/S2					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)

B00H - R0006 - Cleaning Supplies (5.76 m2)

Ceiling Structures/Linings	Vermiculite					
	4411/B00H/R0006/Ceiling Structures/Linings/S2					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00H - R0008 - General Storeroom (11.66 m2)

Ceiling Structures/Linings	Vermiculite					
	4411/B00H/R0006/Ceiling Structures/Linings/S2					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Vinyl Tiles					
	4411/B00H/R0008/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00H - R0009 - Toilets - Girls (47.85 m2)

Ceiling Structures/Linings	Vermiculite					
	4411/B00H/R0006/Ceiling Structures/Linings/S2					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00H/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)

B00H - R0010 - Distribution Board (0.66 m2)

Door lining	Flat AC Sheeting	5m2	West	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4411/B00H/R1009/Door lining/S23					Chrysotile (white asbestos)

Note: No inspection of live electrical installation.

B00H - R0015 - Movement (128.94 m2)

No Asbestos

B00H - R0016 - Stairs (5.26 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4411/B00E/R0017/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00H - R0017 - Disabled Shower/Toilet (5.55 m2)

No Asbestos

B00H - R0018 - Toilet - Lobby (2.09 m2)

No Asbestos

B00H - R0019 - Home Base (44 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0020 - Practical Activities (15.04 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0021 - Withdrawal Space - 2hb (9.3 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0022 - Practical Activities (15.07 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0023 - Home Base (44.14 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0024 - Practical Activities (14.83 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0025 - Home Base (44.14 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0026 - Withdrawal Space - 2hb (9.34 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0027 - Practical Activities (14.92 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0028 - Home Base (44.35 m2)						
Ceiling Structures/Linings	Vermiculite	4411/B00H/R0006/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R1001 - Communications Room (13.5 m2)						
No Asbestos						
B00H - R1002 - Communications Room (13.32 m2)						
No Asbestos						
B00H - R1003 - K.L.A. Store (26.81 m2)						
No Asbestos						
B00H - R1004 - Library Office/Workroom (10.21 m2)						
No Asbestos						
B00H - R1005 - General Storeroom (18.82 m2)						
No Asbestos						
B00H - R1006 - Toilets - Boys (4.37 m2)						
No Asbestos						
B00H - R1007 - Cleaning Supplies (0.85 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R1008 - Movement (12.83 m2)						
No Asbestos						
B00H - R1009 - Distribution Board (0.85 m2)						
Note: No inspection of live electrical installation.						
Door lining	Flat AC Sheeting	5m2	West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4411/B00H/R1009/Door lining/S23					Chrysotile (white asbestos)	
B00H - R1010 - Toilets - Girls (4.37 m2)						
No Asbestos						
B00H - R1011 - Reading Area (282.95 m2)						
No Asbestos						
B00H - R1012 - Movement (3.24 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00H - R1013 - Movement (2.84 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00H - R1014 - Stairs (5.35 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00H/R1012/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4411/B00L/Eaves Linings/S22					No Asbestos Detected
In-fill-panel	Compressed AC Sheet 4411/B00E/In-fill-panel/S21	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior

B00K - R0001 - General Assistant/Bulk Store (8.16 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4411/B00K/R0001/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00K - R0002 - Cleaning Supplies (7.75 m2)

No Asbestos

B00K - R0003 - P.E. Store (22.8 m2)

No Asbestos

B00K - R0004 - Kiln Room (4.69 m2)

No Asbestos

B00K - R0005 - Staff Toilet (4.8 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 4411/B00A/R0014/Partition Walls (Cubicles)/S15	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------	--------------------	---------	--

B00K - R0006 - Staff Toilet (4.75 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 4411/B00A/R0014/Partition Walls (Cubicles)/S15	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------	--------------------	---------	--

B00K - R0007 - Staff Toilet (4.41 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4411/B00K/R0001/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00K - R0008 - Canteen Office/Store (4.85 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4411/B00K/R0001/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00K - R0009 - Canteen (46.75 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4411/B00K/R0001/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00K - R0010 - Canteen Office/Store (4.8 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4411/B00K/R0001/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00K - R0011 - Cleaning Supplies (6.74 m2)

No Asbestos

B00K - R0012 - Movement (44.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4411/B00E/R0017/Ceiling Structures/Linings/S20	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00K - R0013 - Movement (32.89 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4411/B00E/R0017/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Communal Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 4411/B00L/Eaves Linings/S22					No Asbestos Detected

Interior

B00L - R0001 - Communal Space (237.25 m2)

No Asbestos

B00L - R0002 - Raised Platform (63.89 m2)

No Asbestos

B00L - R0003 - Movement (7.3 m2)

No Asbestos

B00L - R0004 - Movement (8.63 m2)

No Asbestos

B00L - R0005 - External Movement (48.3 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Communal Facilities - 2004 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00M - R0001 - Sports Store (40.07 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017