

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Winston Hills Public School (4417)  
**Region :** Western Sydney  
**State Electorate :** Seven Hills  
**Local Government Area :** Parramatta

**Initial Survey :** Noel Arnold & Associates : 01 - May - 2008  
**Reviewed By :** Grencap-NAA : 10 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Pupil Facilities - 1970 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/In-fill-panel/S16					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior**

**B00A - R0001 - External Movement (137.76 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	138m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - General Assistant/Bulk Store (9.71 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>

**B00A - R0003 - Cleaning Supplies (6.22 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>

**B00A - R0004 - General Storeroom (8.17 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>

**B00A - R0005 - Staff Toilet (9.75 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0005/Partition Walls (Cubicles)/S17					<b>Chrysotile (white asbestos)</b>

**B00A - R0006 - Staff Toilet (3.89 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0005/Partition Walls (Cubicles)/S17					<b>Chrysotile (white asbestos)</b>

**B00A - R0007 - General Storeroom (11.11 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>

**B00A - R0008 - Cleaning Supplies (4.49 m2)**

No Asbestos

**B00A - R0009 - Cleaning Distributed Store (4.18 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - Cleaning Supplies (10.25 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Adhesive	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0011 - General Storeroom (9.56 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4417/B00G/R0008/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>		
<b>B00A - R0012 - General Storeroom (9.25 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4417/B00G/R0008/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>		
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0013 - Duplicating Workroom (9.47 m2)</b>						
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0014 - Movement (9.68 m2)</b>						
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0015 - Principal (15.96 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0016 - General Storeroom (1.26 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0017 - Staff Toilet (1.91 m2)</b>						
No Asbestos						
<b>B00A - R0018 - Movement (35.45 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0019 - Staff Toilet (3.67 m2)</b>						
No Asbestos						
<b>B00A - R0020 - General Storeroom (1.66 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0021 - Principal (15.78 m2)</b>						
Floor Coverings Res/Textile	Adhesive	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0022 - Duplicating Workroom (15.13 m2)</b>						
No Asbestos						
<b>B00A - R0024 - Interview (10.22 m2)</b>						
Floor Coverings Res/Textile	Adhesive	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0026 - General Storeroom (9.4 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0027 - Sick Bay (9.39 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0028 - General Storeroom (1.45 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0029 - Sports Store (1.62 m2)</b>						
No Asbestos						
<b>B00A - R0030 - Duplicating Workroom (12.68 m2)</b>						
No Asbestos						
<b>B00A - R0031 - Home Base (55.86 m2)</b>						
Floor Coverings Res/Textile	Adhesive	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0032 - Practical Activities - 1hb (13.28 m2)</b>						
No Asbestos						
<b>B00A - R0033 - Practical Activities - 1hb (14.02 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Home Base (54 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Adhesive	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0037 - General Storeroom (14.35 m2)</b>						
No Asbestos						
<b>B00A - R0038 - External Movement (29.77 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0039 - Main Switch Board (7.15 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0040 - Canteen Office/Store (4.37 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
4417/B00G/R0008/Floor Coverings Res/Textile/S9						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0041 - Canteen (27.31 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
4417/B00G/R0008/Floor Coverings Res/Textile/S9						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0042 - Canteen Office/Store (4.45 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0043 - Canteen Office/Store (5.43 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
4417/B00G/R0008/Floor Coverings Res/Textile/S9						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R0044 - Staff Toilet (1.96 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0045 - Staff Room (81.75 m2)</b>						
Floor Coverings Res/Textile	Adhesive	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0046 - Staff Kitchen (6.04 m2)</b>						
No Asbestos						
<b>B00A - R0047 - Clerical Office/Workroom (12.67 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S28					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00A/R0045/Floor Coverings Res/Textile/S29					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0048 - External Movement (1.39 m2)</b>						
No Asbestos						
<b>B00A - R0049 - Disabled Toilet (12.08 m2)</b>						
No Asbestos						
<b>B00A - R0050 - Clerical Office (25.62 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Flat AC Sheeting 4417/B00J/In-fill-panel/S1					<b>No Asbestos Detected</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior**

**B00B - R0001 - External Movement (104.63 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	105m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00B - R0002 - Cleaning Distributed Store (4.13 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					

**B00B - R0003 - Home Base (59.6 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>

**B00B - R0004 - Home Base Store (6.95 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>

**B00B - R0005 - Home Base Store (6.96 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					

**B00B - R0006 - Personal Effects Storage (6.99 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					

**B00B - R0007 - Home Base (86.47 m2)**

No Asbestos

**B00B - R0008 - Toilets - Boys/Girls (3.57 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0014/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B00B - R0009 - Cleaning Distributed Store (2.3 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0014/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B00B - R0010 - Distribution Board (2.53 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0014/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00B - R0011 - Toilets - Boys (16.59 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00B/R0012/Partition Walls (Cubicles)/S20					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0012 - Toilets - Girls (16.64 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00B/R0012/Partition Walls (Cubicles)/S20					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0013 - Home Base Store (6.9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4417/B00G/R0008/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0014 - Personal Effects Storage (6.96 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4417/B00G/R0008/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0015 - Home Base (56.88 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>	

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/In-fill-panel/S27					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior**

**B00C - R0001 - External Movement (113.85 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	114m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00C - R0002 - Personal Effects Storage (6.99 m2)**

No Asbestos

**B00C - R0003 - Home Base Store (6.94 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - Home Base (86.35 m2)**

No Asbestos

**B00C - R0005 - Home Base Store (6.94 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Personal Effects Storage (6.96 m2)**

No Asbestos

**B00C - R0007 - Home Base (56.8 m2)**

Floor Coverings Res/Textile	Adhesive	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>

**B00C - R0008 - Home Base (56.87 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00C/R0008/Floor Coverings Res/Textile/S32					<b>Chrysotile (white asbestos)</b>

**B00C - R0009 - Personal Effects Storage (6.85 m2)**

No Asbestos

**B00C - R0010 - Home Base Store (6.82 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S31					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0008/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)	
<b>B00C - R0011 - Toilets - Girls (16.55 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0003/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
<b>B00C - R0012 - Toilets - Boys (16.53 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0003/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00G/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
<b>B00C - R0013 - Distribution Board (2.45 m2)</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0014/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00C - R0014 - Cleaning Distributed Store (2.34 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B00C/R0014/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
<b>B00C - R0015 - Toilets - Boys/Girls (3.39 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Administration - 1970 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Wall Cladding	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/Wall Cladding/S10					<b>Chrysotile (white asbestos)</b>
Entry Landing	Compressed AC Sheet	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/Entry Landing/S11					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior****B00D - R0001 - Community Clinic (10.74 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Wall Linings Internal/S12					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00D/R0004/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

**B00D - R0002 - Community Clinic (4.13 m2)**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Wall Linings Internal/S12					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00D/R0004/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

**B00D - R0003 - Community Clinic (10.35 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Wall Linings Internal/S12					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00D/R0004/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

**B00D - R0004 - Community Clinic (6.4 m2)**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Wall Linings Internal/S12					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00D/R0004/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00D/R0004/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Support Unit - 1973 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00F/In-fill-panel/S24					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior****B00F - R0001 - External Movement (120.65 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	121m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0002 - Distribution Board (2.35 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0013 - Plant (0.65 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0014 - Plant (1.15 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00F - R0015 - Disabled Toilet (11.15 m2)**

No Asbestos

**B00F - R0016 - Laundry - Type 2 (3.32 m2)**

No Asbestos

**B00F - R0017 - Staff Toilet (2.04 m2)**

No Asbestos

**B00F - R0018 - Movement (4.14 m2)**

No Asbestos

**B00F - R0019 - Movement (3.09 m2)**

No Asbestos

**B00F - R0020 - Staff Room Annexe (13.36 m2)**

No Asbestos

**B00F - R0021 - Home Base - M (71.53 m2)**

No Asbestos

**B00F - R0022 - Home Base - M (71.61 m2)**

No Asbestos

**B00F - R0024 - Staff Kitchen (38.43 m2)**

No Asbestos

**B00F - R0025 - Movement (10.63 m2)**

No Asbestos

**B00F - R0026 - Interview (31.88 m2)**

Floor Coverings Res/Textile	Adhesive					
	4417/B00F/R0026/Floor Coverings Res/Textile/S22					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4417/B00F/R0026/Floor Coverings Res/Textile/S21	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R0027 - Movement (18.11 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4417/B00F/R0026/Floor Coverings Res/Textile/S21	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 4417/B00F/R0026/Floor Coverings Res/Textile/S22					
					<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Pupil Facilities - 1973 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/In-fill-panel/S23					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior****B00G - R0001 - External Movement (117.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	118m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0002 - Home Base (57.66 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0002/Floor Coverings Res/Textile/S25					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4417/B00G/R0002/Floor Coverings Res/Textile/S26					<b>No Asbestos Detected</b>

**B00G - R0003 - Toilets - Girls (16.66 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0003/Partition Walls (Cubicles)/S8					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0004 - Toilets - Boys (16.69 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0003/Partition Walls (Cubicles)/S8					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0005 - Distribution Board (2.35 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	2Unit	East, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Electrical Hazard</b>					
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0006 - Cleaning Distributed Store (2.4 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0007 - Toilets - Boys/Girls (3.37 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00G - R0008 - Practical Activities - 1hb (16.89 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00G/R0008/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R0009 - Home Base (84.28 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00G/R0002/Floor Coverings Res/Textile/S26				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0002/Floor Coverings Res/Textile/S25				<b>Chrysotile (white asbestos)</b>	
<b>B00G - R0010 - Home Base (58.04 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00G/R0002/Floor Coverings Res/Textile/S26				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00G/R0002/Floor Coverings Res/Textile/S25				<b>Chrysotile (white asbestos)</b>	
<b>B00G - R0011 - Practical Activities - 1hb (13.57 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00G/R0008/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	
<b>B00G - R0012 - Practical Activities - 1hb (13.39 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4417/B00G/R0008/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library/General Learning - 1979 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior**

<b>B00H - R0002 - Practical Activities - 1hb (10.8 m2)</b>	No Asbestos
<b>B00H - R0003 - Home Base (56.24 m2)</b>	No Asbestos
<b>B00H - R0004 - Movement (6.57 m2)</b>	No Asbestos
<b>B00H - R0005 - Personal Effects Storage (16.18 m2)</b>	No Asbestos
<b>B00H - R0006 - Movement (6.03 m2)</b>	No Asbestos
<b>B00H - R0007 - External Movement (9.56 m2)</b>	No Asbestos
<b>B00H - R0008 - Entry Vestibule (13.1 m2)</b>	No Asbestos
<b>B00H - R0009 - Toilets - Boys (3.02 m2)</b>	No Asbestos
<b>B00H - R0010 - Toilets - Girls (3.02 m2)</b>	No Asbestos
<b>B00H - R0011 - Distribution Board (0.9 m2)</b>	Note: No inspection of live electrical installation.
<b>B00H - R0012 - Cleaning Supplies (1.6 m2)</b>	No Asbestos
<b>B00H - R0013 - K.L.A. Store (14.38 m2)</b>	No Asbestos
<b>B00H - R0014 - Library Office/Workroom (8.01 m2)</b>	No Asbestos
<b>B00H - R0015 - Library Office/Workroom (24.86 m2)</b>	No Asbestos
<b>B00H - R0016 - Reading Area (145.28 m2)</b>	No Asbestos
<b>B00H - R0017 - Reading Area (74.73 m2)</b>	No Asbestos
<b>B00H - R0018 - Communications Room (13.5 m2)</b>	No Asbestos
<b>B00H - R0019 - Communications Room (13.74 m2)</b>	No Asbestos
<b>B00H - R0020 - Movement (3.64 m2)</b>	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
						No Asbestos
						<b>B00H - R0021 - Movement (3.64 m2)</b>
						No Asbestos
						<b>B00H - R0022 - Movement (6.08 m2)</b>
						No Asbestos
						<b>B00H - R0023 - Home Base Store (24.37 m2)</b>
						No Asbestos
						<b>B00H - R0024 - Home Base (56.31 m2)</b>
						No Asbestos
						<b>B00H - R0025 - Practical Activities - 1hb (10.71 m2)</b>
						No Asbestos
						<b>B00H - R0027 - Personal Effects Storage (13.25 m2)</b>
						No Asbestos
						<b>B00H - R0028 - Movement (4.65 m2)</b>
						No Asbestos
						<b>B00H - R0029 - Home Base (55.73 m2)</b>
						No Asbestos
						<b>B00H - R0030 - Practical Activities - 1hb (10.74 m2)</b>
						No Asbestos
						<b>B00H - R0032 - Movement (13.56 m2)</b>
						No Asbestos
						<b>B00H - R0033 - Outdoor Learning Area (109.97 m2)</b>
						No Asbestos
						<b>B00H - R0034 - Stairs (0.29 m2)</b>
						No Asbestos
						<b>B00H - R0035 - Stairs (0.29 m2)</b>
						No Asbestos
						<b>B00H - R0036 - Stairs (0.29 m2)</b>
						No Asbestos
						<b>B00H - R1001 - Practical Activities - 1hb (10.77 m2)</b>
						No Asbestos
						<b>B00H - R1002 - Home Base (56.52 m2)</b>
						No Asbestos
						<b>B00H - R1003 - Movement (5.54 m2)</b>
						No Asbestos
						<b>B00H - R1004 - Movement (3.37 m2)</b>
						No Asbestos
						<b>B00H - R1005 - Home Base (56.08 m2)</b>
						No Asbestos
						<b>B00H - R1006 - Practical Activities - 1hb (10.77 m2)</b>
						No Asbestos
						<b>B00H - R1007 - Movement (3.79 m2)</b>
						No Asbestos
						<b>B00H - R1008 - Home Base (56.42 m2)</b>
						No Asbestos
						<b>B00H - R1009 - Practical Activities - 1hb (10.77 m2)</b>
						No Asbestos
						<b>B00H - R1010 - Movement (1.49 m2)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00H - R1011 - Movement (1.52 m2)**

No Asbestos

**B00H - R1012 - Stairs (2.58 m2)**

No Asbestos

**B00H - R1013 - Stairs (2.58 m2)**

No Asbestos

**B00H - R1014 - Stairs (2.58 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Communal Facilities - 1970 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B001 - R0001 - External Movement (118.16 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	119m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B001/R0001/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B001 - R0004 - Uniform Shop (20.66 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B001/R0001/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B001 - R0005 - Communal Space (144.53 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	145m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B001/R0001/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B001 - R0006 - Clerical Office (15.97 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B001/R0001/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B001 - R0007 - Staff Kitchen (5.1 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4417/B001/R0001/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting 4417/B00J/In-fill-panel/S1					<b>No Asbestos Detected</b>
Eaves Linings	Flat AC Sheeting	200m2	North, South, East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior****B00J - R0001 - External Movement (102.57 m2)**

No Asbestos

**B00J - R0002 - Home Base (63.42 m2)**

Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

**B00J - R0003 - Toilets - Girls (54.42 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet 4417/B00J/R0003/Partition Walls (Cubicles)/S2	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00J - R0004 - Cleaning Distributed Store (7.78 m2)**

No Asbestos

**B00J - R0005 - Toilets - Boys (51.77 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet 4417/B00J/R0003/Partition Walls (Cubicles)/S2	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00J - R0006 - Distribution Board (1.27 m2)**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

**B00J - R0007 - Home Base (63.98 m2)**

Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4417/B00J/R0007/Floor Coverings Res/Textile/S18	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------------	--	------	------------	--------------------	---------	--

Floor Coverings Res/Textile	Adhesive 4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00J - R0008 - Home Base (64.22 m2)**

Ceiling Structures/Linings	Vermiculite 4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00J - R0009 - Home Base (63.9 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4417/B00J/R0003/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00J - R0010 - Stairs (5.43 m2)</b>						
No Asbestos						
<b>B00J - R0011 - External Movement (55.25 m2)</b>						
No Asbestos						
<b>B00J - R1001 - Home Base (64.23 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00J/R0007/Floor Coverings Res/Textile/S18					<b>Chrysotile (white asbestos)</b>
<b>B00J - R1002 - Practical Activities - 1hb (52.88 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00J/R0007/Floor Coverings Res/Textile/S18					<b>Chrysotile (white asbestos)</b>
<b>B00J - R1003 - Home Base (64.31 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00J/R0007/Floor Coverings Res/Textile/S18					<b>Chrysotile (white asbestos)</b>
<b>B00J - R1004 - Home Base (64.47 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00J/R0007/Floor Coverings Res/Textile/S18					<b>Chrysotile (white asbestos)</b>
<b>B00J - R1006 - Distribution Board (1.26 m2)</b>						
					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Sheet					
	4417/B00J/R1007/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
<b>B00J - R1007 - General Storeroom (0.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	4417/B00J/R1007/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
<b>B00J - R1008 - Cleaning Supplies (0.35 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	4417/B00J/R1007/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
<b>B00J - R1010 - Home Base (64.15 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4417/B00J/R0007/Floor Coverings Res/Textile/S19					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4417/B00J/R0007/Floor Coverings Res/Textile/S18					<b>Chrysotile (white asbestos)</b>
<b>B00J - R1011 - Stairs (12.63 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00J - R1012 - General Storeroom (4.95 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
		4417/B00J/R1007/Floor Coverings Res/Textile/S4				<b>No Asbestos Detected</b>

**B00J - R1013 - Movement (51.54 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Building Services - 2005 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00K - R0001 - General Storeroom (71.46 m2)**

No Asbestos

**B00K - R0002 - General Storeroom (71.46 m2)**

No Asbestos

**B00K - R0003 - External Movement (251.55 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00L - R0001 - Communal Space (198.63 m2)**

No Asbestos

**B00L - R0002 - Raised Platform (55.43 m2)**

No Asbestos

**B00L - R0003 - Chair Storeroom (12.75 m2)**

No Asbestos

**B00L - R0004 - Communal/Performance Store (10.29 m2)**

No Asbestos

**B00L - R0005 - P.E. Store (16.37 m2)**

No Asbestos

**B00L - R0006 - Toilet - Lobby (2.39 m2)**

No Asbestos

**B00L - R0007 - Toilets - Girls (7.02 m2)**

No Asbestos

**B00L - R0008 - Sound Cupboard (2.04 m2)**

No Asbestos

**B00L - R0009 - Toilet - Lobby (3.31 m2)**

No Asbestos

**B00L - R0010 - Toilets - Boys (5.61 m2)**

No Asbestos

**B00L - R0011 - Cleaning Distributed Store (3.52 m2)**

No Asbestos

**B00L - R0012 - Plant (1.71 m2)**

No Asbestos

**B00L - R0013 - Access Shower/Toilet/Change (3.38 m2)**

No Asbestos

**B00L - R0014 - Main Switch Board (6.92 m2)**

No Asbestos

**B00L - R0015 - Covered Outdoor Learning Area (185.33 m2)**

No Asbestos

**B00L - R0016 - Movement (8.54 m2)**

No Asbestos

**B00L - R0017 - Movement (18.59 m2)**

No Asbestos

**B00L - R0018 - Ramp (12.1 m2)**

No Asbestos

**B00L - R0019 - External Movement (3.3 m2)**

No Asbestos

**B00L - R0020 - External Movement (7.51 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 750 - D11099 - Learning Unit - ESL : Placement Date - 4/12/2014**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		5.76 m2

**Interior**

**R1 - Es1**

End wall panel	Flat AC Sheet	Assumed Asbestos		50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		36 m2

**OS 603 - D14962 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/05/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**- D15689 - : Placement Date - 12/09/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017